

SUBJECT: EVQP8 top-mounted side push switch is not recommended for new design

BULLETIN #: NRFND.PG45.06.15.10-1

Date: June 15, 2010

Page 1 of 1

EFFECTIVE DATE: June 15, 2010

RECOMMENDED REPLACEMENT: No direct replacement. Close alternative are EVQP4 with edge-mounting and same size, or EVQPU with top-mounting and smaller size.

OTHER DETAILS: Not recommended for new design due to weaker mounting strength than alternative products EVQP4 and EVQPU.

AFFECTED PART NUMBERS:

EVQP8003M  
EVQP8203M  
EVQP8403M  
EVQP8603M  
EVQP8H03B  
EVQP8K03Q

PRODUCT DATASHEET:

EVQP8 / EVQP4

<http://industrial.panasonic.com/www-cgi/jvcr13pz.cgi?E+PZ+2+ATK0018+0+4+AM>

EVQPU

<http://industrial.panasonic.com/www-cgi/jvcr13pz.cgi?E+PZ+2+ATK0002+0+4+AM>