

PCN-149023

Product Change Notice

Issue Date: 30 July 2021

Change Type:

Alternate die source for affected part number listed below

Part Affected:

HSM9-C280

Description and Extent of Change:


The alternate die source is qualified per Broadcom’s qualification process and it meets Broadcom qualification requirements.


Reasons for Change:

Supply assurance for affected part number.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change in fit, form, quality and reliability. New forward voltage curve and relative radiant intensity curve are as per table below.





Effective Date of Change:

Effective 31 Oct 2021, shipment may contain parts from existing or alternate die source

Qualification Data:

Reliability data will be provided upon request.

These changes have been reviewed and approved by Broadcom engineers and managers per Broadcom procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Broadcom field sales engineer or Contact Center (<http://www.broadcom.com>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.