



Product Change Notification

TE Connectivity

Product Change Notification: P-17-014095

PCN Date: 26-JAN-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Raychem W&C Distribution Location Change Notification

Description of Changes
Dear Valued Customer, This letter is to provide formal advance notification that Raychem Wire and Cable products will be relocating our distribution facility located in Ontario, CA USA to Fremont, CA USA. There will be no AS9102 FAI s or PPAP's needed or made for this warehouse address change.

Reason for Changes:	
Part status change. TE Connectivity Raychem is committed to providing all customers with high quality products. If further information is required regarding this notification, please contact your local TE Connectivity account manager. We thank you for continued support of TE Connectivity's brand of products.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	05-FEB-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
011083-000	NO			"6-1190087-5", "82A0111-8-9"			
147393-000	NO			"2-1191065-3", "55/0314-28-9"			
216009-000	NO			"1-1191561-6", "55A0114-26-9"			
469411-000	NO			"0024A0024-9X", "9-1193517-2"			
931901-000	NO			"2021D0309-0", "1197223-8"			
9839793001	NO			"8-1197601-7", "99M0111-20-9"			
CY2389-000	NO			"7522B1522-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
011083-000	NO			"6-1190087-5", "82A0111-8-9"			
147393-000	NO			"2-1191065-3", "55/0314-28-9"			
216009-000	NO			"1-1191561-6", "55A0114-26-9"			
469411-000	NO			"0024A0024-9X", "9-1193517-2"			
931901-000	NO			"2021D0309-0", "1197223-8"			
9839793001	NO			"8-1197601-7", "99M0111-20-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CY2389-000	NO			"7522B1522-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
011083-000	NO			"6-1190087-5", "82A0111-8-9"			
147393-000	NO			"2-1191065-3", "55/0314-28-9"			
246009-000	NO			"1-1191561-6", "55A0114 26 9"			
469411-000	NO			"0024A0024-9X", "9-1193517-2"			
931901-000	NO			"2021D0309-0", "1197223-8"			
9839793001	NO			"8-1197601-7", "99M0111-20-9"			
CY2389-000	NO			"7522B1522-9"			