



PCN - 12 005

Issue Date: February 16 2012

Product Name:	Terminal Blocks			
	Pluggable socket			
Product Manager:	Frank Yeh			
Subject:	Product Change Notification			
Distribution:	Global			
Type of Change:	Manufacturing Process Change			
Change Description:	Add glue on header nut and change nut to blind hole type.			
Reason for Change:	In order to improve retention force of the mounting screws, FCI is changing the current mounting screw nut to a blind hole type while adding glue on the header nut to fix in place. This change will be implemented immediately as inventories of existing hardware is depleted. There is no impact to products dimension, appearance, fuction or performance as a result of this change.			
Affected Parts:	Product series 20020031, 20020106, 20020107, 20020108, 20020109, 20020110, 20020111, 20020130, 20020131, 20020136, 20020140, 20020141, 20020142			
Effective Date of Change:	February	17	2012	
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Datasheet Attached?	N/A			
Qual/Test Data Attached?	N/A			
Samples Availability Date:	January	15	2012	
Available Alternatives?	N/A			
Questions?	<i>Contact your local FCI Representative, or</i>			
	<i>Frank Yeh FCI Product Manager</i>			
	<i>Phone: 886 3 4549132 email: frank.yeh@fci.com</i>			