


PCN Number:	20180110002	PCN Date:	January 18, 2018
Title:	Datasheet for LP2950-N, LP2951-N		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
Notification Details			
Description of Change:			
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.			
		LP2950-N, LP2951-N <small>SNVS764Q – JANUARY 2000 – REVISED DECEMBER 2017</small>	
Changes from Revision P (May 2016) to Revision Q			Page
<ul style="list-style-type: none"> Changed LP2951-N ESD parameter pin references and added SENSE pin row to LP2951-N ESD parameter in <i>ESD Ratings</i> table..... 			5
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
LP2950-N, LP2951-N	SNVS764P	SNVS764Q	
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/LP2950-N			
Reason for Change:			
To accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
LP2951ACM	LP2951ACMMX-3.3/NOPB	LP2951CM-3.3	LP2951CMX-3.0/NOPB
LP2951ACM-3.0/NOPB	LP2951ACMMX/NOPB	LP2951CM-3.3/NOPB	LP2951CMX-3.3
LP2951ACM-3.3	LP2951ACMX	LP2951CM/NOPB	LP2951CMX-3.3/NOPB
LP2951ACM-3.3/NOPB	LP2951ACMX-3.0/NOPB	LP2951CMM	LP2951CMX/NOPB
LP2951ACM/NOPB	LP2951ACMX-3.3/NOPB	LP2951CMM-3.0/NOPB	LP2951CN/NOPB
LP2951ACMM	LP2951ACMX/NOPB	LP2951CMM-3.3/NOPB	LP2951CSD-3.0/NOPB
LP2951ACMM-3.0	LP2951ACN/NOPB	LP2951CMM/NOPB	LP2951CSD-3.3/NOPB
LP2951ACMM-3.0/NOPB	LP2951ACSD	LP2951CMMX	LP2951CSD/NOPB
LP2951ACMM-3.3	LP2951ACSD/NOPB	LP2951CMMX-3.0/NOPB	LP2951CSDX-3.0/NOPB
LP2951ACMM-3.3/NOPB	LP2951ACSDX-3.3/NOPB	LP2951CMMX-3.3	LP2951CSDX-3.3/NOPB
LP2951ACMM/NOPB	LP2951ACSDX/NOPB	LP2951CMMX-3.3/NOPB	LP2951CSDX/NOPB
LP2951ACMMX-3.0	LP2951CM	LP2951CMMX/NOPB	
LP2951ACMMX-3.0/NOPB	LP2951CM-3.0/NOPB	LP2951CMX	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com