

ID No. 887	<b>Product/Process Change Notification</b>	Date 28.04.2022
<b>Product</b>	<b>Ordering Code</b>	
<b>BGS2T RS232</b>	<b>L30960N2700A100</b>	
Ordering Code changes:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Product</b>	<b>New Ordering Code</b>	
<b>BGS2T RS232</b>	<b>L30960N2700A200</b>	

### Reason of Change:

- |   |  |
|---|--|
| <input checked="" type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement             | <input type="checkbox"/> Location of production moved                    |
| <input type="checkbox"/> Quality improvement              | <input type="checkbox"/> Other:  |

<b>Description of change:</b>	To secure supply continuity even in times of component EOL Thales had to change the built-in variant of the radio module to handle a new memory chip. The functionality of BGS2T is NOT impacted and does not change. All existing BGS2T documentation remains valid also for the new ordering codes.
<b>Schedule details:</b>	23/2022
Availability of SW for evaluation:	n.a.
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW 23/2022
<b>Timing note:</b>	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

<b>Quality assurance measurements:</b>	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

### Attachments: none

28.04.2022

28.04.2022

X *F. Ryll*

F.Ryll  
Product Program Manager  
Signed by: RYLL Frank

X *J. Erdmann*

J.Erdmann  
Head of Quality Management IoT  
Signed by: ERDMANN Joerg