

| | | | |
|-----------------------------|--|-------------------------------------|---------------------|
| Notification Number: | 20150814000A | Notification Date: | 1/25/2015 |
| Title: | Datasheet update for TUSB7340/TUSB7320 | | |
| Customer Contact: | PCN Manager | Dept: | Quality Services |
| Change Type: | | | |
| <input type="checkbox"/> | Assembly Site | <input type="checkbox"/> | Design |
| <input type="checkbox"/> | Assembly Process | <input checked="" type="checkbox"/> | Data Sheet |
| <input type="checkbox"/> | Assembly Materials | <input type="checkbox"/> | Part number change |
| <input type="checkbox"/> | Mechanical Specification | <input type="checkbox"/> | Test Site |
| <input type="checkbox"/> | Packing/Shipping/Labeling | <input type="checkbox"/> | Test Process |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Bump Site |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Bump Material |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Bump Process |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Fab Site |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Fab Materials |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Fab Process |

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is updated as seen in the change revision history below:



TUSB7320, TUSB7340

SLLSE76M – MARCH 2011 – REVISED JULY 2015

www.ti.com

Changes from Revision L (August 2013) to Revision M

Page

- Added Pin Configuration and Functions section, ESD Ratings table, Feature Description section, Device Functional Modes, Application and Implementation section, Power Supply Recommendations section, Layout section, Device and Documentation Support section, and Mechanical, Packaging, and Orderable Information section 1
- Deleted from Section Clock Source Requirements part of the paragraph; -50MHZ. Changed supported Crystal value to 24MHZ and 48 MHz 14
- Deleted the first ItemizedList under Two-Wire Serial-Bus Interface section 15
- Deleted part of sentence from Table 112. in bit row 30, description; 'with the PLL...SEL field..... 55
- Deleted the Description from Table 112, in row 29:24 and replaced with Reserved also, replaced rw with w in same row 55

The datasheet number will be changing.

| | | |
|-------------------|--------------|------------|
| Device Family | Change From: | Change To: |
| TUSB7340/TUSB7320 | SLLSE76L | SLLSE76M |

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/tusb7340>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this Notification:

None.

Product Affected:

| | | | |
|---------------|---------------|--------------|--------------|
| TUSB7340IRKMR | TUSB7340IRKMT | TUSB7340RKMR | TUSB7340RKMT |
| TUSB7320IRKMR | TUSB7320IRKMT | TUSB7320RKMR | TUSB7320RKMT |

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

| Location | E-Mail |
|--------------|--|
| USA | PCNAmericasContact@list.ti.com |
| Europe | PCNEuropeContact@list.ti.com |
| Asia Pacific | PCNAsiaContact@list.ti.com |
| Japan | PCNJapanContact@list.ti.com |