

Material Change Notice: DX4 Receptacle



Due to the discontinuance of the material currently being used, the insulator for the following DX4 receptacle parts will be changing per below:

	Part Number	SJ Drawing	Insulator Material Change
1	DX4R005JJ2R1800	SJ110579	Current Material: 35% GMF LCP TYPE IX SELCION KC173W New Material: 35% GMF LCP TYPE UENO LCP UX101
2	DX4R005HJ5R2000	SJ111771	
3	DX4R005JJER1800	SJ114662	

There is no change in connector performance or SJ drawings.

Effective: **March 2015**

For any questions regarding this matter, please contact your local JAE Sales Rep, Regional Sales Manager, or Marketing at marketing@jae.com.

Thank you for your cooperation.