

**+ CORPORATE
HEADQUARTERS**707 Dayton Road
PO Box 1040
Ottawa, IL 61350
USAp: (800) 346-3119
f: (815) 433-5109**+ EUROPEAN
HEADQUARTERS**Westlink Commercial Park
Unit 10
Oranmore, Co. Galway
Irelandp: + 353 91 792444
f: + 353 91 792445**+ CELLULAR
PRODUCTS GROUP**Sokolská 71
562 04 Ústí nad Orlicí III.
Czech Republicp: +420 465 521 020
f: +420 464 647 299**Product Change Notice**

June 22, 2018

Model	Description
BB-485USBTB-4W-LS	USB TO SERIAL 1PT 485, 4W, TB - LOCKED SERIAL #
BB-485USBTB-4W	USB TO SERIAL 1PT, 4WIRE, TB
BB-485USBTB-2W-LS	USB TO SERIAL 1PT 485, 2W, TB - LOCKED SERIAL #
BB-485USBTB-2W	USB TO SERIAL 1PT 485, 2W, TB

The products listed above will be changed as follows:

1. The products will be updated to use the standard FTDI Virtual COM Port (VCP) driver software, eliminating the need for a specific B+B version of this same VCP driver software. This will streamline the user experience by allowing Windows to find and install the driver software without the need for an installation CD. The nature of this change makes the old driver software incompatible with products produced after the effective date of this change. There are no other changes to the product functionality.
2. Remove the installation CD from the product package. The VCP Driver Software will continue to be available for manual download on our support web pages.
3. Update the product documentation.
4. Due to our internal IT business system needs, our internal part numbers will change.

Model Number	Old B+B Part Number	New B+B Part Number
485USBTB-4W-LS	BB-485USBTB-4W-LS	BB-485USBTB4WLS-A
485USBTB-4W	BB-485USBTB-4W	BB-485USBTB-4W-A
485USBTB-2W-LS	BB-485USBTB-2W-LS	BB-485USBTB2WLS-A
485USBTB-2W	BB-485USBTB-2W	BB-485USBTB-2W-A

Product Migration Path:

This change is effective July 30, 2018.

Best Regards,

Brian Foster | Product Manager