

# Product Obsolescence Memo

## INDUCTIVE COMPONENTS

Bourns Manufacturers Representatives  
Corporate Distributor Product Managers  
Americas Sales Team  
Asia Sales Team  
Europe Sales Team  
Bourns Internal  
Bourns Plant Managers



January, 2011

### **Bourns® SRP1040 High Current Inductor Series with Certain Values to be Discontinued**

Effective **December 1, 2011**, Bourns will no longer accept orders for the **SRP1040** inductor series for the inductance values of 22  $\mu\text{H}$ , 33  $\mu\text{H}$  and 47  $\mu\text{H}$ . A last time buy must be placed on or before **November 30, 2011**. A low sales volume and poor production yield of these inductor values necessitates this action. Effective immediately, Bourns will no longer offer samples of the values to be discontinued.

We regret there is no suitable replacement part for these discontinued inductors.

Affected Bourns® part numbers:

SRP1040-220M  
SRP1040-330M  
SRP1040-470M

If you have any questions, please contact Bourns Customer Service.