



Product Change Notification

TE Connectivity

Product Change Notification: P-19-016788

PCN Date: 15-JAN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Tubing products impacted by new Prop 65

Description of Changes

This PCN is to inform our customers of additional labelling on some Tubing products. The requirements of the Proposition 65 (Prop 65) a Californian Safe water and Toxic Enforcement Act of 1986 now requires that we warn customers that some of our tubing products contain Antimony in the material make up. This requirement only applies to customer in California. However, as TE cannot predict which products will arrive with customers in California we have to label all Antimony containing products, of course these products will be delivered also to customers outside of California. No Action needs to be taken by our customers outside of California unless the products you receive are directly being forwarded through the supply chain to further customer in California USA in which case the warning must accompany the product. Please share this information with your colleagues so they will also be informed.

Reason for Changes:

Product improvement.To comply with Californian Prop 65 regulations.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	16-JAN-2019

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
008339J001	NO			"6-1190064-3", "V4-6.0-0-SP-SM"			
034565-000	NO			"5-1190267-6", "VERSAFIT-1/2-9-FSP"			
046571J001	NO			"7-1190357-5", "V2-18.0-0-FSP-SM"			
080745J001	NO			"2-1190599-8", "V2-1.0-0-SP-SM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
1547294005	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
292801-000	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1"			
3128594003	NO			"6-1192366-9", "CGAT-12/4-0-SP"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
3371890007	NO			"8-1192545-1", "ES-CAP-NO.1-C1-0-50MM"			
4476334005	NO			"7-1193363-1", "V4-3/4-0-SP", "4-27033-2284"			
5020012023	NO			"5-1193752-9", "RP-4800-NO.1-0-STK"			
5020044017	NO			"3-1193753-0", "RP-4800-NO.3-0-SP"			
5020104007	NO			"7-1193753-9", "RP-4800-NO.10-0-SP"			
5038814001	NO			"7-1193794-6", "DCPT-10/5-45-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5050154002	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
5052844025	NO			"4-1193821-8", "RNF-100-3/64-0-SP"			
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894048	NO			"6-1193823-2", "RNF-100-1/16-0-SP"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053224021	NO			"5-1193867-0", "RNF-100-1/2-6-SP"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5053444034	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
5053474006	NO			"6-1193888-1", "RNF-100-3-6-SP"			
5056844010	NO			"9-1193902-5", "RNF-100-1-1/4-BK-SP"			
5058734012	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
5058764004	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
5068034005	NO			"7-1193935-1", "CGPT-1.6/0.8-2-SP"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5125934002	NO			"1194028-6", "NETM1000-3-0-SP"			
5200082006	NO			"6-1194081-5", "CRN-1/2-0-STK"			
5200292033	NO			"1194084-5", "CRN-3/32-0-MS-STK"			
5302194002	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5504062059	NO			"7-1194343-4", "ATUM-3/1-0-STK"			
5504062129	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
5507834098	NO			"8-1194346-9", "ATUM-9/3-0-SP"			
5509112040	NO			"6-1194351-0", "ATUM-24/8-0-STK"			
5509122053	NO			"8-1194352-9", "ATUM-40/13-0-STK", "ATUM-40/13-0-STK"			
560393-000	NO			"8-1194423-2", "VERSAFIT-1/2-5-FSP"			
5677584004	NO			"1194495-2", "RNF-3000-9/3-0-SP", "8252614135"			
5762674002	NO			"1-1194572-1", "RNF-150-1/8-0-SP"			
5983222002	NO			"7-1198045-3", "DSPL-NR2-0-STK"			
6149234001	NO			"5-1194860-9", "CGPT-12/4-2-SP"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK"			
6479954003	NO			"8-1195115-7", "VERSAFIT-3/16-2-SP"			
6679894002	NO			"5-1195260-8", "VERSAFIT-4-0-SP"			
674983J001	NO			"6-1195308-4", "V2-7.0-0-SP-SM"			
6918832001	NO			"9-1195431-6", "RAYRIM-NR12-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			
7574444009	NO			"2-1195902-5", "RAYRIM-NR8-0-SP"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
840595-000	NO			"3-1196558-1", "V4-1/4-0-SP"			
881723J001	NO			"7-1196863-4", "V2-14.0-0-FSP-SM"			
9243974002	NO			"6-1197170-7", "NETM2000-12-0-SP"			
929859J001	NO			"7-1197208-7", "V4-9.0-0-FSP-SM"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
9668274002	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
A82691-000	NO			"6-1200721-2", "VERSAFIT-3/8-KT2-REFILL"			
A92664-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"9-1200589-9", "VERSAFIT-3/4-KT1-REFILL"			
CB5005-000	NO			"BSTS-04X4FR"			
CB5087-000	NO			"9-1899207-4", "HF-07FRX4"			
CB5349-000	NO						
CB5393-000	NO						
CF7300-000	NO			"5-1899235-0", "HF-17FRX4"			
CY6791-000	NO			"CRN-3/64-0-MS-STK"			
CY6792-000	NO			"CRN-1/16-0-MS-STK", "4-1899832-6"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
F37063-000	NO			"1-1200590-3", "VERSAFIT-1/4-KT1-REFILL"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07166001	NO			"BATTU-25.4/12.7-A1-2-51MM", "7-1899840-5"			
NB07186001	NO			"BATTU-12.7/6.1-A1-0-51MM"			
NB08994001	NO						
NB10372001	NO			"ATUM--24/8-0-STK"			
NB10602001	NO						
NB11354001	NO						
NB12034001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
034565-000	NO			"5-1190267-6", "VERSAFIT-1/2-9-FSP"			
080745J001	NO			"2-1190599-8", "V2-1.0-0-SP-SM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
292801-000	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
4476334005	NO			"7-1193363-1", "V4-3/4-0-SP", "4-27033-2284"			
5038814001	NO			"7-1193794-6", "DCPT-10/5-45-SP"			
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5056844010	NO			"9-1193902-5", "RNF-100-1-1/4-BK-SP"			
5058734012	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
5058764004	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5200292033	NO			"1194084-5", "CRN-3/32-0-MS-STK"			
5302194002	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5504062059	NO			"7-1194343-4", "ATUM-3/1-0-STK"			
5504062129	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"7-1194343-9", "ATUM-3/1-0-MS-STK"			
5507834098	NO			"8-1194346-9", "ATUM-9/3-0-SP"			
5509112040	NO			"6-1194351-0", "ATUM-24/8-0-STK"			
5509122053	NO			"8-1194352-9", "ATUM-40/13-0-STK", "ATUM-40/13-0-STK"			
5677584004	NO			"1194495-2", "RNF-3000-9/3-0-SP", "8252614135"			
5762674002	NO			"1-1194572-1", "RNF-150-1/8-0-SP"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK"			
6479954003	NO			"8-1195115-7", "VERSAFIT-3/16-2-SP"			
674983J001	NO			"6-1195308-4", "V2-7.0-0-SP-SM"			
7574444009	NO			"2-1195902-5", "RAYRIM-NR8-0-SP"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
881723J001	NO			"7-1196863-4", "V2-14.0-0-FSP-SM"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
9668274002	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
A82691-000	NO			"6-1200721-2", "VERSAFIT-3/8-KT2-REFILL"			
A92664-000	NO			"9-1200589-9", "VERSAFIT-3/4-KT1-REFILL"			
CB5087-000	NO			"9-1899207-4", "HF-07FRX4"			
CB5349-000	NO						
CY6792-000	NO			"CRN-1/16-0-MS-STK", "4-1899832-6"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
F37063-000	NO			"1-1200590-3", "VERSAFIT-1/4-KT1-REFILL"			
NB10372001	NO			"ATUM--24/8-0-STK"			
NB10602001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
008339J001	NO			"6-1190064-3", "V4-6.0-0-SP-SM"			
034565-000	NO			"5-1190267-6", "VERSAFIT-1/2-9-FSP"			
046571J001	NO			"7-1190357-5", "V2-18.0-0-FSP-SM"			
080745J001	NO			"2-1190599-8", "V2-1.0-0-SP-SM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
1547294005	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
292801-000	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
3371890003	NO			"7-1192545-9", "ES-CAP-NO.1-C1-0-35MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
4476334005	NO			"7-1193363-1", "V4-3/4-0-SP", "4-27033-2284"			
5020044017	NO			"3-1193753-0", "RP-4800-NO.3-0-SP"			
5038814001	NO			"7-1193794-6", "DCPT-10/5-45-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5050154002	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5053444034	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
5056844010	NO			"9-1193902-5", "RNF-100-1-1/4-BK-SP"			
5058734012	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
5058764004	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5125934002	NO			"1194028-6", "NETM1000-3-0-SP"			
5200292033	NO			"1194084-5", "CRN-3/32-0-MS-STK"			
5302194002	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5504062059	NO			"7-1194343-4", "ATUM-3/1-0-STK"			
5504062129	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
5507834098	NO			"8-1194346-9", "ATUM-9/3-0-SP"			
5509112040	NO			"6-1194351-0", "ATUM-24/8-0-STK"			
5509122053	NO			"8-1194352-9", "ATUM-40/13-0-STK", "ATUM-40/13-0-STK"			
560393-000	NO			"8-1194423-2", "VERSAFIT-1/2-5-FSP"			
5677584004	NO			"1194495-2", "RNF-3000-9/3-0-SP", "8252614135"			
5762674002	NO			"1-1194572-1", "RNF-150-1/8-0-SP"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK"			
6479954003	NO			"8-1195115-7", "VERSAFIT-3/16-2-SP"			
6679894002	NO			"5-1195260-8", "VERSAFIT-4-0-SP"			
674983J001	NO			"6-1195308-4", "V2-7.0-0-SP-SM"			
7574444009	NO			"2-1195902-5", "RAYRIM-NR8-0-SP"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
840595-000	NO			"3-1196558-1", "V4-1/4-0-SP"			
881723J001	NO			"7-1196863-4", "V2-14.0-0-FSP-SM"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
9668274002	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
A92664-000	NO			"9-1200589-9", "VERSAFIT-3/4-KT1-REFILL"			
CB5005-000	NO			"BSTS-04X4FR"			
CB5087-000	NO			"9-1899207-4", "HF-07FRX4"			
CB5349-000	NO						
CB5393-000	NO						
CF7300-000	NO			"5-1899235-0", "HF-17FRX4"			
CY6792-000	NO			"CRN-1/16-0-MS-STK", "4-1899832-6"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
F37063-000	NO			"1-1200590-3", "VERSAFIT-1/4-KT1-REFILL"			
NB10372001	NO			"ATUM--24/8-0-STK"			
NB10602001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
008339J001	NO			"6-1190064-3", "V4-6.0-0-SP-SM"			
046571J001	NO			"7-1190357-5", "V2-18.0-0-FSP-SM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
1547294005	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
3128594003	NO			"6-1192366-9", "CGAT-12/4-0-SP"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
3371890007	NO			"8-1192545-1", "ES-CAP-NO.1-C1-0-50MM"			
4476334005	NO			"7-1193363-1", "V4-3/4-0-SP", "4-27033-2284"			
5020012023	NO			"5-1193752-9", "RP-4800-NO.1-0-STK"			
5020044017	NO			"3-1193753-0", "RP-4800-NO.3-0-SP"			
5020104007	NO			"7-1193753-9", "RP-4800-NO.10-0-SP"			
5038814001	NO			"7-1193794-6", "DCPT-10/5-45-SP"			
5052844025	NO			"4-1193821-8", "RNF-100-3/64-0-SP"			
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894048	NO			"6-1193823-2", "RNF-100-1/16-0-SP"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053224021	NO			"5-1193867-0", "RNF-100-1/2-6-SP"			
5053444034	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
5053474006	NO			"6-1193888-1", "RNF-100-3-6-SP"			
5058734012	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
5068034005	NO			"7-1193935-1", "CGPT-1.6/0.8-2-SP"			
5125934002	NO			"1194028-6", "NETM1000-3-0-SP"			
5200082006	NO			"6-1194081-5", "CRN-1/2-0-STK"			
5200292033	NO			"1194084-5", "CRN-3/32-0-MS-STK"			
5302194002	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
5507834098	NO			"8-1194346-9", "ATUM-9/3-0-SP"			
560393-000	NO			"8-1194423-2", "VERSAFIT-1/2-5-FSP"			
5677584004	NO			"1194495-2", "RNF-3000-9/3-0-SP", "8252614135"			
5762674002	NO			"1-1194572-1", "RNF-150-1/8-0-SP"			
5983222002	NO			"7-1198045-3", "DSPL-NR2-0-STK"			
6149234001	NO			"5-1194860-9", "CGPT-12/4-2-SP"			
6479954003	NO			"8-1195115-7", "VERSAFIT-3/16-2-SP"			
6679894002	NO			"5-1195260-8", "VERSAFIT-4-0-SP"			
6918832001	NO			"9-1195431-6", "RAYRIM-NR12-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7574444009	NO			"2-1195902-5", "RAYRIM-NR8-0-SP"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
840595-000	NO			"3-1196558-1", "V4-1/4-0-SP"			
9243974002	NO			"6-1197170-7", "NETM2000-12-0-SP"			
929859J001	NO			"7-1197208-7", "V4-9.0-0-FSP-SM"			
CB5005-000	NO			"BSTS-04X4FR"			
CB5087-000	NO			"9-1899207-4", "HF-07FRX4"			
CB5349-000	NO						
CB5393-000	NO						
CF7300-000	NO			"5-1899235-0", "HF-17FRX4"			
CY6791-000	NO			"CRN-3/64-0-MS-STK"			
CY6792-000	NO			"CRN-1/16-0-MS-STK", "4-1899832-6"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
NB08994001	NO						
NB11354001	NO						
NB12034001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
008339J001	NO			"6-1190064-3", "V4-6.0-0-SP-SM"			
046571J001	NO			"7-1190357-5", "V2-18.0-0-FSP-SM"			
1547294005	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
4476334005	NO			"7-1193363-1", "V4-3/4-0-SP", "4-27033-2284"			
5020044017	NO			"3-1193753-0", "RP-4800-NO.3-0-SP"			
5038814001	NO			"7-1193794-6", "DCPT-10/5-45-SP"			
5050154002	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5053444034	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
5125934002	NO			"1194028-6", "NETM1000-3-0-SP"			
5507834098	NO			"8-1194346-9", "ATUM-9/3-0-SP"			
560393-000	NO			"8-1194423-2", "VERSAFIT-1/2-5-FSP"			
6479954003	NO			"8-1195115-7", "VERSAFIT-3/16-2-SP"			
6679894002	NO			"5-1195260-8", "VERSAFIT-4-0-SP"			
7574444009	NO			"2-1195902-5", "RAYRIM-NR8-0-SP"			
840595-000	NO			"3-1196558-1", "V4-1/4-0-SP"			
CB5005-000	NO			"BSTS-04X4FR"			
CB5087-000	NO			"9-1899207-4", "HF-07FRX4"			
CB5349-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5393-000	NO						
CF7300-000	NO			"5-1899235-0", "HF-17FRX4"			
CY6792-000	NO			"CRN-1/16-0-MS-STK", "4-1899832-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
A82691-000	NO			"6-1200721-2", "VERSAFIT-3/8-KT2-REFILL"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
008339J001	NO			"6-1190064-3", "V4-6.0-0-SP-SM"			
046571J001	NO			"7-1190357-5", "V2-18.0-0-FSP-SM"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
1547294005	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
3128594003	NO			"6-1192366-9", "CGAT-12/4-0-SP"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
3371890005	NO			"8-1192545-0", "ES-CAP-NO.1-C1-0-40MM"			
3371890007	NO			"8-1192545-1", "ES-CAP-NO.1-C1-0-50MM"			
4476334005	NO			"7-1193363-1", "V4-3/4-0-SP", "4-27033-2284"			
5020012023	NO			"5-1193752-9", "RP-4800-NO.1-0-STK"			
5020044017	NO			"3-1193753-0", "RP-4800-NO.3-0-SP"			
5020104007	NO			"7-1193753-9", "RP-4800-NO.10-0-SP"			
5038814001	NO			"7-1193794-6", "DCPT-10/5-45-SP"			
5050154002	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
5052844025	NO			"4-1193821-8", "RNF-100-3/64-0-SP"			
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894048	NO			"6-1193823-2", "RNF-100-1/16-0-SP"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053224021	NO			"5-1193867-0", "RNF-100-1/2-6-SP"			
5053444034	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
5053474006	NO			"6-1193888-1", "RNF-100-3-6-SP"			
5058734012	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"9-1193906-4", "VERSAFIT-3/16-9-SP"			
5068034005	NO			"7-1193935-1", "CGPT-1.6/0.8-2-SP"			
5125934002	NO			"1194028-6", "NETM1000-3-0-SP"			
5200082006	NO			"6-1194081-5", "CRN-1/2-0-STK"			
5200292033	NO			"1194084-5", "CRN-3/32-0-MS-STK"			
5302194002	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
5507834098	NO			"8-1194346-9", "ATUM-9/3-0-SP"			
560393-000	NO			"8-1194423-2", "VERSAFIT-1/2-5-FSP"			
5677584004	NO			"1194495-2", "RNF-3000-9/3-0-SP", "8252614135"			
5762674002	NO			"1-1194572-1", "RNF-150-1/8-0-SP"			
5983222002	NO			"7-1198045-3", "DSPL-NR2-0-STK"			
6149234001	NO			"5-1194860-9", "CGPT-12/4-2-SP"			
6479954003	NO			"8-1195115-7", "VERSAFIT-3/16-2-SP"			
6679894002	NO			"5-1195260-8", "VERSAFIT-4-0-SP"			
6918832001	NO			"9-1195431-6", "RAYRIM-NR12-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			
7574444009	NO			"2-1195902-5", "RAYRIM-NR8-0-SP"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
840595-000	NO			"3-1196558-1", "V4-1/4-0-SP"			
9243974002	NO			"6-1197170-7", "NETM2000-12-0-SP"			
929859J001	NO			"7-1197208-7", "V4-9.0-0-FSP-SM"			
CB5005-000	NO			"BSTS-04X4FR"			
CB5087-000	NO			"9-1899207-4", "HF-07FRX4"			
CB5349-000	NO						
CB5393-000	NO						
CF7300-000	NO			"5-1899235-0", "HF-17FRX4"			
CY6791-000	NO			"CRN-3/64-0-MS-STK"			
CY6792-000	NO			"CRN-1/16-0-MS-STK", "4-1899832-6"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07166001	NO			"BATTU-25.4/12.7-A1-2-51MM", "7-1899840-5"			
NB07186001	NO			"BATTU-12.7/6.1-A1-0-51MM"			
NB08994001	NO						
NB11354001	NO						
NB12034001	NO						