



Product Change Notification

Date Issued :	January 30, 2023	PCN Number :	512825
Reason for Change :	Change Supplier		
Description of Change :	Material change in contact Ethernet RJ45.		
Reason for Short Notice :	Supplier Constraints		
Assessment of Change :	First Article Inspection		
Planned Implementation Date :	February 10, 2023		
Sample Availability Date:	October 28, 2022		
Internal Molex Qualification Date :	October 28, 2022		
Last date to request Samples by Customer :	February 07, 2023		
Traceability Code Markings / Date :	No special marking on the product or packaging		

Before Picture

BEFORE

Old contact material: CuNi2SiPb

AFTER

New contact material: CuNi1Pb1P

After Picture

Overview

- Material change needed because of no availability of raw material for further production.

- Product Impact
 - There is no change in form or function of the component.

- Part Number Impact
 - See attached impacted parts list

RELEASED

You may address inquires regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512825
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512825** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com

PCN No Part List

512825 [1203410571](#)

512825 [1203410700](#)

512825 [1203410701](#)

512825 [1203410703](#)

512825 [1203410705](#)

512825 [1203410706](#)

512825 [1203410750](#)

512825 [1203410751](#)

512825 [1203410752](#)

512825 [1203410753](#)

512825 [1203410755](#)

512825 [1203410756](#)

512825 [1203410757](#)

512825 [1203410890](#)

512825 [1203410891](#)

512825 [1203410892](#)

512825 [1203410915](#)

512825 [1203410958](#)

512825 [1203410959](#)

512825 [1203411009](#)

512825 [1203411010](#)

512825 [1203411077](#)

512825 [1203411100](#)