



February 15, 2018

Product Advisory #1657 VL-EPIC-17 (Newt)

This is a formal notification that products supplied by VersaLogic Corporation are being revised. Our records indicate that your company has purchased one or more of these products.

Please read this notice thoroughly to determine what impact this change may have on you in regards to your currently owned product or future purchases from VersaLogic.

Affected Products

Product	Description	Old Revision Level	New Revision Level
VL-EPIC-17EA VL-EPIC-17EB	Newt SBC	1.01	1.02

Changes Made to Product

The BIOS of the VL-EPIC-17 (Newt) models listed above, was recently updated to revision 1.03. This update resolves an issue which produced video artifacts in the BIOS Setup screen when the EPIC-17 was used in conjunction with an EPM-V7E video interface board.

Customer Impact

Fielded Units

This issue only occurs when the EPIC-17 is used with the EPM-V7E video interface board. Fielded units not connected to an EPM-V7E do not need to be updated.

Fielded units can be updated with BIOS revision 1.03 without returning them to VersaLogic. The BIOS can be downloaded from the [VL-EPIC-17 support page](#).

Future Shipments

New revision boards will begin shipping in March, 2018.

Additional Information

For additional information or assistance related to this change, please contact VersaLogic Customer Support at Support@VersaLogic.com or call (503) 747-2261.