

**Type of Notification:**

**To:** All Customers

- |   |  |                                     |
|---|--|-------------------------------------|
| <input type="checkbox"/> Product Change | <input type="checkbox"/> Process Change          | <input type="checkbox"/> Relocation |
| <input type="checkbox"/> Product Alert  | <input checked="" type="checkbox"/> Obsolescence | <input type="checkbox"/> Other      |

**Notification Date:** April 2, 2103

**Effective Date:** April 2, 2013

AVX Part Number / Series / Product: Series 8026, All part numbers

Customer Part Number / Series / Drawing: N/A

Material Identification: N/A

Date Code / Lot Code: N/A

**Applicable Information for Product Alerts:**

Purchase Order Number: _____	Shipment Date: _____
Packing Slip Number(s): _____	Quantity: _____

**Description of Advisory / Notice:**

The mold tooling for the entire range of 8026 male and female connectors is no longer functional. AVX has made several attempts to revive the 30+ year old tools with no success. Pricing and leadtime was pulled off line several years ago. There is not enough volume left to warrant reinvesting in new tools.

There is no replacement product for this series, it was a sole source product developed in the 1970's

**Point of Contact:**

<b>Name:</b>	<b>Tom Anderson</b>	<b>Title:</b>	<b>Product Manager</b>
<b>Address:</b>	<b>AVX Corporation</b>	<b>Telephone #:</b>	<b>864-228-3421</b>
	<b>One AVX Boulevard</b>	<b>Fax #:</b>	
	<b>Fountain Inn, SC 29664</b>	<b>E-Mail:</b>	<b>tom.anderson@avx.com</b>