



Product Change Notification (PCN)

PCN Number	505255	Date Issued	August 29, 2018
Reason for Change	Supplier Change		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Reason for Short Notice	Force Majeure		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	June 05, 2018		
Sample Availability Date (Changed Part)	June 05, 2018		
Planned Implementation Date	September 07, 2018		
Method of Identifying Change	Date code		

RELEASED

Before Change

▪ Before

Accessory supplier XY (#145165) will be replaced by other two suppliers



▪ After

Accessory supplier LX (#191392) support foam and JG (#168582) support Tape. Also LX, JG are DG qualified suppliers and supply Foams or tapes to DG for many years on other projects.

After Change

Overview

- The key reason for this supplier change is current supplier XY are shut down suddenly. But supplier LX and JG are more professional than XY in foam and tape field with better technology and die-cutting machines.
- Product Impact
 - No impact to fit, form or function.
- Part Number Impact
 - See attached list
- Qualification Reports and samples available upon customer request, already pass Molex FAI process



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505255**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

687860001

687860002

687860003

687860007

745470303

747521051

747521101

747521201

747521301

747522151

747522301

747523501

747524501

747529004

747571101

857271002

857271003

857351008

1002971101

1002971201

1002971301

1003461201

1111451101

1111451251

1111451301

Part numbers affected:

68786-0002
68786-0003
74737-0014
74752-1101
74757-2301
100297-1251
111040-1054