

PRODUCT CHANGE NOTIFICATION

Product Category OUTLETS 20221209-1

Product Group ROAR

ISSUE DATE: 9-Dec-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Existing phone plate kits will have new part numbers to reflect a change in the jack module included with the kit. The TP style jack that is currently found in these kits will be replaced by a punchdown style jack. Product application will not change.

Photos/Drawing (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	1	30
Old product discontinuation date*	2023	3	9

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
KWP5EY	Compatible	KWPK5E
KWP6PY	Compatible	KWPK6