



Product End-of-Life (EOL) Notification

AFFECTED PART NUMBER(S): LZ4-00SW08-xxxx; LZ4-40SW08-xxxx; LZ9-00SW00-xxxx; LZ9-J0SW00-xxxx; LZ9-M0SW00-xxxx; LZC-00SW00-xxxx; LZC-70SW00-xxxx; LZC-C0SW00-xxxx; LZF-00SW00-xxxx; LZF-D0SW00-xxxx;	EOL No. 00014
PART DESCRIPTION: Studio White emitters on LZ4, LZ9, LZC, and LZF platform	DATE: 4/30/2015
RECOMMENDED REPLACEMENT PART NUMBER(S): No replacement as a standard catalog product. May continue to be supported as a non-standard custom order on a case by case basis.	
REASON FOR EOL: Insufficient demand	
LAST ORDER DATE: Existing orders will be fulfilled.	LAST SHIPMENT DATE: 7/31/2015
DISPOSITION OF EXISTING INVENTORY: Use up current inventory	
NOTE: 	
CONTACT PERSON: <i>Ishita Goswami</i> <i>Product Manager</i> <i>651 River Oaks Parkway</i> <i>San Jose, CA 95134</i> <i>igoswami@ledengin.com</i>	