


## Global Change Notification (GCN)

Product Family	MXP120 sealed	10663118
		GCN Number
Series	34900	December 10, 2014
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	To improve connector un-mating ergonomics, we are implementing a different latch design on our receptacle connectors . The change has been already implemented on the 1x4 and needs to be implemented on the 1x6 as they share the same assembly equipment. Change will be implemented on 1x2 and 1x3 as well to be consistent in performance and features across the family. This change has been reviewed and approved by the OEM and immediate implementation has been requested.	



Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.
Reason For Short Notice Exception	Special Request
Assessment Of Change (How Product Will Be Qualified & Validated)	validation testing
Internal Molex Qualification Date (Planned Date Information Available)	January 30, 2015
Sample Availability Date (Changed Part)	January 30, 2015
Date of Implementation	January 31, 2015
Method of Identifying Change	New part numbers issued
Recommended Replacement Parts	NA
Last Time Buy Date for Obsolete Parts	January 30, 2015
Last Time Ship Date for Obsolete Parts	January 30, 2015

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)