



OVERVIEW

DATE ISSUED:	January 6 th , 2023	TRACKING NUMBER:	4134966
ISSUED BY:	IoT Solutions Product Management		
PRODUCTS AFFECTED:	HL7800, HL7802		
SKUS AFFECTED:	See “Details of Change” for SKUs affected		
BULLETIN:	Depopulation of eSIM		
URGENCY:	Normal		
EFFECTIVE DATE:	March 30 th , 2023		
FOR DISTRIBUTION TO:	All HL78 customers and their partners		

Summary

Sierra Wireless is announcing the depopulation of the eSIM component from the affected SKUs covered in this PCN. The eSIM is currently provided on certain SKUs to give the option for customers to use Sierra Wireless Smart Connectivity without the need of an external SIM. Customers wishing to use this feature should migrate to the HL7810 or HL7812 which will continue to have SKU options that include the eSIM. Sierra Wireless Smart Connectivity is also available using external plastic SIM cards.

This change does not affect any fit, form or function (outside of the eSIM feature) of the product, nor does it have any impact on country, industry, or Mobile operator certifications.

Details of Change

The following table summarizes the affected SKUs.

SKU#	Description
1104888	HL7800,GENERIC,GENERIC,4.6.9.4,,AVMS,GNSS=AB,SWIR IMEI,UART=115200 BDS,R2C
1104956	HL7800,GENERIC,GENERIC,4.6.9.4,,AVMS,GNSS=AB,SWIR IMEI,USB,R2C
1104503	HL7802,GENERIC,GENERIC,4.3.9,,AVMS,GNSS=AB,SWIR IMEI,UART=115200 BDS,R2C
1104845	HL7802,GENERIC,GENERIC,4.6.8.0,,AVMS,GNSS=AB,SWIR IMEI,UART=115200 BDS,R2C
1104889	HL7802,GENERIC,GENERIC,4.6.9.4,,AVMS,GNSS=AB,SWIR IMEI,UART=115200 BDS,R2C
1105030	HL7802,GENERIC,GENERIC,4.6.9.4,,AVMS,GNSS=AB,SWIR IMEI,USB,R2C

Effective Dates

This change is expected to take affect at the end of March 2023.

More information

For more information please contact your Sierra Wireless sales/technical support person.