



TE Connectivity

Product Change Notification: P-15-012042

PCN Date: 07-SEP-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

090 SLD 3P Plug Assy (PN: 936251)


Description of Changes

Reinforce for protector guide on the plug housing. the protector guide height will increase.

Countermeasure

✓ 090 SLD 3P PLUG HSG (PN:936252)

- ◆ Push Lever Broken
- ◆ Reinforce Lever Protector Height



Information is Teys Electronics Confidential & Proprietary
Do Not Reproduce or Distribute

Related PCN-1

1/5 28/01/1

E-15-003538 : Summary Report

generated Sep 7, 2015 8:22 PM

Attributes

Type:	PCN	PCN General Product Description:	090 SLD 3P PLUG ASSY (PN: 936251)
Name:	E-15-003538	PCN Description Of Change:	REINFORCE FOR LEVER PROTECTOR
State:	Distributed	PCN Reason For Change:	Customer Request, CUSTOMER REQUEST
Originated:	Mar 4, 2015 3:17:03 AM	PCN Classification:	Part FN Function Change
Modified:	Mar 16, 2015 8:40:02 PM	Estimated First Ship Date For Changed Parts:	5/29/2015 11:00:00 AM
		Mixed Shipments Possible For Changed Parts:	No
		Estimated Last Date For Mixed Shipments:	
		Estimated Last Order Date For Obsolete Parts:	
		Estimated Last Ship Date For Obsolete Parts:	

Approvals

Name	Signature	Signer	Status	Description
No Signatures or Routes in Approvals				

Routes

Name	Description	Status	Due Date	Owner
No objects found				

Affected Items(Revised Parts)

Name	Type	Material Type	Recent Sales?	On Agreement 49?	Agreement 49 Wait Period (days)	PCN Required
936251-2	Part	Finished Product	Yes	Yes	0	For Customer Approval
936251-3	Part	Finished Product	Yes	No	90	For Notification Only
936252-2	Part	Semi-Finished Product	Yes	No	0	For Notification Only
936252-3	Part	Semi-Finished Product	No	No	0	Not Required

<http://plmcentral.tycoelectronics.com/TEC/plmapp/tes/tesEng/PCNSummaryReport.jsp?objectid=2335445586.34912.32320>

2015-09-08

Related PCN-2

2/5 28/01/1

Affected Items(Specifications)

Name	Type	Revision	Related To Part On Agreement 49?	Agreement 49 Wait Period (days)	PCN Required
936251	Customer Drawing	A	No	0	Not Required
936251	Production Drawing	A	Yes	90	Not Required
936252	Production Drawing	A	No	0	Not Required

Affected Items(Obsolete Parts)

Name	Type	Material Type	Recent Sales?	On Agreement 49?	Agreement 49 Wait Period (days)	PCN Required
No obsolete parts are found for this						

Files

Name	Type	Title	Format
No Files are found			

Images

No Images are found			
---------------------	--	--	--

Other attachments:

[Customer View Modeling](#)

<http://plmcentral.tycoelectronics.com/TEC/plmapp/tes/tesEng/PCNSummaryReport.jsp?objectid=2335445586.34912.32320>

2015-09-08

Reason for Changes:

Customer Request.The protector guide on housing will increase height more than before by local customer requirements. Please check it and refer attached countermeasure.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

16-NOV-2015

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
936251-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
936251-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
936251-2	NO						