



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000804

DATE: 30-Jun-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX15301AA01+CK	N/A			Part reactivated from prior notice: M000789
Reactivation	MAX15301AA01+TCK	N/A			Part reactivated from prior notice: M000789
Reactivation	MAX9668ETP+	N/A			Part reactivated from prior notice: M000802
Reactivation	MAX9668ETP+T	N/A			Part reactivated from prior notice: M000802
Reactivation	MAX9679BETG+	N/A			Part reactivated from prior notice: M000802
Reactivation	MAX9679BETG+T	N/A			Part reactivated from prior notice: M000802
Change to Prior Notice	MAX9812LEXT+	MAX9814ETD+	17-Dec-2015	30-Jun-2017	Part can no longer be manufactured
Change to Prior Notice	MAX9812LEXT+T	MAX9814ETD+T	17-Dec-2015	30-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 31-Jul-2015