



## Product Change Notification / GBNG-11YGIP429

---

### Date:

17-Nov-2020

### Product Category:

Clock and Timing - Clock Generation, Clock and Timing - Oscillators

### PCN Type:

Manufacturing Change

### Notification Subject:

CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

### Affected CPNs:

[GBNG-11YGIP429\\_Affected\\_CPN\\_11172020.pdf](#)

[GBNG-11YGIP429\\_Affected\\_CPN\\_11172020.csv](#)

### Notification Text:

**PCN Status:** Final notification

**PCN Type:** Manufacturing Change

**Microchip Parts Affected:** Please open one of the icons found in the Affected CPNs section above.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**Description of Change:** Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

#### Pre Change:

With top mark DCPYYWW at the 2nd line marking.

#### Post Change:

With top mark DCPYYWW or DAPYYW at the 2nd line marking.

**Pre and Post Change Summary:**

	Pre Change	Post Change
Top mark	See attached pre and post marking change	

**Impacts to Data Sheet:** None

**Change Impact:**None

**Reason for Change:**

To improve manufacturability and traceability by implementing top marking changes for DSCxxx and DSxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages.

**Change Implementation Status:**

In Progress

**Estimated First Ship Date:**

November 19, 2020 (date code: 2047)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

**Time Table Summary:**

	November 2020				
Workweek	45	46	47	48	49
Final PCN Issue Date			X		
Estimated Implementation Date			X		

**Method to Identify Change:**

Traceability code, top marking

**Qualification Report:**

Not applicable

**Revision History:**

**November 17, 2020:** Issued final notification. Provided estimated first ship date to be on November 19, 2020.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

**Attachments:**

## PCN\_GBNG-11YGIP429\_Marking Pre and Post Change.pdf

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

DSA1101DA2-025.0000TVAO  
DSA1101DA2-050.0000TVAO  
DSA1121DA2-025.0000TVAO  
DSA1121DA2-027.0000TVAO  
DSA1121DA2-050.0000TVAO  
DSA1121DA2-100.0000TVAO  
DSA1121DA2-125.0000TVAO  
DSA1101DA3-054.0000TVAO  
DSA1101DA3-122.8800TVAO  
DSA1101DA3-125.0000TVAO  
DSA1121DA3-004.0000TVAO  
DSA1121DA3-008.0000TVAO  
DSA1121DA3-016.0000TVAO  
DSA1121DA3-020.0000TVAO  
DSA1121DA3-030.0000TVAO  
DSA2311KA1-R0075TVAO  
DSA2311KA2-R0002TVAO  
DSA2311KA2-R0005TVAO  
DSA2311KA2-R0009TVAO  
DSA2311KA2-R0011TVAO  
DSA2311KA2-R0015TVAO  
DSA2311KA2-R0021TVAO  
DSA2311KA2-R0065TVAO  
DSA2311KA2-R0067TVAO  
DSA2311KA2-R0073TVAO  
DSA2311KA2-R0076TVAO  
DSA2311KA3-R0021TVAO  
DSA2311KA3-R0041TVAO  
DSA2311KA3-R0073TVAO  
DSA2311KA1-R0024TVAO  
DSC1001CC1-024.0000  
DSC1001CC1-025.0000  
DSC1001CC1-040.0000  
DSC1001CC1-047.3333  
DSC1001CC2-012.5000  
DSC1001CC2-024.0000  
DSC1001CC2-025.0000  
DSC1001CC1-125.0000  
DSC1001CC5-008.5920  
DSC1001CC2-050.0000  
DSC1001CC2-100.0000  
DSC1001CC2-125.0000  
DSC1001CC5-024.5760  
DSC1001CC2-012.2880  
DSC1001CC1-008.0000  
DSC1001CC2-033.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CC1-027.0000  
DSC1001BC1-020.0000  
DSC1001BC1-024.0000  
DSC1001DC1-004.9152  
DSC1101DL5-052.8000T  
DSC1123DL5-200.0000T  
DSC1123DL1-125.0000T  
DSC1101DL1-027.0000T  
DSC2311KL1-R0002T  
DSC1121DL2-008.0000T  
DSC1101DL5-020.0000T  
DSC1103DL5-125.0000T  
DSC1101DL5-016.0000T  
DSC1121DL2-032.0000T  
DSC2311KL2-R0040T  
DSC2311KL2-R0052T  
DSC1121DE1-050.0000T  
DSC1101DL2-050.6880T  
DSC1103DL2-147.4560T  
DSC1123DE2-399.6800T  
DSC1123DE2-400.0000T  
DSC2311KL1-R0054T  
DSC1103DL2-156.2500T  
DSC1101DL1-150.0000T  
DSC1121DL5-026.0000T  
DSC1121DL1-025.0000T  
DSC1121DL1-033.0000T  
DSC1104DL1-027.0000T  
DSC1123DL5-135.0000T  
DSC1123DL5-150.0000T  
DSC1101DL5-024.5760T  
DSC1101DL5-018.4320T  
DSC1101DE5-040.0000T  
DSC1101DE5-012.2880T  
DSC1121DE2-025.0000T  
DSC1101DE2-049.1520T  
DSC1101DE2-045.1584T  
DSC1123DL2-100.0000T  
DSC2311KL2-R0002T  
DSC1121DL2-072.0000T  
DSC1121DL1-040.0000T  
DSC1101DL3-PROGT  
DSC1101DL5-PROGT  
DSC1100DL3-PROGT  
DSC1100DL5-PROGT  
DSC2311KE2-R0016T  
DSC1123DL5-176.5000T  
DSC1123DL5-206.5000T  
DSC1123DL5-136.5000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103DL1-025.0013T  
DSC1103DL2-025.0012T  
DSC1123DE1-148.3516T  
DSC1101DE2-024.5760T  
DSC1101DE2-022.5792T  
DSC1101DE2-100.0000T  
DSC1121DL5-072.0000T  
DSC1121DE5-072.0000T  
DSC1103DL2-100.0000T  
DSC1124DL2-100.0000T  
DSC1103DL2-122.8800T  
DSC1103DL2-098.3040T  
DSC1101DE2-012.0000T  
DSC1104DE5-100.0000T  
DSC1104DL3-100.0000T  
DSC1124DL5-100.0000T  
DSC1124DL1-100.0000T  
DSC1103DL5-156.2500T  
DSC1123DL2-250.0000T  
DSC1121DE1-010.0000T  
DSC2311KL2-R0071T  
DSC1101DL2-033.3300T  
DSC1104DL2-026.0000T  
DSC2311KL1-R0072T  
DSC1122DL2-220.0000T  
DSC1124DL1-027.0000T  
DSC1123DL2-050.0000T  
DSC1121DE3-150.3330T  
DSC1101DL1-020.0000T  
DSC1123DE1-125.0000T  
DSC1122DL1-072.0000T  
DSC1102DL1-212.5000T  
DSC2311KE2-R0002T  
DSC2311KE2-R0081T  
DSC1123DE1-156.2500T  
DSC1103DL5-027.0000T  
DSC1103DL5-100.0000T  
DSC1101DL2-025.0000T  
DSC1123DL1-025.0000T  
DSC1122DE5-254.6500T  
DSC1103DL5-063.5000T  
DSC1103DL2-135.0000T  
DSC2311KE1-R0085T  
DSC1123DL2-156.2500T  
DSC1123DL1-156.2500T  
DSC2311KL2-R0091T  
DSC2311KE2-R0090T  
DSC1103DE5-254.6500T  
DSC1123DL3-100.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA231TKL1-R0009TVAO

DSA1103DL1-125.0000TVAO

DSA1105DL1-027.0000TVAO

DSC1103CL3-250.0000

DSC1101CE1-080.0000

DSC1103CL1-020.0000

DSC1124CL5-027.0000

DSC1121CE1-030.0000

DSC1121CE2-030.0000

DSC1101CE3-024.0000

DSC1121CE5-025.0000

DSC1121CL5-027.0000

DSC1101CE5-045.1584

DSC1103CE5-135.0000

DSC1103CE1-100.0000

DSC1124CE2-027.0000

DSC1101CL2-026.0000

DSC1124CL5-100.0000

DSC1123CE5-393.2160

DSC1121CE1-124.2000

DSC1121CL2-020.5710

DSC1121CL5-125.0000

DSC1123CL2-026.0000

DSC1121CL2-024.0000

DSC1123CL3-125.0000

DSC1121CL5-003.3000

DSC1123CL3-100.0000

DSC1123CL3-250.0000

DSC1123CL3-093.4400

DSC557-0344FI1

DSC557-0343FI1

DSC2011FI2-E0002

DSC2044FI2-H0006

DSC2222FI1-F0006

DSC2022FI1-F0006

DSC2044FI2-F0022

DSC2211FI1-E0021

DSC2144FI2-F0022

DSC2110FI2-A0008

DSC2110FI2-A0006

DSC2011FI2-F0035

DSC2033FI2-F0003

DSC2011FI1-F0036

DSC2033FI2-F0037

DSC2033FI2-F0038

DSC2033FI2-F0039

DSC2041FI1-F0025

DSC2033FI2-F0040

DSC2144FI2-E0023

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2123FI2-E0024

DSC2030FI5-B0011

DSC2030FI1-B0019

DSC2011FI2-F0042

DSC2022FI1-H0006

DSC2011FI1-F0043

DSC2122FI2-E0025

DSC2033FI2-F0044

DSC2030FI2-B0020

DSC2033FI1-F0039

DSC2222FI2-E0026

DSC2010FI2-A0018

DSC2010FI2-A0021

DSC2030FI2-C0009

DSC2030FI2-C0010

DSC1123DL3-100.0000

DSA2311KL1-R0009VAO

DSA1103DL1-125.0000VAO

DSA1105DL1-027.0000VAO

DSA1123DL1-100.0000VAO

DSA1124DL1-100.0000VAO

DSA1101DL2-026.0000VAO

DSA1103DL2-156.2500VAO

DSA1121DL2-033.3333VAO

DSA1123DL2-125.0000VAO

DSA1124DL2-024.0000VAO

DSA1124DL2-100.0000VAO

DSA1101DL3-016.0000VAO

DSA1101DL3-020.0000VAO

DSA1101DL3-025.0000VAO

DSA1101DL3-026.0000VAO

DSA1105DL3-033.3330VAO

DSA1123DL3-100.0000VAO

DSA1123DL3-125.0000VAO

DSA2311KL1-R0015VAO

DSA2311KL1-R0065VAO

DSA2311KL2-R0009VAO

DSA2311KL1-R0078VAO

DSA2311KL2-R0015VAO

DSA2311KL2-R0027VAO

DSA2311KL2-R0065VAO

DSA2311KL2-R0073VAO

DSA2311KL2-R0084VAO

DSA2311KL2-R0087VAO

DSC2011FE2-E0004

DSC2011FL1-E0002

DSC2011FL2-F0020

DSC2030FE1-C0001

DSC2031FE1-J0001



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2033FE2-F0010

DSC2040FE1-D0001

DSC2041FE1-K0003

DSC2044FE1-H0002

DSC2044FE1-H0003

DSC2130FE1-C0003

DSC2010FE1-B0013

DSC2043FE1-F0023

DSC557-0333FL0

DSC2033FL2-F0028

DSC2044FL1-F0022

DSC2044FL1-H0005

DSC2044FE1-F0022

DSC2044FE1-F0024

DSC2041FE1-F0014

DSC557-0333FE0

DSC557-0341FE1

DSC557-0344FE0

DSC557-0344FE1

DSC557-0344FL1

DSC2044FE2-H0006

DSC2030FE5-B0018

DSC2022FE2-F0034

DSC2111FE1-E0022

DSC2033FL1-F0022

DSC2010FL2-B0014

DSC2041FE1-K0002

DSC2033FL2-F0004

DSC2031FL2-F0045

DSC2011FL2-E0005

DSC2110FL1-A0029

DSC2110FL2-C0011

DSC2144FL2-F0022

DSC2033FL2-F0051

DSC2033FL2-E0005

DSC2031FL2-F0052

DSC2210FL2-A0026

DSC2041FL1-F0014

DSC2011FE1-F0057

DSA557-0333FL0VAO

DSA557-0344FL0VAO

DSA557-0344FL1VAO

DSC1101CL2-016.3840T

DSC1101CL5-027.0000T

DSC1103CE1-200.0000T

DSC1103CE2-135.0000T

DSC1101CL2-002.5000T

DSC1103CE2-200.0000T

DSC1103CE5-150.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103CL5-106.2500T  
DSC8123CL1T  
DSC1121CE1-016.0000T  
DSC1121CE1-025.0000T  
DSC8123CL5T  
DSC1121CE1-025.0012T  
DSC1121CE1-075.0000T  
DSC1121CE2-025.0000T  
DSC1121CE2-100.0000T  
DSC1121CL2-025.0000T  
DSC1121CL2-050.0000T  
DSC1121CL5-024.0000T  
DSC1121CL5-048.0000T  
DSC1123CE1-156.2500T  
DSC1121BM1-060.0000T  
DSC1121BM1-016.0000T  
DSC1121BM1-026.0000T  
DSC1121BM1-012.2880T  
DSC1121BM2-131.0720T  
DSC1121BM2-020.0000T  
DSC1121BM2-025.0000T  
DSC1121BM2-032.0000T  
DSC1121BM1-032.0000T  
DSC1123BM1-287.0000T  
DSC1123BM1-166.0000T  
DSC1121BM1-014.7456T  
DSC1121BM1-005.5296T  
DSC1121AM1-025.0000T  
DSC1121AM1-030.0000T  
DSC1121AM1-050.0000T  
DSC1121AM2-010.0000T  
DSC1121AM2-027.0000T  
DSC1121AM2-125.0000T  
DSC1101AM2-014.3950T  
DSC1121AM1-010.0000T  
DSC1101AM2-030.0000T  
DSC1121AM1-020.0000T  
DSC1121AM1-027.0000T  
DSC1121AM1-012.2880T  
DSC1103AM1-287.0000T  
DSC1123AM1-287.0000T  
DSC1121AM1-032.7680T  
DSC1121AM1-014.7456T  
DSC1001BI5-018.4320T  
DSC1001BI2-029.4912T  
DSC1001BI3-033.0000T  
DSC1001BI3-050.0000T  
DSC1001BI2-001.5440T  
DSC1001BI1-033.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001BI1-133.0000T  
DSC1003BI5-040.0000T  
DSC1001BI2-011.0592T  
DSC1001BI5-019.6800T  
DSC1001BI1-003.6864T  
DSC1004BI5-121.5000T  
DSC1001BI2-003.1250T  
DSC1001BI5-066.6660T  
DSC1004BI5-005.0000T  
DSC1001BI1-099.0000T  
DSC1001BI2-099.0000T  
DSC1001BI5-040.9600T  
DSC1001BI2-003.6864T  
DSC1001BI3-020.0000T  
DSC1001BI2-040.6800T  
DSC1001BI2-033.3300T  
DSA1001BI2-125.0000TVAO  
DSC1001DI1-001.8432T  
DSC1001DI1-003.6864T  
DSC1001DI1-004.0000T  
DSC1001DI1-005.0000T  
DSC1001DI1-005.0196T  
DSC1001DI1-008.0000T  
DSC1001DI1-010.0000T  
DSC1001DI1-012.0000T  
DSC1001DI1-014.7456T  
DSC1001DI1-016.0000T  
DSC1001DI1-016.3840T  
DSC1001DI1-019.2000T  
DSC1001DI1-020.0000T  
DSC1001DI1-024.0000T  
DSC1001DI1-024.5760T  
DSC1001DI1-025.0000T  
DSC1001DI1-026.0000T  
DSC1001DI1-027.0000T  
DSC1001DI1-033.3000T  
DSC1001DI1-133.0000T  
DSC1001DI1-033.3330T  
DSC1001DI1-033.3333T  
DSC1001CI5-024.0000  
DSC1001CI5-025.0000  
DSC1001CI5-026.0000  
DSC1001CI5-032.7680  
DSC1001CI5-037.1250  
DSC1001CI5-040.0000  
DSC1001CI5-050.0000  
DSC1001CI2-054.0000  
DSC1001CI5-100.0000  
DSC1003CI1-050.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003CI5-020.0000  
DSC1003CI5-087.5000  
DSC1001CI2-125.0000  
DSC1001CI5-012.0000  
DSC1004CI5-081.0000  
DSC1001CI5-008.0000  
DSC8001CI1  
DSC8001CI2  
DSC8001CI5  
DSC1001CI5-012.2880  
DSC8004CI2  
DSC1001CI2-096.0000  
DSC1003CI5-025.0000  
DSC1001CI5-018.4320  
DSC1001CI5-016.0000  
DSC1001CI5-024.5760  
DSC1001CI5-027.0000  
DSC1001CI5-030.0000  
DSC1001CI1-003.6864  
DSC1001CI2-012.5000  
DSC1001CI5-009.6000  
DSC1001CI1-100.0000  
DSC1001CI2-006.0000  
DSC1001CI5-044.0000  
DSC1001CI5-019.0000  
DSC1001CI5-060.0000  
DSC1001CI1-033.0000  
DSC1001CI5-011.0592  
DSC1001CI2-031.2500  
DSC1001CI2-049.1520  
DSC1001CI2-032.0000  
DSC1001CI5-133.3330  
DSC1001CI5-070.4550  
DSC1001CI2-008.1920  
DSC1001CI2-010.4857  
DSC1001CI2-001.9521  
DSC8003CI2  
DSC1001CI2-007.3728  
DSC1001CI2-150.0000  
DSC1001CL5-044.0000  
DSC1001CL1-016.6400  
DSC1003CL2-050.0000  
DSC1001CE1-100.0000  
DSC1001CE1-110.0000  
DSC1001CE1-032.0000  
DSC1001CL3-024.0000  
DSC1001CL3-072.0000  
DSC1001CE2-019.2000  
DSC1001CE2-108.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CE3-005.0000  
DSC1001CL2-048.0000  
DSC1001CL2-090.0000  
DSC1001CE2-064.0000  
DSC1001CL3-008.0000  
DSC1001CL1-012.0000  
DSC1001CL2-022.5792  
DSC1001CL5-007.3728  
DSC1001CL5-028.0000  
DSC1004CL2-003.2768  
DSC1001CL1-008.0000  
DSC1001CL2-026.0000  
DSC1001CL5-064.0000  
DSC1001CE2-013.5600  
DSC1001CE5-032.2123  
DSC1001CE1-048.0000  
DSC1001CL2-006.0052  
DSC1001CL1-040.0000  
DSC1003CL1-020.0000  
DSC1001CL1-006.0053  
DSC1121BM2-032.0000  
DSC1121BM1-032.0000  
DSC1123BM1-287.0000  
DSC1123BM1-166.0000  
DSC1121BM1-014.7456  
DSC1121BM1-005.5296  
DSC1101AM1-160.0000  
DSC1101AM2-004.0000  
DSC1101AM2-100.0000  
DSC1121AM2-004.0000  
DSC1121AM2-010.0000  
DSC1121AM2-016.0000  
DSC1121AM2-024.0000  
DSC1121AM2-024.5760  
DSC1121AM2-025.0000  
DSC1121AM2-027.0000  
DSC1121AM2-033.3330  
DSC1121AM2-050.0000  
DSC1121AM2-066.6660  
DSC8121AM2  
DSC1121AM2-125.0000  
DSC1121AM1-100.0000  
DSC1121AM2-008.0000  
DSC1101AM2-014.3950  
DSC1121AM1-010.0000  
DSC1101AM2-030.0000  
DSC1121AM1-020.0000  
DSC1121AM1-027.0000  
DSC1121AM1-012.2880

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103AM1-287.0000  
DSC1123AM1-287.0000  
DSC1121AM1-032.7680  
DSC1121AM1-014.7456  
DSC1121AM1-041.5000  
DSC1121AM2-041.5000  
DSC1121AM1-029.4912  
DSC1121AM1-024.5760  
DSC1121AM1-033.0000  
DSC1101AM2-156.2500  
DSC1121AM1-064.0000  
DSC1101DM1-033.3330  
DSC1101DM2-020.0000  
DSC1101DM2-016.0000  
DSC1101DM2-025.0000  
DSC1101DM2-125.0000  
DSC1121DM2-007.3728  
DSC1121DM2-125.0000  
DSC2311KM1-R0036  
DSC2311KM2-R0005  
DSC612NI3A-01KV  
DSC6003JI2B-001.0000  
DSC6003JI2B-003.5700  
DSC6102JI2B-100.0000  
DSC6001JI3B-008.0000  
DSC6001JI3B-024.5760  
DSC6101JI3B-075.0000  
DSC6331JI1CB-027.0000  
DSC6101JI1B-024.0000  
DSC6003JI2B-012.0000  
DSC6111JI1B-024.0000  
DSC6011JI2B-002K000  
DSC6011JI2B-032K768  
DSC6011JI2B-250K000  
DSC6011JI2B-432K000  
DSC6011JI2B-720K000  
DSC6013JI2B-001.0000  
DSC6013JI2B-032K768  
DSC6013JI2B-250K000  
DSC6013JI2B-432K000  
DSC6013JI2B-720K000  
DSC6111JI2B-032K768  
DSC6111JI2B-250K000  
DSC6111JI2B-432K000  
DSC6111JI2B-720K000  
DSC6112JI2B-001.0000  
DSC6112JI2B-032K768  
DSC6112JI2B-250K000  
DSC6112JI2B-432K000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6112JI2B-720K000  
DSC6111JI2B-004K000  
DSC6112JI2B-004K000  
DSC6011JI1B-012.0000  
DSC6011JI3B-025.0000  
DSC6101JI2B-025.0000  
DSC6102JI2B-025.0000  
DSC6102JI2B-027.0000  
DSC6013JI1B-032.7680  
DSC6013JI1B-008.0000  
DSC6111JI1B-025.0000  
DSC6111JI2B-024.0000  
DSC6001JI3B-439K000  
DSC6101JI3B-439K000  
DSC6011JI1B-025.0000  
DSC6013JI1B-025.0000  
DSC6112JI1B-050.0000  
DSC6101JI2B-027.0000  
DSC6011JI2B-025.0000  
DSA6331JA2GB-025.0000VAO  
DSA6001JA3B-004.0000VAO  
DSA6001JA3B-010.0000VAO  
DSA6001JA3B-016.0000VAO  
DSA6041JA3B-016.0000VAO  
DSC612PA3A-0118  
DSC612PA3A-0119  
DSC612PA3A-011A  
DSC612PA3A-0176  
DSC613PA2A-018W  
DSC612PA3A-01EQ  
DSC612PA3A-010K  
DSC612PA1A-01H5  
DSA612PA2A-01DMVAO  
DSA612PA3A-0130VAO  
DSA612PA3A-01DQVAO  
DSC612RA3A-010S  
DSC613RA2A-0106  
DSC612RA3A-0138  
DSC612RA1A-0173  
DSC612RA1A-0174  
DSC612RA3A-0181  
DSC613RA3A-018B  
DSC612RA3A-01B2  
DSC612RA3A-014S  
DSC612RA1A-01H5  
DSC612RA1A-01JJ  
DSC612RA3A-01JW  
DSC612RA1A-0102  
DSA612RA1A-01KGVVAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA612KA2A-01GMVAO

DSA613RA2A-01BGVAO

DSC6001HI2B-012.0000

DSC6001HI2B-024.0000

DSC6003HI2B-012.0000

DSC6001HI3B-032K768

DSC6003HI3B-010.0000

DSC6101HI3B-019.2000

DSC6003HI2B-025.0000

DSC6003HI2B-024.0000

DSC6011HI2B-002K000

DSC6011HI2B-032K768

DSC6011HI2B-250K000

DSC6011HI2B-432K000

DSC6011HI2B-720K000

DSC6013HI2B-001.0000

DSC6013HI2B-002K000

DSC6013HI2B-032K768

DSC6013HI2B-250K000

DSC6013HI2B-432K000

DSC6013HI2B-720K000

DSC6112HI2B-001.0000

DSC6111HI2B-032K768

DSC6111HI2B-250K000

DSC6111HI2B-432K000

DSC6111HI2B-720K000

DSC6112HI2B-032K768

DSC6112HI2B-250K000

DSC6112HI2B-432K000

DSC6112HI2B-720K000

DSC6111HI2B-004K000

DSC6112HI2B-004K000

DSC6001HI2B-048.0000

DSC6003HI3B-027.0000

DSC6111HI3B-010.0000

DSC6013HI2B-003.6864

DSC6021HI3B-016R

DSC6001HI2B-006.0000

DSC6001HI2B-008.0000

DSC6011HI1B-016.0000

DSC6011HI1B-024.0000

DSC6011HI1B-025.0000

DSC6011HI1B-009.6000

DSC6021HI2B-018E

DSC6011HI3B-064.0128

DSC6013HI3B-064.0128

DSC6003HI2B-019.2000

DSC6111HI1B-032K768

DSC6001HI1B-020.0000



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121AI1-064.0000T  
DSC1102AI1-050.0000T  
DSC1122AI1-159.3750T  
DSC1101AI1-025.0000T  
DSC1121AI2-150.0000T  
DSC1123AI1-150.0000T  
DSC1123AI2-062.5000T  
DSC1123AI1-120.0000T  
DSC1123AI2-156.2570T  
DSC1101AI2-080.0000T  
DSC1101AI2-040.0000T  
DSC1101AI2-064.0000T  
DSC1123AI2-027.0000T  
DSC1123AI2-050.0000T  
DSC1122NI2-150.0000T  
DSC1123NI1-100.0000T  
DSC1123NI2-125.0000T  
DSC1124NI1-100.0000T  
DSC1124NI1-156.2500T  
DSC1123NI2-312.5000T  
DSC1101NI5-025.0000T  
DSC1101NI5-020.0000T  
DSC400-0101Q0096KE2  
DSC400-3331Q0097KE1  
DSC400-3331Q0097KE2  
DSC400-3331Q0098KE1  
DSC400-3331Q0098KE2  
DSC400-3333Q0099KE1  
DSC400-3333Q0099KE2  
DSC400-3133Q0100KE1  
DSC400-3133Q0100KE2  
DSC400-0103Q0102KE1  
DSC400-0103Q0102KE2  
DSC400-0401Q0103KE1  
DSC400-0401Q0103KE2  
DSC400-2222Q0104KE1  
DSC400-2222Q0104KE2  
DSC400-2222Q0105KE1  
DSC400-2222Q0105KE2  
DSC400-3333Q0104KE1  
DSC400-3333Q0104KE2  
DSC400-0202Q0106KE1  
DSC400-0202Q0106KE2  
DSC400-0202Q0107KE1  
DSC400-0202Q0107KE2  
DSC400-0202Q0108KE1  
DSC400-0202Q0108KE2  
DSC400-0202Q0109KE1  
DSC400-0202Q0109KE2

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6003MI2B-014.0000T  
DSC6003MI2B-026.0000T  
DSC6101MI2B-048.0000T  
DSC6001MI3B-004.0960T  
DSC6111MI2B-027.0000T  
DSC6111MI2B-024.5454T  
DSC6331MI2CB-008.0000T  
DSC6331MI2DB-008.0000T  
DSC6331MI2EB-008.0000T  
DSC6011MI2B-025.0000T  
DSC6011MI2B-056.0000T  
DSC6101MI2B-006.1679T  
DSC6003MI3B-032K768T  
DSC6003MI3B-012.0000T  
DSC6003MI2B-027.0000T  
DSC6111MI2B-006.1679T  
DSC6011MI1B-007.3728T  
DSC6102MI2B-125K000T  
DSC6101MI2B-008.0000T  
DSC6001MI3B-032K768T  
DSC6003MI2B-080.0000T  
DSC6003MI2B-032K768T  
DSC6003MI2B-050.0000T  
DSC6111MI2B-025.0000T  
DSC6001MI2B-007.3728T  
DSC6001MI1B-007.3728T  
DSC6011MI2B-007.3728T  
DSC6021MI1B-01B1T  
DSC6301MI2CB-008.0000T  
DSC6001MI1B-032K768T  
DSC6001MI2B-032K768T  
DSC6001MI2B-027.0000T  
DSC6102MI3B-038.4000T  
DSC6001MI2B-032.7680T  
DSC6111MI3B-033.3333T  
DSC6011MI3B-048.0000T  
DSC6101MI2B-024.0000T  
DSC6101MI1B-050.0000T  
DSC6101MI1B-024.0000T  
DSC6011MI2B-004.0960T  
DSC6311MI2CB-008.0000T  
DSC6011MI3B-032.0000T  
DSC6001MI1B-080.0000T  
DSC6102MI1B-500K000T  
DSC6101MI1B-019.2000T  
DSC6111MI3B-025.0000T  
DSC6011MI2B-024.0000T  
DSC6011MI2B-006K144T  
DSC6011MI3B-025.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6102MI3B-080.0000T  
DSC6101MI1B-027.0000T  
DSC6102MI2B-027.0000T  
DSC6101MI2B-025.0000T  
DSC6112MI2B-025.0000T  
DSC6112MI2B-014.7456T  
DSC6021MI2B-01K2T  
DSC6112MI3B-060.0000T  
DSC6121MI2B-01MPT  
DSC6122MI2B-01MQT  
DSC6101MI1B-020.0000T  
DSC6011MI1B-012.2880T  
DSA6001MI1B-024.5760TVAO  
DSA6001MI2B-032.7680TVAO  
DSA6003MI2B-032K768TVAO  
DSA6311MI2CB-008.0000TVAO  
DSA6003MI3B-032K768TVAO  
DSA6102MI3B-038.4000TVAO  
DSC612NI3A-010GT  
DSC612NI3A-010TT  
DSC613NI2A-0106T  
DSC613NI3A-0105T  
DSC612NI3A-010GB  
DSC612NI3A-010TB  
DSC400-1111Q0137KI1T  
DSC400-1111Q0137KI2T  
DSC400-0111Q0138KI1T  
DSC400-0111Q0138KI2T  
DSC400-0111Q0139KI1T  
DSC400-0111Q0139KI2T  
DSC400-0144Q0140KI1T  
DSC400-0144Q0140KI2T  
DSC400-1221Q0141KI1T  
DSC400-1221Q0141KI2T  
DSC400-0434Q0009KI1T  
DSC400-0434Q0009KI2T  
DSC400-0313Q0136KI1T  
DSC400-0313Q0136KI2T  
DSC400-1111Q0142KI1T  
DSC400-1111Q0142KI2T  
DSC400-1111Q0143KI1T  
DSC400-1111Q0143KI2T  
DSC400-0333Q0144KI1T  
DSC400-0333Q0144KI2T  
DSC400-3333Q0145KI1T  
DSC400-3333Q0145KI2T  
DSC400-3333Q0023KI1T  
DSC400-3333Q0023KI2T  
DSC400-3333Q0146KI1T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-3333Q0146KI2T  
DSC400-1111Q0147KI1T  
DSC400-1111Q0147KI2T  
DSC400-1111Q0078KI1T  
DSC400-1111Q0078KI2T  
DSC400-0323Q0009KI1T  
DSC400-0323Q0009KI2T  
DSC400-1111Q0148KI1T  
DSC400-1111Q0148KI2T  
DSC400-1313Q0094KI1T  
DSC400-1313Q0094KI2T  
DSC400-1111Q0149KI1T  
DSC400-1111Q0149KI2T  
DSC400-1333Q0078KI1T  
DSC400-1333Q0078KI2T  
DSC400-1111Q0150KI1T  
DSC400-1111Q0150KI2T  
DSC400-3333Q0151KI1T  
DSC400-3333Q0151KI2T  
DSC400-4144Q0152KI1T  
DSC400-4144Q0152KI2T  
DSC1001DC1-025.0000  
DSC1001DC1-027.0000  
DSC1001DC1-050.0000  
DSC1001DC2-004.9152  
DSC1001DC2-025.0000  
DSC1001DC2-027.0000  
DSC1001DC5-012.0000  
DSC1001DC5-024.5760  
DSC1001DC5-038.8800  
DSC1001DC5-040.0000  
DSC1004DC1-020.0000  
DSC1001DC5-037.4000  
DSC1001DC5-012.8000  
DSC1001DC1-100.0000  
DSC1001AC1-024.0000  
DSC1001AC1-033.3333  
DSC1001AC1-040.0000  
DSC1001AC1-075.0000  
DSC1001AC2-027.0000  
DSC1001AC2-125.0025  
DSC1001AC1-027.0000  
DSC1001AC1-008.0000  
DSC1001AC1-125.0000  
DSC1001CI1-001.0000  
DSC1001CI1-008.0000  
DSC1001CI1-012.0000  
DSC1001CI1-012.2880  
DSC1123DI5-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123DI5-125.0000  
DSC1123DI5-200.0000  
DSC2311KI1-R0009  
DSC2311KI2-R0001  
DSC2311KI2-R0002  
DSC2311KI2-R0005  
DSC2311KI2-R0009  
DSC2311KI2-R0011  
DSC2311KI2-R0029  
DSC2311KI2-R0041  
DSC8101DI2  
DSC8101DI5  
DSC8102DI2  
DSC8102DI5  
DSC8103DI2  
DSC8104DI5  
DSC8121DI2  
DSC8121DI5  
DSC8122DI2  
DSC8123DI2  
DSC8124DI2  
DSC1103DI5-125.0060  
DSC2311KI2-R0043  
DSC8123DI5  
DSC1101DI1-025.0000  
DSC2311KI1-R0046  
DSC1121DI1-026.6000  
DSC1122DI2-200.0000  
DSC2311KI1-R0051  
DSC2311KI2-R0049  
DSC1103DI2-148.3500  
DSC1103DI5-010.0000  
DSC1103DI5-022.0000  
DSC1103DI5-032.0000  
DSC1121DI5-008.0000  
DSC1004DI5-016.0000  
DSC1001DI3-040.0000  
DSC1004DI1-026.0000  
DSC1001DI2-070.0000  
DSC1001DI3-060.0000  
DSC1001DI5-057.5580  
DSC1003DI2-024.0000  
DSC1003DI2-033.3333  
DSC1001DI1-036.0000  
DSC1001DI1-038.0000  
DSC1001DI5-030.7200  
DSC1001DI3-027.0000  
DSC1001DI2-014.3181  
DSC1001DI5-040.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DI1-069.1200  
DSC1001DI5-032.4000  
DSC1001DI5-041.1420  
DSC1001DI5-014.7456  
DSA1001DI1-005.0000VAO  
DSA1001DI1-012.5000VAO  
DSC613NI2A-0106B  
DSC613NI3A-0105B  
DSC613NI1A-016ET  
DSC613NI1A-016GT  
DSC613NI3A-01A6T  
DSC612NI1A-01H3T  
DSC612NI2A-01K7T  
DSC612NI3A-013CT  
DSC612NI3A-01KVT  
DSC6003JI2B-001.0000T  
DSC6003JI2B-003.5700T  
DSC6102JI2B-100.0000T  
DSC6001JI3B-008.0000T  
DSC6001JI3B-024.5760T  
DSC6101JI3B-075.0000T  
DSC6331JI1CB-027.0000T  
DSC6101JI1B-024.0000T  
DSC6003JI2B-012.0000T  
DSC6111JI1B-024.0000T  
DSC6011JI2B-002K000T  
DSC6011JI2B-032K768T  
DSC6011JI2B-250K000T  
DSC6011JI2B-432K000T  
DSA1123DL1-100.0000TVAO  
DSA1124DL1-100.0000TVAO  
DSA1101DL2-026.0000TVAO  
DSA1103DL2-156.2500TVAO  
DSA1121DL2-033.3333TVAO  
DSA1123DL2-125.0000TVAO  
DSA1124DL2-024.0000TVAO  
DSA1124DL2-100.0000TVAO  
DSA1101DL3-016.0000TVAO  
DSA1101DL3-020.0000TVAO  
DSA1101DL3-025.0000TVAO  
DSA1101DL3-026.0000TVAO  
DSA1105DL3-033.3330TVAO  
DSA1123DL3-100.0000TVAO  
DSA1123DL3-125.0000TVAO  
DSA2311KL1-R0015TVAO  
DSA2311KL1-R0065TVAO  
DSA2311KL2-R0009TVAO  
DSA2311KL1-R0078TVAO  
DSA2311KL2-R0015TVAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA2311KL2-R0027TVAO  
DSA2311KL2-R0065TVAO  
DSA2311KL2-R0073TVAO  
DSA2311KL2-R0084TVAO  
DSA2311KL2-R0087TVAO  
DSC1001DL5-003.6864T  
DSC1001DE2-001.0000T  
DSC1001DE2-090.0000T  
DSC1004DL5-025.0000T  
DSC1001DE2-022.0000T  
DSC1001DL5-037.1250T  
DSC1001DL5-150.0000T  
DSC1001DL2-033.3300T  
DSC1001DE5-025.0000T  
DSC1001DE1-024.5760T  
DSC1001DL5-047.0016T  
DSC1001DL1-005.0196T  
DSC1001DL2-005.0196T  
DSC1001DL5-005.0196T  
DSC1001DE3-080.0000T  
DSC1001DL1-150.0000T  
DSC1001DE3-008.0000T  
DSC1001DE5-150.0000T  
DSC1003DL1-025.0000T  
DSC1003DL1-016.0000T  
DSC1003DL1-050.0000T  
DSC1003DL1-048.0000T  
DSC1003DL2-024.0000T  
DSC1004DE1-026.0000T  
DSC1001DL1-050.0000T  
DSC1001DE5-049.1520T  
DSC1001DE5-045.1584T  
DSC1001DL1-040.0000T  
DSC1001DL5-064.0000T  
DSC1004DE2-025.0000T  
DSC1001DL5-028.6363T  
DSC1001DL5-006.0000T  
DSC1001DL1-033.3330T  
DSC1001DL5-029.4912T  
DSC1001DL1-004.0000T  
DSC1001DL2-100.0000T  
DSC1001DL5-032.4000T  
DSC1001DL5-049.5000T  
DSC1001DL2-012.5000T  
DSC1001DL1-012.5000T  
DSC1001DL3-125.0000T  
DSC1001DL5-026.5980T  
DSC1001DL5-120.0000T  
DSC1001DL5-087.0655T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DL2-049.5000TVAO  
DSA1001DL1-008.0000TVAO  
DSA1001DL1-010.2400TVAO  
DSA1001DL1-016.6666TVAO  
DSA1001DL1-020.0000TVAO  
DSA1001DL1-024.0000TVAO  
DSA1001DL1-024.5760TVAO  
DSA1001DL1-024.8000TVAO  
DSA1001DL1-024.9000TVAO  
DSA1001DL1-025.0000TVAO  
DSA1001DL1-025.1000TVAO  
DSA1001DL1-033.3330TVAO  
DSA1001DL1-048.0000TVAO  
DSA1001DL1-054.0000TVAO  
DSA1001DL1-060.0000TVAO  
DSA1001DL1-074.2500TVAO  
DSA1001DL1-100.0000TVAO  
DSA1001DL1-125.0000TVAO  
DSA1004DL1-100.0000TVAO  
DSA1004DL1-125.0000TVAO  
DSA1001DL2-006.0053TVAO  
DSA1001DL2-007.2000TVAO  
DSA1001DL2-008.0000TVAO  
DSA1001DL2-010.0000TVAO  
DSA1001DL2-016.0000TVAO  
DSA1001DL2-020.0000TVAO  
DSA1001DL2-024.0000TVAO  
DSA1001DL2-024.5640TVAO  
DSA1001DL2-024.5760TVAO  
DSA1001DL2-025.0000TVAO  
DSA1001DL2-026.0000TVAO  
DSA1001DL2-027.0000TVAO  
DSA1001DL2-028.6364TVAO  
DSA1001DL2-030.0000TVAO  
DSA1001DL2-033.0000TVAO  
DSA1001DL2-033.3333TVAO  
DSA1001DL2-036.8640TVAO  
DSA1001DL2-037.1250TVAO  
DSA1001DL2-040.0000TVAO  
DSA1001DL2-048.0000TVAO  
DSA1001DL2-049.5000TVAO  
DSA1001DL2-050.0000TVAO  
DSA1001DL2-054.0000TVAO  
DSA1001DL2-066.0000TVAO  
DSA1001DL2-072.0000TVAO  
DSA1001DL2-080.0000TVAO  
DSA1001DL2-087.0655TVAO  
DSC1001CI2-088.0000  
DSC1001CI2-020.0036



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CI2-020.0057  
DSC1001CI1-003.5800  
DSC1001CI1-125.0000  
DSC1001CI2-029.5000  
DSC1001CI5-026.6000  
DSC1004CI5-025.0000  
DSC1004CI5-026.6000  
DSC1001CI5-099.9990  
DSC1001CI2-024.9600  
DSC1003CI1-025.0000  
DSC1001BI1-010.0000  
DSC1001BI1-032.0000  
DSC1001BI1-048.0000  
DSC1001BI1-050.0000  
DSC1001BI1-054.0000  
DSC1001BI1-060.0000  
DSC1001BI1-075.0000  
DSC1001BI1-027.0000  
DSC1001BI2-005.5296  
DSC1001BI2-012.0000  
DSC1001BI2-012.2880  
DSC1001BI2-016.0000  
DSC1001BI2-022.8000  
DSC1001BI2-024.0000  
DSC1001BI2-025.0000  
DSC1001BI2-040.0000  
DSC1001BI5-040.0000  
DSC1001BI2-033.3330  
DSC1001BI2-042.5000  
DSC1001BI2-048.0000  
DSC1001BI2-050.0000  
DSC1001BI2-008.0000  
DSC1001BI2-002.0480  
DSC1001BI2-100.0000  
DSC1001BI2-125.0000  
DSC1001BI2-133.0000  
DSC1001BI5-010.0000  
DSC1001BI2-024.5760  
DSC1001BI5-025.0000  
DSC1001BI2-007.3728  
DSC1001BI2-027.0000  
DSC1001BI5-050.0000  
DSC1001BI5-100.0000  
DSC1001BI5-125.0000  
DSC1004BI2-033.0000  
DSC1004BI2-100.0000  
DSC8001BI2  
DSC8001BI5  
DSC8004BI2

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001BI1-038.4000  
DSC1001BI2-148.5000  
DSC1001BI5-008.0000  
DSC1001BI5-016.0000  
DSC1001BI5-024.0000  
DSC1001BI5-032.0000  
DSC1001BI1-008.0000  
DSC1001BI2-018.4320  
DSC1001BI5-020.0000  
DSC1001BI5-133.3330  
DSC1001BI1-004.0000  
DSC1001BI2-030.0000  
DSC1001BI2-016.3840  
DSC1001BI1-012.2880  
DSC1001BI1-022.1184  
DSC1001BI1-024.0000  
DSC1001BI1-024.5760  
DSC1001BI1-025.0000  
DSC1001BI1-040.0000  
DSC1001BI1-125.0000  
DSC1001BI2-014.7456  
DSC1001BI2-020.0000  
DSC1001BI2-014.3181  
DSC1001BI1-020.0000  
DSC1001BI5-090.0000  
DSC1004BI2-010.0000  
DSC1001BI1-066.6666  
DSC1001BI2-133.3330  
DSC8003BI2  
DSC1001BI2-012.5000  
DSC1001BI5-013.5600  
DSC1001BI1-100.0000  
DSC1001BI1-012.0000  
DSC1001BI2-033.0000  
DSC1001BI2-006.0000  
DSC1001BI2-026.0000  
DSC1001BI5-084.0000  
DSC1001BI1-033.3330  
DSC1001BI2-012.2888  
DSC1001BI2-004.0000  
DSC1003BI2-025.0000  
DSC1001BI2-010.0000  
DSC1001BI2-013.0810  
DSC1003BI1-008.0000  
DSC1001BI2-054.0000  
DSC1001BI5-014.7456  
DSC1001BI2-028.6363  
DSC1001BI5-033.0000  
DSC1001BI2-016.9344

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1004BI5-016.0000  
DSC1001BI5-027.0000  
DSC1001BI1-080.0000  
DSC1001BI1-019.6608  
DSC1001BI5-028.6363  
DSC1001BI5-001.6000  
DSC1003BI5-001.7000  
DSC1001BI1-001.8432  
DSC1001BI5-125.0031  
DSC1001BI1-011.0592  
DSC1001BI5-080.0000  
DSC1003BI5-001.6500  
DSC1003BI1-100.0000  
DSC1001BI1-026.0000  
DSC1001BI3-024.0000  
DSC1001BI3-012.0000  
DSC1001BI5-018.4320  
DSC1001BI2-029.4912  
DSC1001BI3-033.0000  
DSC1001BI3-050.0000  
DSC1001BI2-001.5440  
DSC1001BI1-033.0000  
DSC1001BI1-133.0000  
DSC1003BI5-040.0000  
DSC1001BI2-011.0592  
DSC1001BI5-019.6800  
DSC1001BI1-003.6864  
DSC1001BI2-004.0000T  
DSC1003BI2-025.0000T  
DSC1001BI2-010.0000T  
DSC1001BI2-013.0810T  
DSC1003BI1-008.0000T  
DSC1001BI2-054.0000T  
DSC1001BI5-014.7456T  
DSC1001BI2-028.6363T  
DSC1001BI5-033.0000T  
DSC1001BI2-016.9344T  
DSC1004BI5-016.0000T  
DSC1001BI5-027.0000T  
DSC1001BI1-080.0000T  
DSC1001BI1-019.6608T  
DSC1001BI5-028.6363T  
DSC1001BI5-001.6000T  
DSC1003BI5-001.7000T  
DSC1001BI1-001.8432T  
DSC1001BI5-125.0031T  
DSC1001BI1-011.0592T  
DSC1001BI5-080.0000T  
DSC1003BI5-001.6500T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003BI1-100.0000T  
DSC1001BI1-026.0000T  
DSC1001BI3-024.0000T  
DSC1001BI3-012.0000T  
DSC1003AI2-025.0000  
DSC1001AI1-050.0000  
DSC1001AI2-010.0000  
DSC1001AI2-027.0000  
DSC1001AI2-011.7000  
DSC1001AI2-012.3667  
DSC1001AI5-040.0000  
DSC1001AI5-024.0000  
DSC1001AI1-033.0000  
DSC1001AI2-040.0000  
DSC1001AI1-049.1520  
DSC1001AI5-012.2880  
DSC1001AI1-016.0000  
DSC1004AI5-099.7200  
DSC1001AI1-001.0000  
DSC1001AI5-066.0000  
DSC1001AI1-066.0000  
DSC1001AI1-020.0000  
DSC1001AI1-013.1072  
DSC1001AI1-024.5760  
DSC1001AI1-030.0000  
DSC1001AI5-050.0000  
DSC1001AI1-008.0000  
DSC1001AI1-032.7680  
DSC1001AI2-002.0480  
DSC1001AI1-033.3333  
DSC1001AI2-065.5360  
DSC1001AI2-032.7680  
DSC1001AI1-003.5700  
DSC1003AI2-075.0000  
DSC1001AI5-028.6363  
DSC1001AI2-075.0000  
DSC1004AI1-012.0000  
DSC1004AI1-004.9152  
DSC1004AI1-007.3728  
DSC1001AI2-150.0000  
DSC1001AI1-007.3728  
DSC1001AI1-004.9152  
DSC1001AI1-012.0000  
DSC1003AI3-100.0000  
DSC1001AI2-033.3330  
DSC1001AI5-016.3840  
DSC1001AI5-010.0000  
DSC1001AI5-106.2500  
DSC1003AI5-003.6864

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003AI5-012.0000  
DSC1001AI1-014.3182  
DSC1001AI3-025.0000  
DSC1001AI3-030.0000  
DSC1001AI1-033.3330  
DSC1001AI1-024.5450  
DSC1001AI5-001.7000  
DSC1001AI5-014.7456  
DSC1001AI2-029.4912  
DSC1001AI3-100.0000  
DSC1001AI1-075.0000  
DSC1001AI2-129.6000  
DSC1001AI3-040.0000  
DSC1001AI2-066.6666  
DSC1001AI1-029.4912  
DSC1001AI5-002.0480  
DSC1001AI1-026.0000  
DSC1001AI1-016.3840  
DSC1001AI1-032.0000  
DSC1001AI5-003.6864  
DSC1001CE1-004.0000  
DSC1001CE1-012.2880  
DSC1001CE1-012.0000  
DSC1001CE1-014.3182  
DSC1001CE1-019.6608  
DSC1001CE1-024.0000  
DSC1001CE1-024.5760  
DSC1001CE1-025.0000  
DSC1001CE1-033.8688  
DSC1001CE1-037.1250  
DSC1001CE1-060.0000  
DSC1001CE1-064.8000  
DSC1001CE1-069.2480  
DSC8003CL5  
DSC1001CE2-001.8432  
DSC1001CE2-006.0000  
DSC1001CE2-010.0000  
DSC1001CE2-020.0000  
DSC1001CE2-024.0000  
DSC1001CE2-024.5760  
DSC1001CE2-025.0000  
DSC1001CE2-027.0000  
DSC1001CE2-034.0000  
DSC1001CE2-040.0000  
DSC1001CE2-048.0000  
DSC1001CE2-050.0000  
DSC1001CL1-001.8432  
DSC1001CL1-016.0000  
DSC1001CL1-020.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CL1-025.0000  
DSC1001CL1-030.0000  
DSC1001CL1-032.0000  
DSC1001CE2-100.0000  
DSC1001CL1-066.0000  
DSC2044FI2-H0004  
DSC2110FI1-A0005  
DSC2122FI1-F0006  
DSC2130FI2-C0005  
DSC2042FI1-M0005  
DSC2133FI2-E0020  
DSC2230FI2-C0006  
DSC2233FI2-F0018  
DSC2044FI1-H0001  
DSC2033FI1-F0028  
DSC2010FI2-B0014  
DSC2011FI1-E0012  
DSC2210FI2-A0006  
DSC2210FI2-A0028  
DSC2211FI2-E0018  
DSC2033FI2-K0003  
DSC2033FI2-F0030  
DSC2033FI2-F0031  
DSC2042FI1-F0014  
DSC2033FI2-F0032  
DSC2011FI1-F0033  
DSC2233FI2-G0002  
DSC2010FI2-B0015  
DSC2133FI2-G0001  
DSC2033FI1-F0025  
DSC2033FI1-F0026  
DSC2120FI1-A0027  
DSC2030FI2-C0002  
DSC2033FI2-F0022  
DSC2033FI1-F0022  
DSC557-0334FI1  
DSC557-0343FI0  
DSC557-0344FI0  
DSC6001JI2B-025.0000  
DSC6001JI2B-027.0000  
DSC6001JI1B-025.0000  
DSC6011JI1B-008.0000  
DSC6111JI1B-098.3040  
DSC6011JI3B-001.0640  
DSC6111JI2B-100K000  
DSC6111JI3B-100.0000  
DSC6001JI3B-004K000  
DSC6011JI3B-032K768  
DSC6013JI1B-768K000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6001JI1B-460K800  
DSC6331JI2BB-025.0000  
DSC6331JI2IB-025.0000  
DSC6001JI2B-001.8432  
DSC6011JI2B-012.0000  
DSC6101JI2B-100.0000  
DSC6101JI2B-024.0000  
DSC6003JI2B-025.0000  
DSC6011JI1B-050.0000  
DSC6331JI2EB-025.0000  
DSC6001JI2B-116K000  
DSC6101JI2B-050.0000  
DSC6001JI2B-068.1818  
DSC6331JI2BB-024.0000  
DSC6013JI1B-012.0000  
DSC6001JI1B-012.0000  
DSC6001JI2B-032K000  
DSC6101JI3B-100.0000  
DSC6001JI3B-024.0000  
DSC6003JI2B-032K768  
DSC6023JI3B-019H  
DSC6011JI1B-014.7456  
DSC6003JI2B-004.5160  
DSC6003JI2B-008.0000  
DSC6003JI2B-027.0950  
DSC6003JI2B-063.2220  
DSC6011JI2B-016.0000  
DSC6013JI1B-032K768  
DSC6001JI3B-014.1875  
DSC6101JI3B-485K000  
DSC6013JI3B-032.0000  
DSC6101JI2B-020.0000  
DSC6001JI2B-024.0000  
DSC6003JI2B-024.0000  
DSC6013JI1B-300K000  
DSC6111JI3B-012.0000  
DSC6101JI1B-007K085  
DSC6121JI2B-01BB  
DSC6001JI1B-032K768  
DSC6102JI3B-001.6800  
DSC6003JI2B-307K000  
DSC6331JI2KB-025.0000  
DSC6001JI2B-032K768  
DSC6001JI2B-012.2880  
DSC6011JI3B-048K500  
DSC6331JI1DB-025.0000  
DSC6001JI1B-010.0000  
DSC6011JI1B-001.0000  
DSC6001JI3B-025.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6101JI2B-040K000  
DSC6331JI2CB-027.0000  
DSC6331JI2CB-024.0000  
DSC6101JI2B-012.2880  
DSC6331JI2FB-025.0000  
DSC6111JI1B-200K000  
DSC6001JI2B-022.5792  
DSC6311JI1DB-036.0000  
DSC6311JI1DB-075.0000  
DSC6311JI1DB-100.0000  
DSC6102JI1B-060.0000  
DSC6101JI2B-019.2000  
DSA1001DI1-019.2000VAO  
DSA1001DI1-020.0000VAO  
DSA1001DI1-024.5760VAO  
DSA1001DI1-025.0000VAO  
DSA1001DI1-033.0000VAO  
DSA1001DI1-050.0000VAO  
DSA1003DI1-050.0000VAO  
DSA1001DI2-012.2880VAO  
DSA1001DI2-019.2000VAO  
DSA1001DI2-025.0000VAO  
DSA1001DI2-026.0000VAO  
DSA1001DI2-027.0000VAO  
DSA1001DI2-033.3333VAO  
DSA1001DI2-125.0000VAO  
DSA1001DI3-012.0000VAO  
DSA1001DI3-020.0000VAO  
DSA1001DI3-024.0000VAO  
DSA1001DI3-027.0000VAO  
DSA1001DI3-050.0000VAO  
DSA1001DI3-150.0000VAO  
DSC1001AI1-005.0000  
DSC1001AI1-012.2880  
DSC1001AI2-006.0000  
DSC1001AI2-012.0000  
DSC1001AI1-025.0000  
DSC1001AI2-014.7456  
DSC1001AI2-024.0000  
DSC1001AI2-025.0000  
DSC1001AI2-008.0000  
DSC1001AI2-033.3333  
DSC1001AI2-048.0000  
DSC1001AI2-050.0000  
DSC1001AI2-054.0000  
DSC1001AI2-080.0000  
DSC1001AI2-083.3330  
DSC1001AI2-100.0000  
DSC1001AI2-125.0000



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AI2-016.0000  
DSC1001AI5-002.4576  
DSC1001AI2-025.0007  
DSC1001AI2-026.0000  
DSC1001AI2-032.0000  
DSC1001AI2-014.3180  
DSC1001AI5-025.0000  
DSC1001AI5-072.0000  
DSC1001AI5-144.0000  
DSC1001AI5-150.0000  
DSC8001AI1  
DSC8001AI2  
DSC8001AI5  
DSC1001AI2-120.0000  
DSC1001AI5-008.0000  
DSC1001AI5-011.0592  
DSC1001AI5-012.0000  
DSC1001AI5-016.0000  
DSC1001AI5-027.0000  
DSC1001AI5-029.4912  
DSC1001AI5-033.3330  
DSC1001AI5-048.0000  
DSC1001AI5-080.0000  
DSC1001AI5-100.0000  
DSC1001AI5-125.0000  
DSC1001AI5-125.0060  
DSC1001AI2-066.6600  
DSC1001AI2-066.6670  
DSC1001AI1-055.3330  
DSC1001AI5-032.0000  
DSC1001AI2-096.0000  
DSC1001AI5-033.0000  
DSC1001AI2-001.0000  
DSC1001AI2-064.0000  
DSC1004AI2-001.0000  
DSC8003AI2  
DSC1001AI5-070.6760  
DSC1122CI5-100.0000T  
DSC1102CI5-156.2500T  
DSC1124CI5-133.0000T  
DSC1124CI5-133.3300T  
DSC1104CI2-316.0000T  
DSC1103CI5-125.0000T  
DSC1101CI1-008.0000T  
DSC1101CI1-010.0000T  
DSC1123CI2-035.0000T  
DSC1101CI5-125.0000T  
DSC1122CI5-050.0000T  
DSC1121CI2-155.5200T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1122CI2-212.5000T  
DSC1123CI2-060.0000T  
DSC1123CI2-175.0000T  
DSC1103CI5-045.0000T  
DSC1123CI1-050.0000T  
DSC1123CI5-096.0000T  
DSC1123CI2-086.0000T  
DSC1101CI5-100.0000T  
DSC1124CI1-027.0000T  
DSC1104CI1-027.0000T  
DSC1123CI2-050.0000T  
DSC1101CI5-027.0000T  
DSC1103CI5-180.0000T  
DSC1121CI2-008.0000T  
DSC1101CI5-026.0000T  
DSC1103CI5-156.2500T  
DSC1103CI5-016.0000T  
DSC1103CI2-106.2500T  
DSC1103CI2-074.2500T  
DSC1103CI2-050.0000T  
DSC1102CI1-135.0000T  
DSC1123CI5-233.2090T  
DSC1104CI2-027.0000T  
DSC1123CI5-150.0000T  
DSC1123CI2-270.0000T  
DSC1123CI3-148.5000T  
DSC1122CI5-433.9200T  
DSC1103CI5-150.0000T  
DSC1123CI2-322.2650T  
DSC1123CI2-266.5000T  
DSC1121CI5-026.0000T  
DSC1103CI3-200.0000T  
DSC1103CI3-125.0000T  
DSC1103CI5-250.0000T  
DSC1103CI2-250.0000T  
DSC1103CI2-300.0000T  
DSC1124CI2-027.0000T  
DSC1101CI1-012.0000T  
DSC1102CI2-400.0000T  
DSC1101CI2-133.0000T  
DSC1101CI5-032.0000T  
DSC1101CI2-032.0000T  
DSC1104CI2-100.0000T  
DSC1121CI2-080.0000T  
DSC1124CI1-100.0000T  
DSC1101CI1-050.0000T  
DSC1101CI2-066.6667T  
DSC1101CI2-125.0000T  
DSC1123CI2-266.5250T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101CI1-018.7500T  
DSC1103CI2-052.0000T  
DSC1103CI5-075.0300T  
DSC1103CI5-033.3330T  
DSC1103CI2-024.0000T  
DSC1103CI2-025.0000T  
DSC1123CI2-125.0987T  
DSC1101CI5-048.0000T  
DSC1102CI2-148.5000T  
DSC1101CI5-072.0000T  
DSC1123CI2-160.0000T  
DSC1103CI1-026.0000T  
DSC1103CI1-027.0000T  
DSC1123CI2-180.0000T  
DSC1123CI2-265.5250T  
DSC1123CI2-144.0000T  
DSC1123CI2-072.0000T  
DSC1102CI2-156.2500T  
DSC1103CI5-026.0000T  
DSC1103CI5-027.0000T  
DSC1101CI1-085.2070T  
DSC1101CI5-024.0000T  
DSC1101CI2-020.0000T  
DSC1103CI5-103.1250T  
DSC1103CI2-103.1250T  
DSC1103CI3-100.0000T  
DSC1103CI3-250.0000T  
DSC1104CI3-027.0000T  
DSC1102CI1-108.0000T  
DSC1121CI2-045.1580T  
DSC1121CI2-049.1520T  
DSC1121CI2-045.1584T  
DSC1121CI2-014.3181T  
DSC1121CI5-045.1584T  
DSC400-3331Q0153KI1T  
DSC400-3331Q0153KI2T  
DSC400-2222Q0031KI1T  
DSC400-2222Q0031KI2T  
DSC400-0333Q0154KI1T  
DSC400-0333Q0154KI2T  
DSC400-0111Q0155KI1T  
DSC400-0111Q0155KI2T  
DSC400-3133Q0156KI1T  
DSC400-3133Q0156KI2T  
DSC400-0133Q0157KI1T  
DSC400-0133Q0157KI2T  
DSC400-3113Q0158KI1T  
DSC400-3113Q0158KI2T  
DSC400-3113Q0159KI1T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-3113Q0159KI2T  
DSC400-1111Q0160KI1T  
DSC400-1111Q0160KI2T  
DSC400-0333Q0162KI1T  
DSC400-0333Q0162KI2T  
DSC400-3333Q0163KI1T  
DSC400-3333Q0163KI2T  
DSA400-1111Q0004KI1TVAO  
DSA400-1111Q0004KI2TVAO  
DSA400-1111Q0085KI1TVAO  
DSA400-1111Q0085KI2TVAO  
DSA400-1111Q0161KI1TVAO  
DSA400-1111Q0161KI2TVAO  
DSA400-4134Q0152KI1TVAO  
DSA400-4134Q0152KI2TVAO  
DSA557-04444KI1TVAO  
DSA557-054444KI1TVAO  
DSC1101BM2-PROG  
DSC1101DM2-PROG  
DSA1101DA1-004.0000VAO  
DSA1101DA1-007.3700VAO  
DSA1101DA1-008.0000VAO  
DSA1101DA1-016.0000VAO  
DSA1101DA1-025.0000VAO  
DSA1101DA1-026.9973VAO  
DSA1101DA1-033.3330VAO  
DSA1101DA1-040.0000VAO  
DSA1121DA1-100.0000VAO  
DSA1123DA1-100.0000VAO  
DSA1125DA1-027.0000VAO  
DSA1125DA1-033.3333VAO  
DSA1101DA2-020.0000VAO  
DSA1101DA2-025.0000VAO  
DSA1101DA2-050.0000VAO  
DSA1121DA2-025.0000VAO  
DSA1121DA2-027.0000VAO  
DSA1121DA2-050.0000VAO  
DSA1121DA2-100.0000VAO  
DSA1121DA2-125.0000VAO  
DSA1101DA3-054.0000VAO  
DSA1101DA3-122.8800VAO  
DSA1101DA3-125.0000VAO  
DSA1121DA3-004.0000VAO  
DSA1121DA3-008.0000VAO  
DSA1121DA3-016.0000VAO  
DSA1121DA3-020.0000VAO  
DSA1121DA3-030.0000VAO  
DSA2311KA1-R0075VAO  
DSA2311KA2-R0002VAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA2311KA2-R0005VAO  
DSA2311KA2-R0009VAO  
DSA2311KA2-R0011VAO  
DSA2311KA2-R0015VAO  
DSA2311KA2-R0021VAO  
DSA2311KA2-R0065VAO  
DSA2311KA2-R0067VAO  
DSA2311KA2-R0073VAO  
DSA2311KA2-R0076VAO  
DSA2311KA3-R0021VAO  
DSA2311KA3-R0041VAO  
DSA2311KA3-R0073VAO  
DSA2311KA1-R0024VAO  
DSA1105DA1-022.5792VAO  
DSC1101CM1-008.0000  
DSC1101CM1-025.0000  
DSC1101CM2-020.0000  
DSC1101CM2-062.2080  
DSC1121CM1-016.0000  
DSC1121CM1-024.0000  
DSC1121CM1-025.0000  
DSC1121CM1-026.5625  
DSC1121CM1-027.0000  
DSC1121CM1-075.0000  
DSC1121CM1-050.0000  
DSC1121CM2-033.3333  
DSC1121CM2-024.5454  
DSC8121CM2  
DSC1121CM2-027.0000  
DSC1121CM2-062.2080  
DSC1101CM1-075.0000  
DSC1101CM1-005.0000  
DSC1101CM1-033.3333  
DSC1121CM2-040.0000  
DSC1101CM2-008.0000  
DSC1121CM2-006.7800  
DSC1121CM1-012.0000  
DSC1121CM1-012.2880  
DSC8101CM2  
DSC8121CM1  
DSC1121CM1-040.0000  
DSC1101CM2-012.0000  
DSC1101CM2-048.0000  
DSC1121CM1-066.6660  
DSC1121CM1-100.0000  
DSC1121CM1-036.0000  
DSC1121CM1-018.0000  
DSC1101CM1-040.0000  
DSC1121CM2-008.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121CM2-025.0000  
DSC1121CM1-030.0000  
DSC1101CM3-024.0000  
DSC1121CM1-014.7456  
DSC1101CM1-032.0000  
DSC1121CM1-032.0000  
DSC1123CM1-375.0000  
DSC1121CM2-003.1152  
DSC1121CM1-003.1152  
DSC1121CM1-005.5296  
DSC1121CM2-024.0000  
DSC1101BM2-025.0000  
DSC1101BM2-100.0000  
DSC1121BM1-008.0000  
DSC1121BM1-025.0000  
DSC1121BM1-030.0000  
DSC1121BM1-048.0000  
DSC1121BM1-100.0000  
DSC1121BM2-007.3728  
DSC8121BM2  
DSC1101BM2-074.2500  
DSC1121BM1-010.0000  
DSC1121BM1-024.0000  
DSC1101BM2-027.0000  
DSC1121BM1-050.0000  
DSC1121BM2-016.0000  
DSC1121BM2-030.0000  
DSC1101BM2-050.0000  
DSC1101BM2-054.0000  
DSC1121BM1-024.5760  
DSC1121BM1-060.0000  
DSC1121BM1-016.0000  
DSC1121BM1-026.0000  
DSC1121BM1-012.2880  
DSC1121BM2-131.0720  
DSC1121BM2-020.0000  
DSC1121BM2-025.0000  
DSA1001DL3-080.0000TVAO  
DSA1001DL3-100.0000TVAO  
DSA1001DL3-125.0000TVAO  
DSA1001DL1-027.0000TVAO  
DSA1001DL1-033.0000TVAO  
DSC1001AE1-050.0000T  
DSC1001AE1-016.6667T  
DSC1001AE1-025.0000T  
DSC1001AE1-033.3333T  
DSC1001AE1-048.0000T  
DSC1001AE1-125.0000T  
DSC1001AE2-125.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AE5-098.3040T  
DSC1001AL5-007.3728T  
DSC1001AL5-001.8432T  
DSC1001AL5-004.0000T  
DSC1001AL5-008.0000T  
DSC1001AL5-012.0000T  
DSC1001AL5-016.0000T  
DSC1001AL5-016.3840T  
DSC1001AL5-018.4320T  
DSC1001AL5-080.0000T  
DSC1001AL5-100.0000T  
DSC1001AL5-032.0000T  
DSC1001AL5-040.0000T  
DSC1001AL5-050.0000T  
DSC1001AL5-060.0000T  
DSC8001AL5T  
DSC1001AL5-125.0000T  
DSC1003AE1-050.0000T  
DSC1001AE1-066.6660T  
DSC1004AL1-001.0000T  
DSC1004AL2-001.0000T  
DSC1001AE1-019.6608T  
DSC1001AE1-024.0000T  
DSC1001AE2-002.0480T  
DSC1001AL5-024.0000T  
DSC1001AE5-024.5760T  
DSC1001AE1-027.0000T  
DSC1001AL5-033.0000T  
DSC1001AL5-025.0000T  
DSC1001AE1-006.1440T  
DSC1001AE1-111.0000T  
DSC1001AL5-027.0000T  
DSC1001AE1-014.3182T  
DSC1001AE1-024.5761T  
DSC1001AE1-003.6864T  
DSC1001AE1-054.0000T  
DSC1001AE5-040.0000T  
DSC1121CL2-025.0000  
DSC1121CL2-050.0000  
DSC1121CL5-050.0000  
DSC1122CE1-125.0000  
DSC1123CE1-050.0000  
DSC1123CE1-156.2500  
DSC1123CE2-062.0000  
DSC1123CE2-148.3516  
DSC1123CE2-148.5000  
DSC1123CE5-100.0000  
DSC1123CE5-150.0000  
DSC1123CE5-156.2500

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123CL1-150.0000  
DSC1123CL2-125.0000  
DSC1123CL5-100.0000  
DSC1124CE1-156.2500  
DSC8101CL5  
DSC8121CL5  
DSC1124CL2-200.0000  
DSC1101CL5-100.0000  
DSC1103CE1-125.0000  
DSC1123CE1-125.0000  
DSC1101CL5-014.7456  
DSC1121CE1-133.3333  
DSC1103CE1-156.2500  
DSC1124CE1-010.2400  
DSC1121CE5-050.0000  
DSC1121CL2-040.0000  
DSC1124CL2-100.0000  
DSC1101CL2-024.7500  
DSC1101CL3-PROG  
DSC1101CL5-PROG  
DSC1101CE2-100.0000  
DSC1123CL1-400.0000  
DSC1123CL1-025.0000  
DSC1103CE5-100.0000  
DSC1103CL5-100.0000  
DSC1123CL5-050.0000  
DSC1123CL5-025.0000  
DSC1103CE5-045.0000  
DSC1121CE1-125.0000  
DSC1123CE2-250.0000  
DSC1123CE2-312.5000  
DSC1103CE1-266.7000  
DSC1103CE1-233.3000  
DSC1123CE1-150.0000  
DSC1124CE1-100.0000  
DSC1121CL5-150.0000  
DSC1124CL1-100.0000  
DSC1122CL2-156.2500  
DSC1121CE1-033.3333  
DSC1121CE5-033.3333  
DSC1101CE5-010.0000  
DSC1121AM1-041.5000T  
DSC1121AM2-041.5000T  
DSC1121AM1-029.4912T  
DSC1121AM1-024.5760T  
DSC1121AM1-033.0000T  
DSC1101AM2-156.2500T  
DSC1121AM1-064.0000T  
DSC1101DM1-033.3330T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101DM2-020.0000T  
DSC1101DM2-016.0000T  
DSC1101DM2-056.2500T  
DSC1101DM2-125.0000T  
DSC1121DM2-003.3333T  
DSC1121DM2-007.3728T  
DSC1121DM2-125.0000T  
DSC2311KM2-R0005T  
DSC2311KM2-R0040T  
DSC1101DM2-004.0000T  
DSC2311KM2-R0002T  
DSC2311KM2-R0050T  
DSC1101DM1-012.0000T  
DSC1101DM2-012.0000T  
DSC1101DM1-033.3333T  
DSC1101DM2-033.3333T  
DSC1121DM1-033.3333T  
DSC1101DM2-008.0000T  
DSC1101DM2-024.0000T  
DSC1121DM1-030.0000T  
DSC1101DM1-080.0000T  
DSC1121DM2-025.0000T  
DSC1121DM2-033.0000T  
DSC1001CL3-025.0000  
DSC1001CL2-006.0053  
DSC1001CE2-033.3333  
DSC1001CL3-040.0000  
DSC1004CL2-030.0000  
DSA1001CL2-033.3300VAO  
DSA1001CL2-033.3333VAO  
DSA1001CL2-125.0000VAO  
DSA1001CL3-080.0000VAO  
DSA1001CL3-133.3330VAO  
DSC1001BE1-025.0000  
DSC1001BE1-040.0000  
DSC1001BE1-048.0000  
DSC1001BE1-024.0000  
DSC1001BE1-125.0000  
DSC1001BE2-024.0000  
DSC1001BE2-025.0000  
DSC1001BE2-027.0000  
DSC1001BE2-033.3330  
DSC1001BE2-050.0000  
DSC1001BE2-100.0000  
DSC1001BL1-002.1760  
DSC1001BL2-050.0000  
DSC1001BL5-010.0000  
DSC1001BL5-100.0000  
DSC8001BL2

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC800IBL5

DSC1001BL5-025.0000  
DSC1001BL2-025.0000  
DSC1001BL5-050.0000  
DSC1001BL5-016.0000  
DSC1001BL5-080.0000  
DSC1001BE1-050.0000  
DSC1001BE5-022.5792  
DSC1001BE2-001.6000  
DSC1001BE1-012.0000  
DSC1001BE2-010.0000  
DSC1001BL5-095.0000  
DSC1001BL1-016.0000  
DSC1001BE5-064.0000  
DSC1001BL5-064.0000  
DSC1001BL2-020.0000  
DSC1003AE5-100.0000T  
DSC1001AL5-066.0000T  
DSC1001AE1-018.1059T  
DSC1001AL5-030.0000T  
DSC1001AE1-049.1520T  
DSC1001AL1-001.0000T  
DSC1001AL1-048.0000T  
DSC1001AL5-016.7772T  
DSC1001AE2-148.5000T  
DSC1001AE2-048.0000T  
DSC1001AE5-022.5792T  
DSC1003AL5-025.0000T  
DSC1001AE1-001.4850T  
DSC1001AL2-016.0000T  
DSC1001AE2-080.0000T  
DSC1001AL1-020.0000T  
DSC1001AE1-004.0000T  
DSC1001AE1-099.0000T  
DSC1001AE1-098.0000T  
DSC1001AL2-025.0000T  
DSC1001AE5-004.0000T  
DSC1001AE5-020.0000T  
DSC1001AE5-125.0000T  
DSC1001AE5-012.0000T  
DSC1003AE1-022.1184T  
DSC1001AE1-010.0000T  
DSC1003AE5-025.0000T  
DSC1001AL5-001.0000T  
DSC1001AE2-050.0000T  
DSC1001AE2-054.0000T  
DSC1001AE5-029.1621T  
DSC1001AE5-031.6440T  
DSC1001AL5-011.0592T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AL1-050.0000T  
DSC1001AL5-010.0000T  
DSC1000AL3-PROGT  
DSC1000AL5-PROGT  
DSC1004AE2-024.0000T  
DSC1001AL5-133.3330T  
DSC1001AL2-020.0000T  
DSC1001AL2-060.0000T  
DSC1001AE3-013.5600T  
DSC1001AE1-064.0000T  
DSC1001AE1-040.0000T  
DSC1003AE3-007.3728T  
DSC1001AL5-014.7456T  
DSC1001AE5-017.1776T  
DSC1001AE5-001.2000T  
DSC1001AL2-029.4912T  
DSC1001AL2-050.0000T  
DSC1003AL2-005.0000T  
DSC1001AE1-003.5700T  
DSC1001AL5-033.3330T  
DSC1001AL2-024.0000T  
DSC1001AL2-125.0000T  
DSC1001AL1-025.0000T  
DSC1001AL1-027.0000T  
DSC1001AL2-100.0000T  
DSC1001AL5-029.4912T  
DSC1001CC1-010.0000T  
DSC1001CC1-047.3333T  
DSC1001CC1-076.0686T  
DSC1001CC1-125.0000T  
DSC1001CC5-008.5920T  
DSC1001CC2-025.0000T  
DSC1001CC5-004.1943T  
DSC1001CC5-024.5760T  
DSC1001CI1-132.0000T  
DSC1001CC2-012.2880T  
DSC1001CC1-008.0000T  
DSC1001CC2-033.0000T  
DSC1001CC2-024.0000T  
DSC1001BC1-020.0000T  
DSC1001BC1-024.0000T  
DSC1001BC1-050.0000T  
DSC1001DC1-025.0000T  
DSC1001DC1-050.0000T  
DSC1001DC1-072.0000T  
DSC1001DC1-074.2500T  
DSC1001DC5-038.8800T  
DSC1004DC1-050.0000T  
DSC1001DC5-037.4000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1004DC1-020.0000T  
DSC1001DC5-012.8000T  
DSC1001DC1-100.0000T  
DSC1001AC2-025.0000T  
DSC1001AC1-008.0000T  
DSC1001AC1-125.0000T  
DSC1001CI1-001.8432T  
DSC1001CI1-007.5000T  
DSC1001CI1-008.0000T  
DSC1001CI1-010.0000T  
DSC1001CI1-013.5600T  
DSC1001CI1-014.7456T  
DSC1001CI1-016.0000T  
DSC1001CI1-019.2000T  
DSC1001CI1-020.0000T  
DSC1001CI1-024.0000T  
DSC1001CI1-024.5760T  
DSC1001CI1-025.0000T  
DSC1001CI1-026.0000T  
DSC1001CI1-027.0000T  
DSC1001CI1-030.0000T  
DSC1001CI2-004.0000T  
DSC1001CI2-008.0000T  
DSC1001CI1-033.3333T  
DSC1001CI1-047.3333T  
DSC1001CI2-018.4320T  
DSC1001CI1-050.0000T  
DSC1001CI1-076.0686T  
DSC1001CI2-014.3181T  
DSC1001CI2-001.0000T  
DSC1001CI2-002.0480T  
DSC1001CI2-003.5795T  
DSC1001CI2-022.5792T  
DSC1001CI2-006.1400T  
DSC1001CI2-011.0592T  
DSC1001CI2-012.0000T  
DSC1001CI2-012.2880T  
DSC1001CI2-014.7456T  
DSC1001CI2-016.0000T  
DSC1001CI2-024.0000T  
DSC1001DE1-013.0000T  
DSC1001DL2-012.2880T  
DSC1001DL2-125.0000T  
DSC1001DL2-004.0000T  
DSC1001DL1-016.0000T  
DSC1001DL2-023.0000T  
DSC1001DE1-020.0000T  
DSC1001DL2-026.6500T  
DSC1001DL5-014.3181T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DE2-008.0000T  
DSC1001DE2-012.0000T  
DSC1001DE2-027.0000T  
DSC1001DE2-025.0000T  
DSC1001DL5-016.7722T  
DSC1004DL1-025.0000T  
DSC1004DL1-033.0000T  
DSC1001DL2-048.0000T  
DSC1001DL2-066.6700T  
DSC1001DE1-024.3050T  
DSC1001DL2-002.0000T  
DSC1001DL1-004.0960T  
DSC1001DL2-049.1520T  
DSC6003ME1B-013.1072T  
DSC6001ME1B-008.0000T  
DSC6001ME2B-009.0000T  
DSC6001ME1B-052.4280T  
DSC6011ME2B-012.0000T  
DSA6101ML2B-026.0000TVAO  
DSA6101ML3B-014.7456TVAO  
DSA6101ML3B-016.6666TVAO  
DSA6101ML3B-025.0000TVAO  
DSA6101ML3B-033.3333TVAO  
DSA6011ML1B-025.0000TVAO  
DSC612NL3A-012RT  
DSC612NL3A-014ET  
DSC612NL2A-014ET  
DSC612NL2A-0151T  
DSC613NE2A-016WT  
DSC612NL3A-0142T  
DSC612NL3A-019AT  
DSA612NL2A-019BTVAO  
DSA612NL2A-01C1TVAO  
DSA612NL2A-01C3TVAO  
DSA612NL2A-01C4TVAO  
DSA612NL2A-01CPTVAO  
DSC6001JL2B-027.0000T  
DSC6101JL2B-033.3333T  
DSC6003JL3B-004.0096T  
DSC6003JL3B-007.3728T  
DSC6101JL3B-038.4000T  
DSC6101JL3B-050.0000T  
DSC6003JL3B-004.0960  
DSC6311JL1BB-028.6364T  
DSC6311JL1AB-028.6364T  
DSC6331JE1CB-024.0000T  
DSC6001JE1B-024.0000T  
DSC6003JE1B-024.0000T  
DSC6101JL2B-026.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6111JE1B-033.3333T  
DSC6011JE2B-032K768T  
DSC6121JL2B-015GT  
DSC6003JL2B-032K768T  
DSC6011JE1B-025.0000T  
DSC6011JL2B-025.0000T  
DSC6011JE3B-003K898T  
DSC6001JE1B-025.0000T  
DSC6311JL2AB-027.0000T  
DSC6311JL2BB-027.0000T  
DSC6111JL2B-008.0000T  
DSC6011JE1B-840K000T  
DSC6121JL2B-0170T  
DSC6101JL3B-025.0000T  
DSC6001JE3B-040K000T  
DSC1001DI2-064.0000  
DSC1001DI3-024.0000  
DSC1003DI2-024.5670  
DSC1001DI5-032.7680  
DSC1001DI1-011.0592  
DSC1001DI3-012.0000  
DSC1001DI2-033.0000  
DSC1003DI5-025.0000  
DSC1001DI5-011.0592  
DSC1001DI2-133.0000  
DSC1003DI1-012.0000  
DSC1001DI2-002.0970  
DSC1001DI3-100.0000  
DSC1001DI3-133.0000  
DSC1001DI1-064.0000  
DSC1001DI5-019.6800  
DSC1001DI1-025.0008  
DSC1001DI5-090.0000  
DSC1001DI5-014.3181  
DSC1001DI1-116.6666  
DSC1001DI2-066.6670  
DSC1003DI2-050.0000  
DSC1004DI2-050.0000  
DSC1003DI1-052.0000  
DSC1001DI5-009.2160  
DSC1001DI2-060.0000  
DSC1001DI5-005.0196  
DSC1001DI5-037.4000  
DSC1001DI1-028.6363  
DSC1001DI3-012.2880  
DSC1004DI5-024.0000  
DSC400-3333Q0130KI2T  
DSC400-3111Q0131KI1T  
DSC400-3111Q0131KI2T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-4111Q0131KI1T  
DSC400-4111Q0131KI2T  
DSC400-1111Q0132KI1T  
DSC400-1111Q0132KI2T  
DSC400-0311Q0026KI1T  
DSC400-0311Q0026KI2T  
DSC400-0211Q0026KI1T  
DSC400-0211Q0026KI2T  
DSC400-1111Q0133KI1T  
DSC400-1111Q0133KI2T  
DSC400-1121Q0134KI1T  
DSC400-1121Q0134KI2T  
DSC400-1411Q0135KI1T  
DSC400-1411Q0135KI2T  
DSC400-0212Q0136KI1T  
DSC400-0212Q0136KI2T  
DSC2311KM2-R0040  
DSC8121DM2  
DSC2311KM2-R0002  
DSC2311KM2-R0050  
DSC1101DM1-012.0000  
DSC1101DM2-012.0000  
DSC1101DM2-004.0000  
DSC1101DM1-033.3333  
DSC1101DM2-033.3333  
DSC1121DM1-033.3333  
DSC1101DM2-008.0000  
DSC1101DM2-024.0000  
DSC1121DM1-030.0000  
DSC1101DM1-080.0000  
DSC1121DM2-025.0000  
DSC1121DM2-033.0000  
DSC1121DM2-016.6400  
DSC1121DM2-014.7456  
DSC2311KM1-R0002  
DSC1101DM2-007.3700  
DSC1121DM3-032.0000  
DSC1101DM1-032.0000  
DSC1101DM1-007.3700  
DSC1101DM2-040.0000  
DSC1121DM2-026.0000  
DSC1121DM2-019.2000  
DSC1101DM2-048.0000  
DSC2311KM2-R0065  
DSC1101DM1-020.0000  
DSC2311KM2-R0073  
DSC2311KM2-R0067  
DSC2311KM2-R0015  
DSC2311KM2-R0080

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC231TKMZ-R0089

DSC1101DM2-050.0000

DSC2010FM2-B0006

DSC2011FM1-E0005

DSC2011FM2-E0001

DSC2011FM2-E0015

DSC2010FM2-A0001

DSC2011FM1-E0015

DSC2011FM1-F0041

DSC2011FM2-E0005

DSC2011FM2-F0049

DSC2210FM2-A0030

DSC2210FM2-A0031

DSC1101CI1-148.3516

DSC1101CI1-148.5000

DSC1101CI2-014.7456

DSC1101CI2-025.0000

DSC1101CI5-040.0000

DSC1121CI2-156.0063

DSC1103CI3-135.0000

DSC1121CI2-045.0000

DSC1121CI2-055.0000

DSC1123CI3-100.0000

DSC1123CI3-135.0000

DSC1123CI3-165.0000

DSC1123CI3-200.0000

DSC1123CI1-100.0000

DSC1123CI1-156.2500

DSC1122CI2-050.0000

DSC1101BI5-022.5792

DSC1101BI5-024.5760

DSC1101BI5-050.0000

DSC1102BI5-108.0000

DSC1103BI2-150.0000

DSC1104BI5-100.0000

DSC1121BI2-025.0000

DSC1121BI2-050.0000

DSC1121BI2-125.0037

DSC1122BI5-036.7000

DSC1122BI2-150.0000

DSC1123BI1-200.0000

DSC1123BI2-025.0000

DSC1122BI2-133.3300

DSC1123BI2-050.0000

DSC1123BI2-125.0000

DSC1123BI2-156.2500

DSC1123BI5-100.0000

DSC1123BI2-100.0000

DSC1123BI5-155.5200



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123BI5-156.2500  
DSC1123BI5-200.0000  
DSC1124BI1-100.0000  
DSC1124BI2-125.0000  
DSC8101BI2  
DSC8101BI5  
DSC8102BI2  
DSC1123BI2-200.0000  
DSC1123BI5-148.3516  
DSC8104BI2  
DSC1124BI2-100.0000  
DSC8121BI2  
DSC8122BI2  
DSC8122BI5  
DSC8123BI2  
DSC8124BI2  
DSC8103BI2  
DSC1122BI2-156.2500  
DSC1121BI2-080.0000  
DSC1122BI2-100.0000  
DSC1122BI2-114.2850  
DSC1122BI2-155.5200  
DSC1102BI1-100.0000  
DSC1122BI1-100.0000  
DSC1121BI2-012.2880  
DSC1101BI5-133.0000  
DSC1123BI2-148.5000  
DSC1102BI2-125.0000  
DSC1102BI2-153.6000  
DSC1103BI2-125.0000  
DSC1121BI2-025.0007  
DSC1121BI2-156.2540  
DSC1123BI1-156.2500  
DSC1102BI2-100.0000  
DSC1122BI5-400.0000  
DSC1104BI2-100.0000  
DSC1123BI1-125.0000  
DSC1123BI1-100.0000  
DSC1121BI2-100.0000  
DSC1121BI2-125.0000  
DSC8123BI5  
DSC1122BI2-156.2539  
DSC1124BI5-100.0000  
DSC1103BI2-100.0000  
DSC1103BI2-135.0000  
DSC1103BI2-148.5000  
DSC1102BI2-156.2500  
DSC1102BI2-155.2500  
DSC1102BI2-114.2850

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101BI2-125.0000  
DSC1121BI2-022.5792  
DSC1101BI2-024.5760  
DSC1123BI2-155.5200  
DSC1121BI2-114.2850  
DSC1121BI2-024.5760  
DSC1121BI2-033.3330  
DSC1102BI2-155.5200  
DSC1122BI2-156.2570  
DSC1123BI2-156.2570  
DSC1123BI2-300.0000  
DSC1122BI2-020.0000  
DSC1122BI2-322.0000  
DSC1123BI2-270.0000  
DSC1123BI2-210.0000  
DSC1123BI2-180.0000  
DSC1123BI2-206.0000  
DSC1123BI2-068.0000  
DSC1121BI1-008.0000  
DSC1121BI2-156.2500  
DSC1124BI5-020.0000  
DSC1123BI2-050.0013  
DSC1001BL5-058.9824T  
DSC1001BE1-060.0000T  
DSC1003BL3-030.0000T  
DSC1003BL3-008.1920T  
DSC1001BE3-022.1184T  
DSC1003BL3-020.0000T  
DSC1003BL3-032.7680T  
DSC1003BL3-013.8420T  
DSC1003BL3-025.0000T  
DSC1003BL3-010.2400T  
DSC1003BL3-018.4320T  
DSC1001BL5-032.0000T  
DSC1001BE5-030.6400T  
DSC1001BL5-106.2500T  
DSC1001BL2-125.0000T  
DSC1004BL2-025.0000T  
DSC1004BL2-024.0000T  
DSC1001BE1-004.0625T  
DSC1001BE1-004.0960T  
DSC1001BL2-012.0000T  
DSC1001BE5-027.0000T  
DSC1001BE5-030.0000T  
DSC1001BE1-033.3333T  
DSC1001BL2-012.5000T  
DSC1001BL3-001.0000T  
DSC1001DE1-024.0000T  
DSC1001DE1-026.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DE1-027.0000T  
DSC1001DE1-048.0000T  
DSC1001DE1-054.0000T  
DSC1001DE1-100.0000T  
DSC1001DE1-125.0000T  
DSC1001DE2-020.0000T  
DSC1001DE2-024.0000T  
DSC1001DE2-050.0000T  
DSC1001DL1-008.0000T  
DSC1001DE5-019.2000T  
DSC1001DL1-025.0000T  
DSC1001DL1-027.0000T  
DSC1001DL2-012.0000T  
DSC1001DL2-008.0000T  
DSC1001DL2-020.0000T  
DSC1001DL2-025.0000T  
DSC1001DL2-024.0000T  
DSC1001DL2-027.0000T  
DSC1001DL2-030.0000T  
DSC1001DL2-032.0000T  
DSC1001DL2-050.0000T  
DSC1001DL5-001.8432T  
DSC1001DL5-007.3728T  
DSC1001DL5-008.0000T  
DSC1001DL5-010.0000T  
DSC1001DL5-011.0592T  
DSC1001DL5-016.0000T  
DSC1001DL5-019.2000T  
DSC1001DL5-020.0000T  
DSC1001DL5-024.0000T  
DSC1001DL5-024.5760T  
DSC1001DL5-025.0000T  
DSC1001DL5-026.0000T  
DSC1001DL5-027.0000T  
DSC1001DL5-030.0000T  
DSC1001DL5-031.2500T  
DSC1001DL5-033.0000T  
DSC1001DL5-033.3330T  
DSC1001DL5-048.0000T  
DSC1001DL5-050.0000T  
DSC1001DL5-048.0000D  
DSC1003DL5-100.0000T  
DSC1001DL5-075.0000T  
DSC1001DL5-080.0000T  
DSC1001DL5-100.0000B  
DSC1001DL5-100.0000T  
DSC1001DL5-125.0000T  
DSC1003DL2-008.0000T  
DSC1003DL2-050.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003DL2-090.0000T  
DSC1003DL2-148.5000T  
DSC1003DL5-020.0000T  
DSC1003DL5-125.0000T  
DSC1001DE1-012.0000T  
DSC1001DL5-015.3600T  
DSC1003DL2-070.0000T  
DSC612RI1A-01GCT  
DSC612RI2A-01GET  
DSC613RI2A-01GJT  
DSC612RI1A-01GVT  
DSC613RI3A-0131T  
DSC613RI3A-01J3T  
DSC612RI2A-01J8T  
DSC612RI3A-01M3T  
DSC613RI3A-01M7T  
DSC613RI3A-01M8T  
DSC612RI2A-01K9T  
DSC612RI2A-01KAT  
DSC612RI2A-01KKT  
DSC612RI3A-013CT  
DSC612RI1A-01JMT  
DSC612RI3A-01K3T  
DSC612RI3A-01P3T  
DSA613RI3A-01BMTVAO  
DSC6101HA2B-072.0000T  
DSC6003HA3B-016.0000T  
DSC6001HA3B-PROGT  
DSC6003HA3B-PROGT  
DSC6101HA3B-PROGT  
DSC6003HA1B-020.0000T  
DSC6101HA2B-072.5000T  
DSC6001HA2B-029.4912T  
DSC6101HA3B-024.0000T  
DSC6111HA3B-024.0000T  
DSC6111HA2B-024.0000T  
DSC6332HA3AB-002.4576T  
DSC6332HA3AB-031.9488T  
DSC6301HA1FB-020.0000T  
DSC6301HA1FB-020.0000B  
DSC6021HA3B-01D0T  
DSC6003HA3B-032K768T  
DSC6011HA1B-032K768T  
DSC6011HA2B-032K768T  
DSC6011HA2B-025.0000T  
DSC6011HA2B-008.0000T  
DSC6013HA2B-048.0000T  
DSC6011HA2B-029.4912T  
DSA6101HA1B-005.0000TVAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA6101HA1B-008.0000TVAO

DSA6101HA1B-027.0000TVAO

DSA6301HA1AB-027.0000TVAO

DSA6001HA2B-029.4912TVAO

DSA6122HA3B-01ECTVAO

DSC6001MA2B-020.0000T

DSC6003MA3B-032K768T

DSC1101BL3-PROGT

DSC1101BL5-PROGT

DSC1100BL3-PROGT

DSC1100BL5-PROGT

DSC1121BE5-024.0000T

DSC1121BL5-012.0000T

DSC1124BE5-156.2500T

DSC1123BL5-200.0000T

DSC1122BE2-156.2500T

DSC1102BE2-312.5000T

DSC1121BL3-016.0000T

DSC1121BL3-012.2880T

DSC1121BE5-144.0800T

DSC1123BL1-100.0000T

DSC1123BL1-125.0000T

DSC1123BE2-200.0000T

DSC1103BE5-150.0000T

DSC1123BE1-025.0000T

DSC1101BL5-024.0000T

DSC1122BE5-123.0000T

DSC1101BE3-024.0000T

DSC1122BL2-018.4320T

DSC1101BL5-018.4320T

DSC1121BL5-025.0000T

DSC1123BL2-200.0000T

DSC1101BL5-022.1184T

DSC1103BE1-156.2500T

DSC1103BL1-100.0000T

DSC1104BE2-027.0000T

DSC1123BL2-212.5000T

DSC1123BL2-250.0000T

DSC1121BE5-098.3040T

DSC1103BL5-026.8800T

DSC1121BL2-040.6800T

DSC1123BE2-085.0000T

DSC1103BE5-100.0000T

DSC1101AE3-084.6720T

DSC1101AE3-090.3168T

DSC1104AE2-145.2000T

DSC1101AE5-022.5792T

DSC1101AE5-024.5760T

DSC1103AL1-287.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121AE5-012.0000T  
DSC1102AE5-416.0000T  
DSC1121AE5-005.2500T  
DSC400-2222Q0118KI2T  
DSC400-0244Q0009KI1T  
DSC400-0244Q0009KI2T  
DSC400-0101Q0119KI1T  
DSC400-0101Q0119KI2T  
DSC400-1111Q0120KI1T  
DSC400-1111Q0120KI2T  
DSC400-0111Q0026KI1T  
DSC400-0111Q0026KI2T  
DSC400-1111Q0121KI1T  
DSC400-1111Q0121KI2T  
DSC400-1114Q0122KI1T  
DSC400-1114Q0122KI2T  
DSC400-0321Q0123KI1T  
DSC400-0321Q0123KI2T  
DSC400-3333Q0124KI1T  
DSC400-3333Q0124KI2T  
DSC400-1331Q0125KI1T  
DSC400-1331Q0125KI2T  
DSC400-1333Q0126KI1T  
DSC400-1333Q0126KI2T  
DSC400-0223Q0127KI1T  
DSC400-0223Q0127KI2T  
DSC400-0133Q0128KI1T  
DSC400-0133Q0128KI2T  
DSC400-0331Q0128KI1T  
DSC400-0331Q0128KI2T  
DSC400-0101Q0129KI1T  
DSC400-0101Q0129KI2T  
DSC400-3333Q0130KI1T  
DSC1123DI2-315.0000T  
DSC1123DI2-312.0000T  
DSC1124DI2-315.0000T  
DSC1123DI2-312.2000T  
DSC1122DI2-050.0000T  
DSC2311KI1-R0054T  
DSC1103DI5-360.0000T  
DSC2311KI2-R0055T  
DSC1101DI1-125.0000T  
DSC1123DI2-025.0000T  
DSC2311KI2-R0056T  
DSC1101DI5-013.5288T  
DSC2311KI2-R0057T  
DSC1101DI5-032.0000T  
DSC1122DI2-156.2500T  
DSC1124DI1-100.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2311KI2-R00581

DSC1101DI2-049.1520T

DSC1101DI1-038.0000T

DSC1121DI5-100.0000T

DSC2311KI2-R0059T

DSC1103DI2-100.0000T

DSC1103DI2-108.0000T

DSC1121DI5-072.0000T

DSC1121DI5-050.0000T

DSC1121DI5-032.0000T

DSC1121DI1-100.0000T

DSC2311KI1-R0041T

DSC2311KI2-R0060T

DSC1102DI5-135.0000T

DSC1123DI5-148.4258T

DSC1123DI2-148.4258T

DSC2311KI1-R0059T

DSC1101DI3-025.0000T

DSC1103DI2-135.0000T

DSC1121DI2-010.0000T

DSC1101DI1-100.0000T

DSC2311KI2-R0008T

DSC1102DI2-125.0000T

DSC1124DI1-027.0000T

DSC2311KI2-R0061T

DSC2311KI2-R0062T

DSC2311KI2-R0063T

DSC1101DI5-024.0000T

DSC1101DI5-100.0000T

DSC1101DI5-045.1584T

DSC1101DI5-049.1520T

DSC1101DI5-018.4320T

DSC1121DI3-050.0000T

DSC2311KI2-R0065T

DSC1124DI2-027.0000T

DSC1102DI2-156.2500T

DSC1103DI5-074.2500T

DSC1103DI5-200.0000T

DSC1103DI5-100.0000T

DSC2311KI2-R0066T

DSC1101DI3-012.0000T

DSC1123DI1-125.0000T

DSC2311KI2-R0067T

DSC1101DI2-060.0000T

DSC2311KI2-R0068T

DSC1124DI3-100.0000T

DSC2311KI1-R0069T

DSC2311KI2-R0070T

DSC1122DI5-272.8000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC112TDI2-100.0000T  
DSC1124DI3-027.0000T  
DSC400-1111Q0078KE2  
DSC400-0323Q0009KE1  
DSC400-0323Q0009KE2  
DSC400-1111Q0148KE1  
DSC400-1111Q0148KE2  
DSC400-1313Q0094KE1  
DSC400-1313Q0094KE2  
DSC400-1111Q0149KE1  
DSC400-1111Q0149KE2  
DSC400-1333Q0078KE1  
DSC400-1333Q0078KE2  
DSC400-1111Q0150KE1  
DSC400-1111Q0150KE2  
DSC400-3333Q0151KE1  
DSC400-3333Q0151KE2  
DSC400-4144Q0152KE1  
DSC400-4144Q0152KE2  
DSC400-3331Q0153KE1  
DSC400-3331Q0153KE2  
DSC400-2222Q0031KE1  
DSC400-2222Q0031KE2  
DSC400-0333Q0154KE1  
DSC400-0333Q0154KE2  
DSC400-0111Q0155KE1  
DSC400-0111Q0155KE2  
DSC400-3133Q0156KE1  
DSC400-3133Q0156KE2  
DSC400-0133Q0157KE1  
DSC400-0133Q0157KE2  
DSC1123AI1-161.1328T  
DSC1101AI5-080.0000T  
DSC1101AI5-064.0000T  
DSC1102AI1-156.2500T  
DSC1102AI2-156.2500T  
DSC1121AI2-013.0000T  
DSC1103AI2-148.0000T  
DSC1124AI1-100.0000T  
DSC1121AI3-025.0000T  
DSC1101AI2-027.0000T  
DSC1101AI1-008.0000T  
DSC1101AI5-060.0000T  
DSC1121AI5-022.5792T  
DSC1102AI5-156.2500T  
DSC1122AI5-025.0007T  
DSC1103AI2-300.0000T  
DSC1123AI2-135.0000T  
DSC1121AI2-008.0000T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121AI2-016.0000T  
DSC1121AI2-066.6660T  
DSC1121AI2-033.3330T  
DSC1121AI1-156.2500T  
DSC1121AI1-090.0000T  
DSC1101AI5-114.2850T  
DSC1101AI3-125.0000T  
DSC1103AI5-180.0000T  
DSC1121AI5-008.0000T  
DSC1123AI2-155.5200T  
DSC1102AI2-106.0000T  
DSC1102AI5-160.0000T  
DSC1102AI5-400.0000T  
DSC1121AI2-159.3750T  
DSC1102AI2-156.2540T  
DSC1121AI2-081.0000T  
DSC1121AI2-041.5000T  
DSC1121AI5-041.5000T  
DSC1121AI1-041.5000T  
DSC1123AI2-185.0000T  
DSC1123AI2-250.0000T  
DSC1123AI2-074.2500T  
DSC1123AI2-312.5000T  
DSC1103AI2-156.2500T  
DSC1101AI2-066.6666T  
DSC1121AI1-100.0000T  
DSC1102AI1-250.0000T  
DSC1123AI2-055.0000T  
DSC6101HI2B-080.0000  
DSC6102HI2B-025.0000  
DSC6001HI1B-032.7680  
DSC6111HI2B-012.0000  
DSC6013HI3B-409K600  
DSC6011HI3B-048.0000  
DSC6101HI2B-010.0000  
DSC6011HI3B-032K000  
DSC6001HI2B-018.4320  
DSC6301HI2BB-012.0000  
DSC6301HI2DB-012.0000  
DSC6301HI2FB-012.0000  
DSC6111HI1B-013.5600  
DSC6041HI2B-025.0000  
DSC6041HI2B-027.0000  
DSC6011HI2B-025.0000  
DSC6011HI2B-027.0000  
DSC6111HI1B-080.0000  
DSC6001HI2B-025.0000  
DSC6101HI1B-007K085  
DSC6001HI1B-025.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6101HI3B-100.0000  
DSC6011HI1B-012.0000  
DSC6101HI1B-012.0000  
DSC6003HI2B-745K000  
DSC6001HI2B-004.0960  
DSC6001HI2B-032.0000  
DSC6001HI2B-003.5900  
DSC6003HI2B-048.0000  
DSC6112HI2B-025.0000  
DSC6013HI2B-048.0000  
DSC6011HI2B-012.0000  
DSC6061HI1B-01MC  
DSC6111HI3B-027.0000  
DSC6111HI3B-074.2500  
DSC6051HI2B-012.0000  
DSC6151HI2B-025.0000  
DSC6151HI2B-027.0000  
DSC6331HI2AB-012.0000  
DSC6102HI2B-024.0000  
DSA6001HI2B-019.2000VAO  
DSA6001HI2B-024.0000VAO  
DSA6001HI2B-025.0000VAO  
DSA6011HI2B-002K730VAO  
DSA6331HI2AB-012.0000VAO  
DSA6331HI2AB-025.0000VAO  
DSC6001MI2B-012.2880  
DSC1123CE5-100.0000T  
DSC1123CE2-135.0000T  
DSC1123CL5-100.0000T  
DSC1123CE5-150.0000T  
DSC1123CE5-156.2500T  
DSC1123CL2-125.0000T  
DSC8121CL5T  
DSC1124CL2-200.0000T  
DSC1101CL5-100.0000T  
DSC1103CE1-125.0000T  
DSC1123CE1-125.0000T  
DSC1101CL5-014.7456T  
DSC1121CE1-133.3333T  
DSC8123CI5T  
DSC1103CE1-156.2500T  
DSC1124CE1-010.2400T  
DSC1121CE5-050.0000T  
DSC1121CL2-040.0000T  
DSC1121CL5-050.0000T  
DSC1124CL2-100.0000T  
DSC1101CL2-024.7500T  
DSC1101CL3-PROGT  
DSC1101CL5-PROGT

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101CE2-100.0000T  
DSC1123CL1-400.0000T  
DSC1123CL1-025.0000T  
DSC1103CE5-100.0000T  
DSC1103CL5-100.0000T  
DSC1123CL5-050.0000T  
DSC1123CL5-025.0000T  
DSC1103CE5-045.0000T  
DSC1121CE1-125.0000T  
DSC1123CE2-250.0000T  
DSC1123CE2-312.5000T  
DSC1103CE1-266.7000T  
DSC1103CE1-233.3000T  
DSC1123CE1-150.0000T  
DSC1124CE1-100.0000T  
DSC1121CL5-150.0000T  
DSC1124CL1-100.0000T  
DSC1122CL2-156.2500T  
DSC1121CE1-033.3333T  
DSC1121CE5-033.3333T  
DSC1101CE5-010.0000T  
DSC1101CL2-040.0000T  
DSC1121CL1-024.0000T  
DSC1121CL1-028.6364T  
DSC1121CL1-027.0000T  
DSC1103CL5-150.0000T  
DSC1103CE2-156.2500T  
DSC1101CE2-045.1584T  
DSC1101CE2-049.1520T  
DSC1104CE2-027.0000T  
DSC1123CL5-433.0000T  
DSC1121CE1-025.6000T  
DSC1121CL5-040.0000T  
DSC1121CL5-080.0000T  
DSC1101CL1-125.0000T  
DSC1124CE2-100.0000T  
DSC1124CE5-100.0000T  
DSC1100CL3-PROGT  
DSC1100CL5-PROGT  
DSC1101CL5-030.0000T  
DSC1123CL5-322.2656T  
DSC1101CE5-025.0000T  
DSC1101CE2-025.0000T  
DSC1103CL2-233.3333T  
DSC1101CE1-024.5790T  
DSC1101CE1-022.5792T  
DSC1101CE1-011.2896T  
DSC1101CL5-052.5000T  
DSC1101CE1-024.5760T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103CL2-333.3333T  
DSC1123CE2-100.0000T  
DSC1101CE5-024.0000T  
DSC1101CE5-100.0000T  
DSC1101CE5-045.1854T  
DSC1101CE5-049.1520T  
DSC1103CL2-125.0000T  
DSC1103CL2-052.0000T  
DSC1103CL5-033.3330T  
DSC1103CL5-075.0300T  
DSC1123CL2-333.3333T  
DSC1101CE5-022.5792T  
DSC1101CE5-024.5760T  
DSC1101CL3-025.0000T  
DSC1121CL5-033.3333T  
DSC1123CL2-200.0000T  
DSC1123CL3-040.0000T  
DSC1123CL1-287.0000T  
DSC1121CE5-002.4880T  
DSC1101CE1-100.0000T  
DSC1101CE1-054.0000T  
DSC1122CL1-135.0000T  
DSC1121CL1-050.0000T  
DSC1101CL2-025.0000T  
DSC1101CL2-050.0000T  
DSC1101CL2-100.0000T  
DSC1101CL2-125.0000T  
DSC1123CE3-422.3000T  
DSC1103CL1-075.0000T  
DSC1123CL2-156.2500T  
DSC1123CL1-100.0000T  
DSC1123CL2-100.0000T  
DSC1124CL3-100.0000T  
DSC1103CL1-200.0000T  
DSC1103CL1-100.0000T  
DSC1103CL1-125.0000T  
DSC1103CL1-150.0000T  
DSC1103CL1-026.0000T  
DSC1103CL1-027.0000T  
DSC1103CL3-093.4400T  
DSC1103CL3-100.0000T  
DSC1103CL3-125.0000T  
DSC1103CL3-250.0000T  
DSC1101CE1-080.0000T  
DSC1103CL1-020.0000T  
DSC1124CL5-027.0000T  
DSC1121CE1-030.0000T  
DSC1121CE2-030.0000T  
DSC1101CE3-024.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121CE5-025.0000T

DSC1121CL5-027.0000T

DSC612RL1A-014ST

DSC612RL2A-0130T

DSC612RL2A-0168T

DSC612RL2A-013CT

DSC612RE1A-0169T

DSC613RE2A-016YT

DSC613RE1A-017QT

DSC612RL2A-018KT

DSC613RE1A-0197T

DSC612RE1A-0199T

DSC612RL3A-019BT

DSC612RL1A-019TT

DSC612RL3A-01AMT

DSC612RE2A-01ATT

DSC612RE1A-01B2T

DSC613RE1A-01BVT

DSC613RE2A-01DGT

DSC612RL2A-01E7T

DSC612RE1A-01GQT

DSC612RE2A-01GQT

DSC612RL3A-01KST

DSC612RE3A-01M0T

DSC612RE2A-01MRT

DSA612RL2A-01GATVAO

DSA612RL2A-01H6TVAO

DSA612RL2A-01K9TVAO

DSA612RL2A-01KMTVAO

DSA612RL2A-01MGTVAO

DSA613RL2A-016PTVAO

DSC6001HI2B-012.0000T

DSC6001HI2B-024.0000T

DSC6003HI2B-012.0000T

DSC6001HI3B-032K768T

DSC6003HI3B-010.0000T

DSC6101HI3B-019.2000T

DSC6003HI2B-025.0000T

DSC6003HI2B-024.0000T

DSC6011HI2B-002K000T

DSC6011HI2B-032K768T

DSC6011HI2B-250K000T

DSC6011HI2B-432K000T

DSC6011HI2B-720K000T

DSC6013HI2B-001.0000T

DSC6013HI2B-002K000T

DSC6013HI2B-032K768T

DSC6013HI2B-250K000T

DSC6013HI2B-432K000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6013HI2B-720K000T  
DSC6112HI2B-001.0000T  
DSC6111HI2B-032K768T  
DSC6111HI2B-250K000T  
DSC6111HI2B-432K000T  
DSC6111HI2B-720K000T  
DSC6112HI2B-032K768T  
DSC6112HI2B-250K000T  
DSC6112HI2B-432K000T  
DSC6112HI2B-720K000T  
DSC6111HI2B-004K000T  
DSC6112HI2B-004K000T  
DSC6001HI2B-048.0000T  
DSC6003HI3B-027.0000T  
DSC6111HI3B-010.0000T  
DSC6013HI2B-003.6864T  
DSC6021HI3B-016RT  
DSC6001HI2B-006.0000T  
DSC6001HI2B-008.0000T  
DSC6011HI1B-016.0000T  
DSC6011HI1B-024.0000T  
DSC6011HI1B-025.0000T  
DSC6011HI1B-009.6000T  
DSC6021HI2B-018ET  
DSC6011HI3B-064.0128T  
DSC6013HI3B-064.0128T  
DSC6003HI2B-019.2000T  
DSC6111HI1B-032K768T  
DSC6001HI1B-020.0000T  
DSC6101HI2B-080.0000T  
DSC6102HI2B-025.0000T  
DSC6001HI1B-032.7680T  
DSC6111HI2B-012.0000T  
DSC6013HI3B-409K600T  
DSC6011HI3B-048.0000T  
DSC6101HI2B-010.0000T  
DSC6011HI3B-032K000T  
DSC6001HI2B-018.4320T  
DSC6301HI2BB-012.0000T  
DSC6301HI2DB-012.0000T  
DSC6301HI2FB-012.0000T  
DSC6111HI1B-013.5600T  
DSC6041HI2B-025.0000T  
DSC6041HI2B-027.0000T  
DSC6011HI2B-025.0000T  
DSC6011HI2B-027.0000T  
DSC6111HI1B-080.0000T  
DSC6001HI2B-025.0000T  
DSC6101HI1B-007K085T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6001HI1B-025.0000T  
DSC6101HI3B-100.0000T  
DSC6011HI1B-012.0000T  
DSC6101HI1B-012.0000T  
DSC6003HI2B-745K000T  
DSC6001HI2B-004.0960T  
DSC6001HI2B-032.0000T  
DSC6001HI2B-003.5900T  
DSC6003HI2B-048.0000T  
DSC6112HI2B-025.0000T  
DSC6013HI2B-048.0000T  
DSC6011HI2B-012.0000T  
DSC6061HI1B-01MCT  
DSC6111HI3B-027.0000T  
DSC6111HI3B-074.2500T  
DSC6051HI2B-012.0000T  
DSC6151HI2B-025.0000T  
DSC6151HI2B-027.0000T  
DSC6331HI2AB-012.0000T  
DSC6102HI2B-024.0000T  
DSA6001HI2B-019.2000TVAO  
DSA6001HI2B-024.0000TVAO  
DSA6001HI2B-025.0000TVAO  
DSA6011HI2B-002K730TVAO  
DSA6331HI2AB-012.0000TVAO  
DSA6331HI2AB-025.0000TVAO  
DSC6001MI2B-012.2880T  
DSC2011FL2-F0020T  
DSC557-0333FE0T  
DSC2033FE2-F0010T  
DSC2041FE1-K0003T  
DSC2044FE1-H0002T  
DSC2010FE1-B0013T  
DSC2043FE1-F0023T  
DSC557-0333FL0T  
DSC2033FL2-F0028T  
DSC2130FE1-C0003T  
DSC2044FL1-F0022T  
DSC2044FL1-H0005T  
DSC2044FE1-H0003T  
DSC2044FE1-F0024T  
DSC2041FE1-F0014T  
DSC557-0341FE1T  
DSC557-0344FE0T  
DSC557-0344FL1T  
DSC2044FE2-H0006T  
DSC2030FE5-B0018T  
DSC2022FE2-F0034T  
DSC2111FE1-E0022T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2033FL1-F002Z1  
DSC2010FL2-B0014T  
DSC2041FE1-K0002T  
DSC2033FL2-F0004T  
DSC2031FL2-F0045T  
DSC2011FL2-E0005T  
DSC2110FL1-A0029T  
DSC2110FL2-C0011T  
DSC2144FL2-F0022T  
DSC2033FL2-F0051T  
DSC2033FL2-E0005T  
DSC1001DL5-010.2000T  
DSC1001DL2-037.1250T  
DSC1001DE1-040.0000T  
DSC1001DE1-050.0000T  
DSC1001DL2-150.0000T  
DSC1001DL2-090.0000T  
DSC1001DL5-012.0000T  
DSC1003DL5-148.5000T  
DSC1001DL5-004.0000T  
DSC1001DE1-025.0000T  
DSC1001DL5-133.3330T  
DSC1001DL1-010.0000T  
DSC1001DL2-072.0000T  
DSC1003DL2-100.0000T  
DSC1001DL2-087.0655T  
DSC1001DL5-060.0000T  
DSC1001DL1-037.1250  
DSC1001DL1-080.0000T  
DSC1001DL5-014.7456T  
DSC1001DL2-049.5000T  
DSC1003DE1-050.0000T  
DSC1003DL1-125.0000T  
DSC1003DL2-025.0000T  
DSC1003DL5-025.0000T  
DSC1001DL1-024.0000T  
DSC1001DL2-040.0000T  
DSC1001DL1-001.8432T  
DSC1001DL2-001.8432T  
DSC1001DL2-033.3333T  
DSC1001DL1-033.3333T  
DSC1001DE1-075.0000T  
DSC8001DL5T  
DSC1001DE2-100.0000T  
DSC1001DL2-016.0000T  
DSC1001DL1-025.2000T  
DSC1004DL5-040.0000T  
DSC1001DE1-033.3333T  
DSC1001DL5-040.0000T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DE1-019.2000T  
DSC1001DL2-007.3728T  
DSC1001DL5-072.0000T  
DSC1003DL2-080.0000T  
DSC1001DL5-012.2880T  
DSC1003DL1-027.0000T  
DSC1004DL1-027.0000T  
DSC1001DE2-038.4000T  
DSC1101DI5-016.0000T  
DSC1101DI2-050.6880T  
DSC1103DI2-048.0000T  
DSC1101DI5-030.2400T  
DSC1124DI2-100.0000T  
DSC2311KI1-R0053T  
DSC1001DI2-012.2880T  
DSC1001DI2-016.0000T  
DSC1001DL5-001.0000T  
DSC1001DI2-033.3300T  
DSC1001DI2-019.2000T  
DSC1001DI2-020.0000T  
DSC1001DI2-022.0000T  
DSC1001DI2-022.5792T  
DSC1001DI2-024.0000T  
DSC1001DI2-024.5455T  
DSC1001DI2-024.5760B  
DSC1001DI2-024.5760T  
DSC1001DI2-025.0000T  
DSC1001DI2-026.0000T  
DSC1001DI2-027.0000T  
DSC1001DI2-028.3220T  
DSC1001DI2-029.5000T  
DSC1001DI2-032.0000T  
DSC1001DI2-066.6600T  
DSC1001DI2-033.3333T  
DSC1001DI2-036.8182T  
DSC1001DI2-037.1250T  
DSC1001DI5-002.4576T  
DSC1001DI2-038.4000T  
DSC1001DI2-040.0000T  
DSC1001DI2-048.0000T  
DSC1001DI2-049.0909T  
DSC1001DI2-050.0000T  
DSC1001DI2-072.0000T  
DSC1001DI2-074.1758T  
DSC1001DI2-074.2500T  
DSC1001DI2-080.0000T  
DSC1001DI2-100.0000T  
DSC1001DI2-125.0000T  
DSC1001DI2-128.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DI4-010.0000T  
DSC1001DI4-010.0503T  
DSC1001DI4-010.0587T  
DSC1001DI4-059.7800T  
DSC1001DI4-060.0700T  
DSC1001DI4-066.4860T  
DSC1001DI4-066.5800T  
DSC1004DI2-025.0000T  
DSC1001DI5-002.0480T  
DSC1001DI2-047.3885T  
DSC1001DI1-038.4000T  
DSC1001DI2-026.6000T  
DSC1001DI1-066.0000T  
DSC1001DI5-008.0000T  
DSC1001DI5-047.3885T  
DSC1001DI5-013.3333T  
DSC1001DI5-022.5792T  
DSC1001DI5-030.0000T  
DSC1001DI2-024.5454T  
DSC1001DI5-033.0000T  
DSC1001DI1-100.0000T  
DSC1004DI2-012.0000T  
DSC1003DI2-024.5760T  
DSC1001DI1-033.0000T  
DSC1001DI1-072.0000T  
DSC1001DI1-030.0000T  
DSC1001DI1-050.0000B  
DSC1001DI5-150.0000T  
DSC1004DI2-010.0000T  
DSC1001DI1-032.0000T  
DSC1001DI2-014.7456T  
DSC1003DI2-100.0000T  
DSC1001DI2-028.6363T  
DSC1001DI2-031.2500T  
DSC1004DI2-016.0000T  
DSC8003DI2T  
DSC1001DI5-003.6864T  
DSC1001DI5-004.0000T  
DSC8123BL2  
DSC1122BE1-156.2500  
DSC1124BL1-100.0000  
DSC1101BE5-024.5760  
DSC1101BE5-022.5792  
DSC1121BE2-155.5200  
DSC1123BE1-050.0000  
DSC1101BE1-012.0000  
DSC1121BL5-108.7200  
DSC1121BL5-110.5400  
DSC1123BL5-125.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123BE5-100.0000  
DSC1123BE1-100.0000  
DSC1101BL3-PROG  
DSC1101BL5-PROG  
DSC1100BL3-PROG  
DSC1100BL5-PROG  
DSC1121BE5-024.0000  
DSC1121BL5-012.0000  
DSC1124BE5-156.2500  
DSC1123BL5-200.0000  
DSC1122BE2-156.2500  
DSC1102BE2-312.5000  
DSC1121BL3-016.0000  
DSC1121BL3-012.2880  
DSC1121BE5-144.0800  
DSC1123BL1-100.0000  
DSC1123BL1-125.0000  
DSC1123BE2-200.0000  
DSC1103BE5-150.0000  
DSC1123BE1-025.0000  
DSC1101BL5-024.0000  
DSC1122BE5-123.0000  
DSC1101BE3-024.0000  
DSC1122BL2-018.4320  
DSC1101BL5-018.4320  
DSC1121BL5-025.0000  
DSC1123BL2-200.0000  
DSC1101BL5-022.1184  
DSC1103BE1-156.2500  
DSC1103BL1-100.0000  
DSC1104BE2-027.0000  
DSC1123BL2-212.5000  
DSC1123BL2-250.0000  
DSC1121BE5-098.3040  
DSC1103BL5-026.8800  
DSC1121BL2-040.6800  
DSC1123BE2-085.0000  
DSC1103BE5-100.0000  
DSC1101AE5-007.6800  
DSC1101AE5-040.6080  
DSC1101AE3-084.6720  
DSC1101AE3-090.3168  
DSC1104AE2-145.2000  
DSC1101AE5-022.5792  
DSC1101AE5-024.5760  
DSC1103AL1-287.0000  
DSC1121AE5-012.0000  
DSC1102AE5-416.0000  
DSC1121AE5-005.2500

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123AE2-003.5000  
DSC1101AL5-045.1584  
DSC1101AL5-049.1520  
DSC1123AE2-156.2500  
DSC1121AE2-004.9152  
DSC1121AE2-133.0000  
DSC1102AE2-400.0000  
DSC1101AE3-024.0000  
DSC1103AL5-150.0000  
DSC1103AL5-015.0000  
DSC1102AE2-155.5200  
DSC1103AE3-416.0000  
DSC1121AL5-041.5000  
DSC1121AE2-041.5000  
DSC1121AE5-041.5000  
DSC1121AL2-041.5000  
DSC1121AL1-041.5000  
DSC1123AE1-159.3750  
DSC1103AL1-125.0000  
DSC1122AE2-075.0000  
DSC1121AL5-012.0000  
DSC1101AL2-156.2500  
DSC1103AE2-085.0000  
DSC1123AE2-085.0000  
DSC1121AE5-025.0000  
DSC1121AE5-020.0000  
DSC1100AL3-PROG  
DSC1101AL3-PROG  
DSC1100AL5-PROG  
DSC1101AL5-PROG  
DSC1123AE2-100.0000  
DSC1122AE2-156.2500  
DSC1123AE1-200.0000  
DSC1121AL2-020.0000  
DSC1123AE2-040.0000  
DSC1121AL5-010.0000  
DSC1121AL5-100.0000  
DSC1123AL2-125.0000  
DSC1103AE2-135.0000  
DSC1123AL5-100.0000  
DSC1123AL5-148.5000  
DSC1121AE5-010.0000  
DSC1101AL5-112.4400  
DSC1123AL2-100.0000  
DSC1103AL2-147.4560  
DSC1121AL5-112.2400  
DSC1121AE5-022.5792  
DSC1121AE5-024.5760  
DSC1121AL5-170.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121AL5-024.5760  
DSC1121AL5-022.5792  
DSC1121AL5-125.0000  
DSC1101AE2-027.1200  
DSC1123AL1-148.5000  
DSC1103AL1-100.0000  
DSC1103AE2-212.5000  
DSC1124AE5-065.0000  
DSC1101AE5-032.0000  
DSC1123AL5-156.2500  
DSC1123AL5-125.0000  
DSC1103AL2-125.0031  
DSC1123AE5-148.5000  
DSC1123AE5-148.3516  
DSC1123AE5-074.1758  
DSC1123AE1-125.0000  
DSC1101AE2-016.3840  
DSC1123AE2-200.0000  
DSC1123AE2-300.0000  
DSC1123AL2-025.0000  
DSC1123AL2-050.0000  
DSC8101AL2  
DSC8121AL2  
DSC1123AE1-148.3500  
DSC1123AE1-148.5000  
DSC1123AL1-150.0000  
DSC1102AE5-412.5000  
DSC1101AE3-098.3040  
DSC1121AE2-025.0000  
DSC1121AE2-156.2500  
DSC1121AL2-025.0000  
DSC1123AE2-148.3516  
DSC1103NE1-125.0000  
DSC1122NE1-025.0000  
DSC1122NE2-156.2500  
DSC1124NE1-100.0000  
DSC1122NE1-133.3330  
DSC1122NE1-150.0000  
DSC1123NE2-156.2500  
DSC1123NE2-125.0000  
DSC1123NL2-100.0000  
DSC1102NE1-148.5000  
DSC1102NE1-125.0000  
DSC1103NE1-114.2850  
DSC1123NE1-100.0000  
DSC1123NL5-125.0000  
DSC1123NL5-100.0000  
DSC1121NL1-025.0000  
DSC1101NL3-PROG

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101NL5-PROG  
DSC1100NL3-PROG  
DSC1100NL5-PROG  
DSC1122NL2-025.0006  
DSC1103NL2-147.4560  
DSC1103NL2-098.3040  
DSC1123NE1-200.0000  
DSC1103NL5-125.0000  
DSC1103NL2-100.0000  
DSC1103NL2-106.2500  
DSC1103NL2-135.0000  
DSC1101DE2-008.0000  
DSC1101DL1-033.3330  
DSC1101DL1-100.0000  
DSC1101DL2-040.0000  
DSC1101DL5-050.0000  
DSC1101DL5-013.5600  
DSC1101DL5-025.0000  
DSC1121DL2-024.7500  
DSC1121DL2-025.0000  
DSC1123DE1-131.0720  
DSC1123DL5-156.2500  
DSC1123DE5-200.0000  
DSC1123DL2-125.0000  
DSC1123DL5-100.0000  
DSC1123DL5-125.0000  
DSC2311KE1-R0002  
DSC1123DL5-212.5000  
DSC2311KL1-R0009  
DSC2311KL1-R0021  
DSC2311KL2-R0009  
DSC2311KL2-R0015  
DSC2311KL2-R0027  
DSC1105DL1-027.0000  
DSC2311KE1-R0042  
DSC1103DL5-125.0000  
DSC2311KE1-R0047  
DSC2311KL2-R0048  
DSC1101DL5-052.8000  
DSC1123DL5-200.0000  
DSC1123DL1-125.0000  
DSC1101DL1-027.0000  
DSC2311KL1-R0002  
DSC1121DL2-008.0000  
DSC1101DL5-020.0000  
DSC1101DL5-016.0000  
DSC1121DL2-032.0000  
DSC2311KL2-R0040  
DSC2311KL2-R0052

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121DE1-050.0000  
DSC1101DL2-050.6880  
DSC1103DL2-147.4560  
DSC1123DE2-399.6800  
DSC1123DE2-400.0000  
DSC2311KL1-R0054  
DSC1103DL2-156.2500  
DSC1101DL1-150.0000  
DSC1121DL5-026.0000  
DSC1121DL1-025.0000  
DSC1121DL1-033.0000  
DSC1104DL1-027.0000  
DSC1123DL5-135.0000  
DSC1123DL5-150.0000  
DSC1101DL5-024.5760  
DSC1101DL5-018.4320  
DSC1101DE5-040.0000  
DSC1101DE5-012.2880  
DSC1121DE2-025.0000  
DSC1101DE2-049.1520  
DSC1101DE2-045.1584  
DSC1123DL2-100.0000  
DSC2311KL2-R0002  
DSC1121DL2-072.0000  
DSC1121DL1-040.0000  
DSC1101DL3-PROG  
DSC1101DL5-PROG  
DSC1100DL3-PROG  
DSC1100DL5-PROG  
DSC2311KE2-R0016  
DSC1123DL5-176.5000  
DSC1123DL5-206.5000  
DSC1123DL5-136.5000  
DSC1103DL1-025.0013  
DSC1103DL2-025.0012  
DSC1123DE1-148.3516  
DSC1101DE2-024.5760  
DSC1101DE2-022.5792  
DSC1101DE2-100.0000  
DSC1121DL5-072.0000  
DSC1121DE5-072.0000  
DSC1103DL2-100.0000  
DSC1124DL2-100.0000  
DSC1103DL2-122.8800  
DSC1103DL2-098.3040  
DSC1101DE2-012.0000  
DSC1104DE5-100.0000  
DSC1104DL3-100.0000  
DSC1124DL5-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1124DL1-100.0000  
DSC1103DL5-156.2500  
DSC1123DL2-250.0000  
DSC1121DE1-010.0000  
DSC2311KL2-R0071  
DSC1101DL2-033.3300  
DSC1104DL2-026.0000  
DSC2311KL1-R0072  
DSC1122DL2-220.0000  
DSC1124DL1-027.0000  
DSC1123DL2-050.0000  
DSC1121DE3-150.3330  
DSC1101DL1-020.0000  
DSC1123DE1-125.0000  
DSC1122DL1-072.0000  
DSC1102DL1-212.5000  
DSC2311KE2-R0002  
DSC2311KE2-R0081  
DSC1123DE1-156.2500  
DSC1103DL5-027.0000  
DSC1103DL5-100.0000  
DSC1101DL2-025.0000  
DSC1123DL1-025.0000  
DSC1122DE5-254.6500  
DSC1103DL5-063.5000  
DSC1103DL2-135.0000  
DSC2311KE1-R0085  
DSC1123DL2-156.2500  
DSC1123DL1-156.2500  
DSC2311KL2-R0091  
DSC2311KE2-R0090  
DSC1103DE5-254.6500  
DSC2033FI2-F0012T  
DSC2111FI2-E0029T  
DSC2043FI1-F0058T  
DSC2011FI1-F0056T  
DSA557-0344FI0TVAO  
DSA557-0344FI1TVAO  
DSC1101CM2-062.2080T  
DSC1121CM1-010.0000T  
DSC1121CM1-016.0000T  
DSC1121CM1-020.0000T  
DSC1121CM1-024.0000T  
DSC1121CM1-025.0000T  
DSC1121CM1-048.0000T  
DSC1121CM1-050.0000T  
DSC1121CM1-075.0000T  
DSC1121CM1-125.0000T  
DSC1121CM2-033.3333T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121CM2-027.0000T  
DSC1101CM1-075.0000T  
DSC1101CM1-005.0000T  
DSC1101CM1-033.3333T  
DSC1121CM2-040.0000T  
DSC1121CM2-006.7800T  
DSC1121CM1-012.0000T  
DSC1121CM1-012.2880T  
DSC1121CM1-040.0000T  
DSC1101CM2-012.0000T  
DSC1101CM2-048.0000T  
DSC1121CM1-066.6660T  
DSC1121CM1-100.0000T  
DSC1121CM1-036.0000T  
DSC1121CM1-018.0000T  
DSC1101CM1-040.0000T  
DSC1121CM2-008.0000T  
DSC1121CM2-025.0000T  
DSC1121CM1-030.0000T  
DSC1101CM3-024.0000T  
DSC1121CM1-014.7456T  
DSC1101CM1-032.0000T  
DSC1121CM1-032.0000T  
DSC1123CM1-375.0000T  
DSC1121CM2-003.1152T  
DSC1121CM1-003.1152T  
DSC1121CM1-005.5296T  
DSC1121CM2-024.0000T  
DSC1101BM2-025.0000T  
DSC1101BM2-100.0000T  
DSC1121BM1-008.0000T  
DSC1121BM1-025.0000T  
DSC1121BM1-027.0000T  
DSC1121BM1-030.0000T  
DSC1121BM1-048.0000T  
DSC1121BM1-100.0000T  
DSC1101BM2-074.2500T  
DSC1121BM1-010.0000T  
DSC1121BM1-024.0000T  
DSC1101BM2-027.0000T  
DSC1121BM1-050.0000T  
DSC1121BM2-016.0000T  
DSC1121BM2-030.0000T  
DSC1101BM2-050.0000T  
DSC1101BM2-054.0000T  
DSC1121BM1-024.5760T  
DSC1123AI5-270.0000  
DSC1122AI2-100.3000  
DSC1101AI2-150.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103AI1-155.5200  
DSC1103AI1-161.1328  
DSC1103AI2-125.0031  
DSC1122AI2-125.0000  
DSC1123AI1-155.5200  
DSC1123AI1-161.1300  
DSC1123AI1-161.1328  
DSC1101AI5-080.0000  
DSC1101AI5-064.0000  
DSC1102AI1-156.2500  
DSC1102AI2-156.2500  
DSC1121AI2-013.0000  
DSC1103AI2-148.0000  
DSC1124AI1-100.0000  
DSC1121AI3-025.0000  
DSC1101AI2-027.0000  
DSC1101AI1-008.0000  
DSC1101AI5-060.0000  
DSC1121AI5-022.5792  
DSC1102AI5-156.2500  
DSC1122AI5-025.0007  
DSC1103AI2-300.0000  
DSC1123AI2-135.0000  
DSC1121AI2-008.0000  
DSC1121AI2-016.0000  
DSC1121AI2-066.6660  
DSC1121AI2-033.3330  
DSC1121AI1-156.2500  
DSC1121AI1-090.0000  
DSC1101AI5-114.2850  
DSC1101AI3-125.0000  
DSC1103AI5-180.0000  
DSC1121AI5-008.0000  
DSC1123AI2-155.5200  
DSC1102AI2-106.0000  
DSC1102AI5-160.0000  
DSC1102AI5-400.0000  
DSC1121AI2-159.3750  
DSC1102AI2-156.2540  
DSC1121AI2-081.0000  
DSC1121AI2-041.5000  
DSC1121AI5-041.5000  
DSC1121AI1-041.5000  
DSC1123AI2-185.0000  
DSC1123AI2-250.0000  
DSC1123AI2-074.2500  
DSC1123AI2-312.5000  
DSC1103AI2-156.2500  
DSC1101AI2-066.6666

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121AI1-100.0000  
DSC1102AI1-250.0000  
DSC1123AI2-055.0000  
DSC1121AI1-064.0000  
DSC1102AI1-050.0000  
DSC1122AI1-159.3750  
DSC1101AI1-025.0000  
DSC1121AI2-150.0000  
DSC1123AI2-062.5000  
DSC8121AI5  
DSC8123AI5  
DSC1123AI2-156.2570  
DSC1101AI2-080.0000  
DSC1101AI2-040.0000  
DSC1101AI2-064.0000  
DSC1123AI2-027.0000  
DSC1123AI2-050.0000  
DSC8121NI2  
DSC8122NI2  
DSC8123NI2  
DSC8124NI2  
DSC1101NI1-125.0062  
DSC1101NI1-156.2500  
DSC1101NI5-100.0000  
DSC1103NI2-400.0000  
DSC1121NI2-018.4320  
DSC1122NI2-150.0000  
DSC1123NI1-100.0000  
DSC1123NI1-125.0000  
DSC1123NI2-125.0000  
DSC1123NI2-150.0000  
DSC1123NI2-312.5000  
DSC1101NI5-025.0000  
DSC8122NI5  
DSC1101NI5-020.0000  
DSC1101NI5-012.8000  
DSC1101NI5-016.3840  
DSC1124NI1-100.0000  
DSC1124NI1-156.2500  
DSC1104NI2-100.0000  
DSC1122NI5-025.0020  
DSC1122NI2-050.0000  
DSC1103NI2-125.0000  
DSC1121NI1-100.0000  
DSC1121NI2-125.0000  
DSC1121NI2-025.0000  
DSC1101NI1-050.0000  
DSC1102NI5-156.2500  
DSC1123NI1-156.2500

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1122NI2-156.2500

DSC1103NI2-148.5000

DSC1103NI2-156.2500

DSC1101NI5-018.7500

DSC1122NI2-148.5000

DSC1123NI2-200.0000

DSC1123NI5-100.0000

DSC1123NI5-125.0000

DSC1123NI5-156.2500

DSC1123NI5-322.2656

DSC1101NI2-050.0000

DSC1103NI1-135.0000

DSC1122NI5-025.0007

DSC1123NI3-050.0015

DSC1103NI5-150.0000

DSC1123NI2-100.0000

DSC1122NI5-200.0000

DSC1102NI5-400.0000

DSC1102NI5-200.0000

DSC1101NI2-025.0000

DSC1101NI2-018.7500

DSC1121DI2-024.0000

DSC1101DI2-025.0000

DSC1101DI5-020.0000

DSC1101DI5-026.0000

DSC1101DI5-072.0000

DSC1102DI1-156.2500

DSC400-0333Q0154KI2

DSC400-0111Q0155KI1

DSC400-0111Q0155KI2

DSC400-3133Q0156KI1

DSC400-3133Q0156KI2

DSC400-0133Q0157KI1

DSC400-0133Q0157KI2

DSC400-3113Q0158KI1

DSC400-3113Q0158KI2

DSC400-3113Q0159KI1

DSC400-3113Q0159KI2

DSC400-1111Q0160KI1

DSC400-1111Q0160KI2

DSC400-0333Q0162KI1

DSC400-0333Q0162KI2

DSC400-3333Q0163KI1

DSC400-3333Q0163KI2

DSA400-1111Q0004KI1VAO

DSA400-1111Q0004KI2VAO

DSA400-1111Q0085KI1VAO

DSA400-1111Q0085KI2VAO

DSA400-1111Q0161KI1VAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA400-1111Q0161KI2VAO  
DSA400-4134Q0152KI1VAO  
DSA400-4134Q0152KI2VAO  
DSA557-04444KI1VAO  
DSA557-054444KI1VAO  
DSC400-1111Q0001KE1  
DSC400-1111Q0084KE1  
DSC400-1111Q0084KE2  
DSC400-0101Q0083KE1  
DSC400-0101Q0083KE2  
DSC400-0414Q0033KE1  
DSC400-1111Q0025KE1  
DSC400-1444Q0052KE1  
DSC400-1444Q0060KE2  
DSC400-1444Q0060KI2  
DSC400-4134Q0028KE1  
DSC400-4134Q0050KE1  
DSC400-4244Q0023KE1  
DSC557-053344KL1T  
DSC400-4244Q0069KE1  
DSC557-053333KL1T  
DSC400-4244Q0071KE1  
DSC557-04444KL1  
DSC400-4411Q0072KE1  
DSC400-4411Q0072KE2  
DSC400-4444Q0015KE1  
DSC400-4444Q0015KE2  
DSC400-4444Q0022KE1  
DSC400-1444Q0060KE1  
DSC400-1444Q0060KI1  
DSC400-1111Q0073KE1  
DSC400-1111Q0073KE2  
DSC400-1133Q0079KE1  
DSC400-1133Q0079KE2  
DSC400-1111Q0001KE2  
DSC400-3333Q0078KE1  
DSC400-3333Q0078KE2  
DSC400-1111Q0081KE1  
DSC400-1111Q0081KE2  
DSC400-3133Q0080KE1  
DSC400-3133Q0080KE2  
DSC400-0101Q0082KE1  
DSC400-0101Q0082KE2  
DSC400-1311Q0076KE1  
DSC400-1311Q0076KE2  
DSC400-0303Q0086KE1  
DSC400-0303Q0086KE2  
DSC400-0111Q0087KE1  
DSC400-0111Q0087KE2

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-3111Q0088KE1  
DSC400-3111Q0088KE2  
DSC400-3333Q0089KE1  
DSC400-3333Q0089KE2  
DSC400-4444Q0023KE1  
DSC400-4444Q0023KE2  
DSC400-4444Q0059KE1  
DSC400-4444Q0059KE2  
DSC400-1111Q0090KE1  
DSC400-1111Q0090KE2  
DSC400-1111Q0091KE1  
DSC400-1111Q0091KE2  
DSC400-2222Q0022KE1  
DSC400-2222Q0022KE2  
DSC400-0303Q0092KE1  
DSC400-0303Q0092KE2  
DSC400-3333Q0093KE1  
DSC400-3333Q0093KE2  
DSC400-3333Q0094KE1  
DSC400-3333Q0094KE2  
DSC400-4334Q0022KE1  
DSC400-4334Q0022KE2  
DSC400-0444Q0009KE1  
DSC400-0444Q0009KE2  
DSC400-1111Q0095KE1  
DSC400-1111Q0095KE2  
DSC400-0101Q0096KE1  
DSC1101NI5-012.8000T  
DSC1101NI5-016.3840T  
DSC1104NI2-100.0000T  
DSC1122NI5-025.0020T  
DSC1122NI2-050.0000T  
DSC1103NI2-125.0000T  
DSC1121NI1-100.0000T  
DSC1121NI2-125.0000T  
DSC1121NI2-025.0000T  
DSC1101NI1-050.0000T  
DSC1102NI5-156.2500T  
DSC1123NI1-156.2500T  
DSC1122NI2-156.2500T  
DSC1103NI2-148.5000T  
DSC1103NI2-156.2500T  
DSC1101NI5-018.7500T  
DSC1122NI2-148.5000T  
DSC1123NI2-200.0000T  
DSC1123NI5-100.0000T  
DSC1123NI5-125.0000T  
DSC1123NI5-156.2500T  
DSC1123NI5-322.2656T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101NI2-050.0000T  
DSC1103NI1-135.0000T  
DSC1122NI5-025.0007T  
DSC1123NI3-050.0015T  
DSC1103NI5-150.0000T  
DSC1123NI2-100.0000T  
DSC1122NI5-200.0000T  
DSC1102NI5-400.0000T  
DSC1102NI5-200.0000T  
DSC1101NI2-025.0000T  
DSC1101NI2-018.7500T  
DSC1121DI2-024.0000T  
DSC1101DI2-025.0000T  
DSC1101DI5-072.0000T  
DSC1101DI5-020.0000T  
DSC1101DI5-026.0000T  
DSC1101DM2-025.0000T  
DSC1101DI5-050.0000T  
DSC1101DI5-060.0000T  
DSC1101DL5-025.0000T  
DSC1102DI1-156.2500T  
DSC1103DI2-125.0000T  
DSC1103DI2-312.5000T  
DSC1103DI2-200.0000T  
DSC1103DI5-171.8181T  
DSC1103DI2-400.0000T  
DSC1104DI1-100.0000T  
DSC1104DI1-156.2500T  
DSC1121DI1-036.0000T  
DSC1121DI1-125.0000T  
DSC1121DI5-034.3680T  
DSC1121DI2-025.0000T  
DSC400-3113Q0158KE1  
DSC400-3113Q0158KE2  
DSC400-3113Q0159KE1  
DSC400-3113Q0159KE2  
DSC400-1111Q0160KE1  
DSC400-1111Q0160KE2  
DSC400-0333Q0162KE1  
DSC400-0333Q0162KE2  
DSC400-3333Q0163KE1  
DSC400-3333Q0163KE2  
DSA400-1111Q0004KL1VAO  
DSA400-1111Q0004KL2VAO  
DSA400-1111Q0085KL1VAO  
DSA400-1111Q0085KL2VAO  
DSA400-1111Q0161KL1VAO  
DSA400-1111Q0161KL2VAO  
DSA400-4134Q0152KL1VAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA400-4134Q0152KL2VAO

DSA557-04443KL0VAO

DSA557-04444KL1VAO

DSA557-054444KL1VAO

DSC400-1111Q0001KE1T

DSC400-1111Q0084KE1T

DSC400-1111Q0084KE2T

DSC400-0101Q0083KE1T

DSC400-0101Q0083KE2T

DSC400-1111Q0025KE1T

DSC400-1444Q0060KE2T

DSC400-1444Q0060KI2T

DSC400-4244Q0069KE1T

DSC557-04444KL1T

DSC400-4411Q0072KE1T

DSC400-4411Q0072KE2T

DSC400-4444Q0015KE1T

DSC400-4444Q0015KE2T

DSC400-1444Q0060KE1T

DSC400-1444Q0060KI1T

DSC400-1111Q0073KE1T

DSC400-1111Q0073KE2T

DSC400-1133Q0079KE1T

DSC400-1133Q0079KE2T

DSC400-1111Q0001KE2T

DSC400-3333Q0078KE1T

DSC400-3333Q0078KE2T

DSC400-1111Q0081KE1T

DSC400-1111Q0081KE2T

DSC400-3133Q0080KE1T

DSC400-3133Q0080KE2T

DSC400-0101Q0082KE1T

DSC400-0101Q0082KE2T

DSC400-1311Q0076KE1T

DSC400-1311Q0076KE2T

DSC400-0303Q0086KE1T

DSC400-0303Q0086KE2T

DSC400-0111Q0087KE1T

DSC400-0111Q0087KE2T

DSC400-3111Q0088KE1T

DSC400-3111Q0088KE2T

DSC400-3333Q0089KE1T

DSC400-3333Q0089KE2T

DSC400-4444Q0023KE1T

DSC400-4444Q0023KE2T

DSC400-4444Q0059KE1T

DSC400-4444Q0059KE2T

DSC400-1111Q0090KE1T

DSC400-1111Q0090KE2T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-1111Q0091KE1T  
DSC400-1111Q0091KE2T  
DSC1001BI5-030.0000T  
DSC1001BI1-038.4000T  
DSC1001BI2-018.4320T  
DSC1001BI5-020.0000T  
DSC1001BI5-133.3330T  
DSC1001BI1-004.0000T  
DSC1001BI2-030.0000T  
DSC1001BI1-012.2880T  
DSC1001BI2-014.3181T  
DSC1001BI1-020.0000T  
DSC1001BI5-090.0000T  
DSC1004BI2-010.0000T  
DSC1001BI1-066.6666T  
DSC8001BI5T  
DSC1001BI2-133.3330T  
DSC1001BI1-016.0000T  
DSC8003BI2T  
DSC1001BI2-012.5000T  
DSC1001BI5-013.5600T  
DSC1001BI1-100.0000T  
DSC1001BI1-012.0000T  
DSC1001BI2-033.0000T  
DSC1001BI2-026.0000T  
DSC1001BI5-084.0000T  
DSC1001BI1-033.3330T  
DSC1001BI2-012.2888T  
DSC1101DI5-060.0000  
DSC1121DI1-025.0000  
DSC1103DI2-019.2000  
DSC1103DI2-125.0000  
DSC1103DI2-148.5000  
DSC1103DI2-200.0000  
DSC1103DI2-312.5000  
DSC1103DI2-400.0000  
DSC1103DI5-171.8181  
DSC1121DI1-036.0000  
DSC1104DI1-100.0000  
DSC1104DI1-156.2500  
DSC1121DI2-011.0590  
DSC1121DI2-022.5792  
DSC1121DI2-024.5760  
DSC1121DI2-027.0000  
DSC1121DI5-034.3680  
DSC1121DI5-044.0000  
DSC1121DI5-044.7360  
DSC1122DI2-100.0000  
DSC1122DI2-106.2500

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121DI2-125.0000  
DSC1121DI5-010.0000  
DSC1123DI2-050.0000  
DSC1123DI2-086.0000  
DSC1121DI2-025.0000  
DSC1123DI2-106.2500  
DSC1123DI2-125.0000  
DSC1123DI2-148.5000  
DSC1123DI2-156.2500  
DSC1123DI2-200.0000  
DSC6003JI1B-100K000T  
DSC6011JI1B-003.6864T  
DSC6021JI2B-01HMT  
DSC6101JI3B-038.4000T  
DSC6001JI1B-024.0000T  
DSC6332JI3AB-050.0000T  
DSC6332JI3FB-050.0000T  
DSC6001JI1B-040.0000T  
DSC6001JI2B-042.5000T  
DSC6021JI2B-01J5T  
DSC6013JI2B-004.0960T  
DSC6331JI1DB-075.0000T  
DSC6331JI1AB-025.0000T  
DSC6311JI1FB-075.0000T  
DSC6101JI2B-012.0000T  
DSC6001JI1B-008K000T  
DSC6001JI1B-008.0000T  
DSC6001JI2B-008.0000T  
DSC6011JI3B-020.0000T  
DSC6112JI2B-024.0000T  
DSC6311JI1BB-012.0000T  
DSC6101JI1B-080.0000T  
DSC6021JI2B-01KQT  
DSC6011JI1B-024.0000T  
DSC6121JI2B-01MHT  
DSC6111JI2B-100.0000T  
DSC6111JI2B-074.2500T  
DSC6111JI2B-027.0000T  
DSC6001JI1B-006.5536T  
DSC6331JI2AB-010.0000T  
DSC6331JI2AB-016.0000T  
DSC6331JI2AB-100.0000T  
DSC6331JI2CB-012.2880T  
DSC6001JI3B-259K200T  
DSC6102JI1B-080.0000T  
DSC6101JI2B-037.1250T  
DSC6001JI2B-001.0000T  
DSC6001JI2B-016.0000T  
DSC6003JI2B-250K000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA6001JI1B-052K768TVAO  
DSA6001JI1B-080.0000TVAO  
DSA6003JI1B-020.0000TVAO  
DSA6013JI1B-300K000TVAO  
DSA6101JI1B-050.0000TVAO  
DSA6111JI1B-008.0000TVAO  
DSA6331JI1CB-027.0000TVAO  
DSA6003JI2B-032K768TVAO  
DSA6101JI2B-012.2880TVAO  
DSA6101JI2B-018.4320TVAO  
DSA6101JI2B-032K768TVAO  
DSA6101JI2B-036.8640TVAO  
DSA6101JI2B-100.0000TVAO  
DSA6111JI2B-032K768TVAO  
DSA6331JI2FB-024.5760TVAO  
DSA6001JI3B-005.0000TVAO  
DSA6011JI3B-032K768TVAO  
DSA6023JI3B-01JGTVAO  
DSC612PI3A-010JT  
DSC612PI3A-010KT  
DSC612PI3A-010TT  
DSC613PI3A-0105T  
DSC612PI3A-010JB  
DSC612PI3A-010KB  
DSC612PI3A-010TB  
DSC613PI3A-0105B  
DSC612PI2A-012QT  
DSC613PI2A-0131T  
DSC612PI2A-0130T  
DSC612PI2A-013CT  
DSC612PI3A-013JT  
DSC612PI2A-015PT  
DSC612PI2A-0166T  
DSC612PI1A-016ST  
DSC612PI3A-0130T  
DSC613PI3A-0195T  
DSC613PI3A-01CRT  
DSC613PI3A-01D4T  
DSC613PI3A-01EYT  
DSC612PI2A-01GVT  
DSC612PI1A-01HTT  
DSC612PI3A-012YT  
DSC612PI2A-01M1T  
DSC612PI2A-01MDT  
DSC612PI2A-014JT  
DSC612PI2A-01JRT  
DSC612PI2A-012YT  
DSC613PI2A-01JST  
DSC613PI2A-01JTT

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC613PI2A-01JU1  
DSC613PI2A-01JVT  
DSC612PI2A-01KWT  
DSC612PI2A-01JQT  
DSA613PI3A-01G8TVAO  
DSC612RI3A-010GT  
DSC400-3333Q0023KI1  
DSC400-3333Q0023KI2  
DSC400-3333Q0146KI1  
DSC400-3333Q0146KI2  
DSC400-1111Q0147KI1  
DSC400-1111Q0147KI2  
DSC400-1111Q0078KI1  
DSC400-1111Q0078KI2  
DSC400-0323Q0009KI1  
DSC400-0323Q0009KI2  
DSC400-1111Q0148KI1  
DSC400-1111Q0148KI2  
DSC400-1313Q0094KI1  
DSC400-1313Q0094KI2  
DSC400-1111Q0149KI1  
DSC400-1111Q0149KI2  
DSC400-1333Q0078KI1  
DSC400-1333Q0078KI2  
DSC400-1111Q0150KI1  
DSC400-1111Q0150KI2  
DSC400-3333Q0151KI1  
DSC400-3333Q0151KI2  
DSC400-4144Q0152KI1  
DSC400-4144Q0152KI2  
DSC400-3331Q0153KI1  
DSC400-3331Q0153KI2  
DSC400-2222Q0031KI1  
DSC400-2222Q0031KI2  
DSC400-0333Q0154KI1  
DSC1001CI2-028.6363  
DSC1001CI1-016.0000  
DSC1001CI1-019.2000  
DSC1001CI1-024.0000  
DSC1001CI1-025.0000  
DSC1001CI1-026.0000  
DSC1001CI1-027.0000  
DSC1001CI1-020.0000  
DSC1001CI1-033.3333  
DSC1001CI1-047.3333  
DSC1001CI1-048.0000  
DSC1001CI1-050.0000  
DSC1001CI2-002.0480  
DSC1001CI2-004.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CI2-008.0000

DSC1001CI2-011.0592

DSC1001CI2-012.0000

DSC1001CI2-012.2880

DSC1001CI2-014.3181

DSC1001CI2-014.7456

DSC1001CI2-016.0000

DSC1001CI2-018.0000

DSC1001CI2-018.4320

DSC1001CI2-020.0000

DSC1001CI2-022.5792

DSC1001CI2-024.0000

DSC1001CI2-024.5760

DSC1001CI2-025.0000

DSC1001CI2-027.0000

DSC1001CI2-003.5795

DSC1001CI1-007.5000

DSC1001CI2-032.7680

DSC1001CI2-033.0000

DSC1001CI2-033.3300

DSC1001CI2-033.3333

DSC1001CI2-026.0000

DSC1001CI2-037.1250

DSC1001CI2-040.0000

DSC1001CI2-048.0000

DSC1001CI2-050.0000

DSC1001CI2-060.0000

DSC1001CI2-066.6666

DSC1001CI2-074.2500

DSC1001CI2-080.0000

DSC1001CI2-100.0000

DSC1001CI5-004.9152

DSC1001CI5-010.0000

DSC1001CI5-019.2000

DSC1001CI5-020.0000

DSC612PA1A-01H5T

DSA612PA2A-01DMTVAO

DSA612PA3A-0130TVAO

DSA612PA3A-01DQTVAO

DSC612RA3A-010ST

DSC613RA2A-0106T

DSC612RA3A-010SB

DSC613RA2A-0106B

DSC612RA3A-0138T

DSC612RA1A-0173T

DSC612RA1A-0174T

DSC612RA3A-0181T

DSC613RA3A-018BT

DSC612RA3A-01B2T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC612RA3A-014S1

DSC612RA1A-01H5T

DSC612RA1A-01JJT

DSC612RA3A-01JWT

DSC612RA1A-0102T

DSA612RA1A-01KGTVAO

DSA612RA2A-01GMTVAO

DSA613RA2A-01BGTVAO

DSC400-0331Q0026KI2

DSC400-1111Q0084KI1

DSC400-1111Q0084KI2

DSC400-0111Q0138KE1

DSC400-0111Q0138KE2

DSC400-0111Q0139KE1

DSC400-0111Q0139KE2

DSC400-0144Q0140KE1

DSC400-0144Q0140KE2

DSC400-1221Q0141KE1

DSC400-1221Q0141KE2

DSC400-0434Q0009KE1

DSC400-0434Q0009KE2

DSC400-0313Q0136KE1

DSC400-0313Q0136KE2

DSC400-1111Q0142KE1

DSC400-1111Q0142KE2

DSC400-1111Q0143KE1

DSC400-1111Q0143KE2

DSC400-0333Q0144KE1

DSC400-0333Q0144KE2

DSC400-3333Q0145KE1

DSC400-3333Q0145KE2

DSC400-3333Q0023KE1

DSC400-3333Q0023KE2

DSC400-3333Q0146KE1

DSC400-3333Q0146KE2

DSC400-1111Q0147KE1

DSC400-1111Q0147KE2

DSC400-1111Q0078KE1

DSC1103CL5-156.2500

DSC1103CL5-125.0000

DSC1103CE5-254.6500

DSC1124CE2-038.4000

DSC1104CL1-100.0000

DSC1103CL5-135.0000

DSC1103CL5-148.5000

DSC1103CL5-200.0000

DSC1103CE2-100.0000

DSC1123CL2-027.0000

DSC1103CE2-020.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103CL5-212.5000  
DSC1101CL3-033.3300  
DSC1103BE1-150.0000  
DSC1103BL2-125.0000  
DSC1103BL2-200.0000  
DSC1121BE2-100.0000  
DSC1121BE5-025.0000  
DSC1122BE1-133.3300  
DSC1122BE2-050.0000  
DSC1122BE2-150.0000  
DSC1123BE2-050.0000  
DSC1123BE5-156.2500  
DSC1123BL2-125.0000  
DSC1123BL5-156.2500  
DSC8101BL2  
DSC1103BL5-062.5000  
DSC8103BL5  
DSC1124BE2-100.0000  
DSC1104BE2-100.0000  
DSC1103BE5-156.2500  
DSC1121DI2-125.0000B  
DSC1121DI2-125.0000T  
DSC1121DI5-010.0000T  
DSC1123DI2-050.0000T  
DSC1122DI2-100.0000T  
DSC1122DI2-125.0000B  
DSC1123DI2-148.5000T  
DSC1122DI2-125.0000T  
DSC1123DI2-148.5000B  
DSC1123DI2-086.0000T  
DSC1123DI2-100.0000B  
DSC1123DI5-200.0000T  
DSC2311KI1-R0009T  
DSC1123DI2-200.0000T  
DSC2311KI2-R0005T  
DSC2311KI2-R0009T  
DSC2311KI2-R0001T  
DSC2311KI2-R0002T  
DSC2311KI2-R0041T  
DSC8123DI5T  
DSC1103DI5-125.0060T  
DSC2311KI2-R0043T  
DSC1101DI1-025.0000T  
DSC1123DI2-156.2500T  
DSC2311KI1-R0046T  
DSC1121DI1-026.6000T  
DSC1122DI2-200.0000T  
DSC2311KI1-R0051T  
DSC2311KI2-R0049T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103DI2-148.3500T  
DSC1103DI2-148.5000T  
DSC1121DI5-008.0000T  
DSC1123DI2-125.0000T  
DSC1123DI2-125.0000B  
DSC1123DI2-025.0000B  
DSC2311KI1-R0003T  
DSC2311KI2-R0003T  
DSC2311KI2-R0016T  
DSC2311KI2-R0045T  
DSC1123DI5-156.2500T  
DSC1123DI2-100.0000T  
DSC1121DI2-156.2500T  
DSC1101DI1-012.0000T  
DSC1101DI5-012.0000T  
DSC1101DI1-150.0000T  
DSC1103DI2-048.0000  
DSC1101DI5-030.2400  
DSC1124DI2-100.0000  
DSC2311KI1-R0053  
DSC1123DI2-315.0000  
DSC1123DI2-312.0000  
DSC1124DI2-315.0000  
DSC1123DI2-312.2000  
DSC1122DI2-050.0000  
DSC2311KI1-R0054  
DSC1103DI5-360.0000  
DSC2311KI2-R0055  
DSC1101DI1-125.0000  
DSC1123DI2-025.0000  
DSC2311KI2-R0056  
DSC1101DI5-013.5288  
DSC2311KI2-R0057  
DSC1101DI5-032.0000  
DSC1122DI2-156.2500  
DSC1124DI1-100.0000  
DSC2311KI2-R0058  
DSC1101DI2-049.1520  
DSC1101DI1-038.0000  
DSC1121DI5-100.0000  
DSC2311KI2-R0059  
DSC1103DI2-100.0000  
DSC1103DI2-108.0000  
DSC1121DI5-072.0000  
DSC1121DI5-050.0000  
DSC1121DI5-032.0000  
DSC1121DI1-100.0000  
DSC2311KI1-R0041  
DSC2311KI2-R0060



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1102DI5-135.0000  
DSC1123DI5-148.4258  
DSC1123DI2-148.4258  
DSC2311KI1-R0059  
DSC1101DI3-025.0000  
DSC1103DI2-135.0000  
DSC1121DI2-010.0000  
DSC1101DI1-100.0000  
DSC2311KI2-R0008  
DSC1102DI2-125.0000  
DSC1124DI1-027.0000  
DSC2311KI2-R0061  
DSC2311KI2-R0062  
DSC2311KI2-R0063  
DSC1101DI5-024.0000  
DSC1101DI5-100.0000  
DSC1101DI5-045.1584  
DSC1101DI5-049.1520  
DSC1101DI5-018.4320  
DSC1121DI3-050.0000  
DSC2311KI2-R0065  
DSC1124DI2-027.0000  
DSC1102DI2-156.2500  
DSC1103DI5-074.2500  
DSC1103DI5-200.0000  
DSC1103DI5-100.0000  
DSC2311KI2-R0066  
DSC1101DI3-012.0000  
DSC1123DI1-125.0000  
DSC2311KI2-R0067  
DSC1101DI2-060.0000  
DSC2311KI2-R0068  
DSC1124DI3-100.0000  
DSC2311KI1-R0069  
DSC2311KI2-R0070  
DSC1122DI5-272.8000  
DSC1121DI2-100.0000  
DSC1124DI3-027.0000  
DSC1123DI5-010.0000  
DSC1103DI5-300.0000  
DSC1101DI5-025.0000  
DSC1123DI2-072.0000  
DSC1101DI5-036.0000  
DSC1101DI1-036.0000  
DSC1123DI2-010.0000  
DSC1103DI5-160.0000  
DSC1101DI2-012.0000  
DSC1101DI5-125.0000  
DSC2311KI2-R0074

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123DI2-148.3516

DSC2311KI2-R0073

DSC2311KI2-R0021

DSC2311KI2-R0023

DSC2311KI2-R0079

DSC1104DI2-100.0000

DSC1102DI1-212.5000

DSC1102DI2-212.5000

DSC2311KI2-R0012

DSC1123DI1-100.0000

DSC1104DI5-100.0000

DSC1124DI5-100.0000

DSC2311KI2-R0082

DSC1121DI1-048.0000

DSC1122DI2-121.1090

DSC1101DI1-033.3330

DSC2311KI1-R0083

DSC1103DI2-250.0000

DSC2311KI1-R0070

DSC2311KI1-R0052

DSC1121DI5-125.0000

DSC2311KI2-R0085

DSC2311KI2-R0086

DSC2311KI1-R0078

DSC2311KI1-R0073

DSC1123DI2-160.0000

DSC2311KI2-R0088

DSC2311KI1-R0016

DSC1123DI5-125.0060

DSC1123DI1-322.2656

DSC2311KI1-R0040

DSC1103DI1-156.2500

DSC1103DI2-156.2500

DSC1103DI1-080.0000

DSA2311KI1-R0003VAO

DSA1101DI1-004.0000VAO

DSA1101DI1-050.0000VAO

DSA1121DI3-033.3333VAO

DSA2311KI2-R0064VAO

DSA2311KI2-R0065VAO

DSA2311KI2-R0077VAO

DSA2311KI3-R0067VAO

DSA2311KI1-R0016VAO

DSA2311KI1-R0041VAO

DSA2311KI2-R0015VAO

DSC2010FI2-A0001

DSC2010FI2-A0003

DSC557-0333FI0

DSC6331JI2EB-012.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6011JI2B-024.0000  
DSC6003JI2B-050.0000  
DSC6311JI2EB-018.4320  
DSC6301JI2GB-024.0000  
DSC6311JI1AB-025.0000  
DSC6011JI2B-018.0000  
DSC6101JI1B-048.0000  
DSC6013JI2B-050.0000  
DSC6001JI1B-027.0000  
DSC6331JI3CB-018.4320  
DSC6331JI1CB-018.4320  
DSC6111JI1B-028.1250  
DSC6021JI2B-01G3  
DSC6112JI2B-028.1250  
DSC6001JI1B-020.0000  
DSC6111JI1B-008.0000  
DSC6331JI2FB-024.5760  
DSC6051JI2B-014.3180  
DSC6011JI1B-006.5536  
DSC6011JI3B-012.0000  
DSC6051JI3B-032K768  
DSC6001JI3B-032K768  
DSA1001DL2-100.0000TVAO  
DSA1001DL2-125.0000TVAO  
DSA1004DL2-072.0000TVAO  
DSA1001DL3-004.0000TVAO  
DSA1001DL3-006.0053TVAO  
DSA1001DL3-008.0000TVAO  
DSA1001DL3-012.2888TVAO  
DSA1001DL3-012.5000TVAO  
DSA1001DL3-016.0000TVAO  
DSA1001DL3-016.3840TVAO  
DSA1001DL3-020.0000TVAO  
DSA1001DL3-022.5792TVAO  
DSA1001DL3-024.0000TVAO  
DSA1001DL3-025.0000TVAO  
DSA1001DL3-026.0000TVAO  
DSA1001DL3-027.0000TVAO  
DSA1001DL3-032.7680TVAO  
DSA1001DL3-033.0000TVAO  
DSA1001DL3-033.3330TVAO  
DSA1001DL3-045.0000TVAO  
DSA1001DL3-048.0000TVAO  
DSA1001DL3-054.0000TVAO  
DSA1001DL3-055.4666TVAO  
DSA1001DL3-060.0000TVAO  
DSC2031FL2-F0052T  
DSC2210FL2-A0026T  
DSC2041FL1-F0014T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC201TFE1-F00571

DSA557-0333FL0TVAO

DSA557-0344FL0TVAO

DSA557-0344FL1TVAO

DSC1101CI2-025.0000T

DSC1101CI2-050.0000T

DSC1101CI2-100.0000T

DSC1101CI5-020.0000T

DSC1102CI1-125.0000T

DSC1101CI5-010.0000T

DSC1103CI1-156.2500T

DSC1103CI1-200.0000T

DSC1102CI5-200.0000T

DSC1103CI2-125.0000T

DSC1103CI2-100.0000T

DSC1103CI2-200.0000T

DSC1103CI5-025.0000T

DSC1103CI5-050.0000T

DSC1103CI5-100.0000T

DSC1103CI5-106.2500T

DSC1103CI5-148.5000T

DSC1121CI2-014.7456T

DSC1103CI5-200.0000T

DSC1121CI1-024.0000T

DSC1103CI5-233.3333T

DSC1121CI1-125.0000T

DSC1121CI2-010.0000T

DSC1121CI2-012.2880T

DSC1121CI2-013.0000T

DSC1103CI5-300.0000T

DSC1121CI2-024.0000T

DSC1121CI2-025.0000T

DSC1121CI1-025.0000T

DSC1121CI2-048.0000T

DSC1121CI2-050.0000T

DSC1121CI2-060.0000T

DSC1121CI2-066.6660T

DSC1121CI2-100.0000T

DSC1121CI2-125.0000T

DSC1121CI2-133.3330T

DSC1121CI2-148.5000T

DSC1121CI5-040.0000T

DSC1121CI5-049.1520T

DSC1122CI1-156.2500T

DSC1122CI2-062.5000T

DSC1122CI2-100.0000T

DSC1122CI2-125.0000T

DSC1122CI2-133.3300T

DSC1122CI2-150.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1122CI2-156.2500T  
DSC1122CI2-050.0000T  
DSC1123CI1-100.0000T  
DSC1123CI1-125.0000T  
DSC1123CI1-150.0000T  
DSC1123CI1-200.0000T  
DSC1123CI2-100.0000T  
DSC1123CI2-125.0000T  
DSC1123CI2-148.5000T  
DSC1123CI2-150.0000T  
DSC1123CI2-156.2500T  
DSC1121CI2-024.5760T  
DSC1121CI2-020.0000T  
DSC1122CI2-103.1250T  
DSC1124CI5-156.2500T  
DSC1101CI5-025.0000T  
DSC1103CI5-224.8200T  
DSC1123CI2-333.3300T  
DSC8122CI2T  
DSC1123CI1-022.8800T  
DSC1123CI5-156.2500T  
DSC1123CI2-212.5000T  
DSC1001CI2-024.5760T  
DSC1001CI2-025.0000T  
DSC1001CI2-026.0000T  
DSC1001CI2-027.0000T  
DSC1001CI2-027.6000T  
DSC1001CI2-028.6363T  
DSC1001CI2-080.0000T  
DSC1001CI2-032.7680T  
DSC1001CI2-033.0000T  
DSC1001CI2-033.3300T  
DSC1001CI2-033.3333T  
DSC1001CI2-034.3000T  
DSC1001CI2-036.0000T  
DSC1001CI5-032.7680T  
DSC1001CI2-037.1250T  
DSC1001CI2-040.0000T  
DSC1001CI2-048.0000T  
DSC1001CI2-050.0000T  
DSC1001CI2-054.0000T  
DSC1001CI2-060.0000T  
DSC1001CI2-066.6660T  
DSC1001CI2-066.6666T  
DSC1001CI2-074.2500T  
DSC1003CI1-050.0000T  
DSC1001CI2-100.0000T  
DSC1001CI2-125.0000T  
DSC1001CI4-002.0480T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CI4-049.1520T  
DSC1001CI4-054.0000T  
DSC1001CI5-004.0000T  
DSC1001CI5-004.9152T  
DSC1001CI5-008.0000T  
DSC1001CI5-010.0000T  
DSC1001CI5-012.0000T  
DSC1001CI5-012.2880T  
DSC1001CI5-016.0000T  
DSC1001CI5-018.4320T  
DSC1001CI5-019.2000T  
DSC1001CI5-020.0000T  
DSC1001CI5-024.0000T  
DSC1001CI5-024.5760T  
DSC1001CI5-025.0000T  
DSC1001CI5-026.0000T  
DSC1001CI5-027.0000T  
DSC1001CI5-030.0000T  
DSC1001CI1-003.6864T  
DSC1001CI2-012.5000T  
DSC1001CI5-009.6000T  
DSC1001CI1-100.0000T  
DSC1001CI2-020.0000T  
DSC1001CI2-006.0000T  
DSC1001CI5-040.0000T  
DSC1001CI5-044.0000T  
DSC1001CI5-019.0000T  
DSC1001CI5-060.0000T  
DSC1001CI1-033.0000T  
DSC1001CI1-048.0000T  
DSC1001CI5-011.0592T  
DSC1001CI2-031.2500T  
DSC1001CI2-049.1520T  
DSC1001CI2-032.0000T  
DSC1001CI2-096.0000T  
DSC1001CI2-100.0000B  
DSC1001CI5-133.3330T  
DSC1001CI5-070.4550T  
DSC1001CI2-008.1920T  
DSC1001CI2-010.4857T  
DSC8001CI5T  
DSC1001CI1-011.0592T  
DSC1001CI2-001.9521T  
DSC8003CI2T  
DSC1001CI2-019.4400T  
DSC1001CI2-026.000T  
DSC1001CI2-133.0000T  
DSC1001CI5-016.3840T  
DSC1001CI5-033.3333T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CI5-032.0000T  
DSC1001CI5-033.0000T  
DSC1001CI5-033.3330T  
DSC1001CI2-030.0000T  
DSC1001CI5-048.0000T  
DSC1001CI5-050.0000T  
DSC1001CI5-064.0000T  
DSC1001CI5-100.0000T  
DSC1001CI5-125.0000T  
DSC1001CI5-150.0000T  
DSC1004CI2-027.0000T  
DSC1004CI2-033.0000T  
DSC1004CI2-054.0000T  
DSC1001CI5-080.0000T  
DSC1004CI5-050.0000T  
DSC1004CI5-125.0000T  
DSC8001CI2T  
DSC1001CI1-060.0000T  
DSC1001CI2-007.3728T  
DSC1001CI2-044.2360T  
DSC1003CI5-025.0000T  
DSC1001CI1-033.3330T  
DSC1001CI2-066.6666B  
DSC1004CI5-016.0000T  
DSC1001CI2-072.0000T  
DSC1001CI2-028.3220T  
DSC1001CI2-108.0000T  
DSC1001CI2-043.0000T  
DSC1001CI1-012.0000T  
DSC1001CI2-019.2000T  
DSC1001CI2-038.4000T  
DSC1001CI2-052.0000T  
DSC1001CI2-025.0000B  
DSC1003CI2-025.0000T  
DSC1003CI2-050.0000T  
DSC1001CI2-001.9512T  
DSC1001CI2-033.3330T  
DSC1001CI5-024.3050T  
DSC1001CI5-033.3300T  
DSC1001CI5-014.3181T  
DSC1001CI5-026.8000T  
DSC1001CI2-026.8000T  
DSC1001CI2-010.4858T  
DSC1004CI2-098.3040T  
DSC1001CI1-031.9488T  
DSC1003CI5-099.7200T  
DSC1001CI1-004.0000T  
DSC2010FI2-A0024  
DSC2010FI2-B0004

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2010FI2-B0005

DSC2010FI2-B0009

DSC2011FI1-F0017

DSC2011FI2-E0001

DSC2011FI2-E0005

DSC2011FI2-F0016

DSC2011FI2-F0017

DSC2011FI2-F0021

DSC2020FI2-B0012

DSC2022FI2-F0001

DSC2030FI2-C0001

DSC2030FI2-C0004

DSC2030FI2-C0006

DSC2010FI2-A0017

DSC2030FI2-C0012

DSC2030FI5-C0001

DSC2031FI2-J0001

DSC2033FI1-G0002

DSC2033FI2-G0001

DSC2033FI2-G0002

DSC2033FI2-G0004

DSC2033FI2-G0006

DSC2033FI2-G0007

DSC2044FI1-H0006

DSC2042FI2-M0005

DSC2044FI2-F0012

DSC2044FI2-H0001

DSC1001CL2-006.0052T

DSC1001CL1-040.0000T

DSC1003CL1-020.0000T

DSC1001CL1-006.0053T

DSC1001CL3-025.0000T

DSC1001CL2-006.0053T

DSC1001CE2-033.3333T

DSC1001CL3-040.0000T

DSC1004CL2-030.0000T

DSA1001CL2-033.3300TVAO

DSA1001CL2-033.3333TVAO

DSA1001CL2-125.0000TVAO

DSA1001CL3-080.0000TVAO

DSA1001CL3-133.3330TVAO

DSC1001BE1-016.0000T

DSC1001BE1-024.0000T

DSC1001BE1-025.0000T

DSC1001BE1-048.0000T

DSC1001BE1-050.0000T

DSC1001BE1-125.0000T

DSC1001BE1-133.3300T

DSC1001BE2-012.0000T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC100TBE2-125.0000T  
DSC1001BL1-027.0000T  
DSC1001BL1-048.0000T  
DSC1001BL2-027.0000T  
DSC1001BL2-050.0000T  
DSC1001BL5-008.0000T  
DSC400-1111Q0110KE1  
DSC400-1111Q0110KE2  
DSC400-1111Q0111KE1  
DSC400-1111Q0111KE2  
DSC400-4111Q0112KE1  
DSC400-4111Q0112KE2  
DSC400-4334Q0023KE1  
DSC400-4334Q0023KE2  
DSC400-1133Q0113KE1  
DSC400-1133Q0113KE2  
DSC400-0101Q0114KE1  
DSC400-0101Q0114KE2  
DSC400-0101Q0115KE1  
DSC400-0101Q0115KE2  
DSC400-0111Q0116KE1  
DSC400-0111Q0116KE2  
DSC400-0111Q0117KE1  
DSC400-0111Q0117KE2  
DSC400-2222Q0118KE1  
DSC400-2222Q0118KE2  
DSC400-0244Q0009KE1  
DSC400-0244Q0009KE2  
DSC400-0101Q0119KE1  
DSC400-0101Q0119KE2  
DSC400-1111Q0120KE1  
DSC400-1111Q0120KE2  
DSC400-0111Q0026KE1  
DSC400-0111Q0026KE2  
DSC400-1111Q0121KE1  
DSC400-1111Q0121KE2  
DSC400-1114Q0122KE1  
DSC400-1114Q0122KE2  
DSC400-0321Q0123KE1  
DSC400-0321Q0123KE2  
DSC400-3333Q0124KE1  
DSC400-3333Q0124KE2  
DSC400-1331Q0125KE1  
DSC400-1331Q0125KE2  
DSC400-1333Q0126KE1  
DSC400-1333Q0126KE2  
DSC400-0223Q0127KE1  
DSC400-0223Q0127KE2  
DSC400-0133Q0128KE1

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-0133Q0128KE2  
DSC400-0331Q0128KE1  
DSC400-0331Q0128KE2  
DSC400-0101Q0129KE1  
DSC400-0101Q0129KE2  
DSC400-3333Q0130KE1  
DSC400-3333Q0130KE2  
DSC400-3111Q0131KE1  
DSC400-3111Q0131KE2  
DSC400-4111Q0131KE1  
DSC400-4111Q0131KE2  
DSC400-1111Q0132KE1  
DSC400-1111Q0132KE2  
DSC400-0311Q0026KE1  
DSC400-0311Q0026KE2  
DSC400-0211Q0026KE1  
DSC400-0211Q0026KE2  
DSC400-1111Q0133KE1  
DSC400-1111Q0133KE2  
DSC400-1121Q0134KE1  
DSC400-1121Q0134KE2  
DSC400-1411Q0135KE1  
DSC400-1411Q0135KE2  
DSC400-0212Q0136KE1  
DSC400-0212Q0136KE2  
DSC400-1111Q0137KE1  
DSC400-1111Q0137KE2  
DSC1123CI5-100.0000T  
DSC1123CI2-020.0000T  
DSC1123CI1-027.0000T  
DSC1123CI2-333.3333T  
DSC1123CI2-312.5000T  
DSC1101CI1-025.0000T  
DSC1103CI1-125.0000T  
DSC1124CI5-156.2578T  
DSC1103CI2-148.3500T  
DSC1103CI2-148.5000T  
DSC1123CI1-156.2500T  
DSC1123CI2-300.0000T  
DSC1123CI2-200.0000T  
DSC1123CI5-125.0000T  
DSC1123CI5-032.0000T  
DSC1123CI5-040.0000T  
DSC1124CI1-156.2500T  
DSC1124CI2-100.0000T  
DSC1124CI5-156.2422T  
DSC1124CI2-200.0000T  
DSC1124CI5-100.0000T  
DSC1123CI2-062.5000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103CI5-233.2090T  
DSC1123CI2-025.0000T  
DSC8121CI2T  
DSC8123CI2T  
DSC1121CI2-030.0000T  
DSC1121CI2-051.8400T  
DSC1122CI1-156.2500TA  
DSC1124CI1-156.2500TA  
DSC1121CI1-050.0000T  
DSC1121CI5-016.6667T  
DSC1121CI5-025.0000T  
DSC1121CI5-027.0000T  
DSC1121CI5-066.0000T  
DSC1121CI5-117.0000T  
DSC1103CI1-122.8800T  
DSC1121CI2-027.0000T  
DSC1101CI1-125.0000T  
DSC1102CI5-150.0000T  
DSC1123CI1-122.8800T  
DSC1121CI5-016.0000T  
DSC1121CI2-012.0000T  
DSC1104CI5-125.0000T  
DSC1121CI2-066.6667T  
DSC1124CI2-156.2500T  
DSC1102CI1-050.0000T  
DSC1102CI1-156.2500T  
DSC1102CI1-025.0000T  
DSC400-3333Q0093KI2  
DSC400-3333Q0094KI1  
DSC400-3333Q0094KI2  
DSC400-4334Q0022KI1  
DSC400-4334Q0022KI2  
DSC400-0444Q0009KI1  
DSC400-0444Q0009KI2  
DSC400-1111Q0095KI1  
DSC400-1111Q0095KI2  
DSC400-0101Q0096KI1  
DSC400-0101Q0096KI2  
DSC400-3331Q0097KI1  
DSC400-3331Q0097KI2  
DSC400-3331Q0098KI1  
DSC400-3331Q0098KI2  
DSC400-3333Q0099KI1  
DSC400-3333Q0099KI2  
DSC400-3133Q0100KI1  
DSC400-3133Q0100KI2  
DSC400-0103Q0102KI1  
DSC400-0103Q0102KI2  
DSC400-0401Q0103KI1

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-0401Q0103KI2  
DSC400-2222Q0104KI1  
DSC400-2222Q0104KI2  
DSC400-2222Q0105KI1  
DSC400-2222Q0105KI2  
DSC400-3333Q0104KI1  
DSC400-3333Q0104KI2  
DSC400-0202Q0106KI1  
DSC400-0202Q0106KI2  
DSC400-0202Q0107KI1  
DSC400-0202Q0107KI2  
DSC400-0202Q0108KI1  
DSC400-0202Q0108KI2  
DSC400-0202Q0109KI1  
DSC400-0202Q0109KI2  
DSC400-1111Q0110KI1  
DSC400-1111Q0110KI2  
DSC400-1111Q0111KI1  
DSC400-1111Q0111KI2  
DSC400-4111Q0112KI1  
DSC400-4111Q0112KI2  
DSC400-4334Q0023KI1  
DSC400-4334Q0023KI2  
DSC400-1133Q0113KI1  
DSC400-1133Q0113KI2  
DSC400-0101Q0114KI1  
DSC400-0101Q0114KI2  
DSC400-0101Q0115KI1  
DSC400-0101Q0115KI2  
DSC400-0111Q0116KI1  
DSC400-0111Q0116KI2  
DSC400-0111Q0117KI1  
DSC400-0111Q0117KI2  
DSC400-2222Q0118KI1  
DSC400-2222Q0118KI2  
DSC400-0244Q0009KI1  
DSC400-0244Q0009KI2  
DSC400-0101Q0119KI1  
DSC400-0101Q0119KI2  
DSC400-1111Q0120KI1  
DSC400-1111Q0120KI2  
DSC400-0111Q0026KI1  
DSC400-0111Q0026KI2  
DSC400-1111Q0121KI1  
DSC400-1111Q0121KI2  
DSC400-1114Q0122KI1  
DSC400-1114Q0122KI2  
DSC400-0321Q0123KI1  
DSC400-0321Q0123KI2

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-3333Q0124KI1  
DSC400-3333Q0124KI2  
DSC400-1331Q0125KI1  
DSC400-1331Q0125KI2  
DSC400-1333Q0126KI1  
DSC400-1333Q0126KI2  
DSC400-0223Q0127KI1  
DSC400-0223Q0127KI2  
DSC400-0133Q0128KI1  
DSC400-0133Q0128KI2  
DSC400-0331Q0128KI1  
DSC400-0331Q0128KI2  
DSC400-0101Q0129KI1  
DSC400-0101Q0129KI2  
DSC400-3333Q0130KI1  
DSC400-3333Q0130KI2  
DSC400-3111Q0131KI1  
DSC400-3111Q0131KI2  
DSC400-4111Q0131KI1  
DSC400-4111Q0131KI2  
DSC400-1111Q0132KI1  
DSC400-1111Q0132KI2  
DSC400-0311Q0026KI1  
DSC400-0311Q0026KI2  
DSC400-0211Q0026KI1  
DSC400-0211Q0026KI2  
DSC400-1111Q0133KI1  
DSC400-1111Q0133KI2  
DSC400-1121Q0134KI1  
DSC400-1121Q0134KI2  
DSC400-1411Q0135KI1  
DSC400-1411Q0135KI2  
DSC400-0212Q0136KI1  
DSC400-0212Q0136KI2  
DSC400-1111Q0137KI1  
DSC400-1111Q0137KI2  
DSC400-0111Q0138KI1  
DSC400-0111Q0138KI2  
DSC400-0111Q0139KI1  
DSC400-0111Q0139KI2  
DSC400-0144Q0140KI1  
DSC400-0144Q0140KI2  
DSC400-1221Q0141KI1  
DSC400-1221Q0141KI2  
DSC400-0434Q0009KI1  
DSC400-0434Q0009KI2  
DSC400-0313Q0136KI1  
DSC400-0313Q0136KI2  
DSC400-1111Q0142KI1

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-1111Q0142KI2  
DSC400-1111Q0143KI1  
DSC400-1111Q0143KI2  
DSC400-0333Q0144KI1  
DSC400-0333Q0144KI2  
DSC400-3333Q0145KI1  
DSC400-3333Q0145KI2  
DSC1121CI5-024.0000T  
DSC1123CI1-025.0000T  
DSC1101CI2-060.0000T  
DSC1103CI2-072.0000T  
DSC1101CI2-036.0000T  
DSC1123CI2-360.0000T  
DSC1123CI2-010.0000T  
DSC1103CI3-060.0000T  
DSC1103CI3-150.0000T  
DSC1103CI3-175.0000T  
DSC1103CI1-150.0000T  
DSC1103CI2-066.0000T  
DSC1102CI5-020.0000T  
DSC1101CI5-016.0000T  
DSC1101CI5-008.0000T  
DSC1121CI2-066.0000T  
DSC1124CI2-133.3300T  
DSC1103CI2-133.3300T  
DSC1102CI1-212.5000T  
DSC1103CI1-300.0000T  
DSC1104CI2-200.0000T  
DSC1101CI5-157.2864T  
DSC1101CI1-024.0000T  
DSC1124CI2-125.0000T  
DSC1123CI5-066.6670T  
DSC1123CI2-148.3516T  
DSC1101CI5-040.0000T  
DSC1121CI2-156.0063T  
DSC1103CI3-135.0000T  
DSC1121CI2-045.0000T  
DSC1121CI2-055.0000T  
DSC1123CI3-100.0000T  
DSC1123CI3-135.0000T  
DSC1123CI3-165.0000T  
DSC1123CI3-200.0000T  
DSC1121CM1-027.0000T  
DSC1101BI5-050.0000T  
DSC1104BI5-100.0000T  
DSC1121BI2-013.0000T  
DSC1121BI2-025.0000T  
DSC1121BI2-050.0000T  
DSC1121BI2-120.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121BI2-125.0057T  
DSC1121BI2-150.0000T  
DSC1123BI1-200.0000T  
DSC1122BI2-074.2500T  
DSC1122BI2-075.0000T  
DSC1123BI2-025.0000T  
DSC1122BI2-133.3300T  
DSC1122BI2-148.5000T  
DSC1122BI2-150.0000T  
DSC1123BI1-150.0000T  
DSC1123BI5-100.0000T  
DSC1123BI2-100.0000T  
DSC1123BI5-155.5200T  
DSC1123BI5-156.2500T  
DSC1123BI2-156.2500T  
DSC1123BI2-200.0000T  
DSC1123BI2-212.5000T  
DSC1123BI5-200.0000T  
DSC1123BI5-148.3516T  
DSC1124BI1-100.0000T  
DSC1124BI2-100.0000T  
DSC1124BI2-125.0000T  
DSC1124BI2-156.2500T  
DSC8102BI2T  
DSC8123BI2T  
DSC8103BI2T  
DSC1122BI2-156.2500T  
DSC1121BI2-080.0000T  
DSC1122BI2-100.0000T  
DSC1122BI2-114.2850T  
DSC1122BI2-155.5200T  
DSC1102BI1-100.0000T  
DSC1122BI1-100.0000T  
DSC1121BI2-012.2880T  
DSC1101BI5-133.0000T  
DSC1123BI2-125.0000T  
DSC1123BI2-148.5000T  
DSC1102BI2-125.0000T  
DSC1102BI2-153.6000T  
DSC1103BI2-125.0000T  
DSC1121BI2-025.0007T  
DSC1121BI2-156.2540T  
DSC1123BI1-156.2500T  
DSC1102BI2-100.0000T  
DSC1122BI5-400.0000T  
DSC1104BI2-100.0000T  
DSC1123BI1-125.0000T  
DSC1121BI2-048.0000T  
DSC1123BI1-100.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121BI2-100.0000T  
DSC1121BI2-125.0000T  
DSC8123BI5T  
DSC1122BI2-156.2539T  
DSC1124BI5-100.0000T  
DSC1103BI2-100.0000T  
DSC6001JI2B-012.0000  
DSC6011JI2B-008.0000  
DSC6121JI3B-01GP  
DSC6311JI2CB-025.0000  
DSC6111JI3B-019.2000  
DSC6331JI1BB-018.4320  
DSC6001JI2B-007.3730  
DSC6301JI1B-050.0000  
DSC6102JI1B-500K000  
DSC6101JI1B-019.2000  
DSC6021JI1B-01H4  
DSC6331JI1BB-024.0000  
DSC6001JI3B-005K280  
DSC6001JI3B-004K280  
DSC6021JI1B-01HA  
DSC6003JI1B-100K000  
DSC6011JI1B-003.6864  
DSC6021JI2B-01HM  
DSC6112JI2B-024.0000  
DSC6101JI3B-038.4000  
DSC6001JI1B-024.0000  
DSC6332JI3AB-050.0000  
DSC6332JI3FB-050.0000  
DSC6001JI1B-040.0000  
DSC6001JI2B-042.5000  
DSC6021JI2B-01J5  
DSC6013JI2B-004.0960  
DSC6331JI1DB-075.0000  
DSC6331JI1AB-025.0000  
DSC6311JI1FB-075.0000  
DSC6101JI2B-012.0000  
DSC6001JI1B-008K000  
DSC6001JI1B-008.0000  
DSC6001JI2B-008.0000  
DSC6011JI3B-020.0000  
DSC6311JI1BB-012.0000  
DSC6101JI1B-080.0000  
DSC6021JI2B-01KQ  
DSC6011JI1B-024.0000  
DSC6121JI2B-01MH  
DSC6111JI2B-100.0000  
DSC6111JI2B-074.2500  
DSC6111JI2B-027.0000



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6001JI1B-006.5536  
DSC6331JI2AB-010.0000  
DSC6331JI2AB-016.0000  
DSC6331JI2AB-100.0000  
DSC6331JI2CB-012.2880  
DSC6001JI3B-259K200  
DSC6102JI1B-080.0000  
DSC6101JI2B-037.1250  
DSC6001JI2B-001.0000  
DSC6001JI2B-016.0000  
DSC6003JI2B-250K000  
DSA6001JI1B-032K768VAO  
DSA6001JI1B-080.0000VAO  
DSA6003JI1B-020.0000VAO  
DSA6013JI1B-300K000VAO  
DSA6101JI1B-050.0000VAO  
DSA6111JI1B-008.0000VAO  
DSA6331JI1CB-027.0000VAO  
DSA6003JI2B-032K768VAO  
DSA6101JI2B-012.2880VAO  
DSA6101JI2B-018.4320VAO  
DSA6101JI2B-032K768VAO  
DSA6101JI2B-036.8640VAO  
DSA6101JI2B-100.0000VAO  
DSA6111JI2B-032K768VAO  
DSA6331JI2FB-024.5760VAO  
DSA6001JI3B-005.0000VAO  
DSA6011JI3B-032K768VAO  
DSA6023JI3B-01JGVAO  
DSC612PI3A-010J  
DSC612PI3A-010K  
DSC612PI3A-010T  
DSC613PI3A-0105  
DSC612PI2A-012Q  
DSC613PI2A-0131  
DSC612PI2A-0130  
DSC612PI2A-013C  
DSC612PI3A-013J  
DSC612PI2A-015P  
DSC612PI2A-0166  
DSC612PI1A-016S  
DSC612PI3A-0130  
DSC613PI3A-0195  
DSC613PI3A-01CR  
DSC613PI3A-01D4  
DSC613PI3A-01EY  
DSC612PI2A-01GV  
DSC612PI1A-01HT  
DSC612PI3A-012Y

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC612PI2A-01MI  
DSC612PI2A-01MD  
DSC612PI2A-014J  
DSC612PI2A-01JR  
DSC612PI2A-012Y  
DSC613PI2A-01JS  
DSC613PI2A-01JT  
DSC613PI2A-01JU  
DSC613PI2A-01JV  
DSC612PI2A-01KW  
DSC1001BL1-060.0000  
DSC1001BE2-012.2880  
DSC1001BE2-014.7450  
DSC1001BE1-001.8432  
DSC1001BE1-026.0000  
DSC1001BE2-048.0000  
DSC1001BE1-014.3182  
DSC1001BE1-014.7456  
DSC1001BE2-014.7456  
DSC1001BE1-133.0000  
DSC1001BL5-001.1385  
DSC1001BL5-001.1386  
DSC1001BL5-001.1387  
DSC1001BL5-001.1388  
DSC1001BL5-001.1389  
DSC1001BL5-108.0000  
DSC1001BE5-020.0000  
DSC1001BL5-033.3330  
DSC1001BL5-026.7000  
DSC1001BL5-026.6500  
DSC1001BE5-016.0000  
DSC1001BL2-048.0000  
DSC1001BL2-026.0000  
DSC1003BE1-025.0000  
DSC1001BL5-026.0000  
DSC1001BL5-120.0000  
DSC1001BL5-014.7456  
DSC1001BL5-033.0000  
DSC1001BE2-090.0000  
DSC1001BL2-024.0000  
DSC1001BL5-125.0000  
DSC1001BE5-024.0000  
DSC1001BL5-030.0000  
DSC1001BE1-066.6666  
DSC1001BL5-049.5000  
DSC1001BE1-001.4850  
DSC1003BL1-010.0000  
DSC1001BL5-072.0000  
DSC1001BL5-066.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1000BL5-PROG

DSC1000BL5-PROG

DSC1001BE5-033.3330

DSC1001BL5-075.0000

DSC1001BL5-004.0000

DSC1003BE1-024.0000

DSC1001BE5-012.0000

DSC1001BE3-026.0000

DSC1001BL5-058.9824

DSC1001BE1-060.0000

DSC1003BL3-030.0000

DSC1003BL3-008.1920

DSC1001BE3-022.1184

DSC1003BL3-020.0000

DSC1003BL3-032.7680

DSC1003BL3-013.8420

DSC1003BL3-025.0000

DSC1003BL3-010.2400

DSC1003BL3-018.4320

DSC1001BL5-032.0000

DSC1001BE5-030.6400

DSC1001BL5-106.2500

DSC1001BL2-125.0000

DSC1004BL2-025.0000

DSC1004BL2-024.0000

DSC1001BE1-004.0625

DSC1001BE1-004.0960

DSC1001BL2-012.0000

DSC1001BE5-027.0000

DSC1001BE5-030.0000

DSC1001BE1-033.3333

DSC1001BL2-012.5000

DSC1001BL3-001.0000

DSC1001DE1-018.4320

DSC1001DE1-019.6608

DSC1001DE1-024.0000

DSC1001DE1-027.0000

DSC1001DE1-048.0000

DSC1001DE1-074.2500

DSC1001DE1-100.0000

DSC1001DE1-125.0000

DSC1001DE2-016.0000

DSC1001DE2-050.0000

DSC1001DE2-032.0000

DSC1001DE5-016.0000

DSC1001BI2-007.3728T

DSC1001BI2-027.0000T

DSC1001BI2-028.8000T

DSC1001BI2-032.0000T

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001BI2-033.3330T  
DSC1001BI2-040.0000T  
DSC1001BI2-042.5000T  
DSC1001BI2-044.0000T  
DSC1001BI2-048.0000T  
DSC1001BI2-049.0908T  
DSC1001BI2-050.0000T  
DSC1001BI2-059.0000T  
DSC1001BI2-062.5000T  
DSC1001BI2-080.0000T  
DSC1001BI2-100.0000T  
DSC1001BI2-106.2500T  
DSC1001BI2-125.0000T  
DSC1001BI2-133.0000T  
DSC1001BI2-148.5000T  
DSC1001BI5-003.6864T  
DSC1001BI5-004.0000T  
DSC1001BI5-007.3728T  
DSC1001BI5-008.0000T  
DSC1001BI5-010.0000T  
DSC1001BI5-012.0000T  
DSC1001BI5-016.0000T  
DSC1001BI5-024.0000T  
DSC1001BI5-025.0000T  
DSC1001BI5-032.0000T  
DSC1001BI5-033.3330T  
DSC1001BI5-040.0000T  
DSC1001BI5-048.0000T  
DSC1001BI5-050.0000T  
DSC1001BI5-066.0000T  
DSC1001BI5-066.6666T  
DSC1001BI5-072.0000T  
DSC1001BI5-100.0000T  
DSC1001BI5-120.0000T  
DSC1001BI5-125.0000T  
DSC1003BI1-060.0000T  
DSC8001BI2T  
DSC6011JI2B-720K000T  
DSC6013JI2B-001.0000T  
DSC6013JI2B-032K768T  
DSC6013JI2B-250K000T  
DSC6013JI2B-432K000T  
DSC6013JI2B-720K000T  
DSC6111JI2B-032K768T  
DSC6111JI2B-250K000T  
DSC6111JI2B-432K000T  
DSC6111JI2B-720K000T  
DSC6112JI2B-001.0000T  
DSC6112JI2B-032K768T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6112JI2B-250K000T  
DSC6112JI2B-432K000T  
DSC6112JI2B-720K000T  
DSC6111JI2B-004K000T  
DSC6112JI2B-004K000T  
DSC6011JI1B-012.0000T  
DSC6011JI3B-025.0000T  
DSC6101JI2B-025.0000T  
DSC6102JI2B-025.0000T  
DSC6102JI2B-027.0000T  
DSC6013JI1B-032.7680T  
DSC6013JI1B-008.0000T  
DSC6111JI1B-025.0000T  
DSC400-0202Q0106KI1T  
DSC400-0202Q0106KI2T  
DSC400-0202Q0107KI1T  
DSC400-0202Q0107KI2T  
DSC400-0202Q0108KI1T  
DSC400-0202Q0108KI2T  
DSC400-0202Q0109KI1T  
DSC400-0202Q0109KI2T  
DSC400-1111Q0110KI1T  
DSC400-1111Q0110KI2T  
DSC400-1111Q0111KI1T  
DSC400-1111Q0111KI2T  
DSC400-4111Q0112KI1T  
DSC400-4111Q0112KI2T  
DSC400-4334Q0023KI1T  
DSC400-4334Q0023KI2T  
DSC400-1133Q0113KI1T  
DSC400-1133Q0113KI2T  
DSC400-0101Q0114KI1T  
DSC400-0101Q0114KI2T  
DSC400-0101Q0115KI1T  
DSC400-0101Q0115KI2T  
DSC400-0111Q0116KI1T  
DSC400-0111Q0116KI2T  
DSC400-0111Q0117KI1T  
DSC400-0111Q0117KI2T  
DSC400-2222Q0118KI1T  
DSC1001BL5-010.0000T  
DSC1001BL5-012.0000T  
DSC8001BL5T  
DSC1001BL5-024.0000T  
DSC1001BL5-024.5760T  
DSC1001BL5-025.0000T  
DSC1001BL5-040.0000T  
DSC1001BL5-048.0000T  
DSC1001BL5-066.6666T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001BL5-100.0000T  
DSC1001BL5-133.3330T  
DSC1001BL5-150.0000T  
DSC1001BL2-025.0000T  
DSC1001BL5-050.0000T  
DSC1001BL5-016.0000T  
DSC1001BL5-080.0000T  
DSC1001BE5-022.5792T  
DSC1001BL5-020.0000T  
DSC1001BE1-012.0000T  
DSC1001BL1-016.0000T  
DSC1001BE5-064.0000T  
DSC1001BL5-064.0000T  
DSC1001BL2-020.0000T  
DSC1001BL1-060.0000T  
DSC1001BE2-012.2880T  
DSC1001BE2-014.7450T  
DSC1001BE1-001.8432T  
DSC1001BE1-026.0000T  
DSC1001BE2-048.0000T  
DSC1001BE1-014.3182T  
DSC1001BE1-014.7456T  
DSC1001BE2-014.7456T  
DSC1001BE1-133.0000T  
DSC1001BL5-001.1385T  
DSC1001BL5-001.1386T  
DSC1001BL5-001.1387T  
DSC1001BL5-001.1388T  
DSC1001BL5-001.1389T  
DSC1001BL5-108.0000T  
DSC1001BE5-020.0000T  
DSC1001BL5-033.3330T  
DSC1001BL5-026.7000T  
DSC1001BL5-026.6500T  
DSC1001BE5-016.0000T  
DSC1001BL2-048.0000T  
DSC1001BL2-026.0000T  
DSC1003BE1-025.0000T  
DSC1001BL5-026.0000T  
DSC1001BL5-120.0000T  
DSC1001BL5-014.7456T  
DSC1001BL5-033.0000T  
DSC1001BE2-090.0000T  
DSC1001BL2-024.0000T  
DSC1001BL5-125.0000T  
DSC1001BE5-024.0000T  
DSC1001BL5-030.0000T  
DSC1001BE1-066.6666T  
DSC1001BL5-049.5000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001BE1-001.4850T  
DSC1003BL1-010.0000T  
DSC1001BL5-072.0000T  
DSC1001BL5-066.0000T  
DSC1000BL3-PROGT  
DSC1000BL5-PROGT  
DSC1001BE5-033.3330T  
DSC1001BL5-075.0000T  
DSC1001BL5-004.0000T  
DSC1003BE1-024.0000T  
DSC1001BE5-012.0000T  
DSC1001BE3-026.0000T  
DSC612RI2A-01B2  
DSC612PI2A-01JQ  
DSA613PI3A-01G8VAO  
DSC612RI3A-010G  
DSC612RI3A-010J  
DSC613RI3A-010U  
DSC612RI1A-012M  
DSC613RI2A-012S  
DSC612RI2A-012P  
DSC612RI3A-012V  
DSC613RI3A-012W  
DSC612RI1A-0133  
DSC613RI2A-0134  
DSC613RI2A-013G  
DSC612RI2A-013H  
DSC613RI3A-014C  
DSC612RI1A-0159  
DSC613RI2A-015H  
DSC613RI2A-016P  
DSC612RI1A-016Q  
DSC613RI2A-017C  
DSC612RI1A-017M  
DSC612RI3A-019C  
DSC612RI2A-01A0  
DSC612RI2A-01A2  
DSC612RI2A-01A3  
DSC613RI3A-016P  
DSC613RI3A-01A4  
DSC612RI1A-01B2  
DSC1103BI2-135.0000T  
DSC1103BI2-148.5000T  
DSC1102BI2-156.2500T  
DSC1102BI2-155.2500T  
DSC1102BI2-114.2850T  
DSC1101BI2-125.0000T  
DSC1121BI2-022.5792T  
DSC1101BI2-024.5760T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123BI2-155.5200T  
DSC1121BI2-114.2850T  
DSC1121BI2-024.5760T  
DSC1121BI2-033.3330T  
DSC1102BI2-155.5200T  
DSC1122BI2-156.2570T  
DSC1123BI2-156.2570T  
DSC1123BI2-300.0000T  
DSC1122BI2-020.0000T  
DSC1122BI2-322.0000T  
DSC1123BI2-270.0000T  
DSC1123BI2-210.0000T  
DSC1123BI2-180.0000T  
DSC1123BI2-206.0000T  
DSC1123BI2-068.0000T  
DSC1121BI1-008.0000T  
DSC1121BI2-156.2500T  
DSC1124BI5-020.0000T  
DSC1123BI2-050.0013T  
DSC1103BI2-200.0000T  
DSC1121BI2-016.3840T  
DSC1121BI2-020.0000T  
DSC1121BI2-131.0720T  
DSC1103BI2-050.0000T  
DSC1101BI2-125.0031T  
DSC1102BI1-010.0000T  
DSC1123BI5-148.5000T  
DSC1123BI5-010.0000T  
DSC1124BI2-027.0000T  
DSC1101BI5-010.0000T  
DSC1122BI2-125.0000T  
DSC1123BI2-156.0000T  
DSC1122BI1-025.0000T  
DSC1121BI2-008.0000T  
DSC1123BI2-034.0000T  
DSC1101BI3-025.0000T  
DSC1101BI2-125.0037T  
DSC1124BI1-027.0000T  
DSC1121BI5-022.5792T  
DSC1121BI5-024.5760T  
DSC1123BI2-125.0037T  
DSC1123BI5-125.0000T  
DSC1121BI3-100.0000T  
DSC1121BI5-024.0000T  
DSC1121BI2-012.0000T  
DSC1123BI3-050.0000T  
DSC1101BI2-008.0000T  
DSC1103BI2-062.5000T  
DSC1101BI5-016.0000T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101BI5-012.0000T  
DSC1101BI5-020.0000T  
DSC1123BI2-010.0000T  
DSC1121BI5-045.1854T  
DSC1121BI5-049.1520T  
DSC1104BI1-027.0000T  
DSC1101BI3-013.5600T  
DSC1101BI2-027.1200T  
DSC1124BI3-027.0000T  
DSC1121BI1-020.0000T  
DSC1101BI1-145.2000T  
DSC1103BI1-156.2500T  
DSC1122BI3-166.6000T  
DSC1121BI5-125.0000T  
DSC1121BI5-025.6000T  
DSC1121BI5-125.0000B  
DSC1121BI2-040.6800T  
DSC1123BI3-080.0000T  
DSC1103BI2-235.0000T  
DSC1123BI1-148.5000T  
DSC1103BI5-148.5000T  
DSC1123BI5-040.0000T  
DSC1103BI2-156.2500T  
DSC8103AI2T  
DSC8123AL2T  
DSC1101AI2-148.5000T  
DSC1121AI2-156.2500T  
DSC8102AI2T  
DSC1123AI5-322.2656T  
DSC1103AI1-125.0000T  
DSC1103AI2-025.0000T  
DSC1103AI2-100.0000T  
DSC1103AI2-125.0000T  
DSC1103AI2-130.0000T  
DSC1103AI2-171.8181T  
DSC1103AI2-200.0000T  
DSC1121AI2-148.5000T  
DSC1121AI2-053.1250T  
DSC1123AI5-100.0000T  
DSC1103AI5-120.0000T  
DSC1104AI2-100.0000T  
DSC1103AI5-156.2500T  
DSC1001CI5-014.7456T  
DSC1001CI5-008.1920T  
DSC1001CI2-003.0720T  
DSC1003CI2-024.0000T  
DSC1003CI2-080.0000T  
DSC1003CI1-070.0000T  
DSC1001CI1-080.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CI5-022.0000T  
DSC1001CI2-100.8000T  
DSC1003CI2-027.0000T  
DSC1001CI5-022.5792T  
DSC1001CI2-024.3050T  
DSC1001CI1-004.0960T  
DSC1001CI5-003.2768T  
DSC1001CI5-007.3728T  
DSC1001CI2-003.2768T  
DSC1001CI3-024.0000T  
DSC1001CI3-025.0000T  
DSC1001CI3-027.0000T  
DSC1001CI3-013.8240T  
DSC1001CI5-015.0000T  
DSC1001CI5-144.0000T  
DSC1001CI5-029.4912T  
DSC1001CI2-133.3330T  
DSC1001CI3-100.0000T  
DSC1001CI2-074.1750T  
DSC1001CI5-003.6864T  
DSC1004CI2-024.5760T  
DSC1001CI3-003.5790T  
DSC1001CI1-018.4320T  
DSC1001CI1-040.0000T  
DSC1001CI2-066.0000T  
DSC1001CI2-026.6363T  
DSC1001CI1-064.0000T  
DSC1001CI2-003.8000T  
DSC1001CI3-012.0000T  
DSC1001CI3-033.0000T  
DSC1003CI5-080.0000T  
DSC1001CI1-005.0000T  
DSC1001CI3-019.2000T  
DSC1001CI3-050.0000T  
DSC1001CI1-004.9152T  
DSC1003CI2-010.0000T  
DSC1004CI5-121.5000T  
DSC1001CI2-034.0000T  
DSC1001CI5-037.4000T  
DSC1004CI2-060.0000T  
DSC1001CI2-004.0960T  
DSC1001CI5-037.0879T  
DSC1001CI2-013.0000T  
DSC1004CI1-016.0000T  
DSC1001CI1-028.6363T  
DSC1001CI3-013.5000T  
DSC1001CI1-008.1920T  
DSC1001CI2-038.0000T  
DSC1001CI3-004.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1004CI5-100.0000T  
DSC1001CI5-013.5000T  
DSC1001CI2-020.7500T  
DSC1003CI5-040.0000T  
DSC1001CI5-013.3300T  
DSC1003CI2-020.0000T  
DSC1001CI2-088.0000T  
DSC1001CI2-020.0036T  
DSC1001CI2-020.0037T  
DSC1001CI1-003.5800T  
DSC1001CI1-125.0000T  
DSC1001CI2-029.5000T  
DSC1001CI5-026.6000T  
DSC1004CI5-025.0000T  
DSC1004CI5-026.6000T  
DSC1001CI5-099.9990T  
DSC1001CI2-024.9600T  
DSC1003CI1-025.0000T  
DSC1001BI1-008.0000T  
DSC1001BI1-010.0000T  
DSC1001BI1-032.0000T  
DSC1001BI1-022.1184T  
DSC1001BI1-024.0000T  
DSC1001BI1-024.5760T  
DSC1001BI1-025.0000T  
DSC1001BI1-027.0000T  
DSC1001BI1-030.0000T  
DSC1001BI1-040.0000T  
DSC1001BI1-048.0000T  
DSC1001BI1-050.0000T  
DSC1001BI1-060.0000T  
DSC1001BI1-125.0000T  
DSC1001BI2-001.8432T  
DSC1001BI2-002.0480T  
DSC1001BI2-005.5296T  
DSC1001BI2-006.0000T  
DSC1001BI2-008.0000T  
DSC1001BI2-012.0000T  
DSC1001BI2-012.2880T  
DSC1001BI2-014.7456T  
DSC1001BI2-016.0000T  
DSC1001BI2-016.3840T  
DSC1001BI2-020.0000T  
DSC1001BI2-020.0016T  
DSC1001BI2-022.5790T  
DSC1001BI2-024.0000T  
DSC1001BI2-024.5760T  
DSC1001BI2-025.0000T  
DSC2040FI2-D0002

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2040FI2-D0003  
DSC2042FI2-M0004  
DSC2010FI1-A0003  
DSC2033FI2-F0046  
DSC2033FI2-F0047  
DSC2033FI2-F0048  
DSC2133FI2-E0027  
DSC2011FI2-F0050  
DSC2041FI1-K0001  
DSC2040FI2-B0021  
DSC2033FI2-F0053  
DSC2031FI2-F0023  
DSC557-0333FI1  
DSC2011FI1-F0054  
DSC2030FI2-B0022  
DSC2033FI2-H0005  
DSC2033FI2-F0060  
DSC2110FI1-A0012  
DSC2033FI2-F0059  
DSC2033FI2-F0012  
DSC2111FI2-E0029  
DSC2043FI1-F0058  
DSC2011FI1-F0056  
DSA557-0344FI0VAO  
DSA557-0344FI1VAO  
DSC1101CE1-024.0000  
DSC1101CL2-016.3840  
DSC1101CL2-020.0000  
DSC1101CL5-027.0000  
DSC1101CL5-040.0000  
DSC1103CE1-200.0000  
DSC1103CE2-135.0000  
DSC1103CE2-200.0000  
DSC1103CE5-150.0000  
DSC1103CE5-156.2500  
DSC1103CL5-106.2500  
DSC8123CL1  
DSC1121CE1-016.0000  
DSC8123CL5  
DSC1121CE1-025.0012  
DSC1121CE5-012.2880  
DSC1121CE5-024.5670  
DSC1121CE2-025.0000  
DSC1121CL2-024.7500  
DSC613RI2A-01BC  
DSC612RI3A-01CJ  
DSC612RI2A-01CM  
DSC612RI1A-01DY  
DSC613RI2A-01G0

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC612RI1A-01GC  
DSC612RI2A-01GE  
DSC613RI2A-01GJ  
DSC612RI1A-01GV  
DSC613RI3A-0131  
DSC613RI3A-01J3  
DSC612RI2A-01J8  
DSC612RI3A-01M3  
DSC613RI3A-01M7  
DSC613RI3A-01M8  
DSC612RI2A-01K9  
DSC612RI2A-01KA  
DSC612RI2A-01KK  
DSC612RI3A-013C  
DSC612RI1A-01JM  
DSC612RI3A-01K3  
DSC612RI3A-01P3  
DSA613RI3A-01BMVAO  
DSC6001HL2B-026.0000  
DSC6003HL2B-024.0000  
DSC6003HL3B-014.0000  
DSC6003HL3B-032K768  
DSC6101HL3B-025.0000  
DSC6101HL3B-027.0000  
DSC6041HL2B-009.8460  
DSC6331HE1CB-024.0000  
DSC6013HE1B-032K768  
DSC6021HE3B-0157  
DSC6023HE3B-015C  
DSC6023HE3B-015D  
DSC6331HL1AB-072.5000  
DSC6102HL2B-072.5000  
DSC6101HL2B-072.5000  
DSC6101HL2B-072.0000  
DSC6011HE1B-084K000  
DSC6013HE2B-084K000  
DSC6001HE1B-011.0592  
DSC6301HL1FB-020.0000  
DSC6111HL1B-032K768  
DSC6101HL3B-024.0000  
DSC6111HL1B-010.0000  
DSC6111HL1B-014.7456  
DSC6111HL1B-024.0000  
DSC6001HE3B-027.1200  
DSC6011HE2B-050.0000  
DSC6021HE2B-01AB  
DSC6011HL3B-003.0720  
DSC6001HL2B-009.8460  
DSC6001HL2B-012.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC601HE2B-008.7040  
DSC6001HE2B-015.0000  
DSC6053HE1B-006.2500  
DSC6013HE2B-048.0000  
DSC6013HL2B-048.0000  
DSC6011HE2B-064.0000  
DSC6001HE1B-008.0000  
DSC6111HE1B-050.0000  
DSC6001HE1B-001.0000  
DSA6301HL1AB-027.0000VAO  
DSA6011HL2B-032K768VAO  
DSA6101HL3B-072.0000VAO  
DSC6101ML2B-066.6666  
DSC6001ML3B-026.0000  
DSC6003ML3B-008.1920  
DSC6101ML3B-025.0000  
DSC6101ML3B-027.0000  
DSC6011ME2B-050.0000  
DSC6311ML1AB-027.0000  
DSC6003ML2B-032K768  
DSC6021ML3B-015R  
DSC6001ML2B-040.0000  
DSC6101ML3B-016.6666  
DSC6101ML3B-014.7456  
DSC6101ML2B-072.0000  
DSC6001ML2B-025.0000  
DSC6001ME1B-050.0000  
DSC6001ME1B-075.0000  
DSC6111ME1B-012.0000  
DSC6311ML2DB-016.6700  
DSC6011ML3B-003.0720  
DSC6101ML3B-032.0000  
DSC6301ML1EB-010.0000  
DSC6301ML1AB-010.0000  
DSC6003ME1B-013.1072  
DSC6001ME1B-008.0000  
DSC6001ME2B-009.0000  
DSC6001ME1B-052.4280  
DSC6011ME2B-012.0000  
DSA6101ML2B-026.0000VAO  
DSA6101ML3B-014.7456VAO  
DSA6101ML3B-016.6666VAO  
DSA6101ML3B-025.0000VAO  
DSA6101ML3B-033.3333VAO  
DSA6011ML1B-025.0000VAO  
DSC612NL3A-012R  
DSC612NL3A-014E  
DSC612NL2A-014E  
DSC612NL2A-0151

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC613NE2A-016W

DSC612NL3A-0142

DSC612NL3A-019A

DSA612NL2A-019BVAO

DSA612NL2A-01C1VAO

DSA612NL2A-01C3VAO

DSA612NL2A-01C4VAO

DSA612NL2A-01CPVAO

DSC6001JL2B-027.0000

DSC6101JL2B-033.3333

DSC6003JL3B-004.0096

DSC6003JL3B-007.3728

DSC6101JL3B-038.4000

DSC6101JL3B-050.0000

DSC6003JL3B-004.0960T

DSC6311JL1BB-028.6364

DSC6311JL1AB-028.6364

DSC6331JE1CB-024.0000

DSC6001JE1B-024.0000

DSC6003JE1B-024.0000

DSC6101JL2B-026.0000

DSC6111JE1B-033.3333

DSC6011JE2B-032K768

DSC1103BI2-200.0000

DSC6101JA3B-024.0000

DSC6011JA1B-040.0000

DSC6101JA2B-027.0000

DSA6101JA1B-027.0000VAO

DSA6111JA1B-027.0000VAO

DSA6112JA1B-027.0000VAO

DSA6311JA1AB-024.0000VAO

DSA6311JA1AB-025.0000VAO

DSA6311JA1AB-027.0000VAO

DSA6331JA1BB-100.0000VAO

DSA6331JA1CB-100.0000VAO

DSA6001JA2B-003K277VAO

DSA6001JA2B-019.2000VAO

DSA6001JA2B-032K768VAO

DSA6001JA2B-045.0000VAO

DSA6011JA2B-012.0000VAO

DSA6011JA2B-032K768VAO

DSA6021JA2B-01ARVAO

DSA6102JA2B-016.0000VAO

DSA6311JA2AB-024.0000VAO

DSA6311JA2AB-025.0000VAO

DSA6331JA2BB-025.0000VAO

DSA1001DL1-024.0000VAO

DSA1001DL1-024.5760VAO

DSA1001DL1-024.8000VAO

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA1001DL1-024.9000VAO  
DSA1001DL1-025.0000VAO  
DSA1001DL1-025.1000VAO  
DSA1001DL1-033.3330VAO  
DSA1001DL1-048.0000VAO  
DSA1001DL1-054.0000VAO  
DSA1001DL1-060.0000VAO  
DSA1001DL1-074.2500VAO  
DSA1001DL1-100.0000VAO  
DSA1001DL1-125.0000VAO  
DSA1004DL1-100.0000VAO  
DSA1004DL1-125.0000VAO  
DSA1001DL2-006.0053VAO  
DSA1001DL2-007.2000VAO  
DSA1001DL2-008.0000VAO  
DSA1001DL2-010.0000VAO  
DSA1001DL2-016.0000VAO  
DSA1001DL2-020.0000VAO  
DSA1001DL2-024.0000VAO  
DSA1001DL2-024.5640VAO  
DSA1001DL2-024.5760VAO  
DSA1001DL2-026.0000VAO  
DSA1001DL2-027.0000VAO  
DSA1001DL2-028.6364VAO  
DSA1001DL2-030.0000VAO  
DSA1001DL2-033.0000VAO  
DSA1001DL2-033.3333VAO  
DSA1001DL2-036.8640VAO  
DSA1001DL2-037.1250VAO  
DSA1001DL2-040.0000VAO  
DSA1001DL2-048.0000VAO  
DSA1001DL2-049.5000VAO  
DSA1001DL2-050.0000VAO  
DSA1001DL2-054.0000VAO  
DSA1001DL2-066.0000VAO  
DSA1001DL2-072.0000VAO  
DSA1001DL2-080.0000VAO  
DSA1001DL2-087.0655VAO  
DSA1001DL2-100.0000VAO  
DSA1001DL2-125.0000VAO  
DSA1004DL2-072.0000VAO  
DSA1001DL3-004.0000VAO  
DSA1001DL3-006.0053VAO  
DSA1001DL3-008.0000VAO  
DSA1001DL3-012.2888VAO  
DSA1001DL3-012.5000VAO  
DSA1001DL3-016.0000VAO  
DSA1001DL3-016.3840VAO  
DSA1001DL3-020.0000VAO



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA1001DL3-022.5792VAO  
DSA1001DL3-024.0000VAO  
DSA1001DL3-025.0000VAO  
DSA1001DL3-026.0000VAO  
DSA1001DL3-027.0000VAO  
DSA1001DL3-032.7680VAO  
DSA1001DL3-033.0000VAO  
DSA1001DL3-033.3330VAO  
DSA1001DL3-045.0000VAO  
DSA1001DL3-048.0000VAO  
DSA1001DL3-054.0000VAO  
DSA1001DL3-055.4666VAO  
DSA1001DL3-060.0000VAO  
DSA1001DL3-080.0000VAO  
DSA1001DL3-100.0000VAO  
DSA1001DL3-125.0000VAO  
DSA1001DL1-027.0000VAO  
DSA1001DL1-033.0000VAO  
DSC1001AE1-016.6667  
DSC1001AE1-033.3333  
DSC1001AE1-025.0000  
DSC1001AE1-033.0000  
DSC1001AE1-048.0000  
DSC1001AE1-050.0000  
DSC1001AE1-125.0000  
DSC1001AE1-133.0000  
DSC1001AE2-100.0000  
DSC1001AE2-125.0000  
DSC1001AL2-027.0000  
DSC1001AL5-007.3728  
DSC1001AL5-012.0000  
DSC1001AL5-016.0000  
DSC1001AL5-004.0000  
DSC1001AL5-024.5760  
DSC1001AL5-025.0000  
DSC1001AL5-016.3840  
DSC1001AL5-018.4320  
DSC1001AL5-080.0000  
DSC1001AL5-100.0000  
DSC1001AL5-032.0000  
DSC1001AL5-040.0000  
DSC1001AL5-050.0000  
DSC8001AL2  
DSC8001AL5  
DSC1001AE1-066.6660  
DSC1004AL2-001.0000  
DSC1004AL1-001.0000  
DSC1001AL5-001.8432  
DSC1001AE1-019.6608

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AE1-024.0000  
DSC1001AL5-060.0000  
DSC1001AL5-125.0000  
DSC1001AE2-002.0480  
DSC1001AL5-024.0000  
DSC1001AE5-024.5760  
DSC1001AE1-027.0000  
DSC1001AL5-033.0000  
DSC1001AL5-033.3333  
DSC1001AE1-055.0000  
DSC1001AL5-048.0000  
DSC1001AL5-008.0000  
DSC1001AE1-006.1440  
DSC1001AE1-111.0000  
DSC1001AL5-027.0000  
DSC1001AE1-014.3182  
DSC1001AE1-024.5761  
DSC1001AE1-003.6864  
DSC1001AE1-054.0000  
DSC1001DL2-045.1584T  
DSC1001DE5-037.4000T  
DSC1001DL5-096.0000T  
DSC1001DL2-066.0000T  
DSC1003DL5-019.2000T  
DSC1001DE5-012.0000T  
DSC1001DL2-026.0000T  
DSC1001DL2-019.2000T  
DSC1003DL1-033.3333T  
DSC1003DL1-024.5454T  
DSC1004DL2-072.0000T  
DSC1001DE2-120.0000T  
DSC1004DL2-025.0000T  
DSC1000DL3-PROGT  
DSC1000DL5-PROGT  
DSC1001DL2-054.0000T  
DSC1001DL3-027.0000T  
DSC1001DL3-024.0000T  
DSC1001DL5-016.3840T  
DSC1001DL2-016.3690T  
DSC1001DL2-061.2500T  
DSC1003DL2-033.3333T  
DSC1001DL5-018.4320T  
DSC1001DL5-033.3333T  
DSC1001DL2-003.6864T  
DSC613RE1A-0136  
DSC612RL2A-0137  
DSC612RL2A-013D  
DSC612RL2A-013E  
DSC612RL3A-0142

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC612RE1A-014J  
DSC613RL1A-0131  
DSC612RL1A-014S  
DSC612RL2A-0130  
DSC612RL2A-0168  
DSC612RL2A-013C  
DSC612RE1A-0169  
DSC613RE2A-016Y  
DSC613RE1A-017Q  
DSC612RL2A-018K  
DSC613RE1A-0197  
DSC612RE1A-0199  
DSC612RL3A-019B  
DSC612RL1A-019T  
DSC612RL3A-01AM  
DSC612RE2A-01AT  
DSC612RE1A-01B2  
DSC613RE1A-01BV  
DSC613RE2A-01DG  
DSC612RL2A-01E7  
DSC612RE1A-01GQ  
DSC612RE2A-01GQ  
DSC612RL3A-01KS  
DSC612RE3A-01M0  
DSC612RE2A-01MR  
DSA612RL2A-01GAVAO  
DSA612RL2A-01H6VAO  
DSA612RL2A-01K9VAO  
DSA612RL2A-01KMVAO  
DSA612RL2A-01MGVAO  
DSA613RL2A-016PVAO  
DSC6001HL2B-026.0000T  
DSC6003HL2B-024.0000T  
DSC6003HL3B-014.0000T  
DSC6003HL3B-032K768T  
DSC6101HL3B-025.0000T  
DSC6101HL3B-027.0000T  
DSC6041HL2B-009.8460T  
DSC6331HE1CB-024.0000T  
DSC6013HE1B-032K768T  
DSC6021HE3B-0157T  
DSC6023HE3B-015CT  
DSC6023HE3B-015DT  
DSC6331HL1AB-072.5000T  
DSC6102HL2B-072.5000T  
DSC6101HL2B-072.5000T  
DSC6101HL2B-072.0000T  
DSC6011HE1B-084K000T  
DSC6013HE2B-084K000T

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6001HE1B-011.0592T  
DSC6301HL1FB-020.0000T  
DSC6111HL1B-032K768T  
DSC6101HL3B-024.0000T  
DSC6111HL1B-010.0000T  
DSC6111HL1B-014.7456T  
DSC6111HL1B-024.0000T  
DSC6001HE3B-027.1200T  
DSC6011HE2B-050.0000T  
DSC6021HE2B-01ABT  
DSC6011HL3B-003.0720T  
DSC6001HL2B-009.8460T  
DSC6001HL2B-012.0000T  
DSC6011HE2B-008.7040T  
DSC6001HE2B-015.0000T  
DSC6053HE1B-006.2500T  
DSC6013HE2B-048.0000T  
DSC6013HL2B-048.0000T  
DSC6011HE2B-064.0000T  
DSC6001HE1B-008.0000T  
DSC6111HE1B-050.0000T  
DSC6001HE1B-001.0000T  
DSA6301HL1AB-027.0000TVAO  
DSA6011HL2B-032K768TVAO  
DSA6101HL3B-072.0000TVAO  
DSC6101ML2B-066.6666T  
DSC6001ML3B-026.0000T  
DSC6003ML3B-008.1920T  
DSC6101ML3B-025.0000T  
DSC6101ML3B-027.0000T  
DSC6011ME2B-050.0000T  
DSC6311ML1AB-027.0000T  
DSC6003ML2B-032K768T  
DSC6021ML3B-015RT  
DSC6001ML2B-040.0000T  
DSC6101ML3B-016.6666T  
DSC6101ML3B-014.7456T  
DSC6101ML2B-072.0000T  
DSC6001ML2B-025.0000T  
DSC6001ME1B-050.0000T  
DSC6001ME1B-075.0000T  
DSC6111ME1B-012.0000T  
DSC6311ML2DB-016.6700T  
DSC6011ML3B-003.0720T  
DSC6101ML3B-032.0000T  
DSC6301ML1EB-010.0000T  
DSC6301ML1AB-010.0000T  
DSC1001AE5-040.0000  
DSC1003AE5-100.0000

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AL5-066.0000  
DSC1001AE1-018.1059  
DSC1001AL5-030.0000  
DSC1001AE1-049.1520  
DSC1001AL1-001.0000  
DSC1001AL1-048.0000  
DSC1001AL5-016.7772  
DSC1001AE2-148.5000  
DSC1001AE2-048.0000  
DSC1001AE5-022.5792  
DSC1003AL5-025.0000  
DSC1001AE1-001.4850  
DSC1001AL2-016.0000  
DSC1001AE2-080.0000  
DSC1001AL1-020.0000  
DSC1001AE1-004.0000  
DSC1001AE1-099.0000  
DSC1001AE1-098.0000  
DSC1001AL2-025.0000  
DSC1001AE5-004.0000  
DSC1001AE5-020.0000  
DSC1001AE5-125.0000  
DSC1001AE5-012.0000  
DSC1003AE1-022.1184  
DSC1001AE1-010.0000  
DSC1003AE5-025.0000  
DSC1001AL5-001.0000  
DSC1001AE2-050.0000  
DSC1001AE2-054.0000  
DSC1001AE5-029.1621  
DSC1001AE5-031.6440  
DSC1001AL5-011.0592  
DSC1001AL1-050.0000  
DSC1001AL5-010.0000  
DSC1000AL3-PROG  
DSC1000AL5-PROG  
DSC1004AE2-024.0000  
DSC1001AL5-133.3330  
DSC1001AL2-020.0000  
DSC1001AL2-060.0000  
DSC1001AE3-013.5600  
DSC1001AE1-064.0000  
DSC1001AE1-040.0000  
DSC1003AE3-007.3728  
DSC1001AL5-014.7456  
DSC1001AE5-017.1776  
DSC1001AE5-001.2000  
DSC1001AL2-029.4912  
DSC1001AL2-050.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003AL2-005.0000  
DSC1001AE1-003.5700  
DSC1001AL5-033.3330  
DSC1001AL2-024.0000  
DSC1001AL2-125.0000  
DSC1001AL1-025.0000  
DSC1001AL1-027.0000  
DSC1001AL2-100.0000  
DSC1001AL5-029.4912  
DSC1001CE1-004.0000T  
DSC1001CE1-006.0000T  
DSC1001CE1-012.0000T  
DSC1001CE1-012.2880T  
DSC1001CE1-015.3600T  
DSC1001CE1-016.5000T  
DSC1001CE1-020.0000T  
DSC1001CE1-020.8300T  
DSC1001CE1-024.0000T  
DSC1001CE1-024.5760T  
DSC1001CE1-025.0000T  
DSC1001CE2-001.8432T  
DSC1001CE1-033.8688T  
DSC1001CE1-048.0000T  
DSC1001CE2-024.0000T  
DSC1001CE1-069.2480T  
DSC1001CE1-086.5600T  
DSC1001CE2-025.0000T  
DSC1001CE2-011.2896T  
DSC1001CE2-050.0000T  
DSC1001CE2-026.0000T  
DSC1001CE2-027.0000T  
DSC1001CE2-032.1100T  
DSC1001CE2-033.0000T  
DSC1001CL1-020.0000T  
DSC1001CE2-037.1250T  
DSC1001CE2-040.0000T  
DSC1001CL1-016.0000T  
DSC1001CL1-025.0000T  
DSC1001CE2-054.0000T  
DSC1001CE2-074.2500T  
DSC1001CE2-100.0000T  
DSC1001CL1-125.0000T  
DSC1001CL2-012.0000T  
DSC1001CL2-020.0000T  
DSC1001CL2-022.5972T  
DSC1001CL1-030.0000T  
DSC1001CL1-033.0000T  
DSC1001CL2-037.1250T  
DSC1001CL2-033.3333T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CL1-066.0000T  
DSC1001CL2-050.0000T  
DSC1001CL2-004.0000T  
DSC1001CL2-025.0000T  
DSC1001CL2-027.0000T  
DSC1001CL2-033.3000T  
DSC1001CL5-040.0000T  
DSC1001CL5-001.8432T  
DSC1001CL5-008.0000T  
DSC1001CL5-150.0000T  
DSC1001CL5-012.0000T  
DSC1001CL5-019.2000T  
DSC1001CL5-020.0000T  
DSC1001CL5-024.0000T  
DSC1001CL5-024.5760T  
DSC1001CL5-025.0000T  
DSC1001CL5-026.0000T  
DSC1001CL5-027.0000T  
DSC1001CL5-030.0000T  
DSC1001CL5-032.0000T  
DSC1001CL5-033.3330T  
DSC1001CL5-050.0000T  
DSC1001CL5-033.0000T  
DSC1001CL5-060.0000T  
DSC1001CE1-037.1250T  
DSC1001CL5-114.0000T  
DSC1001CL1-100.0000T  
DSC8001CL5T  
DSC1001CL5-014.7456T  
DSC1001CL5-016.0000T  
DSC1001CL5-014.3181T  
DSC1001CL5-010.0000T  
DSC1001CE1-125.0000T  
DSC1001CE1-022.1184T  
DSC1001CL5-080.0000T  
DSC1001CL5-100.0000T  
DSC1001CL5-125.0000T  
DSC1001CL5-133.3330T  
DSC1001CL5-012.0000TABR  
DSC1003CL1-048.0000T  
DSC1003CL1-095.0000T  
DSC1001CL1-001.8432T  
DSC1001CE2-012.2880T  
DSC1001CE2-003.5800T  
DSC1001CL1-001.6000T  
DSC1001CE1-027.0000T  
DSC1001CL2-024.0000T  
DSC1001CE5-148.5000T  
DSC1001CE1-014.3182T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CE2-022.5792T  
DSC1001CL1-033.3333T  
DSC1001CL1-048.0000T  
DSC1001CE1-066.6666T  
DSC1001CE2-012.0000T  
DSC1001CL1-024.0000T  
DSC1001CL2-030.0000T  
DSC1001CE1-019.2000T  
DSC1001CL1-003.2500T  
DSC1001CL2-008.0000T  
DSC1001CL2-025.5760T  
DSC1001CE1-083.3300T  
DSC1001CE2-032.0000T  
DSC1001CE1-050.0000T  
DSC1001CL5-006.7700T  
DSC1001CL5-006.7900T  
DSC1001CL5-013.5400T  
DSC1001CL5-013.5800T  
DSC1001CL5-050.3500T  
DSC1001CL5-001.6000T  
DSC1001CL5-025.6000T  
DSC1001CL5-011.0592T  
DSC1001CE2-018.4320T  
DSC1001CL5-012.8000T  
DSC1001CL2-100.0000T  
DSC1001CL2-054.0000T  
DSC1004CE1-033.3333T  
DSC1003CL2-025.0000T  
DSC1001CE5-016.0000T  
DSC1001CE1-008.0000T  
DSC1001CE5-025.0000T  
DSC1001CL5-048.0000T  
DSC1001CE1-080.0000T  
DSC1004CL5-016.0000T  
DSC1001CE1-033.3300T  
DSC1001CL2-024.5760T  
DSC1001CL1-050.0000T  
DSC1001CL2-014.7456T  
DSC1001CL2-148.5000T  
DSC1001CL2-016.0000T  
DSC1001CE5-012.2880T  
DSC1003CL2-027.0000T  
DSC1004CL2-027.0000T  
DSC1001CL5-016.3840T  
DSC1001CE5-002.0000T  
DSC1001CE5-008.0000T  
DSC1001CE1-026.0000T  
DSC1004CE1-025.6000T  
DSC1001CL2-032.0000T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CL2-033.3300T  
DSC1001CL5-004.0000T  
DSC1001CE1-033.3333T  
DSC1001CL5-075.0000T  
DSC1003CL5-050.0000T  
DSC1003CL2-024.0000T  
DSC1001CE2-060.0000T  
DSC1001CL1-002.0000T  
DSC1000CL3-PROGT  
DSC1000CL5-PROGT  
DSC1001CL5-018.4320T  
DSC1001CL3-012.2880T  
DSC1001DI5-006.0000T  
DSC1001DI5-007.3728T  
DSC1001DI5-008.0174T  
DSC1001DI5-008.1920T  
DSC1001DI5-010.0000T  
DSC1001DI5-012.0000T  
DSC1001DI5-016.0000T  
DSC1001DI5-019.2000T  
DSC1001DI5-020.0000T  
DSC1001DI5-024.0000T  
DSC1001DI5-024.5760T  
DSC1001DI5-025.0000T  
DSC1001DI5-026.0000T  
DSC1001DI5-027.0000T  
DSC1001DI5-028.6363T  
DSC1001DI5-029.4912T  
DSC1001DI5-032.0000T  
DSC1001DI5-033.3330T  
DSC1001DI5-001.8432T  
DSC1001DI2-018.0000T  
DSC1001DI5-044.0000T  
DSC1001DI5-048.0000T  
DSC1001DI5-050.0000T  
DSC1001DI5-060.0000T  
DSC1001DI5-075.0000T  
DSC1001DI5-080.0000T  
DSC1001DI5-100.0000T  
DSC1001DI5-125.0000T  
DSC1001DI1-074.2500T  
DSC1004DI1-024.0000T  
DSC1001DL5-032.0000T  
DSC1004DI2-072.0000T  
DSC1004DI5-010.0000T  
DSC1001DI1-054.0000T  
DSC1004DI5-066.4860T  
DSC1004DI5-066.5800T  
DSC8001DI2T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DI2-006.7800T  
DSC1001DI2-054.0000T  
DSC1001DI5-047.3385T  
DSC1001DI5-038.4000T  
DSC1001DI1-060.0000T  
DSC1001DI2-030.0000T  
DSC1001DI2-001.8432T  
DSC1001DI5-033.3333T  
DSC1001DI2-066.0000T  
DSC1001DI5-133.3330T  
DSC1004DI1-006.7800T  
DSC1001DI5-018.4320T  
DSC1001DI1-018.4320T  
DSC1001DI2-004.0000T  
DSC1001DI1-004.9152T  
DSC1001DI2-045.1584T  
DSC1001DI2-049.1520T  
DSC1001DI2-011.0592T  
DSC1003DI2-027.1200T  
DSC1001DI2-032.7680T  
DSC1001DI1-016.6666T  
DSC1001DI5-087.0655T  
DSC1001DI1-045.1584T  
DSC1001DI5-025.6000T  
DSC1001DI1-045.5840T  
DSC1001DI1-013.3300T  
DSC1001DI2-003.0720T  
DSC1001DI2-057.2727T  
DSC1003DI2-013.5288T  
DSC1001DI2-096.0000T  
DSC1001DI2-023.0000T  
DSC1001DI5-054.0000T  
DSC1001DI1-029.4912T  
DSC1001DI5-013.5288T  
DSC1004DI2-133.0000T  
DSC1004DI1-050.0000T  
DSC1001DI1-007.3728T  
DSC1001DI1-080.0000T  
DSC1001DI1-002.0000T  
DSC1001DI2-064.0000T  
DSC1001DI3-024.0000T  
DSC1003DI2-024.5670T  
DSC1001DI5-032.7680T  
DSC1001DI1-011.0592T  
DSC1001DI3-012.0000T  
DSC1001DI2-033.0000T  
DSC1003DI5-025.0000T  
DSC1001DI5-011.0592T  
DSC1001DI2-133.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003DI1-012.0000T

DSC1001DI2-002.0970T

DSC1001DI3-100.0000T

DSC1001DI3-133.0000T

DSC1001DI1-064.0000T

DSC1001DI5-019.6800T

DSC1001DI1-025.0008T

DSC1001DI5-090.0000T

DSC1001DI5-014.3181T

DSC1001DI1-116.6666T

DSC1001DI2-066.6670T

DSC1003DI2-050.0000T

DSC1004DI2-050.0000T

DSC1003DI1-052.0000T

DSC1001DI5-009.2160T

DSC1001DI2-060.0000T

DSC1001DI5-005.0196T

DSC1001DI5-037.4000T

DSC1001DI1-028.6363T

DSC1001DI3-012.2880T

DSC1004DI5-024.0000T

DSC1004DI5-016.0000T

DSC1001DI3-040.0000T

DSC1004DI1-026.0000T

DSC1001DI2-070.0000T

DSC1001DI3-060.0000T

DSC1001DI5-057.5580T

DSC1003DI2-024.0000T

DSC1003DI2-033.3333T

DSC1001DI1-036.0000T

DSC1001DI1-038.0000T

DSC1001DI5-030.7200T

DSC1001DI3-027.0000T

DSC1001DI2-014.3181T

DSC1001DI5-040.0000T

DSC1001DI1-069.1200T

DSC1001DI5-032.4000T

DSC1001DI5-041.1420T

DSC1001DI5-014.7456T

DSA1001DI1-005.0000TVAO

DSA1001DI1-012.5000TVAO

DSA1001DI1-019.2000TVAO

DSA1001DI1-020.0000TVAO

DSA1001DI1-024.5760TVAO

DSA1001DI1-025.0000TVAO

DSA1001DI1-033.0000TVAO

DSA1001DI1-050.0000TVAO

DSA1003DI1-050.0000TVAO

DSA1001DI2-012.2880TVAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA1001DI2-019.2000TVAO  
DSA1001DI2-025.0000TVAO  
DSA1001DI2-026.0000TVAO  
DSA1001DI2-027.0000TVAO  
DSA1001DI2-033.3333TVAO  
DSA1001DI2-125.0000TVAO  
DSA1001DI3-012.0000TVAO  
DSA1001DI3-020.0000TVAO  
DSA1001DI3-024.0000TVAO  
DSA1001DI3-027.0000TVAO  
DSA1001DI3-050.0000TVAO  
DSA1001DI3-150.0000TVAO  
DSC1001AI1-012.2880T  
DSC1001AI2-006.0000T  
DSC1001AI1-025.0000T  
DSC1001AI2-008.0000T  
DSC1001AI2-012.0000T  
DSC1001AI2-012.2880T  
DSC1001AI2-016.0000T  
DSC1001AI2-016.3840T  
DSC1001AI2-125.0000T  
DSC1001AI2-024.0000T  
DSC1001AI2-024.5760T  
DSC1001AI2-025.0000T  
DSC1001AI2-025.0007T  
DSC1001AI2-026.0000T  
DSC1001AI2-032.0000T  
DSC1001AI2-014.3180T  
DSC1001AI2-050.0000T  
DSC1001AI2-054.0000T  
DSC1001AI5-150.0000T  
DSC1001AI2-066.0000T  
DSC1001AI2-098.3040T  
DSC1001AI2-100.0000T  
DSC1001AI2-120.0000T  
DSC1001AI2-133.0000T  
DSC1001AI5-002.4576T  
DSC1001AI5-008.0000T  
DSC1001AI5-011.0592T  
DSC1001AI5-012.0000T  
DSC1001AI5-016.0000T  
DSC1001AI5-018.4320T  
DSC1001AI5-020.0000T  
DSC1001AI5-024.5760T  
DSC1001AI5-025.0000T  
DSC1001AI5-027.0000T  
DSC1001AI5-029.4912T  
DSC1001AI5-033.3330T  
DSC1001AI5-048.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AI5-080.0000T  
DSC1001AI5-100.0000T  
DSC1001AI5-125.0000T  
DSC1001AI5-125.0060T  
DSC1001AI2-066.6600T  
DSC1003AI2-050.0000T  
DSC1004AI2-040.0000T  
DSC8001AI2T  
DSC1001AI1-120.0000T  
DSC1001AI2-027.0016T  
DSC1001AI2-066.6670T  
DSC1001AI1-055.3330T  
DSC1001AI5-032.0000T  
DSC1001AI2-096.0000T  
DSC1001AI5-033.0000T  
DSC1001AI2-001.0000T  
DSC1001AI2-064.0000T  
DSC1004AI2-001.0000T  
DSC8003AI2T  
DSC1001AI2-048.0000T  
DSC1001AI1-050.0000T  
DSC1001AI2-010.0000T  
DSC1001AI2-027.0000T  
DSC1001AI2-011.7000T  
DSC1001AI2-012.3667T  
DSC1001AI5-040.0000T  
DSC1001AI5-024.0000T  
DSC1001AI1-033.0000T  
DSC1001AI2-040.0000T  
DSC1001AI1-049.1520T  
DSC1001AI5-012.2880T  
DSC1001AI1-016.0000T  
DSC1004AI5-099.7200T  
DSC1001AI1-001.0000T  
DSC1001AI5-066.0000T  
DSC1001AI1-066.0000T  
DSC1001AI1-020.0000T  
DSC1001AI1-013.1072T  
DSC1001AI1-024.5760T  
DSC1001AI1-030.0000T  
DSC1001AI5-050.0000T  
DSC1001AI1-008.0000T  
DSC1001AI1-032.7680T  
DSC1001AI2-002.0480T  
DSC1001AI1-033.3333T  
DSC1001AI2-065.5360T  
DSC1001AI2-032.7680T  
DSC1001AI1-003.5700T  
DSC1003AI2-075.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001AI5-028.6363T

DSC1001AI2-075.0000T

DSC1004AI1-012.0000T

DSC1004AI1-004.9152T

DSC1004AI1-007.3728T

DSC1001AI2-150.0000T

DSC1001AI1-007.3728T

DSC1001AI1-004.9152T

DSC1001AI1-012.0000T

DSC1003AI3-100.0000T

DSC1001AI2-033.3330T

DSC1001AI5-016.3840T

DSC1001AI5-010.0000T

DSC1001AI5-106.2500T

DSC1003AI5-003.6864T

DSC1003AI3-012.0000T

DSC1001AI1-014.3182T

DSC1001AI3-025.0000T

DSC1001AI3-030.0000T

DSC1001AI1-033.3330T

DSC1001AI1-024.5450T

DSC1001AI5-001.7000T

DSC1001AI5-014.7456T

DSC1001AI2-029.4912T

DSC1001AI3-100.0000T

DSC1001AI1-075.0000T

DSC1001AI2-129.6000T

DSC1001AI3-040.0000T

DSC1001AI2-066.6666T

DSC1001AI1-029.4912T

DSC1001AI5-002.0480T

DSC1001AI1-026.0000T

DSC1001AI1-016.3840T

DSC1001AI1-032.0000T

DSC1001AI5-003.6864T

DSC2311KI1-R0003

DSC2311KI2-R0003

DSC2311KI2-R0016

DSC2311KI2-R0045

DSC1123DI5-156.2500

DSC1123DI2-100.0000

DSC1121DI2-156.2500

DSC1101DI1-012.0000

DSC1101DI5-012.0000

DSC1101DI1-150.0000

DSC1101DI5-016.0000

DSC1101DI2-050.6880

DSA6011JL2B-025.0000TVAO

DSA6011JL2B-027.0000TVAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA6101JL2B-032K768TVAO  
DSA6101JL2B-049.5000TVAO  
DSA6111JL2B-024.0000TVAO  
DSA6111JL2B-025.0000TVAO  
DSA6111JL2B-027.0000TVAO  
DSA6331JL2AB-012.2880TVAO  
DSA6331JL2CB-024.0000TVAO  
DSA6001JL3B-024.5760TVAO  
DSA6011JL3B-012.0000TVAO  
DSA6101JL3B-012.2888TVAO  
DSA6101JL3B-024.5760TVAO  
DSA6101JL3B-027.0000TVAO  
DSA6101JL3B-037.1250TVAO  
DSA6101JL3B-060.0000TVAO  
DSA6101JL3B-087.0655TVAO  
DSA6102JL3B-037.1250TVAO  
DSA6102JL3B-087.0655TVAO  
DSA6112JL3B-054.0000TVAO  
DSA6301JL3AB-054.0000TVAO  
DSA6311JL3AB-054.0000TVAO  
DSA6101JL3B-027.0000BVAO  
DSA6101JL1B-020.0000TVAO  
DSC613PL3A-0106T  
DSC613PL3A-0106B  
DSC612PL2A-0132T  
DSC613PL2A-0131T  
DSC612PL2A-0130T  
DSC612PL3A-012YT  
DSC612PE3A-013KT  
DSC612PE3A-014VT  
DSC613PE1A-017QT  
DSC612PE3A-017RT  
DSC613PE2A-017QT  
DSC613PE1A-01CKT  
DSC612PL3A-01D5T  
DSC613PL2A-01DGT  
DSC612PL2A-01ERT  
DSC613PE2A-01KDT  
DSC613PE2A-01M2T  
DSC613PE2A-01KCT  
DSA612PL2A-01CSTVAO  
DSA612PL3A-01BHTVAO  
DSC612RL3A-010KT  
DSC612RL3A-010KB  
DSC613RL2A-0131T  
DSC613RE1A-0135T  
DSC613RE1A-0136T  
DSC612RL2A-0137T  
DSC612RL2A-013DT

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC612RL2A-013E1  
DSC612RL3A-0142T  
DSC612RE1A-014JT  
DSC613RL1A-0131T  
DSC1004CE1-050.0000  
DSC1004CE2-072.0000  
DSC8001CL2  
DSC8001CL5  
DSC1001CL5-050.0000  
DSC1001CL5-033.0000  
DSC1001CL5-060.0000  
DSC1001CL5-114.0000  
DSC1001CL1-100.0000  
DSC1001CL5-014.7456  
DSC1001CL5-016.0000  
DSC1001CL5-014.3181  
DSC1001CL5-010.0000  
DSC1001CE1-125.0000  
DSC1001CE5-148.0000  
DSC1001CE2-032.1100  
DSC1001CE1-022.1184  
DSC1001CL2-040.0000  
DSC1003CL2-066.0000  
DSC1001CL5-080.0000  
DSC1001CL5-100.0000  
DSC1001CE2-012.2880  
DSC1001CE2-003.5800  
DSC1001CL1-001.6000  
DSC1001CE1-027.0000  
DSC1001CE5-148.5000  
DSC1001CE2-022.5792  
DSC1001CL1-033.3333  
DSC1001CL1-048.0000  
DSC1001CE1-066.6666  
DSC1001CE2-012.0000  
DSC1001CL1-024.0000  
DSC1001CL2-030.0000  
DSC1001CE1-019.2000  
DSC1001CL1-003.2500  
DSC1001CL2-008.0000  
DSC1001CL2-025.5760  
DSC1001CE1-083.3300  
DSC1001CE2-032.0000  
DSC1001CE1-050.0000  
DSC1001CL5-006.7700  
DSC1001CL5-006.7900  
DSC1001CL5-013.5400  
DSC1001CL5-013.5800  
DSC1001CL5-050.3500



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CL5-001.6000  
DSC1001CL5-025.6000  
DSC1001CL5-011.0592  
DSC1001CE2-018.4320  
DSC1001CL5-012.8000  
DSC1001CL2-100.0000  
DSC1001CL2-054.0000  
DSC1004CE1-033.3333  
DSC1003CL2-025.0000  
DSC1001CE5-016.0000  
DSC1001CE1-008.0000  
DSC1001CE5-025.0000  
DSC1001CL5-048.0000  
DSC1001CE1-080.0000  
DSC1004CL5-016.0000  
DSC1001CE1-033.3300  
DSC1001CL2-024.5760  
DSC1001CL1-050.0000  
DSC1001CL2-014.7456  
DSC1001CL2-148.5000  
DSC1001CL2-016.0000  
DSC1001CE5-012.2880  
DSC1003CL2-027.0000  
DSC1004CL2-027.0000  
DSC1001CL5-016.3840  
DSC1001CE5-002.0000  
DSC1001CE5-008.0000  
DSC1001CE1-026.0000  
DSC1004CE1-025.6000  
DSC1001CL2-032.0000  
DSC1001CL2-033.3300  
DSC1001CL5-004.0000  
DSC1001CE1-033.3333  
DSC1001CL5-075.0000  
DSC1003CL5-050.0000  
DSC1003CL2-024.0000  
DSC1001CE2-060.0000  
DSC1001CL1-002.0000  
DSC1000CL3-PROG  
DSC1000CL5-PROG  
DSC1001CL5-018.4320  
DSC1001CL3-012.2880  
DSC1001CL5-029.4912  
DSC1001CL2-064.0000  
DSC1001CL2-003.1250  
DSC1001CL2-029.4912  
DSC1001CL2-066.6660  
DSC1001CL2-125.0000  
DSC1001CL5-003.6864

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CL3-080.0000  
DSC1001CL3-033.0000  
DSC1001CE1-004.0960  
DSC6111JI2B-024.0000T  
DSC6001JI3B-439K000T  
DSC6101JI3B-439K000T  
DSC6011JI1B-025.0000T  
DSC6013JI1B-025.0000T  
DSC6112JI1B-050.0000T  
DSC6101JI2B-027.0000T  
DSC6011JI2B-025.0000T  
DSC6001JI2B-025.0000T  
DSC6001JI2B-027.0000T  
DSC6001JI1B-025.0000T  
DSC6011JI1B-008.0000T  
DSC6111JI1B-098.3040T  
DSC6011JI3B-001.0640T  
DSC6111JI2B-100K000T  
DSC6111JI3B-100.0000T  
DSC6001JI3B-004K000T  
DSC6011JI3B-032K768T  
DSC6013JI1B-768K000T  
DSC6001JI1B-460K800T  
DSC6331JI2BB-025.0000T  
DSC6331JI2IB-025.0000T  
DSC6001JI2B-001.8432T  
DSC6011JI2B-012.0000T  
DSC6101JI2B-100.0000T  
DSC6101JI2B-024.0000T  
DSC6003JI2B-025.0000T  
DSC6011JI1B-050.0000T  
DSC6331JI2EB-025.0000T  
DSC6001JI2B-116K000T  
DSC6101JI2B-050.0000T  
DSC6001JI2B-068.1818T  
DSC6331JI2BB-024.0000T  
DSC6013JI1B-012.0000T  
DSC6001JI1B-012.0000T  
DSC6001JI2B-032K000T  
DSC6101JI3B-100.0000T  
DSC6001JI3B-024.0000T  
DSC6003JI2B-032K768T  
DSC6023JI3B-019HT  
DSC6011JI1B-014.7456T  
DSC6003JI2B-004.5160T  
DSC6003JI2B-008.0000T  
DSC6003JI2B-027.0950T  
DSC6003JI2B-063.2220T  
DSC6011JI2B-016.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6013JI1B-032K768T  
DSC6001JI3B-014.1875T  
DSC6101JI3B-485K000T  
DSC6013JI3B-032.0000T  
DSC6101JI2B-020.0000T  
DSC6001JI2B-024.0000T  
DSC6003JI2B-024.0000T  
DSC6013JI1B-300K000T  
DSC6111JI3B-012.0000T  
DSC6101JI1B-007K085T  
DSC6121JI2B-01BBT  
DSC6001JI1B-032K768T  
DSC6102JI3B-001.6800T  
DSC6003JI2B-307K000T  
DSC6331JI2KB-025.0000T  
DSC6001JI2B-032K768T  
DSC6001JI2B-012.2880T  
DSC6011JI3B-048K500T  
DSC6331JI1DB-025.0000T  
DSC6001JI1B-010.0000T  
DSC6011JI1B-001.0000T  
DSC6001JI3B-025.0000T  
DSC6101JI2B-040K000T  
DSC6331JI2CB-027.0000T  
DSC6331JI2CB-024.0000T  
DSC6101JI2B-012.2880T  
DSC1121BI2-016.3840  
DSC1121BI2-020.0000  
DSC1121BI2-131.0720  
DSC1103BI2-050.0000  
DSC1101BI2-125.0031  
DSC1102BI1-010.0000  
DSC1123BI5-148.5000  
DSC1123BI5-010.0000  
DSC1124BI2-027.0000  
DSC1101BI5-010.0000  
DSC1122BI2-125.0000  
DSC1123BI2-156.0000  
DSC1122BI1-025.0000  
DSC1121BI2-008.0000  
DSC1123BI2-034.0000  
DSC1101BI3-025.0000  
DSC1101BI2-125.0037  
DSC1124BI1-027.0000  
DSC1121BI5-022.5792  
DSC1121BI5-024.5760  
DSC1123BI2-125.0037  
DSC1123BI5-125.0000  
DSC1121BI3-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1121BI5-024.0000  
DSC1121BI2-012.0000  
DSC1123BI3-050.0000  
DSC1101BI2-008.0000  
DSC1103BI2-062.5000  
DSC1101BI5-016.0000  
DSC1101BI5-012.0000  
DSC1101BI5-020.0000  
DSC1123BI2-010.0000  
DSC1121BI5-045.1854  
DSC1121BI5-049.1520  
DSC1104BI1-027.0000  
DSC1101BI3-013.5600  
DSC1101BI2-027.1200  
DSC1124BI3-027.0000  
DSC1121BI1-020.0000  
DSC1101BI1-145.2000  
DSC1103BI1-156.2500  
DSC1122BI3-166.6000  
DSC1121BI5-125.0000  
DSC1121BI5-025.6000  
DSC1121BI2-040.6800  
DSC1123BI3-080.0000  
DSC1103BI2-235.0000  
DSC1123BI1-148.5000  
DSC1103BI5-148.5000  
DSC1123BI5-040.0000  
DSC1103BI2-156.2500  
DSC1101AI2-148.5000  
DSC1121AI2-156.2500  
DSC8104AI2  
DSC8102AI2  
DSC8103AI2  
DSC1101CL2-040.0000  
DSC1121CL1-024.0000  
DSC1121CL1-028.6364  
DSC1121CL1-027.0000  
DSC1103CL5-150.0000  
DSC1103CE2-156.2500  
DSC1101CE2-045.1584  
DSC1101CE2-049.1520  
DSC1104CE2-027.0000  
DSC1123CL5-433.0000  
DSC1121CE1-025.6000  
DSC1121CL5-040.0000  
DSC1121CL5-080.0000  
DSC1101CL1-125.0000  
DSC1124CE2-100.0000  
DSC1124CE5-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1100CL5-PROG

DSC1100CL5-PROG

DSC1101CL5-030.0000

DSC1123CL5-322.2656

DSC1101CE5-025.0000

DSC1101CE2-025.0000

DSC1103CL2-233.3333

DSC1101CE1-024.5790

DSC1101CE1-022.5792

DSC1101CE1-011.2896

DSC1101CL5-052.5000

DSC1101CE1-024.5760

DSC1103CL2-333.3333

DSC1123CE2-100.0000

DSC1101CE5-024.0000

DSC1101CE5-100.0000

DSC1101CE5-045.1854

DSC1101CE5-049.1520

DSC1103CL2-125.0000

DSC1103CL2-052.0000

DSC1103CL5-033.3330

DSC1103CL5-075.0300

DSC1123CL2-333.3333

DSC1101CE5-022.5792

DSC1101CE5-024.5760

DSC1101CL3-025.0000

DSC1121CL5-033.3333

DSC1123CL2-200.0000

DSC1123CL3-040.0000

DSC1123CL1-287.0000

DSC1121CE5-002.4880

DSC1101CE1-100.0000

DSC1101CE1-054.0000

DSC1122CL1-135.0000

DSC1121CL1-050.0000

DSC1101CL2-025.0000

DSC1101CL2-050.0000

DSC1101CL2-100.0000

DSC1101CL2-125.0000

DSC1123CE3-422.3000

DSC1103CL1-075.0000

DSC1123CL2-156.2500

DSC1123CL1-100.0000

DSC1123CL2-100.0000

DSC1124CL3-100.0000

DSC1103CL1-200.0000

DSC1103CL1-100.0000

DSC1103CL1-125.0000

DSC1103CL1-150.0000

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103CL1-026.0000  
DSC1103CL1-027.0000  
DSC1103CL3-093.4400  
DSC1103CL3-100.0000  
DSC1103CL3-125.0000  
DSC400-2222Q0022KE1T  
DSC1121AI1-025.0000T  
DSC1103AI5-125.0000T  
DSC1121AI2-024.0000T  
DSC1121AI2-025.0000T  
DSC1121AI2-026.0000T  
DSC1121AI2-029.4912T  
DSC1121AI2-048.0000T  
DSC1121AI2-050.0000T  
DSC1121AI2-125.0000T  
DSC1121AI1-155.5200T  
DSC1121AI2-156.2540T  
DSC1121AI5-020.0000T  
DSC1122AI1-150.0000T  
DSC1122AI1-155.5200T  
DSC1122AI2-106.2500T  
DSC1122AI2-150.0000T  
DSC1122AI2-156.2500T  
DSC1122AI2-156.2539T  
DSC1122AI2-425.0000T  
DSC1122AI5-155.5200T  
DSC1122AI5-156.2500T  
DSC1123AI1-100.0000T  
DSC1123AI5-175.0000T  
DSC1123AI1-125.0000T  
DSC1004BI5-121.5000  
DSC1001BI2-003.1250  
DSC1001BI5-066.6660  
DSC1004BI5-005.0000  
DSC1001BI1-099.0000  
DSC1001BI2-099.0000  
DSC1001BI5-040.9600  
DSC1001BI2-003.6864  
DSC1001BI3-020.0000  
DSC1001BI2-040.6800  
DSC1001BI2-033.3300  
DSA1001BI2-125.0000VAO  
DSC1001DI5-133.0000T  
DSC1001DI1-001.8432  
DSC1001DI1-003.6864  
DSC1001DI1-005.0000  
DSC1001DI1-004.0000  
DSC1001DI1-010.0000  
DSC1001DI1-012.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DI1-013.3333  
DSC1001DI1-014.7456  
DSC1001DI1-016.3840  
DSC1001DI1-020.0000  
DSC1001DI1-024.0000  
DSC1001DI1-008.0000  
DSC1001DI1-025.0000  
DSC1001DI1-026.0000  
DSC1001DI1-024.5760  
DSC1001DI1-033.3300  
DSC1001DI1-033.3330  
DSC1001DI1-033.3333  
DSC1001DI1-048.0000  
DSC1001DI1-050.0000  
DSC1001DI1-072.0000  
DSC1001DI1-098.3040  
DSC1001DI1-100.0000  
DSC1001DI1-125.0000  
DSC1001DI1-133.0000  
DSC1001DI2-001.0000  
DSC1001DI2-003.6864  
DSC1001DI2-005.0196  
DSC1001DI2-005.3125  
DSC1001DI2-008.0000  
DSC1001DI2-009.6000  
DSC1001DI2-012.0000  
DSC1001DI2-014.7456  
DSC1001DI2-016.0000  
DSC1001DI2-019.2000  
DSC1001DI2-020.0000  
DSC1001DI2-024.0000  
DSC1001DI2-024.5760  
DSC1001DI2-025.0000  
DSC1001DI2-026.0000  
DSC1001DI2-027.0000  
DSC1001DI2-032.0000  
DSC1001DI2-033.3300  
DSC1001DI2-033.3333  
DSC1001DI2-037.1250  
DSC1001DI2-022.0000  
DSC1001DI2-038.4000  
DSC1001DI2-048.0000  
DSC1001DI2-024.5455  
DSC1001DI2-050.0000  
DSC1001DI2-066.6600  
DSC1001DI2-022.5792  
DSC1001DI2-080.0000  
DSC1001DI2-086.4000  
DSC1001DI2-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DI2-125.0000  
DSC1001DI2-040.0000  
DSC1001DI5-002.4576  
DSC1001DI5-007.3728  
DSC1001DI5-012.0000  
DSC1001DI5-016.0000  
DSC1001DI5-019.2000  
DSC1001DI5-020.0000  
DSC1001DI5-025.0000  
DSC1001DI5-026.0000  
DSC1001DI5-027.0000  
DSC1001DI2-072.0000  
DSC1001DI2-074.2500  
DSC1001DI5-032.2500  
DSC1001DI5-033.3333  
DSC1001DI5-038.4000  
DSC1001DI5-100.0000  
DSC1001DI5-125.0000  
DSC1001DI5-133.0000  
DSC1001DI5-150.0000  
DSC1004DI1-024.0000  
DSC1004DI2-025.0000  
DSC1001DI5-002.0480  
DSC1001DI2-047.3885  
DSC1001DI1-038.4000  
DSC1001DI2-026.6000  
DSC1001DI1-066.0000  
DSC1001DI5-008.0000  
DSC1001DI5-047.3885  
DSC1001DI5-013.3333  
DSC1001DI5-022.5792  
DSC1001DI5-030.0000  
DSC1001DI2-024.5454  
DSC6301JE2AB-050.0000T  
DSC6001JE1B-020.0000T  
DSC6101JE1B-030.0000T  
DSC6101JE1B-033.0000T  
DSC6101JE3B-032K768T  
DSC6101JE1B-022.4000T  
DSC6001JE2B-016.0000T  
DSC6301JE2AB-024.0000T  
DSC6121JE2B-01P0T  
DSC6152JL3B-027.0000T  
DSA6311JL1AB-028.6364TV01  
DSA6331JL2CB-012.2880TVAO  
DSA6101JL1B-019.2000TVAO  
DSA6101JL1B-045.0000TVAO  
DSA6102JL1B-008.0000TVAO  
DSA6311JL1AB-054.0000TVAO



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA6351JL1CB-027.0000TVAO

DSA6001JL2B-008.0000TVAO

DSA6001JL2B-012.2880TVAO

DSA6001JL2B-025.0000TVAO

DSA6001JL2B-027.0000TVAO

DSA6011JL2B-024.0000TVAO

DSC8101CI2

DSC8101CI5

DSC8102CI2

DSC8102CI5

DSC8103CI2

DSC8103CI5

DSC8104CI2

DSC8104CI5

DSC8121CI1

DSC8121CI2

DSC8121CI5

DSC8122CI2

DSC8123CI2

DSC8123CI5

DSC8124CI2

DSC8124CI5

DSC1121CI1-050.0000

DSC1121CI5-016.6667

DSC1121CI5-025.0000

DSC1121CI5-027.0000

DSC1121CI5-066.0000

DSC1121CI5-117.0000

DSC1103CI1-122.8800

DSC1121CI2-027.0000

DSC1123CI1-150.0000

DSC1101CI1-125.0000

DSC1102CI5-150.0000

DSC1123CI1-122.8800

DSC1123CI2-148.5000

DSC1104CI5-125.0000

DSC1121CI2-066.6667

DSC1124CI2-156.2500

DSC1102CI1-050.0000

DSC1102CI1-156.2500

DSC1102CI1-025.0000

DSC1122CI5-100.0000

DSC1102CI5-156.2500

DSC1124CI5-133.0000

DSC1124CI5-133.3300

DSC1104CI2-316.0000

DSC1103CI5-125.0000

DSC1101CI1-008.0000

DSC1101CI1-010.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123CI2-035.0000  
DSC1101CI5-125.0000  
DSC1122CI5-050.0000  
DSC1121CI2-155.5200  
DSC1122CI2-212.5000  
DSC1123CI2-060.0000  
DSC1123CI2-175.0000  
DSC1103CI5-045.0000  
DSC1123CI1-050.0000  
DSC1123CI5-096.0000  
DSC1123CI2-086.0000  
DSC1101CI5-100.0000  
DSC1124CI1-027.0000  
DSC1104CI1-027.0000  
DSC1123CI2-050.0000  
DSC1101CI5-027.0000  
DSC1103CI5-180.0000  
DSC1121CI2-008.0000  
DSC1101CI5-026.0000  
DSC1103CI5-156.2500  
DSC1103CI5-016.0000  
DSC1103CI2-106.2500  
DSC1103CI2-074.2500  
DSC1103CI2-050.0000  
DSC1102CI1-135.0000  
DSC1123CI5-233.2090  
DSC1104CI2-027.0000  
DSC1123CI5-150.0000  
DSC1123CI2-270.0000  
DSC1123CI3-148.5000  
DSC1122CI5-433.9200  
DSC1103CI5-150.0000  
DSC1123CI2-322.2650  
DSC1123CI2-266.5000  
DSC1121CI5-026.0000  
DSC1103CI3-200.0000  
DSC1103CI3-125.0000  
DSC1103CI5-250.0000  
DSC1103CI2-250.0000  
DSC1103CI2-300.0000  
DSC1124CI2-027.0000  
DSC1101CI1-012.0000  
DSC1102CI2-400.0000  
DSC1101CI2-133.0000  
DSC1101CI5-032.0000  
DSC1101CI2-032.0000  
DSC1104CI2-100.0000  
DSC1121CI2-080.0000  
DSC1124CI1-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101CI1-050.0000  
DSC1101CI2-066.6667  
DSC1101CI2-125.0000  
DSC1123CI2-266.5250  
DSC1101CI1-018.7500  
DSC1103CI2-052.0000  
DSC1103CI5-075.0300  
DSC1103CI5-033.3330  
DSC1103CI2-024.0000  
DSC1103CI2-025.0000  
DSC1123CI2-125.0987  
DSC1101CI5-048.0000  
DSC1102CI2-148.5000  
DSC1101CI5-072.0000  
DSC1123CI2-160.0000  
DSC1103CI1-026.0000  
DSC1103CI1-027.0000  
DSC1123CI2-180.0000  
DSC1123CI2-265.5250  
DSC1123CI2-144.0000  
DSC1123CI2-072.0000  
DSC1102CI2-156.2500  
DSC1103CI5-026.0000  
DSC1103CI5-027.0000  
DSC1101CI1-085.2070  
DSC1101CI5-024.0000  
DSC1101CI2-020.0000  
DSC1103CI5-103.1250  
DSC1103CI2-103.1250  
DSC1103CI3-100.0000  
DSC1103CI3-250.0000  
DSC1104CI3-027.0000  
DSC1102CI1-108.0000  
DSC1121CI2-045.1580  
DSC1121CI2-049.1520  
DSC1121CI2-045.1584  
DSC1121CI2-014.3181  
DSC1121CI5-045.1584  
DSC1121CI5-024.0000  
DSC1123CI1-025.0000  
DSC1101CI2-060.0000  
DSC1103CI2-072.0000  
DSC1101CI2-036.0000  
DSC1123CI2-360.0000  
DSC1123CI2-010.0000  
DSC1103CI3-060.0000  
DSC1103CI3-150.0000  
DSC1103CI3-175.0000  
DSC1103CI1-150.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103CI2-066.0000  
DSC1102CI5-020.0000  
DSC1101CI5-016.0000  
DSC1101CI5-008.0000  
DSC1121CI2-066.0000  
DSC1124CI2-133.3300  
DSC1103CI2-133.3300  
DSC1102CI1-212.5000  
DSC1103CI1-300.0000  
DSC1104CI2-200.0000  
DSC1101CI5-157.2864  
DSC1101CI1-024.0000  
DSC1124CI2-125.0000  
DSC1123CI5-066.6670  
DSC1123CI2-148.3516  
DSC612RI3A-010JT  
DSC613RI3A-010UT  
DSC612RI3A-010GB  
DSC612RI3A-010JB  
DSC613RI3A-010UB  
DSC612RI1A-012MT  
DSC613RI2A-012ST  
DSC612RI2A-012PT  
DSC612RI3A-012VT  
DSC613RI3A-012WT  
DSC612RI1A-0133T  
DSC613RI2A-0134T  
DSC613RI2A-013GT  
DSC612RI2A-013HT  
DSC613RI3A-014CT  
DSC612RI1A-0159T  
DSC613RI2A-015HT  
DSC613RI2A-016PT  
DSC612RI1A-016QT  
DSC613RI2A-017CT  
DSC612RI1A-017MT  
DSC612RI3A-019CT  
DSC612RI2A-01A0T  
DSC612RI2A-01A2T  
DSC612RI2A-01A3T  
DSC613RI3A-016PT  
DSC613RI3A-01A4T  
DSC612RI1A-01B2T  
DSC612RI2A-01B2T  
DSC613RI2A-01BCT  
DSC612RI3A-01CJT  
DSC612RI2A-01CMT  
DSC612RI1A-01DYT  
DSC613RI2A-01G0T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DE5-019.2000  
DSC1001DL1-008.0000  
DSC8003DL2  
DSC8003DL5  
DSC1001DE2-024.0000  
DSC1001DL1-027.0000  
DSC1001DL1-025.0000  
DSC1001DL2-001.0000  
DSC1001DL2-001.4850  
DSC1001DL2-008.0000  
DSC1001DL2-012.0000  
DSC1001DL2-013.5600  
DSC1001DL2-020.0000  
DSC1001DL2-024.0000  
DSC1001DL2-025.0000  
DSC1001DL2-027.0000  
DSC1001DL2-030.0000  
DSC1001DL2-033.3333  
DSC1001DL2-032.0000  
DSC1001DL5-001.0000  
DSC1001DL5-001.8432  
DSC1001DL5-002.0000  
DSC1001DL2-050.0000  
DSC1001DL5-008.0000  
DSC1001DL5-007.3728  
DSC1001DL5-016.0000  
DSC1001DL5-010.0000  
DSC1001DL5-020.0000  
DSC1001DL5-024.0000  
DSC1001DL5-025.0000  
DSC1001DL5-027.0000  
DSC1001DL5-030.0000  
DSC1001DL5-031.2500  
DSC1001DL5-054.0000  
DSC1001DL5-026.0000  
DSC1001DL5-100.0000  
DSC1003DE1-040.0000  
DSC1001DL5-033.0000  
DSC1003DL2-008.0000  
DSC1001DL5-048.0000  
DSC1001DL5-050.0000  
DSC1003DL5-020.0000  
DSC1003DL5-100.0000  
DSC1003DL5-125.0000  
DSC1003DL5-148.5000  
DSC8001DL2  
DSC8001DL5  
DSC1001DL5-015.3600  
DSC1003DL1-125.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003DL2-025.0000  
DSC1003DL5-025.0000  
DSC1001DL5-125.0000  
DSC1001DL5-080.0000  
DSC1001DE2-020.0000  
DSC1003DL2-070.0000  
DSC1001DL5-010.2000  
DSC1001DL2-037.1250  
DSC1001DE1-040.0000  
DSC1001DE1-050.0000  
DSC1001DL2-150.0000  
DSC1001DL5-011.0592  
DSC1001DL2-090.0000  
DSC1001DL5-012.0000  
DSC1001DL5-004.0000  
DSC1001DE1-025.0000  
DSC1001DL5-133.3330  
DSC1001DL1-010.0000  
DSC1001DL5-019.2000  
DSC1001DL5-033.3330  
DSC1001DL5-075.0000  
DSC1001DL2-072.0000  
DSC1003DL2-100.0000  
DSC1001DL2-087.0655  
DSC1001DE5-018.4320  
DSC1001DL1-080.0000  
DSC1001DL2-003.9000  
DSC1001DL2-013.5000  
DSC1001DL2-049.5000  
DSC1001DL2-074.2500  
DSC1001DL5-128.0000  
DSC1003DE1-024.0000  
DSC1001DL1-024.0000  
DSC1001DL5-024.5760  
DSC1001DL2-040.0000  
DSC1001DL1-001.8432  
DSC1001DL2-001.8432  
DSC1001DL1-033.3333  
DSC1001DE1-075.0000  
DSC1001DE2-100.0000  
DSC1001DL2-016.0000  
DSC1001DL1-025.2000  
DSC1004DL5-040.0000  
DSC1001DE1-033.3333  
DSC1001DL5-040.0000  
DSC1001DE1-019.2000  
DSC1001DL2-007.3728  
DSC1001DL5-072.0000  
DSC1003DL2-080.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DL5-012.2880  
DSC1003DL1-027.0000  
DSC1004DL1-027.0000  
DSC1001DE2-038.4000  
DSC1001DE1-013.0000  
DSC1001DL2-012.2880  
DSC1001DL2-125.0000  
DSC1001DL2-004.0000  
DSC1001DL1-016.0000  
DSC1001DL2-023.0000  
DSC1001DE1-020.0000  
DSC1001DL2-026.6500  
DSC1001DL5-014.3181  
DSC1001DE2-008.0000  
DSC1001DE2-012.0000  
DSC1001DE2-027.0000  
DSC1001DE2-025.0000  
DSC1001DL5-016.7722  
DSC1004DL1-025.0000  
DSC1004DL1-033.0000  
DSC1001DL2-048.0000  
DSC1001DL2-066.6700  
DSC1001DE1-024.3050  
DSC1001DL2-002.0000  
DSC1001DL1-004.0960  
DSC1001DL2-049.1520  
DSC1001DL2-045.1584  
DSC1001DE5-037.4000  
DSC1001DL5-096.0000  
DSC1001DL2-066.0000  
DSC1003DL5-019.2000  
DSC1001DE5-012.0000  
DSC1001DL2-026.0000  
DSC1001DL2-019.2000  
DSC1003DL1-033.3333  
DSC1003DL1-024.5454  
DSC1004DL2-072.0000  
DSC1001DE2-120.0000  
DSC1004DL2-025.0000  
DSC1000DL3-PROG  
DSC1000DL5-PROG  
DSC1001DL2-054.0000  
DSC1001DL3-027.0000  
DSC1001DL3-024.0000  
DSC1001DL5-016.3840  
DSC1001DL2-016.3690  
DSC1001DL2-061.2500  
DSC1003DL2-033.3333  
DSC1001DL5-018.4320

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DL5-033.3333

DSC1001DL2-003.6864

DSC1001DL5-003.6864

DSC1001DE2-001.0000

DSC1001DE2-090.0000

DSC1004DL5-025.0000

DSC1001DE2-022.0000

DSC1001DL5-037.1250

DSC1001DL5-150.0000

DSC1001DL2-033.3300

DSC1001DE5-025.0000

DSC1001DE1-024.5760

DSC1001DL5-047.0016

DSC1001DL1-005.0196

DSC1001DL2-005.0196

DSC1001DL5-005.0196

DSC1001DE3-080.0000

DSC1001DL1-150.0000

DSC1001DE3-008.0000

DSC1001DE5-150.0000

DSC1003DL1-025.0000

DSC1003DL1-016.0000

DSC1003DL1-050.0000

DSC1003DL1-048.0000

DSC1003DL2-024.0000

DSC1004DE1-026.0000

DSC1001DL1-050.0000

DSC1001DE5-049.1520

DSC1001DE5-045.1584

DSC1001DL1-040.0000

DSC1001DL5-064.0000

DSC1004DE2-025.0000

DSC1001DL5-028.6363

DSC1001DL5-006.0000

DSC1001DL1-033.3330

DSC1001DL5-029.4912

DSC1001DL1-004.0000

DSC1001DL2-100.0000

DSC1001DL5-032.4000

DSC1001DL5-049.5000

DSC1001DL2-012.5000

DSC1001DL1-012.5000

DSC1001DL3-125.0000

DSC1001DL5-026.5980

DSC1001DL5-120.0000

DSC1001DL5-087.0655

DSA1001DL1-008.0000VAO

DSA1001DL1-010.2400VAO

DSA1001DL1-016.6666VAO



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA100IDLT-020.0000VAO

DSC6101HA2B-072.0000

DSC6003HA3B-016.0000

DSC6001HA3B-PROG

DSC6003HA3B-PROG

DSC6101HA3B-PROG

DSC6003HA1B-020.0000

DSC6101HA2B-072.5000

DSC6001HA2B-029.4912

DSC6101HA3B-024.0000

DSC6111HA3B-024.0000

DSC6111HA2B-024.0000

DSC6332HA3AB-002.4576

DSC6332HA3AB-031.9488

DSC6301HA1FB-020.0000

DSC6021HA3B-01D0

DSC6003HA3B-032K768

DSC6011HA1B-032K768

DSC6011HA2B-032K768

DSC6011HA2B-025.0000

DSC6011HA2B-008.0000

DSC6013HA2B-048.0000

DSC6011HA2B-029.4912

DSA6101HA1B-005.0000VAO

DSA6101HA1B-008.0000VAO

DSA6101HA1B-027.0000VAO

DSA6301HA1AB-027.0000VAO

DSA6001HA2B-029.4912VAO

DSA6122HA3B-01ECVAO

DSC6001MA2B-020.0000

DSC6003MA3B-032K768

DSC6101MA3B-019.2000

DSC6101MA3B-027.0000

DSC6001MA3B-PROG

DSC6003MA3B-PROG

DSC6101MA3B-PROG

DSC6331MA1AB-027.0000

DSC6111MA3B-050.0000

DSC6023MA1B-015S

DSC6101MA2B-020.0000

DSC6111MA1B-033.0000

DSC6331MA1AB-025.0000

DSC6101MA3B-016.6666

DSC6111MA1B-033.3300

DSC6101MA3B-026.0000

DSC6011MA3B-006K000

DSC6011MA3B-022K000

DSC6011MA3B-002K000

DSC6011MA3B-020.0000

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6101MA1B-008.0000

DSC6011MA1B-032K768

DSC6011MA3B-025.0000

DSA6001MA1B-013.5600VAO

DSA6101MA1B-033.3300VAO

DSA6121MA1B-01AEVAO

DSA6331MA1AB-025.0000VAO

DSA6331MA1AB-027.0000VAO

DSA6331MA1BB-027.0000VAO

DSA6331MA1DB-027.0000VAO

DSA6101MA2B-008.0000VAO

DSA6101MA2B-010.0000VAO

DSA6311MA2CB-008.0000VAO

DSA6011MA3B-002K000VAO

DSA6011MA3B-020.0000VAO

DSC612NA2A-010J

DSC613NA2A-018Y

DSC612NA1A-01H5

DSC613NA1A-017Q

DSC613NA1A-01KC

DSC613NA1A-01KD

DSC6101JA2B-025.0000

DSC6001JA3B-020.0000

DSC6331JA3BB-004.0000

DSC6331JA3AB-004.0000

DSC6001JA3B-PROG

DSC6003JA3B-PROG

DSC6101JA3B-PROG

DSC6311JA1AB-027.0000

DSC6331JA1CB-054.0000

DSC6311JA1BB-027.0000

DSC6001JA3B-580K000

DSC6311JA1AB-054.0000

DSC6331JA2BB-025.0000

DSC6331JA2IB-025.0000

DSC6331JA2GB-025.0000

DSC6331JA2HB-025.0000

DSC6021JA2B-01AR

DSC6331JA2AB-025.0000

DSC6331JA2DB-024.5760

DSC6011JA3B-016K384

DSC6311JA1AB-045.0000

DSC6311JA1BB-045.0000

DSC6311JA1AB-019.2000

DSC6311JA1BB-019.2000

DSC6001JA2B-016.0000

DSC6102JA1B-125K000

DSC6102JA1B-010K000

DSC6101JA2B-050.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6331JA2AB-004.0000  
DSC6331JA2BB-004.0000  
DSC400-2222Q0022KE2T  
DSC400-0303Q0092KE1T  
DSC400-0303Q0092KE2T  
DSC400-3333Q0093KE1T  
DSC400-3333Q0093KE2T  
DSC400-3333Q0094KE1T  
DSC400-3333Q0094KE2T  
DSC400-4334Q0022KE1T  
DSC400-4334Q0022KE2T  
DSC400-0444Q0009KE1T  
DSC400-0444Q0009KE2T  
DSC400-1111Q0095KE1T  
DSC400-1111Q0095KE2T  
DSC400-0101Q0096KE1T  
DSC400-0101Q0096KE2T  
DSC400-3331Q0097KE1T  
DSC400-3331Q0097KE2T  
DSC400-3331Q0098KE1T  
DSC400-3331Q0098KE2T  
DSC400-3333Q0099KE1T  
DSC400-3333Q0099KE2T  
DSC400-3133Q0100KE1T  
DSC400-3133Q0100KE2T  
DSC400-0103Q0102KE1T  
DSC400-0103Q0102KE2T  
DSC400-0401Q0103KE1T  
DSC400-0401Q0103KE2T  
DSC400-2222Q0104KE1T  
DSC400-2222Q0104KE2T  
DSC400-2222Q0105KE1T  
DSC400-2222Q0105KE2T  
DSC400-3333Q0104KE1T  
DSC400-3333Q0104KE2T  
DSC400-0202Q0106KE1T  
DSC400-0202Q0106KE2T  
DSC400-0202Q0107KE1T  
DSC400-0202Q0107KE2T  
DSC400-0202Q0108KE1T  
DSC400-0202Q0108KE2T  
DSC400-0202Q0109KE1T  
DSC400-0202Q0109KE2T  
DSC400-1111Q0110KE1T  
DSC400-1111Q0110KE2T  
DSC400-1111Q0111KE1T  
DSC400-1111Q0111KE2T  
DSC400-4111Q0112KE1T  
DSC400-4111Q0112KE2T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-4334Q0023KE1T  
DSC400-4334Q0023KE2T  
DSC400-1133Q0113KE1T  
DSC400-1133Q0113KE2T  
DSC400-0101Q0114KE1T  
DSC400-0101Q0114KE2T  
DSC400-0101Q0115KE1T  
DSC400-0101Q0115KE2T  
DSC400-0111Q0116KE1T  
DSC400-0111Q0116KE2T  
DSC400-0111Q0117KE1T  
DSC400-0111Q0117KE2T  
DSC400-2222Q0118KE1T  
DSC400-2222Q0118KE2T  
DSC400-0244Q0009KE1T  
DSC400-0244Q0009KE2T  
DSC400-0101Q0119KE1T  
DSC400-0101Q0119KE2T  
DSC400-1111Q0120KE1T  
DSC400-1111Q0120KE2T  
DSC400-0111Q0026KE1T  
DSC400-0111Q0026KE2T  
DSC400-1111Q0121KE1T  
DSC400-1111Q0121KE2T  
DSC400-1114Q0122KE1T  
DSC400-1114Q0122KE2T  
DSC400-0321Q0123KE1T  
DSC400-0321Q0123KE2T  
DSC400-3333Q0124KE1T  
DSC400-3333Q0124KE2T  
DSC400-1331Q0125KE1T  
DSC400-1331Q0125KE2T  
DSC400-1333Q0126KE1T  
DSC400-1333Q0126KE2T  
DSC400-0223Q0127KE1T  
DSC400-0223Q0127KE2T  
DSC400-0133Q0128KE1T  
DSC400-0133Q0128KE2T  
DSC400-0331Q0128KE1T  
DSC400-0331Q0128KE2T  
DSC400-0101Q0129KE1T  
DSC400-0101Q0129KE2T  
DSC400-3333Q0130KE1T  
DSC400-3333Q0130KE2T  
DSC400-3111Q0131KE1T  
DSC400-3111Q0131KE2T  
DSC400-4111Q0131KE1T  
DSC400-4111Q0131KE2T  
DSC400-1111Q0132KE1T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-1111Q0132KE2T  
DSC400-0311Q0026KE1T  
DSC400-0311Q0026KE2T  
DSC400-0211Q0026KE1T  
DSC400-0211Q0026KE2T  
DSC400-1111Q0133KE1T  
DSC400-1111Q0133KE2T  
DSC400-1121Q0134KE1T  
DSC400-1121Q0134KE2T  
DSC400-1411Q0135KE1T  
DSC400-1411Q0135KE2T  
DSC400-0212Q0136KE1T  
DSC400-0212Q0136KE2T  
DSC400-1111Q0137KE1T  
DSC400-1111Q0137KE2T  
DSC400-0111Q0138KE1T  
DSC400-0111Q0138KE2T  
DSC400-0111Q0139KE1T  
DSC400-0111Q0139KE2T  
DSC400-0144Q0140KE1T  
DSC400-0144Q0140KE2T  
DSC400-1221Q0141KE1T  
DSC400-1221Q0141KE2T  
DSC400-0434Q0009KE1T  
DSC400-0434Q0009KE2T  
DSC400-0313Q0136KE1T  
DSC400-0313Q0136KE2T  
DSC400-1111Q0142KE1T  
DSC400-1111Q0142KE2T  
DSC400-1111Q0143KE1T  
DSC400-1111Q0143KE2T  
DSC400-0333Q0144KE1T  
DSC400-0333Q0144KE2T  
DSC400-3333Q0145KE1T  
DSC400-3333Q0145KE2T  
DSC400-3333Q0023KE1T  
DSC400-3333Q0023KE2T  
DSC400-3333Q0146KE1T  
DSC400-3333Q0146KE2T  
DSC400-1111Q0147KE1T  
DSC400-1111Q0147KE2T  
DSC400-1111Q0078KE1T  
DSC400-1111Q0078KE2T  
DSC400-0323Q0009KE1T  
DSC400-0323Q0009KE2T  
DSC400-1111Q0148KE1T  
DSC400-1111Q0148KE2T  
DSC400-1313Q0094KE1T  
DSC400-1313Q0094KE2T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-1111Q0149KE1T  
DSC400-1111Q0149KE2T  
DSC400-1333Q0078KE1T  
DSC400-1333Q0078KE2T  
DSC400-1111Q0150KE1T  
DSC400-1111Q0150KE2T  
DSC400-3333Q0151KE1T  
DSC400-3333Q0151KE2T  
DSC400-4144Q0152KE1T  
DSC400-4144Q0152KE2T  
DSC400-3331Q0153KE1T  
DSC400-3331Q0153KE2T  
DSC400-2222Q0031KE1T  
DSC400-2222Q0031KE2T  
DSC400-0333Q0154KE1T  
DSC400-0333Q0154KE2T  
DSC400-0111Q0155KE1T  
DSC400-0111Q0155KE2T  
DSC400-3133Q0156KE1T  
DSC400-3133Q0156KE2T  
DSC400-0133Q0157KE1T  
DSC400-0133Q0157KE2T  
DSC400-3113Q0158KE1T  
DSC400-3113Q0158KE2T  
DSC400-3113Q0159KE1T  
DSC400-3113Q0159KE2T  
DSC400-1111Q0160KE1T  
DSC400-1111Q0160KE2T  
DSC400-0333Q0162KE1T  
DSC400-0333Q0162KE2T  
DSC400-3333Q0163KE1T  
DSC400-3333Q0163KE2T  
DSA400-1111Q0004KL1TVAO  
DSA400-1111Q0004KL2TVAO  
DSA400-1111Q0085KL1TVAO  
DSA400-1111Q0085KL2TVAO  
DSA400-1111Q0161KL1TVAO  
DSA400-1111Q0161KL2TVAO  
DSA400-4134Q0152KL1TVAO  
DSA400-4134Q0152KL2TVAO  
DSA557-04443KL0TVAO  
DSA557-04444KL1TVAO  
DSA557-054444KL1TVAO  
DSC400-0331Q0026KI2T  
DSC400-1111Q0084KI1T  
DSC400-1111Q0084KI2T  
DSC400-0101Q0083KI1T  
DSC400-0344Q0051KI1T  
DSC400-0101Q0083KI2T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-1111Q0034KI1T  
DSC400-1111Q0044KI2T  
DSC400-1111Q0085KI1T  
DSC400-1111Q0085KE1T  
DSC400-1122Q0036KI1T  
DSC400-4411Q0072KI1T  
DSC400-4411Q0072KI2T  
DSC400-4444Q0038KI1T  
DSC557-054444KI1T  
DSC400-1111Q0073KI1T  
DSC400-1111Q0073KI2T  
DSC400-1133Q0079KI1T  
DSC400-1133Q0079KI2T  
DSC400-1111Q0001KI1T  
DSC400-1111Q0001KI2T  
DSC400-3333Q0078KI1T  
DSC400-3333Q0078KI2T  
DSC400-1111Q0081KI1T  
DSC400-1111Q0081KI2T  
DSC400-3133Q0080KI1T  
DSC400-3133Q0080KI2T  
DSC400-0101Q0082KI1T  
DSC400-0101Q0082KI2T  
DSC400-1311Q0076KI1T  
DSC400-1311Q0076KI2T  
DSC400-0303Q0086KI1T  
DSC400-0303Q0086KI2T  
DSC400-0111Q0087KI1T  
DSC400-0111Q0087KI2T  
DSC400-3111Q0088KI1T  
DSC400-3111Q0088KI2T  
DSC400-3333Q0089KI1T  
DSC400-3333Q0089KI2T  
DSC400-4444Q0023KI1T  
DSC400-4444Q0023KI2T  
DSC400-4444Q0059KI1T  
DSC400-4444Q0059KI2T  
DSC400-1111Q0090KI1T  
DSC400-1111Q0090KI2T  
DSC400-1111Q0091KI1T  
DSC400-1111Q0091KI2T  
DSC400-2222Q0022KI1T  
DSC400-2222Q0022KI2T  
DSC400-0303Q0092KI1T  
DSC400-0303Q0092KI2T  
DSC400-3333Q0093KI1T  
DSC400-3333Q0093KI2T  
DSC400-3333Q0094KI1T  
DSC400-0101Q0083KI1

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-0353Q0040KI2  
DSC400-0344Q0051KI1  
DSC400-0101Q0083KI2  
DSC400-1111Q0019KI2  
DSC400-1111Q0034KI1  
DSC557-054444KI2  
DSC400-1111Q0044KI2  
DSC400-1111Q0085KI1  
DSC400-1111Q0085KE1  
DSC400-1122Q0036KI1  
DSC400-3333Q0016KI1  
DSC400-3333Q0041KI2  
DSC400-4144Q0054KI1  
DSC400-4411Q0072KI1  
DSC400-4411Q0072KI2  
DSC400-4444Q0038KI1  
DSC557-04333KI1  
DSC557-04444KI1  
DSC557-054444KI1  
DSC400-1111Q0073KI1  
DSC400-1111Q0073KI2  
DSC400-1133Q0079KI1  
DSC400-1133Q0079KI2  
DSC400-1111Q0001KI1  
DSC400-1111Q0001KI2  
DSC1001CI5-009.7280  
DSC1001CI5-016.3840  
DSC1001CI2-133.0000  
DSC1001CI5-033.3333  
DSC1003CI2-100.0000  
DSC1001CI5-032.0000  
DSC1001CI5-033.0000  
DSC1001CI5-033.3330  
DSC1001CI2-030.0000  
DSC1001CI5-048.0000  
DSC1001CI5-125.0000  
DSC1004CI2-027.0000  
DSC1004CI5-050.0000  
DSC1001CI1-010.0000  
DSC1001CI1-033.3330  
DSC1004CI5-016.0000  
DSC1001CI2-072.0000  
DSC1001CI2-108.0000  
DSC1001CI2-028.3220  
DSC1001CI2-043.0000  
DSC1001CI2-019.2000  
DSC1001CI2-038.4000  
DSC1001CI2-052.0000  
DSC1003CI2-025.0000



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1003CI2-050.0000  
DSC1001CI2-001.9512  
DSC1001CI2-033.3330  
DSC1001CI5-024.3050  
DSC1001CI5-033.3300  
DSC1001CI5-014.3181  
DSC1001CI5-026.8000  
DSC1001CI2-026.8000  
DSC1001CI2-010.4858  
DSC1004CI2-098.3040  
DSC1001CI1-031.9488  
DSC1003CI5-099.7200  
DSC1001CI1-004.0000  
DSC1001CI5-014.7456  
DSC1001CI5-008.1920  
DSC1001CI2-003.0720  
DSC1003CI2-024.0000  
DSC1003CI2-080.0000  
DSC1003CI1-070.0000  
DSC1001CI1-080.0000  
DSC1001CI5-022.0000  
DSC1001CI2-100.8000  
DSC1003CI2-027.0000  
DSC1001CI5-022.5792  
DSC1001CI2-024.3050  
DSC1001CI1-004.0960  
DSC1001CI5-003.2768  
DSC1001CI5-007.3728  
DSC1001CI2-003.2768  
DSC1001CI3-024.0000  
DSC1001CI3-025.0000  
DSC1001CI3-027.0000  
DSC1001CI3-013.8240  
DSC1001CI5-015.0000  
DSC1001CI5-144.0000  
DSC1001CI5-029.4912  
DSC1001CI2-133.3330  
DSC1001CI3-100.0000  
DSC1001CI2-074.1750  
DSC1001CI5-003.6864  
DSC1004CI2-024.5760  
DSC1001CI3-003.5790  
DSC1001CI1-018.4320  
DSC1001CI1-040.0000  
DSC1001CI2-066.0000  
DSC1001CI2-026.6363  
DSC1001CI1-064.0000  
DSC1001CI2-003.8000  
DSC1001CI3-012.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CI5-033.0000  
DSC1003CI5-080.0000  
DSC1001CI1-005.0000  
DSC1001CI3-019.2000  
DSC1001CI3-050.0000  
DSC1001CI1-004.9152  
DSC1003CI2-010.0000  
DSC1004CI5-121.5000  
DSC1001CI2-034.0000  
DSC1001CI5-037.4000  
DSC1004CI2-060.0000  
DSC1001CI2-004.0960  
DSC1001CI5-037.0879  
DSC1001CI2-013.0000  
DSC1001CE2-074.2500  
DSC1004CI1-016.0000  
DSC1001CI1-028.6363  
DSC1001CI3-013.5000  
DSC1001CI1-008.1920  
DSC1001CI2-038.0000  
DSC1001CI3-004.0000  
DSC1004CI5-100.0000  
DSC1001CI5-013.5000  
DSC1001CI2-020.7500  
DSC1003CI5-040.0000  
DSC1001CI5-013.3300  
DSC1003CI2-020.0000  
DSC400-3333Q0094KI2T  
DSC400-4334Q0022KI1T  
DSC400-4334Q0022KI2T  
DSC400-0444Q0009KI1T  
DSC400-0444Q0009KI2T  
DSC400-1111Q0095KI1T  
DSC400-1111Q0095KI2T  
DSC400-0101Q0096KI1T  
DSC400-0101Q0096KI2T  
DSC400-3331Q0097KI1T  
DSC400-3331Q0097KI2T  
DSC400-3331Q0098KI1T  
DSC400-3331Q0098KI2T  
DSC400-3333Q0099KI1T  
DSC400-3333Q0099KI2T  
DSC400-3133Q0100KI1T  
DSC400-3133Q0100KI2T  
DSC400-0103Q0102KI1T  
DSC400-0103Q0102KI2T  
DSC400-0401Q0103KI1T  
DSC400-0401Q0103KI2T  
DSC400-2222Q0104KI1T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC400-2222Q0104KI2T  
DSC400-2222Q0105KI1T  
DSC400-2222Q0105KI2T  
DSC400-3333Q0104KI1T  
DSC400-3333Q0104KI2T  
DSC1123DI5-010.0000T  
DSC1103DI5-300.0000T  
DSC1101DI5-025.0000T  
DSC1123DI2-072.0000T  
DSC1101DI5-036.0000T  
DSC1101DI1-036.0000T  
DSC1123DI2-010.0000T  
DSC1103DI5-160.0000T  
DSC1101DI2-012.0000T  
DSC1101DI5-125.0000T  
DSC2311KI2-R0074T  
DSC1123DI2-148.3516T  
DSC2311KI2-R0073T  
DSC2311KI2-R0021T  
DSC2311KI2-R0023T  
DSC2311KI2-R0079T  
DSC1104DI2-100.0000T  
DSC1102DI1-212.5000T  
DSC1102DI2-212.5000T  
DSC2311KI2-R0012T  
DSC1123DI1-100.0000T  
DSC1104DI5-100.0000T  
DSC1124DI5-100.0000T  
DSC2311KI2-R0082T  
DSC1121DI1-048.0000T  
DSC1122DI2-121.1090T  
DSC1101DI1-033.3330T  
DSC2311KI1-R0083T  
DSC6101JE1B-024.0000  
DSC6001JL2B-006.0053  
DSC6001JE2B-024.0000  
DSC6001JE3B-024.0000  
DSC6001JE2B-025.0000  
DSC6101JE1B-050.0000  
DSC6023JE1B-01D6  
DSC6021JE1B-01D7  
DSC6023JE1B-01D8  
DSC6021JE1B-01D9  
DSC6023JE1B-01DS  
DSC6023JE1B-01DV  
DSC6111JE2B-100.0000  
DSC6021JE1B-01EA  
DSC6001JL1B-025K600  
DSC6101JL3B-027.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6311JE1BB-018.4320  
DSC6311JE1CB-018.4320  
DSC6102JL1B-088.0000  
DSC6102JL1B-033.0000  
DSC6112JE1B-100.0000  
DSC6021JE3B-01GB  
DSC6021JL1B-01HB  
DSC6001JE1B-052.0000  
DSC6121JE1B-01HD  
DSC6121JE1B-01HE  
DSC6121JE1B-01HG  
DSC6011JE1B-027.0000  
DSC6311JE2FB-064.0000  
DSC6011JE1B-024.0000  
DSC6301JE2AB-050.0000  
DSC6001JE1B-020.0000  
DSC6101JE1B-030.0000  
DSC6101JE1B-033.0000  
DSC6101JE3B-032K768  
DSC6101JE1B-022.4000  
DSC6001JE2B-016.0000  
DSC6301JE2AB-024.0000  
DSC6121JE2B-01P0  
DSC6152JL3B-027.0000  
DSA6331JL2CB-012.2880VAO  
DSA6101JL1B-019.2000VAO  
DSA6101JL1B-045.0000VAO  
DSA6102JL1B-008.0000VAO  
DSA6311JL1AB-054.0000VAO  
DSA6331JL1CB-027.0000VAO  
DSA6001JL2B-008.0000VAO  
DSA6001JL2B-012.2880VAO  
DSA6001JL2B-025.0000VAO  
DSA6001JL2B-027.0000VAO  
DSA6011JL2B-024.0000VAO  
DSA6011JL2B-025.0000VAO  
DSA6011JL2B-027.0000VAO  
DSA6101JL2B-032K768VAO  
DSA6101JL2B-049.5000VAO  
DSA6111JL2B-024.0000VAO  
DSA6111JL2B-025.0000VAO  
DSA6111JL2B-027.0000VAO  
DSA6331JL2AB-012.2880VAO  
DSA6331JL2CB-024.0000VAO  
DSA6001JL3B-024.5760VAO  
DSA6011JL3B-012.0000VAO  
DSA6101JL3B-012.2888VAO  
DSA6101JL3B-024.5760VAO  
DSA6101JL3B-027.0000VAO

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA6101JL3B-037.1250VAO

DSA6101JL3B-060.0000VAO

DSA6101JL3B-087.0655VAO

DSA6102JL3B-037.1250VAO

DSC1121AE2-025.0000T

DSC1121AE2-156.2500T

DSC1121AE2-075.0000T

DSC1123AE2-148.3516T

DSC1122NE1-025.0000T

DSC1122NE2-150.0000T

DSC1122NE2-156.2500T

DSC1124NE1-100.0000T

DSC1124NL2-100.0000T

DSC1122NE1-133.3330T

DSC1122NE1-150.0000T

DSC1123NE2-156.2500T

DSC1123NE2-125.0000T

DSC1123NL2-100.0000T

DSC1102NE1-148.5000T

DSC1102NE1-125.0000T

DSC1103NE1-114.2850T

DSC1123NE1-100.0000T

DSC1123NL5-125.0000T

DSC1123NL5-100.0000T

DSC1121NL1-025.0000T

DSC1101NL3-PROGT

DSC1101NL5-PROGT

DSC1100NL3-PROGT

DSC1100NL5-PROGT

DSC1122NL2-025.0006T

DSC1103NL2-147.4560T

DSC1103NL2-098.3040T

DSC1123NE1-200.0000T

DSC1103NL5-125.0000T

DSC1103NL2-100.0000T

DSC1103NL2-106.2500T

DSC1103NL2-135.0000T

DSC1101DE2-008.0000T

DSC1101DL1-033.3330T

DSC1101DL5-013.5600T

DSC1121DL2-024.7500T

DSC1121DL2-025.0000T

DSC1123DL2-125.0000T

DSC1123DL5-100.0000T

DSC1123DL5-125.0000T

DSC1123DL5-156.2500T

DSC1123DL5-212.5000T

DSC2311KE1-R0002T

DSC2311KL1-R0015T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2311KLI1-R0021T  
DSC2311KL2-R0015T  
DSC2311KL2-R0018T  
DSC1105DL1-027.0000T  
DSC8121DL5T  
DSC2311KE1-R0042T  
DSC2311KE1-R0047T  
DSC2311KL2-R0048T  
DSC1001CL1-125.0000  
DSC1001CL2-009.5290  
DSC1001CL2-012.0000  
DSC1001CL2-020.0000  
DSC1001CL2-022.5972  
DSC1001CL2-024.0000  
DSC1001CL2-025.0000  
DSC1001CL1-033.0000  
DSC1001CL2-027.0000  
DSC1001CL2-033.3333  
DSC1001CL2-037.1250  
DSC1001CL2-050.0000  
DSC1001CL2-004.0000  
DSC1001CL5-020.0000  
DSC1001CL5-025.0000  
DSC1001CL5-026.0000  
DSC1001CL5-027.0000  
DSC1001CL5-027.1200  
DSC1001CL5-032.0000  
DSC1001CL5-033.3330  
DSC1001CL5-040.0000  
DSC1001CL5-125.0000  
DSC1001CL5-008.0000  
DSC1001CL5-150.0000  
DSC1001CL5-28.63636  
DSC1001CL5-012.0000  
DSC1001CL5-024.0000  
DSC1103DI2-250.0000T  
DSC2311KI1-R0070T  
DSC2311KI1-R0052T  
DSC1121DI5-125.0000T  
DSC2311KI2-R0085T  
DSC2311KI2-R0086T  
DSC2311KI1-R0078T  
DSC2311KI1-R0073T  
DSC1123DI2-160.0000T  
DSC2311KI2-R0088T  
DSC2311KI1-R0016T  
DSC1123DI5-125.0060T  
DSC1123DI1-322.2656T  
DSC2311KI1-R0040T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103DI1-156.2500T

DSC1103DI2-156.2500T

DSC1103DI1-080.0000T

DSA2311KI1-R0003TVAO

DSA1101DI1-004.0000TVAO

DSA1101DI1-050.0000TVAO

DSA1121DI3-033.3333TVAO

DSA2311KI2-R0064TVAO

DSA2311KI2-R0065TVAO

DSA2311KI2-R0077TVAO

DSA2311KI3-R0067TVAO

DSA2311KI1-R0016TVAO

DSA2311KI1-R0041TVAO

DSA2311KI2-R0015TVAO

DSC2010FI2-A0001T

DSC2010FI2-A0017T

DSC557-0333FI0T

DSC2010FI2-A0024T

DSC2010FI2-B0005T

DSC2011FI1-E0012T

DSC2011FI2-E0001T

DSC2011FI2-F0017T

DSC2011FI2-F0021T

DSC2022FI2-F0001T

DSC2030FI2-C0001T

DSC2030FI2-C0004T

DSC2030FI2-C0006T

DSC2030FI2-C0012T

DSC2031FI2-J0001T

DSC2033FI2-G0002T

DSC2033FI2-G0004T

DSC2033FI2-G0006T

DSC2033FI2-G0007T

DSC2042FI2-M0005T

DSC2044FI1-H0006T

DSC2044FI2-H0001T

DSC2044FI2-H0001B

DSC2133FI2-E0020T

DSC2042FI1-M0005T

DSC2233FI2-F0018T

DSC2044FI1-H0001T

DSC2033FI1-F0028T

DSC2010FI2-B0014T

DSC2210FI2-A0006T

DSC2210FI2-A0028T

DSC2211FI2-E0018T

DSC2033FI2-G0001T

DSC2033FI2-K0003T

DSC2033FI2-F0030T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2033FI2-F0031T  
DSC2042FI1-F0014T  
DSC2033FI2-F0032T  
DSC2010FI2-B0009T  
DSC2011FI1-F0033T  
DSC2233FI2-G0002T  
DSC2133FI2-G0001T  
DSC2033FI1-F0025T  
DSC2033FI1-F0026T  
DSC2120FI1-A0027T  
DSC2030FI2-C0002T  
DSC2033FI2-F0022T  
DSC2033FI1-F0022T  
DSC557-0344FI0T  
DSC557-0344FI1T  
DSC557-0343FI1T  
DSC2011FI2-E0002T  
DSC2044FI2-H0006T  
DSC2222FI1-F0006T  
DSC2022FI1-F0006T  
DSC2044FI2-F0022T  
DSC2211FI1-E0021T  
DSC2144FI2-F0022T  
DSC2110FI2-A0008T  
DSC2110FI2-A0006T  
DSC2011FI2-F0035T  
DSC2033FI2-F0003T  
DSC2011FI1-F0036T  
DSC2033FI2-F0037T  
DSC2033FI2-F0038T  
DSC2033FI2-F0039T  
DSC2041FI1-F0025T  
DSC2033FI2-F0040T  
DSC2144FI2-E0023T  
DSC2123FI2-E0024T  
DSC2030FI5-B0011T  
DSC2030FI1-B0019T  
DSC2011FI2-F0042T  
DSC2022FI1-H0006T  
DSC2011FI1-F0043T  
DSC2122FI2-E0025T  
DSC2033FI2-F0044T  
DSC2030FI2-B0020T  
DSC2033FI1-F0039T  
DSC2222FI2-E0026T  
DSC2010FI2-A0018T  
DSC2010FI2-A0021T  
DSC2030FI2-C0009T  
DSC2030FI2-C0010T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2040FI2-D0002T  
DSC2040FI2-D0003T  
DSC2042FI2-M0004T  
DSC2010FI1-A0003T  
DSC2033FI2-F0046T  
DSC2033FI2-F0047T  
DSC2033FI2-F0048T  
DSC2133FI2-E0027T  
DSC557-0344FI1B  
DSC2011FI2-F0050T  
DSC2041FI1-K0001T  
DSC2040FI2-B0021T  
DSC2033FI2-F0053T  
DSC2031FI2-F0023T  
DSC557-0333FI1T  
DSC2011FI1-F0054T  
DSC2030FI2-B0022T  
DSC2033FI2-H0005T  
DSC2033FI2-F0060T  
DSC2110FI1-A0012T  
DSC2033FI2-F0059T  
DSC1121DM2-016.6400T  
DSC1121DM2-014.7456T  
DSC2311KM1-R0002T  
DSC1101DM2-007.3700T  
DSC1121DM3-032.0000T  
DSC1101DM1-032.0000T  
DSC1101DM1-007.3700T  
DSC1101DM2-040.0000T  
DSC1121DM2-026.0000T  
DSC1121DM2-019.2000T  
DSC1101DM2-048.0000T  
DSC2311KM2-R0065T  
DSC1101DM1-020.0000T  
DSC2311KM2-R0073T  
DSC2311KM2-R0067T  
DSC2311KM2-R0015T  
DSC2311KM2-R0080T  
DSC2311KM2-R0089T  
DSC1101DM2-050.0000T  
DSC2010FM2-B0006T  
DSC2011FM1-E0005T  
DSC2011FM2-E0015T  
DSC2010FM2-A0001T  
DSC2011FM1-E0015T  
DSC2011FM1-F0041T  
DSC2011FM2-E0005T  
DSC2011FM2-F0049T  
DSC2210FM2-A0030T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC2210FM2-A00311

DSC2010FM2-A0001B

DSA1101DA1-004.0000TVAO

DSA1101DA1-007.3700TVAO

DSA1101DA1-008.0000TVAO

DSA1101DA1-016.0000TVAO

DSA1101DA1-022.5792TVAO

DSA1101DA1-025.0000TVAO

DSA1101DA1-026.9973TVAO

DSA1101DA1-033.3330TVAO

DSA1101DA1-040.0000TVAO

DSA1105DA1-022.5792TVAO

DSA1121DA1-100.0000TVAO

DSA1123DA1-100.0000TVAO

DSA1125DA1-027.0000TVAO

DSA1125DA1-033.3333TVAO

DSA1101DA2-020.0000TVAO

DSC1001DI1-048.0000T

DSC1001DI1-125.0000T

DSC1001DI1-050.0000T

DSC1001DI1-033.3300T

DSC1001DI1-098.3040T

DSC1001DI2-009.6000T

DSC1001DI2-001.0000T

DSC1001DI2-003.6864T

DSC1001DI2-004.0960T

DSC1001DI2-005.0196T

DSC1001DI2-008.0000T

DSC1001DI2-010.0000T

DSC1001DI2-012.0000T

DSC6101MA3B-019.2000T

DSC6101MA3B-027.0000T

DSC6001MA3B-PROGT

DSC6003MA3B-PROGT

DSC6101MA3B-PROGT

DSC6331MA1AB-027.0000T

DSC6111MA3B-050.0000T

DSC6023MA1B-015ST

DSC6101MA2B-020.0000T

DSC6111MA1B-033.0000T

DSC6331MA1AB-025.0000T

DSC6101MA3B-016.6666T

DSC6111MA1B-033.3300T

DSC6101MA3B-026.0000T

DSC6011MA3B-006K000T

DSC6011MA3B-022K000T

DSC6011MA3B-002K000T

DSC6011MA3B-020.0000T

DSC6101MA1B-008.0000T

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6011MA1B-032K768T

DSC6011MA3B-025.0000T

DSA6001MA1B-013.5600TVAO

DSA6101MA1B-033.3300TVAO

DSA6121MA1B-01AETVAO

DSA6331MA1AB-025.0000TVAO

DSA6331MA1AB-027.0000TVAO

DSA6331MA1BB-027.0000TVAO

DSA6331MA1DB-027.0000TVAO

DSA6101MA2B-008.0000TVAO

DSA6101MA2B-010.0000TVAO

DSA6311MA2CB-008.0000TVAO

DSA6011MA3B-002K000TVAO

DSA6011MA3B-020.0000TVAO

DSC612NA2A-010JT

DSC612NA2A-010JB

DSC613NA2A-018YT

DSC612NA1A-01H5T

DSC613NA1A-017QT

DSC613NA1A-01KCT

DSC613NA1A-01KDT

DSC6101JA2B-025.0000T

DSC6001JA3B-020.0000T

DSC6331JA3BB-004.0000T

DSC6331JA3AB-004.0000T

DSC6001JA3B-PROGT

DSC6003JA3B-PROGT

DSC6101JA3B-PROGT

DSC6311JA1AB-027.0000T

DSC6331JA1CB-054.0000T

DSC6311JA1BB-027.0000T

DSC6001JA3B-580K000T

DSC6311JA1AB-054.0000T

DSC6331JA2BB-025.0000T

DSC6331JA2IB-025.0000T

DSC6331JA2GB-025.0000T

DSC6331JA2HB-025.0000T

DSC6021JA2B-01ART

DSC6331JA2AB-025.0000T

DSC6331JA2DB-024.5760T

DSC6011JA3B-016K384T

DSC6311JA1AB-045.0000T

DSC6311JA1BB-045.0000T

DSC6311JA1AB-019.2000T

DSC6311JA1BB-019.2000T

DSC6001JA2B-016.0000T

DSC6102JA1B-125K000T

DSC6102JA1B-010K000T

DSC6101JA2B-050.0000T

---

Date: Monday, November 16, 2020

---

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6331JA2AB-004.0000T  
DSC6331JA2BB-004.0000T  
DSC6101JA3B-024.0000T  
DSC6011JA1B-040.0000T  
DSC6101JA2B-027.0000T  
DSA6311JA1AB-027.0000TV02  
DSA6101JA1B-027.0000TVAO  
DSA6111JA1B-027.0000TVAO  
DSA6112JA1B-027.0000TVAO  
DSA6311JA1AB-024.0000TVAO  
DSA6311JA1AB-025.0000TVAO  
DSA6311JA1AB-027.0000TVAO  
DSA6331JA1BB-100.0000TVAO  
DSA6331JA1CB-100.0000TVAO  
DSA6001JA2B-003K277TVAO  
DSA6001JA2B-019.2000TVAO  
DSA6001JA2B-032K768TVAO  
DSA6001JA2B-045.0000TVAO  
DSA6011JA2B-012.0000TVAO  
DSA6011JA2B-032K768TVAO  
DSA6021JA2B-01ARTVAO  
DSA6102JA2B-016.0000TVAO  
DSA6311JA2AB-024.0000TVAO  
DSA6311JA2AB-025.0000TVAO  
DSA6331JA2BB-025.0000TVAO  
DSA6331JA2GB-025.0000TVAO  
DSA6001JA3B-004.0000TVAO  
DSA6001JA3B-010.0000TVAO  
DSA6001JA3B-016.0000TVAO  
DSA6041JA3B-016.0000TVAO  
DSC612PA3A-0118T  
DSC612PA3A-0119T  
DSC612PA3A-011AT  
DSC612PA3A-0176T  
DSC613PA2A-018WT  
DSC612PA3A-01EQT  
DSC612PA3A-010KT  
DSC1001DI2-029.5000  
DSC1001DI5-033.0000  
DSC1004DI2-012.0000  
DSC1003DI2-024.5760  
DSC1001DI1-033.0000  
DSC1001DI1-030.0000  
DSC1001DI5-004.0000  
DSC1004DI2-010.0000  
DSC1001DI1-032.0000  
DSC1003DI2-100.0000  
DSC1001DI2-028.6363  
DSC1001DI2-031.2500

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1004DI2-016.0000

DSC8003DI2

DSC1001DI1-012.8000

DSC1003DI5-024.5760

DSC1004DI2-100.0000

DSC1004DI2-048.0000

DSC1004DI2-060.0000

DSC1004DI2-072.0000

DSC1004DI2-086.4000

DSC1004DI5-025.0000

DSC1004DI5-066.4860

DSC1004DI5-066.5800

DSC1001DI5-010.0000

DSC8001DI1

DSC8001DI2

DSC8001DI5

DSC1001DI5-024.0000

DSC1001DI5-024.5760

DSC1001DI5-033.3330

DSC1001DI5-001.8432

DSC1001DI2-018.0000

DSC1001DI5-044.0000

DSC1001DI5-048.0000

DSC1001DI5-050.0000

DSC1001DI5-060.0000

DSC1001DI5-075.0000

DSC1001DI5-080.0000

DSC1001DI1-074.2500

DSC1001DL5-032.0000

DSC1001DI1-054.0000

DSC1001DI1-027.0000

DSC1001DI2-054.0000

DSC1001DI5-047.3385

DSC1001DI1-060.0000

DSC1001DI2-006.7800

DSC1001DI2-004.0960

DSC1001DI2-030.0000

DSC1001DI2-001.8432

DSC1001DI2-066.0000

DSC1001DI5-133.3330

DSC1004DI1-006.7800

DSC1001DI5-018.4320

DSC1001DI1-018.4320

DSC1001DI2-004.0000

DSC1001DI1-004.9152

DSC1001DI2-045.1584

DSC1001DI2-049.1520

DSC1001DI2-011.0592

DSC1003DI2-027.1200

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001DI2-032.7680  
DSC1001DI1-016.6666  
DSC1001DI5-087.0655  
DSC1001DI1-045.1584  
DSC1001DI5-025.6000  
DSC1001DI1-045.5840  
DSC1001DI1-013.3300  
DSC1001DI2-003.0720  
DSC1001DI2-057.2727  
DSC1003DI2-013.5288  
DSC1001DI2-096.0000  
DSC1001DI2-023.0000  
DSC1001DI5-054.0000  
DSC1001DI1-029.4912  
DSC1001DI5-013.5288  
DSC1004DI2-133.0000  
DSC1004DI1-050.0000  
DSC1001DI1-007.3728  
DSC1001DI1-080.0000  
DSC1001DI1-002.0000  
DSC1101CE5-045.1584T  
DSC1103CE5-135.0000T  
DSC1103CE1-100.0000T  
DSC1124CE2-027.0000T  
DSC1101CL2-026.0000T  
DSC1124CL5-100.0000T  
DSC1123CE5-393.2160T  
DSC1121CE1-124.2000T  
DSC1121CL2-020.5710T  
DSC1121CL5-125.0000T  
DSC1123CL2-026.0000T  
DSC1121CL2-024.0000T  
DSC1123CL3-125.0000T  
DSC1121CL5-003.3000T  
DSC1123CL3-100.0000T  
DSC1123CL3-250.0000T  
DSC1123CL3-093.4400T  
DSC1103CL5-156.2500T  
DSC1103CL5-125.0000T  
DSC1103CE5-254.6500T  
DSC1124CE2-038.4000T  
DSC1104CL1-100.0000T  
DSC1103CL5-135.0000T  
DSC1103CL5-148.5000T  
DSC1103CL5-200.0000T  
DSC1103CE2-100.0000T  
DSC1123CL2-027.0000T  
DSC1103CE2-020.0000T  
DSC1103CL5-212.5000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101CL3-033.3300T  
DSC1101BE1-050.0000T  
DSC1102BE2-200.0000T  
DSC1103BE1-150.0000T  
DSC1103BL2-125.0000T  
DSC1103BL2-200.0000T  
DSC1121BE2-100.0000T  
DSC1122BE1-133.3300T  
DSC1122BE1-150.0000T  
DSC1122BE2-050.0000T  
DSC1122BE2-150.0000T  
DSC1123BL2-125.0000T  
DSC1123BL5-156.2500T  
DSC1103BL5-062.5000T  
DSC8103BL5T  
DSC1124BE2-100.0000T  
DSC1104BE2-100.0000T  
DSC1103BE5-156.2500T  
DSC1122BE1-156.2500T  
DSC1124BL1-100.0000T  
DSC1101BE5-024.5760T  
DSC1101BE5-022.5792T  
DSC1121BE2-155.5200T  
DSC1123BE1-050.0000T  
DSC1101BE1-012.0000T  
DSC1121BL5-108.7200T  
DSC1121BL5-110.5400T  
DSC1123BL5-125.0000T  
DSC1123BL5-100.0000T  
DSC1123BE1-100.0000T  
DSC1001CL5-029.4912T  
DSC1001CL2-064.0000T  
DSC1001CL2-003.1250T  
DSC1001CL2-029.4912T  
DSC1001CL2-066.6660T  
DSC1001CL2-125.0000T  
DSC1001CL5-003.6864T  
DSC1001CL3-080.0000T  
DSC1001CL3-033.0000T  
DSC1001CE1-004.0960T  
DSC1001CL5-044.0000T  
DSC1001CL1-016.6400T  
DSC1003CL2-050.0000T  
DSC1001CE1-100.0000T  
DSC1001CE1-110.0000T  
DSC1001CE1-032.0000T  
DSC1001CL3-024.0000T  
DSC1001CL3-072.0000T  
DSC1001CE2-019.2000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1001CE2-108.0000T  
DSC1001CE3-005.0000T  
DSC1001CL2-048.0000T  
DSC1001CL2-090.0000T  
DSC1001CE2-064.0000T  
DSC1001CL3-008.0000T  
DSC1001CL1-012.0000T  
DSC1001CL2-022.5792T  
DSC1001CL5-007.3728T  
DSC1001CL5-028.0000T  
DSC1004CL2-003.2768T  
DSC1001CL1-008.0000T  
DSC1001CL2-026.0000T  
DSC1001CL5-064.0000T  
DSC1001CE2-013.5600T  
DSC1001CE5-032.2123T  
DSC400-3333Q0078KI1  
DSC400-3333Q0078KI2  
DSC400-1111Q0081KI1  
DSC400-1111Q0081KI2  
DSC400-3133Q0080KI1  
DSC400-3133Q0080KI2  
DSC400-0101Q0082KI1  
DSC400-0101Q0082KI2  
DSC400-1311Q0076KI1  
DSC400-1311Q0076KI2  
DSC400-0303Q0086KI1  
DSC400-0303Q0086KI2  
DSC400-0111Q0087KI1  
DSC400-0111Q0087KI2  
DSC400-3111Q0088KI1  
DSC400-3111Q0088KI2  
DSC400-3333Q0089KI1  
DSC400-3333Q0089KI2  
DSC400-4444Q0023KI1  
DSC400-4444Q0023KI2  
DSC400-4444Q0059KI1  
DSC400-4444Q0059KI2  
DSC400-1111Q0090KI1  
DSC400-1111Q0090KI2  
DSC400-1111Q0091KI1  
DSC400-1111Q0091KI2  
DSC400-2222Q0022KI1  
DSC400-2222Q0022KI2  
DSC400-0303Q0092KI1  
DSC400-0303Q0092KI2  
DSC400-3333Q0093KI1  
DSC8103AI5  
DSC1102AI1-100.0000



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC8121AI2

DSC1103AI1-125.0000

DSC8122AI2

DSC8123AI2

DSC1103AI2-100.0000

DSC1103AI2-125.0000

DSC1103AI2-171.8181

DSC1103AI2-200.0000

DSC8101AI2

DSC1121AI2-148.5000

DSC8124AI2

DSC1121AI2-053.1250

DSC1123AI5-100.0000

DSC1103AI5-120.0000

DSC1103AI5-125.0000

DSC1103AI5-156.2500

DSC1103AI5-250.0000

DSC1104AI2-100.0000

DSC1121AI1-025.0000

DSC1121AI1-125.0000

DSC1121AI2-025.0000

DSC1121AI2-026.0000

DSC1121AI2-050.0000

DSC1121AI2-125.0000

DSC1121AI5-020.0000

DSC1121AI5-050.0000

DSC1121AI5-125.0032

DSC1122AI1-125.0000

DSC1122AI2-019.4400

DSC1122AI2-150.0000

DSC1122AI2-155.5200

DSC1122AI2-156.2500

DSC1122AI2-425.0000

DSC1122AI2-156.2539

DSC1122AI5-077.7600

DSC1122AI5-125.0000

DSC1122AI5-133.3300

DSC1122AI5-155.5200

DSC1122AI5-156.2500

DSC1123AI1-075.0000

DSC1123AI1-100.0000

DSC1123AI5-175.0000

DSC1123AI1-125.0000

DSC1123AI1-150.0000

DSC1123AI1-200.0000

DSC1123AI2-025.0000

DSC1123AI2-040.0000

DSC1123AI2-100.0000

DSC1123AI2-120.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123AI2-125.0000  
DSC1123AI2-148.5000  
DSC1123AI2-150.0000  
DSC1123AI2-156.2500  
DSC1123AI2-200.0000  
DSC1122AI5-025.0020  
DSC1123AI5-125.0000  
DSC1123AI5-133.3300  
DSC1123AI5-135.0000  
DSC1123AI5-148.3500  
DSC1123AI5-148.5000  
DSC1123AI5-150.0000  
DSC1123AI5-155.5200  
DSC1123AI5-156.2500  
DSC1123AI5-200.0000  
DSC1123AI5-322.2656  
DSC1121AI2-020.0000  
DSC1101AI5-019.4400  
DSC1123AI5-116.0000  
DSC1101AI2-125.0000  
DSC1123AI5-185.6250  
DSC1123AI2-166.6666  
DSC1123AI2-050.0023  
DSC1101AI2-120.0000  
DSC1122AI2-050.0000  
DSC1123AI2-140.0000  
DSC1101AI5-099.7200  
DSC1121AI1-027.0000  
DSC1101AI2-025.0000  
DSC1124AI2-100.0000  
DSC1121AI2-162.0000  
DSC1101AI5-156.2500  
DSC1101AI2-156.2500  
DSC1101AI5-056.3200  
DSC1101AI5-048.0000  
DSC1121AI2-012.2880  
DSC1121AI5-100.0000  
DSC1123AI5-027.0000  
DSC1121AI5-027.0000  
DSC1121AI2-010.0000  
DSC1121AI2-061.4400  
DSC1101AI5-032.0000  
DSC1103AI2-148.5000  
DSC1102AI2-167.3320  
DSC1123AI5-019.2000  
DSC1101AI5-010.0000  
DSC1101CI2-030.0000  
DSC1101CI2-050.0000  
DSC1101CI2-100.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1101CI5-020.0000  
DSC1101CI5-022.5791  
DSC1101CI5-024.5760  
DSC1101CI5-050.0000  
DSC1102CI1-125.0000  
DSC1102CI5-025.0000  
DSC1102CI5-040.0000  
DSC1102CI5-062.5000  
DSC1103CI1-156.2500  
DSC1102CI5-200.0000  
DSC1103CI1-075.0000  
DSC1103CI1-100.0000  
DSC1103CI1-200.0000  
DSC1103CI2-100.0000  
DSC1103CI2-125.0000  
DSC1103CI2-148.5000  
DSC1103CI2-156.2500  
DSC1103CI5-025.0000  
DSC1103CI5-050.0000  
DSC1103CI5-075.0000  
DSC1103CI5-100.0000  
DSC1103CI5-106.2500  
DSC1103CI5-114.0000  
DSC1103CI5-140.0000  
DSC1103CI5-148.5000  
DSC1121CI2-014.7456  
DSC1103CI5-200.0000  
DSC1103CI5-233.3333  
DSC1103CI5-300.0000  
DSC1121CI1-024.0000  
DSC1121CI1-025.0000  
DSC1121CI2-024.0000  
DSC1103CI1-125.0000  
DSC1121CI2-025.0000  
DSC1121CI2-031.2500  
DSC1121CI2-066.6660  
DSC1121CI2-050.0000  
DSC1121CI2-100.0000  
DSC1121CI2-115.0000  
DSC1121CI2-125.0000  
DSC1121CI2-132.0000  
DSC1121CI2-168.0000  
DSC1121CI5-016.0000  
DSC1121CI5-022.5000  
DSC1121CI5-040.0000  
DSC1121CI5-045.0000  
DSC1121CI5-049.1520  
DSC1122CI1-125.0000  
DSC1122CI1-156.2500

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1122CI2-125.0000  
DSC1122CI2-156.2500  
DSC1122CI2-150.0000  
DSC1122CI5-025.0000  
DSC1122CI5-200.0000  
DSC1123CI1-010.0000  
DSC1123CI1-022.8800  
DSC1123CI1-125.0000  
DSC1123CI1-200.0000  
DSC1123CI2-100.0000  
DSC1123CI2-125.0000  
DSC1123CI2-025.0000  
DSC1123CI2-156.2500  
DSC1121CI2-024.5760  
DSC1121CI2-020.0000  
DSC1122CI2-103.1250  
DSC1101CI5-025.0000  
DSC1103CI5-224.8200  
DSC1123CI2-333.3300  
DSC1123CI5-156.2500  
DSC1123CI2-212.5000  
DSC1123CI5-100.0000  
DSC1123CI2-020.0000  
DSC1123CI1-027.0000  
DSC1123CI2-333.3333  
DSC1123CI2-312.5000  
DSC1101CI1-025.0000  
DSC1124CI5-156.2500  
DSC1103CI2-148.3500  
DSC1103CI2-200.0000  
DSC1123CI2-085.0000  
DSC1123CI2-300.0000  
DSC8122CI5  
DSC1123CI2-150.0000  
DSC1123CI2-200.0000  
DSC1123CI2-432.0000  
DSC1123CI5-026.5625  
DSC1123CI5-032.0000  
DSC1123CI5-034.0000  
DSC1123CI5-040.0000  
DSC1123CI5-125.0000  
DSC1124CI2-100.0000  
DSC1123CI5-409.3750  
DSC1124CI1-156.2500  
DSC1124CI2-200.0000  
DSC1124CI5-100.0000  
DSC1123CI2-062.5000  
DSC1103CI5-233.2090  
DSC8101CI1

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1123AI1-156.2500T  
DSC1123AI2-025.0000T  
DSC1123AI2-100.0000T  
DSC1123AI2-040.0000T  
DSC1123AI2-148.5000T  
DSC1123AI1-200.0000T  
DSC1123AI2-125.0000T  
DSC1123AI2-200.0000T  
DSC1123AI2-156.2500T  
DSC1123AI5-125.0000T  
DSC1123AI5-148.5000T  
DSC1123AI5-133.3300T  
DSC1123AI5-150.0000T  
DSC1123AI5-200.0000T  
DSC1121AI2-020.0000T  
DSC1101AI5-019.4400T  
DSC1123AI5-116.0000T  
DSC1101AI2-125.0000T  
DSC1123AI5-185.6250T  
DSC1123AI2-166.6666T  
DSC1123AI2-050.0023T  
DSC1101AI2-120.0000T  
DSC1122AI2-050.0000T  
DSC1123AI2-140.0000T  
DSC1101AI5-099.7200T  
DSC1121AI1-027.0000T  
DSC1101AI2-025.0000T  
DSC1124AI2-100.0000T  
DSC1121AI2-162.0000T  
DSC1101AI5-156.2500T  
DSC1101AI2-156.2500T  
DSC1101AI5-056.3200T  
DSC1101AI5-048.0000T  
DSC1121AI2-012.2880T  
DSC1121AI5-100.0000T  
DSC1123AI5-027.0000T  
DSC1121AI5-027.0000T  
DSC1121AI2-010.0000T  
DSC1121AI2-061.4400T  
DSC1101AI5-032.0000T  
DSC1103AI2-148.5000T  
DSC1102AI2-167.3320T  
DSC1123AI5-019.2000T  
DSC1101AI5-010.0000T  
DSC1123AI5-270.0000T  
DSC1122AI2-100.3000T  
DSC1101AI2-150.0000T  
DSC1103AI1-155.5200T  
DSC1103AI1-161.1328T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103AI2-125.0031T  
DSC1122AI2-125.0000T  
DSC1123AI1-155.5200T  
DSC1123AI1-161.1300T  
DSC6301JL2AB-027.0000T  
DSC6301JL2BB-027.0000T  
DSC6001JE2B-013.5600T  
DSC6021JE1B-0193T  
DSC6331JE1EB-012.0000T  
DSC6121JE1B-0198T  
DSC6111JE1B-033.0000T  
DSC6101JL2B-033.0000T  
DSC6001JL3B-032.7680T  
DSC6011JL2B-032K768T  
DSC6301JL1LB-001.0000T  
DSC6021JE1B-01B4T  
DSC6101JE3B-024.0000T  
DSC6003JE2B-032K768T  
DSC6001JL3B-025.0000T  
DSC6101JE1B-024.0000T  
DSC6001JL2B-006.0053T  
DSC6001JE2B-024.0000T  
DSC6001JE3B-024.0000T  
DSC6001JE2B-025.0000T  
DSC6101JE1B-050.0000T  
DSC6023JE1B-01D6T  
DSC6021JE1B-01D7T  
DSC6023JE1B-01D8T  
DSC6021JE1B-01D9T  
DSC6023JE1B-01DST  
DSC6023JE1B-01DVT  
DSC6111JE2B-100.0000T  
DSC6021JE1B-01EAT  
DSC6001JL1B-025K600T  
DSC6101JL3B-027.0000T  
DSC6311JE1BB-018.4320T  
DSC6311JE1CB-018.4320T  
DSC6102JL1B-088.0000T  
DSC6102JL1B-033.0000T  
DSC6112JE1B-100.0000T  
DSC6021JE3B-01GBT  
DSC6021JL1B-01HBT  
DSC6001JE1B-052.0000T  
DSC6121JE1B-01HDT  
DSC6121JE1B-01HET  
DSC6121JE1B-01HGT  
DSC6011JE1B-027.0000T  
DSC6311JE2FB-064.0000T  
DSC6011JE1B-024.0000T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSA6102JL3B-087.0655VAO

DSA6112JL3B-054.0000VAO

DSA6301JL3AB-054.0000VAO

DSA6311JL3AB-054.0000VAO

DSA6101JL1B-020.0000VAO

DSC613PL3A-0106

DSC612PL2A-0132

DSC613PL2A-0131

DSC612PL2A-0130

DSC612PL3A-012Y

DSC612PE3A-013K

DSC612PE3A-014V

DSC613PE1A-017Q

DSC612PE3A-017R

DSC613PE2A-017Q

DSC613PE1A-01CK

DSC612PL3A-01D5

DSC613PL2A-01DG

DSC612PL2A-01ER

DSC613PE2A-01KD

DSC613PE2A-01M2

DSC613PE2A-01KC

DSA612PL2A-01CSVAO

DSA612PL3A-01BHVAO

DSC612RL3A-010K

DSC613RL2A-0131

DSC613RE1A-0135

DSC6121JL2B-015G

DSC6003JL2B-032K768

DSC6011JE1B-025.0000

DSC6011JL2B-025.0000

DSC6011JE3B-003K898

DSC6001JE1B-025.0000

DSC6311JL2AB-027.0000

DSC6311JL2BB-027.0000

DSC6111JL2B-008.0000

DSC6011JE1B-840K000

DSC6121JL2B-0170

DSC6101JL3B-025.0000

DSC6001JE3B-040K000

DSC6301JL2AB-027.0000

DSC6301JL2BB-027.0000

DSC6001JE2B-013.5600

DSC6021JE1B-0193

DSC6331JE1EB-012.0000

DSC6121JE1B-0198

DSC6111JE1B-033.0000

DSC6101JL2B-033.0000

DSC6001JL3B-032.7680

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6011JLZB-032K768  
DSC6301JL1LB-001.0000  
DSC6021JE1B-01B4  
DSC6101JE3B-024.0000  
DSC6003JE2B-032K768  
DSC6001JL3B-025.0000  
DSC1123AE2-003.5000T  
DSC1101AL5-045.1584T  
DSC1101AL5-049.1520T  
DSC1123AE2-156.2500T  
DSC1121AE2-004.9152T  
DSC1121AE2-133.0000T  
DSC1102AE2-400.0000T  
DSC1101AE3-024.0000T  
DSC1103AL5-150.0000T  
DSC1103AL5-015.0000T  
DSC1102AE2-155.5200T  
DSC1103AE3-416.0000T  
DSC1121AL5-041.5000T  
DSC1121AE2-041.5000T  
DSC1121AE5-041.5000T  
DSC1121AL2-041.5000T  
DSC1121AL1-041.5000T  
DSC1123AE1-159.3750T  
DSC1103AL1-125.0000T  
DSC1122AE2-075.0000T  
DSC1121AL5-012.0000T  
DSC1101AL2-156.2500T  
DSC1103AE2-085.0000T  
DSC1123AE2-085.0000T  
DSC1121AE5-025.0000T  
DSC1121AE5-020.0000T  
DSC1100AL3-PROGT  
DSC1101AL3-PROGT  
DSC1121AE2-020.0000T  
DSC1100AL5-PROGT  
DSC1101AL5-PROGT  
DSC1123AE2-100.0000T  
DSC1123AE1-150.0000T  
DSC1123AE2-040.0000T  
DSC1121AL5-010.0000T  
DSC1121AL5-100.0000T  
DSC1123AL2-125.0000T  
DSC1103AE2-135.0000T  
DSC1123AL5-100.0000T  
DSC1123AL5-148.5000T  
DSC1121AE5-010.0000T  
DSC1101AL5-112.4400T  
DSC1123AL2-100.0000T



---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC1103AL2-147.4560T  
DSC1121AL5-112.2400T  
DSC1121AE5-022.5792T  
DSC1121AE5-024.5760T  
DSC1121AL5-170.0000T  
DSC1121AL5-024.5760T  
DSC1121AL5-022.5792T  
DSC1121AL5-125.0000T  
DSC1101AE2-027.1200T  
DSC1123AL1-148.5000T  
DSC1103AL1-100.0000T  
DSC1103AE2-212.5000T  
DSC1124AE5-065.0000T  
DSC1101AE5-032.0000T  
DSC1123AL5-156.2500T  
DSC1123AL5-125.0000T  
DSC1103AL2-125.0031T  
DSC1123AE5-148.5000T  
DSC1123AE5-148.3516T  
DSC1123AE5-074.1758T  
DSC1123AE1-125.0000T  
DSC1101AE2-016.3840T  
DSC8121AL2T  
DSC1123AE1-148.3500T  
DSC1123AE1-148.5000T  
DSC1123AL1-150.0000T  
DSC1123AE1-100.0000T  
DSC1101AE3-098.3040T  
DSC6331JI2FB-025.0000T  
DSC6111JI1B-200K000T  
DSC6001JI2B-022.5792T  
DSC6311JI1DB-036.0000T  
DSC6311JI1DB-075.0000T  
DSC6311JI1DB-100.0000T  
DSC6102JI1B-060.0000T  
DSC6101JI2B-019.2000T  
DSC6331JI2EB-012.0000T  
DSC6011JI2B-024.0000T  
DSC6003JI2B-050.0000T  
DSC6311JI2EB-018.4320T  
DSC6301JI2GB-024.0000T  
DSC6311JI1AB-025.0000T  
DSC6011JI2B-018.0000T  
DSC6101JI1B-048.0000T  
DSC6013JI2B-050.0000T  
DSC6001JI1B-027.0000T  
DSC6331JI3CB-018.4320T  
DSC6331JI1CB-018.4320T  
DSC6111JI1B-028.1250T

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6021JI2B-01G31

DSC6112JI2B-028.1250T

DSC6001JI1B-020.0000T

DSC6111JI1B-008.0000T

DSC6331JI2FB-024.5760T

DSC6051JI2B-014.3180T

DSC6011JI1B-006.5536T

DSC6011JI3B-012.0000T

DSC6051JI3B-032K768T

DSC6001JI3B-032K768T

DSC6001JI2B-012.0000T

DSC6011JI2B-008.0000T

DSC6121JI3B-01GPT

DSC6311JI2CB-025.0000T

DSC6111JI3B-019.2000T

DSC6331JI1BB-018.4320T

DSC6001JI2B-007.3730T

DSC6301JI1IB-050.0000T

DSC6102JI1B-500K000T

DSC6101JI1B-019.2000T

DSC6021JI1B-01H4T

DSC6331JI1BB-024.0000T

DSC6001JI3B-005K280T

DSC6001JI3B-004K280T

DSC6021JI1B-01HAT

DSC6003MI2B-014.0000

DSC6003MI2B-026.0000

DSC6101MI2B-048.0000

DSC6001MI3B-004.0960

DSC6111MI2B-027.0000

DSC6111MI2B-024.5454

DSC6331MI2CB-008.0000

DSC6331MI2DB-008.0000

DSC6331MI2EB-008.0000

DSC6011MI2B-025.0000

DSC6011MI2B-056.0000

DSC6101MI2B-006.1679

DSC6003MI3B-032K768

DSC6003MI3B-012.0000

DSC6003MI2B-027.0000

DSC6111MI2B-006.1679

DSC6011MI1B-007.3728

DSC6102MI2B-125K000

DSC6101MI2B-008.0000

DSC6001MI3B-032K768

DSC6003MI2B-080.0000

DSC6003MI2B-032K768

DSC6003MI2B-050.0000

DSC6111MI2B-025.0000

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC6001MI2B-007.3728  
DSC6001MI1B-007.3728  
DSC6011MI2B-007.3728  
DSC6021MI1B-01B1  
DSC6301MI2CB-008.0000  
DSC6001MI1B-032K768  
DSC6001MI2B-032K768  
DSC6001MI2B-027.0000  
DSC6102MI3B-038.4000  
DSC6001MI2B-032.7680  
DSC6111MI3B-033.3333  
DSC6011MI3B-048.0000  
DSC6101MI2B-024.0000  
DSC6101MI1B-050.0000  
DSC6101MI1B-024.0000  
DSC6011MI2B-004.0960  
DSC6311MI2CB-008.0000  
DSC6011MI3B-032.0000  
DSC6001MI1B-080.0000  
DSC6102MI1B-500K000  
DSC6101MI1B-019.2000  
DSC6111MI3B-025.0000  
DSC6011MI2B-024.0000  
DSC6011MI2B-006K144  
DSC6011MI3B-025.0000  
DSC6102MI3B-080.0000  
DSC6101MI1B-027.0000  
DSC6102MI2B-027.0000  
DSC6101MI2B-025.0000  
DSC6112MI2B-025.0000  
DSC6112MI2B-014.7456  
DSC6021MI2B-01K2  
DSC6112MI3B-060.0000  
DSC6121MI2B-01MP  
DSC6122MI2B-01MQ  
DSC6101MI1B-020.0000  
DSC6011MI1B-012.2880  
DSA6001MI1B-024.5760VAO  
DSA6001MI2B-032.7680VAO  
DSA6003MI2B-032K768VAO  
DSA6311MI2CB-008.0000VAO  
DSA6003MI3B-032K768VAO  
DSA6102MI3B-038.4000VAO  
DSC612NI3A-010G  
DSC612NI3A-010T  
DSC613NI2A-0106  
DSC613NI3A-0105  
DSC613NI1A-016E  
DSC613NI1A-016G

---

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

---

DSC613NI3A-01A6

DSC612NI1A-01H3

DSC612NI2A-01K7

DSC612NI3A-013C