



Product Change Notification

TE Connectivity

Product Change Notification: P-20-018896

PCN Date: 08-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of Lead Time changes due to Corona Virus impact on tubing products.

Description of Changes

This is a notification informing TE Connectivity customers that the Lead Times for tubing products are changing due the impact of Covid 19 Virus on Production.

Other attachments:

[PCN - Changes to Tubing lead times](#)

[Appliance Tubing - adjustment lead times 1](#)

[Appliance Tubing - adjustment lead times 2](#)

Reason for Changes:

Document clarification.The Trutnov tubing plant remains open and producing as much heat Shrink tubing as it can however due to the closure of borders in the Czech Republic for reasons of Covid 19 virus protection we are not able to staff the factory at the required levels to keep up with required productivity outputs. This reduction has regrettably forced us to increase Lead Times for the tubing products.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	13-APR-2020

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
1192834001	NO			"8-1190867-4", "CGPT-39/13-6-SP"			
1335390001	NO			"8-1190969-7", "ES-CAP-NO.3-B8-X-50MM"			
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
209731-002	NO			"1191520-1", "RBK-105-KIT-0110-A0"			
3432154007	NO			"6-1192585-5", "RT-375-3/16-X-SP"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053074017	NO			"2-1193843-7", "RNF-100-3/16-6-SP", "RNF-100-3/16-6-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053314033	NO			"6-1193878-2", "RNF-100-1-4-SP"			
5053324010	NO			"5-1193880-0", "RNF-100-1-6-SP"			
5053374008	NO			"9-1193884-9", "RNF-100-1-1/2-6-SP"			
5053394020	NO			"8-1193885-3", "RNF-100-2-0-SP"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			
5068344005	NO			"2-1193941-3", "CGPT-19/9.5-6-SP"			
5070044083	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
5070094021	NO			"8-1193966-2", "RNF-100-3/4-X-SP"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5460874008	NO			"3-1194297-1", "RT-375-1/8-X-SP"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
5677754002	NO			"2-1194503-7", "RNF-3000-39/13-4-SP"			
5751174001	NO			"4-1194564-6", "CGPT-24/8-4-SP"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
627355-002	NO			"8-1194967-9", "RBK-105-KIT-0102-A0"			
6519834003	NO			"1-1195147-1", "VERSAFIT-1/4-4-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
6866744002	NO			"1195392-3", "TUGA-GP-5/2.5-0-SP"			
6904554001	NO			"5-1195421-2", "LSTT-25.4-6-SP"			
7028554007	NO			"2-1195515-6", "RT-375-1/16-X-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
8760694001	NO			"9-1196814-1", "TUGA-GP-20/10-0-SP"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
9859054001	NO			"2-1197616-0", "DCPT-39/13-45-SP"			
CB5018-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5316-000	NO						
CB5406-000	NO			"SST-6-04/97", "6-1899222-4"			
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CF6053-000	NO						
CH03056001	NO			"4-1899462-0", "QSZH-125-NR4-75MM"			
CL0858-000	NO			"SST-48-03/FR/97"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV4360-000	NO			"HT-200-3/8-X-SP"			
D54859-000	NO			"1-1200678-9", "VERSAFIT-KIT-2-COLOR"			
D76139-000	NO			"1200590-6", "VERSAFIT-3/16-KT1-REFILL"			
E31091-000	NO			"1-1200722-2", "VERSAFIT-3/32-KT2-REFILL"			
E40866-000	NO			"7-1200741-1", "RNF-100-MINI-SPL-3/4-BK"			
E42160-000	NO			"6-1201151-2", "DWP-125-KIT3"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EL6529-000	NO						
F27156-000	NO			"8-1200740-9", "VERSAFIT-MINI-SPL-1-BK"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09304001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB09524001	NO						
NB10572001	NO						
NB14234001	NO						
NB14494001	NO						
NB14664001	NO						
NB14684001	NO						
NB14832001	NO						
NB14882001	NO						
NB15704001	NO						
NB15774001	NO						
NB16212001	NO						
NB16994001	NO						
NB17224001	NO						
NB17554001	NO						
NB17794001	NO						
NB18144001	NO						
NB19642001	NO						
NB19914001	NO						
NB20034001	NO						
NB23804001	NO						
NB25862001	NO						
NB25962001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
1335390001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"8-1190969-7", "ES-CAP-NO.3-B8-X-50MM"			
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
3432154007	NO			"6-1192585-5", "RT-375-3/16-X-SP"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			
5070044083	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
5460874008	NO			"3-1194297-1", "RT-375-1/8-X-SP"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
CB5018-000	NO						
CB5316-000	NO						
CB5406-000	NO			"SST-6-04/97", "6-1899222-4"			
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CL0858-000	NO			"SST-48-03/FR/97"			
D54859-000	NO			"1-1200678-9", "VERSAFIT-KIT-2-COLOR"			
D76139-000	NO			"1200590-6", "VERSAFIT-3/16-KT1-REFILL"			
E31091-000	NO			"1-1200722-2", "VERSAFIT-3/32-KT2-REFILL"			
E40866-000	NO			"7-1200741-1", "RNF-100-MINI-SPL-3/4-BK"			
E42160-000	NO			"6-1201151-2", "DWP-125-KIT3"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
F27156-000	NO			"8-1200740-9", "VERSAFIT-MINI-SPL-1-BK"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09312001	NO			"ATUM--12/4-0-STK"			
NB10572001	NO						
NB14234001	NO						
NB14494001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB14664001	NO						
NB14832001	NO						
NB14882001	NO						
NB15774001	NO						
NB16212001	NO						
NB17224001	NO						
NB17554001	NO						
NB18144001	NO						
NB19642001	NO						
NB19914001	NO						
NB20034001	NO						
NB25862001	NO						
NB25962001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
7028554007	NO			"2-1195515-6", "RT-375-1/16-X-SP"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB5018-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CF6053-000	NO						
CL0858-000	NO			"SST-48-03/FR/97"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
1335390001	NO			"8-1190969-7", "ES-CAP-NO.3-B8-X-50MM"			
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
3432154007	NO			"6-1192585-5", "RT-375-3/16-X-SP"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			
5070044083	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5460874008	NO			"3-1194297-1", "RT-375-1/8-X-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
7028554007	NO			"2-1195515-6", "RT-375-1/16-X-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB5018-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CB5316-000	NO						
CB5406-000	NO			"SST-6-04/97", "6-1899222-4"			
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CF6053-000	NO						
CL0858-000	NO			"SST-48-03/FR/97"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV4360-000	NO			"HT-200-3/8-X-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
D54859-000	NO			"1-1200678-9", "VERSAFIT-KIT-2-COLOR"			
D76139-000	NO			"1200590-6", "VERSAFIT-3/16-KT1-REFILL"			
E31091-000	NO			"1-1200722-2", "VERSAFIT-3/32-KT2-REFILL"			
E40866-000	NO			"7-1200741-1", "RNF-100-MINI-SPL-3/4-BK"			
E42160-000	NO			"6-1201151-2", "DWP-125-KIT3"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
F27156-000	NO			"8-1200740-9", "VERSAFIT-MINI-SPL-1-BK"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09312001	NO			"ATUM--12/4-0-STK"			
NB14494001	NO						
NB14832001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
1192834001	NO			"8-1190867-4", "CGPT-39/13-6-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
209731-002	NO			"1191520-1", "RBK-105-KIT-0110-A0"			
3432154007	NO			"6-1192585-5", "RT-375-3/16-X-SP"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053074017	NO			"2-1193843-7", "RNF-100-3/16-6-SP", "RNF-100-3/16-6-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053394020	NO			"8-1193885-3", "RNF-100-2-0-SP"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
5068344005	NO			"2-1193941-3", "CGPT-19/9.5-6-SP"			
5070044083	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
5070094021	NO			"8-1193966-2", "RNF-100-3/4-X-SP"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5460874008	NO			"3-1194297-1", "RT-375-1/8-X-SP"			
5501052008	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
5677754002	NO			"2-1194503-7", "RNF-3000-39/13-4-SP"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
627355-002	NO			"8-1194967-9", "RBK-105-KIT-0102-A0"			
6519834003	NO			"1-1195147-1", "VERSAFIT-1/4-4-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
6866744002	NO			"1195392-3", "TUGA-GP-5/2.5-0-SP"			
7028554007	NO			"2-1195515-6", "RT-375-1/16-X-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
8760694001	NO			"9-1196814-1", "TUGA-GP-20/10-0-SP"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB5018-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CF6053-000	NO						
CH03056001	NO			"4-1899462-0", "QSZH-125-NR4-75MM"			
CL0858-000	NO			"SST-48-03/FR/97"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV4360-000	NO			"HT-200-3/8-X-SP"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09304001	NO						
NB09524001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
1192834001	NO			"8-1190867-4", "CGPT-39/13-6-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
209731-002	NO			"1191520-1", "RBK-105-KIT-0110-A0"			
3432154007	NO			"6-1192585-5", "RT-375-3/16-X-SP"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053074017	NO			"2-1193843-7", "RNF-100-3/16-6-SP", "RNF-100-3/16-6-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053314033	NO			"6-1193878-2", "RNF-100-1-4-SP"			
5053324010	NO			"5-1193880-0", "RNF-100-1-6-SP"			
5053374008	NO			"9-1193884-9", "RNF-100-1-1/2-6-SP"			
5053394020	NO			"8-1193885-3", "RNF-100-2-0-SP"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
5068344005	NO			"2-1193941-3", "CGPT-19/9.5-6-SP"			
5070044083	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
5070094021	NO			"8-1193966-2", "RNF-100-3/4-X-SP"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5460874008	NO			"3-1194297-1", "RT-375-1/8-X-SP"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
5677754002	NO			"2-1194503-7", "RNF-3000-39/13-4-SP"			
5751174001	NO			"4-1194564-6", "CGPT-24/8-4-SP"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
627355-002	NO			"8-1194967-9", "RBK-105-KIT-0102-A0"			
6519834003	NO			"1-1195147-1", "VERSAFIT-1/4-4-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
6866744002	NO			"1195392-3", "TUGA-GP-5/2.5-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6904554001	NO			"5-1195421-2", "LSTT-25.4-6-SP"			
7028554007	NO			"2-1195515-6", "RT-375-1/16-X-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
8760694001	NO			"9-1196814-1", "TUGA-GP-20/10-0-SP"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
9859054001	NO			"2-1197616-0", "DCPT-39/13-45-SP"			
CB5018-000	NO						
CB5147-000	NO			"HRSR-175FR-10", "5-1899230-2"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CF6053-000	NO						
CH03056001	NO			"4-1899462-0", "QSZH-125-NR4-75MM"			
CL0858-000	NO			"SST-48-03/FR/97"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV4360-000	NO			"HT-200-3/8-X-SP"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EL6529-000	NO						
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09304001	NO						
NB09524001	NO						
NB14664001	NO						
NB14684001	NO						
NB15704001	NO						
NB16994001	NO						
NB17224001	NO						
NB17794001	NO						
NB19914001	NO						
NB20034001	NO						
NB23804001	NO						