

Weilburg, August 15, 2022

To whom it may concern

Product Change Note ID ISC.LR(M)1002-E (PCN-220815_LR1002)

FEIG ELECTRONIC GmbH is committed to continuous improvement of our RFID products in order to always provide the best quality, performance, design and availability.

Due to the unexpected discontinuation of a digital component used in our HF Reader ID LR1002-E and ID ISC.LRM1002-E, we are forced to change this component in the next production batch of readers.

The new hardware version is compatible with the previous version including the same RFID interface, communication interface, EMC behavior, hardware and firmware specifications.

It was necessary to use our newest firmware version (V2.05) in this reader, it possible to upgrade existing readers with this new version if you desire to. However, the new readers cannot be loaded with the older V2.04 firmware. We do not anticipate that you will have any issues with this change.

We have made a very slight change to the ordering part number to enable ease in identifying inventory and installed readers if necessary.

Ordering Part Number	Description	Firmware Version	Last Production Run
3758.000.00	ID ISC.LR1002-E	V2.04	31.08.2022
3757.000.00	ID ISC.LRM1002-E	V2.04	

New Ordering Part Number	Description	Firmware Version	Production Beginning
3758.000.01	ID ISC.LR1002-E	V2.05	01.09.2022
3757.000.01	ID ISC.LRM1002-E	V2.05	

Please let us know if you have any questions or concerns

Sincerely,

Wolfgang Meißner
Senior Product Manager

FEIG ELECTRONIC GmbH