

## Product/Process Change Notifications



# PCN - 15 096-R.2

Release Date: September 25 2015

<b>Product Name:</b>	DDR4 TH/SMT/PF		
	DDR4 TH/SMT/PF		
<b>Product Manager:</b>	Bonnie Liu		
<b>Subject:</b>	Notification of Change with Immediate Effectivity		
<b>Distribution:</b>	General		
<b>Type of Change:</b>	Design Change		
<b>Change Description:</b>	<p>Change the latch rib length from 2.5mm to 1.25mm, change the bump straight line length from 0.97mm to 0.47mm.                  Add a chamfer on housing tower slot, the bottom of the slot retains the same size.</p>		
<b>Reason for Change:</b>	<p>To reduce the latch overstress force on housing tower.</p> <p><b>By Revision 2</b> - Part Numbers starting with "10129206-" are removed from the affected list (9Nos) which are unaffected by this change and were added by mistake.</p>		
<b>Affected Parts:</b>	10124632, 10129040, 10130419, 10124677, 10133530, 10135356, 10124806		
<b>Effective Date of Change:</b>	October 15, 2015		
<b>Last Time Buy Date:</b>	NA		
<b>Last Disty Return Date:</b>	NA		
<b>Last Time Shipment Date</b>	NA		
<b>Datasheet Attached?</b>	NA		
<b>Qual/Test Data Attached?</b>	NA		
<b>Samples Availability Date:</b>	September	28	2015
<b>Available Alternatives?</b>	N/A		
<b>Questions?</b>	Contact your local FCI Representative, or Product Manager		
	Bonnie Liu / Product Manager		
	+86 769 88669459/ Bonnie.liu@fci.com		

**Note:**

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date.  
 PCN is considered approved by the customer if no communication is received within 3 weeks