


Product Discontinuation Notice


May, 2010

Discontinuation of DS relay (1.5V)



1. Reason: Low market demand

2. Affected parts:

 <p>DS relays</p>	<p>2 Form C 1.5 V DC type</p>	<p>DS2E-○○-DC1.5V</p>
---	-----------------------------------	-----------------------

3. Last time buy: End of August 2010

4. Substitution:

<p>TX relay 1.5 V DC type</p>	<p>TX2○-○-1.5V</p>
-----------------------------------	--------------------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref# T-1169)