

Timers 88 857 xxx

Phase Out - Internal

| April 2017

- The reason for the phase out is due to an obsolescence by the supplier of some of the key components
- We are investing in a new range, with more performance in order to be able to offer a product solution for this, but unfortunately these replacements are not yet available
 - This range will join the Syr-line family
 - Expected completion Q4 2017 with pre-launch info in Q3



Part Numbers to be Phased Out

88857003 88857820
88857005* 88857821
88857103 88857822
88857105* 88857829
88857301 88857831
88857302 88857832
88857307 88857833
88857311 88857834
88857400 88857835
88857406 88857836
88857409 88857837
88857601 88857841
88857604
88857607
88857701*
88857704
88857707
88857808
88857809

- *Commercialization stop on these 3 part numbers is estimated to be September, but the exact date can vary depending on the demand and the components left
- Production on the rest of the part numbers will stop immediately

THANK YOU
FOR YOUR ATTENTION