

Product Replacement Notification	
AFFECTED PART NUMBER(S): LZ4-00WW08-xxxx; LZ4-40WW08-xxxx; LZ9-00WW00-xxxx; LZ9-J0WW00-xxxx; LZ9-M0WW00-xxxx; LZC-00WW0R-xxxx; LZC-70WW0R-xxxx; LZC-C0WW0R-xxxx; L郑-00WW0R-xxxx; L郑-0WW0R-xxxx;	PCN No. 00019
PART DESCRIPTION: Warm White emitters on LZ4, LZ9, LZC, and L郑 platform	DATE: 4/30/2015
RECOMMENDED REPLACEMENT PART NUMBER(S): Gallery White LZ4, LZ9, LZC & L郑 emitters at 2700K, 2850K & 3000K and 3 SDCM to replace WW LZ4, LZ9, LZC & L郑 emitters as applicable.	
REASON FOR PHASE OUT: General lighting is moving towards high quality CRI>90 warm white products. Therefore replacing CRI>80 WW emitters with GW CRI98 emitters at 2700K, 2850K and 3000K & 3 SDCM.	
LAST ORDER DATE: Existing orders will be fulfilled on a case by case basis. New orders will be recommended to use GW.	LAST SHIPMENT DATE: 7/31/2015
DISPOSITION OF EXISTING INVENTORY: Use up current inventory	
NOTE:	
CONTACT PERSON: <i>Ishita Goswami</i> Product Manager 651 River Oaks Parkway San Jose, CA 95134 <i>igoswami@ledengin.com</i>	