



# Product Change Notice

PCN Number: 15-0940-01  
Issue Date: 09-FEBRUARY-2016

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP336ECT-L/TR	SP336ECT-L	SP336ECY-L/TR	SP336ECY-L
SP336EET-L/TR	SP336EET-L	SP336EEY-L/TR	SP336EEY-L
SP337EBCT-L/TR	SP337EBCT-L	SP337EBCY-L/TR	SP337EBCY-L
SP337EBET-L/TR	SP337EBET-L	SP337EBEY-L/TR	SP337EBEY-L
SP337EUCT-L/TR	SP337EUCT-L	SP337EUCY-L/TR	SP337EUCY-L
SP337EUET-L/TR	SP337EUET-L	SP337EUEY-L/TR	SP337EUEY-L

**CHANGE CATEGORY:**

- |  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material                            | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                              | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Foundry |                                    |   |

**DESCRIPTION OF CHANGE:**

Qualification of alternate foundry subcon, Silan.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 09-MAY-2016

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.