

PRODUCT DISCONTINUATION

#PD-ION-C3ZV-16

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ION	CNC	Discontinuation	Notify Distributors and Field	9/22/2016

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The 37 pin male subcon 2300973 has been discontinued from the Phoenix Contact's subcon family. This is due to unavailability of components to assemble product. There is no plans for a replacement part at this time. We apologize for any inconvenience this may cause you.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y


Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 9/22/2016

Last Scheduled Ship from Phoenix Contact: 9/22/2016

PRODUCT DISCONTINUATION

Previous Product	(if applicable)	New Product
		

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

ANDRES SUAZO WILDT
ASuazo@phoenixcon.com

Thank you,



Ira Sharp, Product Marketing Manager

PRODUCT DISCONTINUATION

Discontinued Part#	Type Description	Replacement Part#	Type Description
2300973	SUBCON 37/M-SH		