



# Product Change Notification

## TE Connectivity

Product Change Notification: P-22-023378

PCN Date: 15-SEP-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
D-099-WASHER-SN63, -SN96, BI58, -PB36, -CD18

**Description of Changes**  
The current fabrication of non-precious Indalloy solders, Tape & Reel, and Flux Coated Preforms resides at the Indium Corporation, Business Park Drive location in Utica, NY (BPD). Operations will move the current equipment set, operations staff, and support services for non-precious Indalloy solder Preforms, Tape & Reel, and Flux Coated Preforms to the Indium Corporation, Success Drive, Rome, NY location (RMD).

**Reason for Changes:**  
Product improvement.Solder WASHER suppliers (Indium) expanding into the Rome, NY facility will allow for immediate capacity growth, accommodate space for additional expansion, and improve supply chain redundancy to ensure customer satisfaction.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	15-SEP-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	05-JAN-2023

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">622025-000</a>	NO			"2-1194916-0", "D-144-25"			
<a href="#">644529-000</a>	NO			"3-1195091-1", "CWT-4174-W122-5/9"			
<a href="#">A39093-000</a>	NO			"8-1201998-5", "B-155-11"			
<a href="#">A70754-000</a>	NO			"8-1201998-9", "B-155-03"			
<a href="#">A88975-000</a>	NO			"9-1201998-0", "B-155-07"			
<a href="#">C21881-000</a>	NO			"7-1202000-4", "B-155-9004"			
<a href="#">C67976-000</a>	NO			"7-1202000-5", "B-155-9001"			
<a href="#">CF6147-000</a>	NO			"B-044-24-N-LF"			
<a href="#">D42180-000</a>	NO			"1201999-3", "B-155-05"			
<a href="#">D61414-000</a>	NO			"2-1202048-4", "B-155-1501"			
<a href="#">E38778-000</a>	NO			"1201999-9", "B-155-3803"			
<a href="#">E74832-000</a>	NO			"8-1202000-3", "B-155-9003"			
<a href="#">E77815-000</a>	NO			"2-1202048-9", "B-155-1503"			
<a href="#">F40876-000</a>	NO			"8-1202000-7", "B-155-9002"			

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">622025-000</a>	NO			"2-1194916-0", "D-144-25"			
<a href="#">644529-000</a>	NO			"3-1195091-1", "CWT-4174-W122-5/9"			
<a href="#">A39093-000</a>	NO			"8-1201998-5", "B-155-11"			
<a href="#">A70754-000</a>	NO			"8-1201998-9", "B-155-03"			
<a href="#">A88975-000</a>	NO			"9-1201998-0", "B-155-07"			
<a href="#">C21881-000</a>	NO			"7-1202000-4", "B-155-9004"			
<a href="#">C67976-000</a>	NO			"7-1202000-5", "B-155-9001"			
<a href="#">CF6147-000</a>	NO			"B-044-24-N-LF"			
<a href="#">D42180-000</a>	NO			"1201999-3", "B-155-05"			
<a href="#">D61414-000</a>	NO			"2-1202048-4", "B-155-1501"			
<a href="#">E38778-000</a>	NO			"1201999-9", "B-155-3803"			
<a href="#">E74832-000</a>	NO			"8-1202000-3", "B-155-9003"			
<a href="#">E77815-000</a>	NO			"2-1202048-9", "B-155-1503"			
<a href="#">F40876-000</a>	NO			"8-1202000-7", "B-155-9002"			