



**Microsemi Corporation**

July 16, 2015

**Product Discontinuance Notification (PDN) No: PDN 2015-07-0001**

**Description:**

Microsemi is announcing the discontinuance of LX2260 and LX2273

**Reason for Discontinuance:** No Demand for over 2 years.

**Customer Impact:** None

**Replacement Parts:** Not Applicable

**Last Order Date:** Not Applicable

**Last Shipment Date:** Not Applicable

**Products Affected by this Discontinuance:**

**LX2260 (Apply to all packages)**

**LX2273 (Apply to all packages)**

**Contact Information:**

Pradeep Ravipati

Quality Manager

Tel. # +1 (408) 643 6401

Email: [pradeep.ravipati@microsemi.com](mailto:pradeep.ravipati@microsemi.com)



Regards,

Microsemi Corporation

Any projected dates in this notification are based on the most current product information at the time this PDN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor.

This PDN is confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

**Discontinuance Notice**