



The DNA of tech.



SPECTROL WIREWOUND MULTITURNS POSITION SENSORS INTRODUCTION OF A NEW LUBRICANT ON SERIES : 162 /164 /502 / 552 / 802 / 830 / 852 / 860 / 872 / 500

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Olivier Gaston
71 CHEMIN DE LA MAUNIERE
-
HYERES France 83400
Phone: +33494123050
Fax: +33494123051
olivier.gaston@vishay.com

Europe

Olivier Gaston
71 CHEMIN DE LA MAUNIERE
-
HYERES France 83400
Phone: +33494123050
Fax: +33494123051
olivier.gaston@vishay.com

Asia

Olivier Gaston
71 CHEMIN DE LA MAUNIERE
-
HYERES France 83400
Phone: +33494123050
Fax: +33494123051
olivier.gaston@vishay.com

Description of Change: Introduction of an alternative lubricant for the lubrication of the sliding contact of various wirewound multiturn Series (all ohmic values).

Classification of Change: The current lubricant is obsolete.

Expected Influence on Quality/Reliability/Performance: None

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay Spectrol

Time Schedule:

Start Shipment Date: Mon Sep 25, 2023

Sample Availability: Yes - On request

Product Identification: Date Code

Qualification Data: Data available upon request

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Thu Apr 27, 2023 or as specified by contract.

Issued By: Olivier Gaston, olivier.gaston@vishay.com



The DNA of tech.™

Product Change Notification



Product Group: SF/Fri Jan 20, 2023/PCN-SF-00323-2023-REV-0

162*	164*	502*	552*	802*
830*	852*	860*	872*	500*