



Title of Change:	Update to PD23406ZA - OPN#; FDS4141-F085 Replacement OPN# Correction
Last Time Buy Date:	NA
Last Ship Date:	NA
Contact information:	Contact your local ON Semiconductor Sales Office or Madoka.Wynveen@onsemi.com
Type of notification:	Customers must notify ON Semiconductor (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

ON Semiconductor wishes to inform customers of this update to PD23406ZA, announcing the correction of FDS4141-F085 replacement part in the previously discontinued part listed in this notice.

This update notice is issued upon customer's request.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)
 ☎ +1 765 868 5022
 USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)
 ☎ +421 33790 2229
 Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)
 ☎ +81 3 5817 1060
 Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)
 ☎ +852 2689 0209
 China

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Device to be Discontinued	Replacement part	Supplier
FDS4141-F085	NVTF5014P04M8L	N/A



Appendix A: Changed Products

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FDS4141-F085			NVTFS014P04M8L	