



Product Change Notification

Date Issued :	June 22, 2022	PCN Number :	512249
Reason for Change :	Obsolete		
Description of Change :	This notification is to inform you that Molex will no longer support this product due Toray resin compromised UL qualification. After 18/Aug/2022, we can only supply without UL. UL qualification compromised with original Resin from Toray, from 18/Aug/2022 we will be able to ship out without UL recognition (Without Label : LTB 31/Dec/2022, LTS 31/Mar/2023)		
Reason for Short Notice :	Special Request		
Planned Implementation Date :	August 31, 2022		
Recommended replacement parts :	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts :	July 01, 2022		
Last Time Ship Date for Obsolete Parts :	August 17, 2022		

RELEASED

After Picture

Overview

- This notification is to inform you that Molex will no longer support this product due Toray resin compromised UL qualification.

After 18/Aug/2022, we can only supply without UL.

UL qualification compromised with original Resin from Toray, from 18/Aug/2022 we will be able to ship out without UL recognition (Without Label : LTB 31/Dec/2022, LTS 31/Mar/2023)

- Product Impact

- Obsolescence with Replacement (Refer to PCN #512035)

- See attached for Impacted part list vs Replacement Part List
- Replacement Part is No impact to Form, Fit or Function.
- LTB/LTS dates are immediate

Contents	Impacted	Replacement
Part Number	54548**33, 54548**71 54550**33, 54550**33	54548**34, 54548**72 54550**34, 54550**72
Resin	TORAY LCP UL-94 V0 (Revocation)	SUMITOMO LCP UL-94 V0

1

Molex Confidential Information
© 2016 Molex – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



RELEASED

"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.

For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link

mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512249

or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512249** " in the e-mail Subject line for faster response.

[Molex, LLC](#)

2222 Wellington Court

Lisle, IL 60532

TEL (800) 786-6539

www.molex.com

Molex Part Number	Replacement part number:
545482033	545482034
545481433	545481434
545481333	545481334
545481233	545481234
545481033	545481034
545480833	545480834
545480733	545480734
545480633	545480634
545480533	545480534
545480433	545480434
545482671	545482672
545482471	545482472
545482271	545482272
545482071	545482072
545481871	545481872
545481671	545481672
545481571	545481572
545481471	545481472
545481371	545481372
545481271	545481272
545481071	545481072
545480971	545480972
545480871	545480872
545480771	545480772
545480671	545480672
545480571	545480572
545480471	545480472
545502433	545502434
545502033	545502034
545501833	545501834
545501533	545501534
545501233	545501234
545501033	545501034
545500933	545500934
545500833	545500834
545500633	545500634
545500533	545500534
545502671	545502672
545502471	545502472
545502171	545502172
545502071	545502072
545501871	545501872
545501671	545501672
545501471	545501472

545501271	545501272
545501071	545501072
545500971	545500972
545500871	545500872
545500771	545500772
545500671	545500672
545500571	545500572
545500471	545500472