



Product Change Notification / SYST-07LJQA059

Date:

08-Sep-2021

Product Category:

Microprocessors

PCN Type:

Document Change

Notification Subject:

Data Sheet - SAM9X35 Data Sheet

Affected CPNs:

[SYST-07LJQA059_Affected_CPN_09082021.pdf](#)

[SYST-07LJQA059_Affected_CPN_09082021.csv](#)

Notification Text:

SYST-07LJQA059

Microchip has released a new Product Documents for the SAM9X35 Data Sheet of devices. If you are using one of these devices please read the document located at [SAM9X35 Data Sheet](#).

Notification Status: Final

Description of Change:– Template update: Moved from Atmel to Microchip template.

- The datasheet is assigned a new document number (DS60001730) and revision letter is reset to A.
- Document number DS60001730 revision A corresponds to what would have been 11055 revision G.
- ISBN number assigned.

Section 10. "Boot Strategies"

Updated Table 10-4 "PIO Driven During Boot Program Execution".

Section 14. "Real-time Clock (RTC)"

Section 14.6.1 "RTC Control Register", Section 14.6.2 "RTC Mode Register", Section 14.6.5 "RTC Time Alarm Register", Section 14.6.6 "RTC Calendar Alarm Register": removed sentence on write protection.

Section 29. "DDR SDR SDRAM Controller (DDRSDC)" Section

29.7.4 "DDRSDC Timing Parameter 0 Register": updated TWTR description.

Section 46. "Electrical Characteristics"

Updated:

- Table 46-7 "Main Oscillator Characteristics", Figure 46-2 "Main Oscillator Schematics"
- Table 46-13 "XIN32 Clock Characteristics": XIN32 Clock min and max rise and fall times updated.
- Figure 46-19 "SSC Transmitter, TK and TF in Input", Figure 46-21 "SSC Receiver, RK in Input and RF in Output", Figure 46-22 "SSC Receiver, RK and RF in Output"

Section 50. "Errata"

Added

- "USART: No frame error detected when the expected last data bit sampled at 1".
- "PMC: Bit OSCSELS in PMC_SR does not work"

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 8 Sept 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[SAM9X35 Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

AT91SAM9X35-CU

AT91SAM9X35-CU-999