



PRODUCT CHANGE NOTIFICATION

Date issued: July 2, 2013

PCN #: RFISS-2013001

PCN # RFISS-2013001: LAST TIME BUY NOTIFICATION

Dear Valued Customer,

This letter is being sent to advise that the Transistor Solutions Division (RFISS) of Microsemi is announcing the End of Life (EOL) for the devices listed in the table below. If you have purchased any of the Products listed in the table below, over the past three (3) years, you are receiving this letter.

Lead Frame	Product Family	Products Affected
B001	MRF5812	MRF5812, MRF5812R1, MRF5812R2, MRF5812G, MRF5812GR1, MRF5812GR2
	MRF4427	MRF4427, MRF4427R1, MRF427R2, MRF4427G, MRF4427GR1, MRF4427GR2
	MRF5943	MRF5943, MRF5943R1, MF5943R2, MRF5943G, MRF5943GR1, MRF5943GR2
	MRF8372	MRF8372, MRF8372R1, MRF8372R2, MRF8372G, MRF8372GR1, MRF8372GR2
B011	MRF581	MRF581A, MRF581AG, MRF581AGT, MRF581AT,
	MRF581G	MRF581G, MRF581GT
	MRF559	MRF559, MRF559G, MRF559GT, MRF559T
B012	BFR96	BFR96, BFR96G
B013	MRF553	MRF553, MRF553G, MRF553GT, MRF553T
	MRF555	MRF555, MRF555G, MRF555GT, MRF555T

The decision to discontinue these products is due to the availability of the lead frames needed to manufacture the products. The lead frame tooling has been de-commissioned; therefore, our supplier is no longer able to provide Microsemi with the necessary key component to manufacture the products listed.

Microsemi does not anticipate any issues in supporting its current backlog on record as of June 28, 2013.

The Transistor Solutions Division (RFISS) apologizes for any inconvenience this may create for you and will do it's very best to support any additional requirements for the devices affected by this End of Life notification.

If you have any questions concerning this notification, please contact:

Richard Pender
Transistor Product Manger
408-764-2481
Richard.pender@microsemi.com