



Product Change Notification

TE Connectivity

Product Change Notification: E-21-005267-C

PCN Date: 31-MAY-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Adjustment on the solder profile:Resistance to soldering heat: THT IEC 60068-2-20

Description of Changes

Changing soldering profile from:Resistance to soldering heat THT IEC 60068-2-20 265C/10s changed to Resistance to soldering heat THT IEC 60068-2-20 260C/10s

Reason for Cancellation:

PCN rejected: improper data quality

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393763-4	NO			"V23100V4024A", "V23100V4024A000"			
1-1393763-7	NO			"V23100V4024A 11", "V23100V4024A011"			
1-1393763-9	NO			"V23100V4305B 10", "V23100V4305B010"			
1393763-1	NO			"V23100V4005A", "V23100V4005A000"			
2-1393763-3	NO			"V23100V4305C 11", "V23100V4305C011"			
4-1393763-0	NO			"V23100V4324C", "V23100V4324C000"			
4-1393763-4	NO			"V23100V4505A", "V23100V4505A000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393763-4	NO			"V23100V4024A", "V23100V4024A000"			
1-1393763-7	NO			"V23100V4024A 11", "V23100V4024A011"			
1-1393763-9	NO			"V23100V4305B 10", "V23100V4305B010"			
1393763-1	NO			"V23100V4005A", "V23100V4005A000"			
4-1393763-0	NO			"V23100V4324C", "V23100V4324C000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4- 1393763- 4	NO			"V23100V4505A", "V23100V4505A000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 1393763- 4	NO			"V23100V4024A", "V23100V4024A000"			
1- 1393763- 9	NO			"V23100V4305B 10", "V23100V4305B010"			
1393763- 1	NO			"V23100V4005A", "V23100V4005A000"			
4- 1393763- 0	NO			"V23100V4324C", "V23100V4324C000"			
4- 1393763- 4	NO			"V23100V4505A", "V23100V4505A000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 1393763- 4	NO			"V23100V4024A", "V23100V4024A000"			
1- 1393763- 9	NO			"V23100V4305B 10", "V23100V4305B010"			
1393763- 1	NO			"V23100V4005A", "V23100V4005A000"			
4- 1393763- 4	NO			"V23100V4505A", "V23100V4505A000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1- 1393763- 4	NO			"V23100V4024A", "V23100V4024A000"			
1- 1393763- 7	NO			"V23100V4024A 11", "V23100V4024A011"			
1- 1393763- 9	NO			"V23100V4305B 10", "V23100V4305B010"			
1393763- 1	NO			"V23100V4005A", "V23100V4005A000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1393763-0	NO			"V23100V4324C", "V23100V4324C000"			
4-1393763-4	NO			"V23100V4505A", "V23100V4505A000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1393763-3	NO			"V23100V4305C 11", "V23100V4305C011"			