

# Part Discontinuity Notification

PDN17-5 – MDM Backshells Kits – Rev A



C&K components SAS – 2 rue Berthollet - B.P. 359 F-39105 Dole Cedex - FRANCE  
Telephone: +33 (0)3 84 72 81 12 - Facsimile: +33 (0)3 84 72 95 92 – [www.ckswitches.com](http://www.ckswitches.com)

Document subject to change without prior notice  
Diffusion: no restriction

---

## Document revision

Revision	Date	Description	Author
A	April 12th, 2017	Creation	R. ANTOINE



C&K components SAS – 2 rue Berthollet - B.P. 359 F-39105 Dole Cedex - FRANCE  
Telephone: +33 (0)3 84 72 81 12 - Facsimile: +33 (0)3 84 72 95 92 – [www.ckswitches.com](http://www.ckswitches.com)

Document subject to change without prior notice  
Diffusion: no restriction

---

## Summary

1. Purpose .....	4
2. Discontinuation details.....	4
2.1 Part numbers affected.....	4
2.2 Possible replacement.....	5
2.3 Reason for discontinuation.....	6
3. Date of application.....	6
4. Support .....	6



C&K components SAS – 2 rue Berthollet - B.P. 359 F-39105 Dole Cedex - FRANCE  
Telephone: +33 (0)3 84 72 81 12 - Facsimile: +33 (0)3 84 72 95 92 – [www.ckswitches.com](http://www.ckswitches.com)

Document subject to change without prior notice  
Diffusion: no restriction

## 1. Purpose

Part Discontinuity of MDM Backshells Kits.

## 2. Discontinuation details

### 2.1 Part numbers affected

Product
All kits of MDM Backshells

P/N	Description
C115288-6267	MDM-115288-6267-A174-FR022
C115288-6268	MDM-115288-6268-A174-FR022
C115288-6269	MDM-115288-6269-A174-FR022
C115288-6270	MDM-115288-6270-A174-FR022
C115288-6271	MDM-115288-6271-A174-FR022
C115288-6272	MDM-115288-6272-A174-FR022
C115288-6273	MDM-115288-6273-FR172-FR022
C115288-6274	MDM-115288-6274-FR172-FR022
C115288-6275	MDM-115288-6275-FR172-FR022
C115288-6276	MDM-115288-6276-FR172-FR022
C115288-6277	MDM-115288-6277-FR172-FR022
C115288-6278	MDM-115288-6278-FR172-FR022
C115366-9687C	MDM-115366-9687-A174(3401)
C115366-9688C	MDM-115366-9688-A174(3401)
C115366-9689C	MDM-115366-9689-A174(3401)
C115366-9690C	MDM-115366-9690-A174(3401)
C115366-9691C	MDM-115366-9691-A174(3401)
C115366-9692C	MDM-115366-9692-A174(3401)
C115366-9693C	MDM-115366-9693-FR172(3401)
C115366-9694C	MDM-115366-9694-FR172(3401)
C115366-9695C	MDM-115366-9695-FR172(3401)
C115366-9696C	MDM-115366-9696-FR172(3401)
C115366-9697C	MDM-115366-9697-FR172(3401)
C115366-9698C	MDM-115366-9698-FR172(3401)

## 2.2 Possible replacement

Part Number affected		Alternative Proposal	
P/N	Designation	P/N	Designation
C115288-6267	MDM-115288-6267-A174-FR022	C115288-6417 and C115288-6511	MDM-BCKS-9-01-A174-FR022 Screwlock for Backshell MDM
C115288-6268	MDM-115288-6268-A174-FR022	C115288-6418 and C115288-6511	MDM-BCKS-15-01-A174-FR022 Screwlock for Backshell MDM
C115288-6269	MDM-115288-6269-A174-FR022	C115288-6419 and C115288-6511	MDM-BCKS-21-01-A174-FR022 Screwlock for Backshell MDM
C115288-6270	MDM-115288-6270-A174-FR022	C115288-6420 and C115288-6511	MDM-BCKS-25-01-A174-FR022 Screwlock for Backshell MDM
C115288-6271	MDM-115288-6271-A174-FR022	C115288-6421 and C115288-6511	MDM-BCKS-31-01-A174-FR022 Screwlock for Backshell MDM
C115288-6272	MDM-115288-6272-A174-FR022	C115288-6422 and C115288-6511	MDM-BCKS-37-01-A174-FR022 Screwlock for Backshell MDM
C115288-6273	MDM-115288-6273-FR172-FR022	C115288-6424 and C115288-6511	MDM-BCKS-9-01-FR172-FR022 Screwlock for Backshell MDM
C115288-6274	MDM-115288-6274-FR172-FR022	C115288-6425 and C115288-6511	MDM-BCKS-15-01-FR172-FR022 Screwlock for Backshell MDM
C115288-6275	MDM-115288-6275-FR172-FR022	C115288-6426 and C115288-6511	MDM-BCKS-21-01-FR172-FR022 Screwlock for Backshell MDM
C115288-6276	MDM-115288-6276-FR172-FR022	C115288-6427 and C115288-6511	MDM-BCKS-25-01-FR172-FR022 Screwlock for Backshell MDM
C115288-6277	MDM-115288-6277-FR172-FR022	C115288-6428 and C115288-6511	MDM-BCKS-31-01-FR172-FR022 Screwlock for Backshell MDM
C115288-6278	MDM-115288-6278-FR172-FR022	C115288-6429 and C115288-6511	MDM-BCKS-37-01-FR172-FR022 Screwlock for Backshell MDM
C115366-9687C	MDM-115366-9687-A174(3401)	C115366-1032D and C115366-1060C	340108701B 340103218B
C115366-9688C	MDM-115366-9688-A174(3401)	C115366-1033D and C115366-1060C	340108702B 340103218B
C115366-9689C	MDM-115366-9689-A174(3401)	C115366-1034D and C115366-1060C	340108703B 340103218B
C115366-9690C	MDM-115366-9690-A174(3401)	C115366-1035D and C115366-1060C	340108704B 340103218B
C115366-9691C	MDM-115366-9691-A174(3401)	C115366-1036D and C115366-1060C	340108705B 340103218B
C115366-9692C	MDM-115366-9692-A174(3401)	C115366-1037D and C115366-1060C	340108706B 340103218B
C115366-9693C	MDM-115366-9693-FR172(3401)	C115366-1032C and C115366-1060C	340108708B 340103218B
C115366-9694C	MDM-115366-9694-FR172(3401)	C115366-1033C and C115366-1060C	340108709B 340103218B



C&K components SAS – 2 rue Berthollet - B.P. 359 F-39105 Dole Cedex - FRANCE  
 Telephone: +33 (0)3 84 72 81 12 - Facsimile: +33 (0)3 84 72 95 92 – www.ckswitches.com

Document subject to change without prior notice  
 Diffusion: no restriction

---

C115366-9695C	MDM-115366-9695-FR172(3401)	and	C115366-1034C	340108710B
			C115366-1060C	340103218B
C115366-9696C	MDM-115366-9696-FR172(3401)	and	C115366-1035C	340108711B
			C115366-1060C	340103218B
C115366-9697C	MDM-115366-9697-FR172(3401)	and	C115366-1036C	340108712B
			C115366-1060C	340103218B
C115366-9698C	MDM-115366-9698-FR172(3401)	and	C115366-1037C	340108713B
			C115366-1060C	340103218B

### 2.3 Reason for discontinuation

- Duplicate products with standard MDM Backshells ESCC/3401-087 certified and CS FR022 quality level.

### 3. Date of application

- Last Time Buy: No order accepted after April 12<sup>th</sup>, 2017.
- Date of discontinuation: April 12<sup>th</sup>, 2017.

### 4. Support

For any question, feel free to contact your Sales Representative.