



**Product Change Notification** **CN-202201004F**

**Issue date:** 15 Feb 2022

**Effective date:** 03 Jan 2023

Here's your personalized quality information concerning products our customers and partners purchased from Nexperia.

For more details please contact your respective Nexperia CSR/AM.



**Release of Business Group Bipolar Discretes Q-Portfolio Wave 3**

**Change Category**

- Wafer
- Fab
- Process
- Wafer
- Fab
- Materials
- Wafer
- Fab
- Location
- Assembl
- y
- Process
- Assembl
- Materials
- Assembl
- y
- Location
- Product Marking
- Mechanical
- Specification
- Packing/Shipping/Labelin
- g
- Test
- Location
- Test
- Process
- Test
- Equipmen
- t
- Design
- Errata
- Electrical
- spec./Tes
- t
- coverage

**Details of this change**

Nexperia's Business Group Bipolar Discretes will remove the "Automotive qualification status" for selected parts of its standard portfolio. At the same time, a new portfolio with Automotive qualified products "Q-Portfolio" will be released. Types of the new Q-Portfolio will be named with "-Q" at the end of the type-number. This PCN contains a cross list for the product types which will be introduced at present.

202201004F\_Automotive\_Plus\_Wave3\_crosslist.xlsx:  
[https://qcm.nexperia.com/Document/DOC-535481/202201004F\\_Automotive\\_Plus\\_Wave3\\_crosslist.xlsx](https://qcm.nexperia.com/Document/DOC-535481/202201004F_Automotive_Plus_Wave3_crosslist.xlsx)

202201004F\_Automotive\_Plus\_Wave3\_crosslist.pdf:  
[https://qcm.nexperia.com/Document/DOC-535480/202201004F\\_Automotive\\_Plus\\_Wave3\\_crosslist.pdf](https://qcm.nexperia.com/Document/DOC-535480/202201004F_Automotive_Plus_Wave3_crosslist.pdf)

202201004F\_Automotive\_Plus\_Wave3-FORM.pdf:  
[https://qcm.nexperia.com/Document/DOC-534524/202201004F\\_Automotive\\_Plus\\_Wave3-FORM.pdf](https://qcm.nexperia.com/Document/DOC-534524/202201004F_Automotive_Plus_Wave3-FORM.pdf)

202201004F\_Automotive\_Plus\_Wave3-Delta-Qualification-Matrix-ZVEI-4\_1.pdf: [https://qcm.nexperia.com/Document/DOC-534523/202201004F\\_Automotive\\_Plus\\_Wave3-Delta-Qualification-Matrix-ZVEI-4\\_1.pdf](https://qcm.nexperia.com/Document/DOC-534523/202201004F_Automotive_Plus_Wave3-Delta-Qualification-Matrix-ZVEI-4_1.pdf)

202201004F\_Automotive\_Plus\_Wave3-Delta-Qualification-Matrix-ZVEI-4\_1.pdf: [https://qcm.nexperia.com/Document/DOC-534522/202201004F\\_Automotive\\_Plus\\_Wave3-Delta-Qualification-Matrix-ZVEI-4\\_1.pdf](https://qcm.nexperia.com/Document/DOC-534522/202201004F_Automotive_Plus_Wave3-Delta-Qualification-Matrix-ZVEI-4_1.pdf)

### **Why do we implement this change?**

To inform customers of standard products that the automotive qualification status will be removed as of 1st January 2023. To inform customers who need automotive qualified products about the change of the type-number and the 12NC (ordering code). If required, customers must change their orderbook to the related Q-parts. In rare cases not all package variants are available as Q-part. Then the default packing variant needs to be used (e.g., order code ending -115).

### **Identification of affected products**

Products of the new Q-Portfolio can be identified by new type number and new 12NC order code. The marking on the product is unchanged.

## Management summary

New type number and ordering code (12NC) for Automotive qualified products. Removal of "Automotive qualification status" of current (standard) products.

## Product availability

### Production

Planned first shipment: 01 Jan 2022

### Sample information

Samples are available upon request

## Impact

No impact to the product's functionality anticipated

For all parts which are affected by this PCN the AEC-Q101 qualification status will be removed, and the legal disclaimer of the related data sheets will change to "not usable for Automotive applications". PPAP support will not be granted for these standard products anymore. The new Q-portfolio products will be identical to the current products as on implementation day. There will be no impact on fit, form, function or reliability. Specifications as stated in the data sheets are guaranteed. No technical qualification is needed at customer side.

### Data sheet revision

A new datasheet will be issued

### Disposition of old products

The changes on standard portfolio will apply from 1st of January 2023 onwards (products with production date-code before 1st of January 2023 are guaranteed AEC Q-101 compliant)

## Timing and logistics

Planned 1st shipment for the different portfolios: The Q-Portfolio is available for shipment from 1st January 2022 onwards. The changes on standard portfolio will apply from 1st of January 2023 onwards.

## Feedback

Your acknowledgement of this change, conform JEDEC J-STD-046, is expected till 17 Mar 2022. Lack of acknowledgement of the PCN constitutes acceptance of the change.

## Remarks

New datasheets for Q-portfolio products are available on Nexperia.com. Updated datasheets of standard products will be available on Nexperia.com with PCN implementation (1st of January 2023). An example of both data sheet versions is attached to this PCN to highlight the differences.

## Contact and support

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support Team.

For specific questions on this notice or the products affected please contact our specialist directly: [pcn@nexperia.com](mailto:pcn@nexperia.com)

In case of distribution, please contact you distribution partner.

## About Nexperia B.V.

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

**Affected Sales Item Affected Orderable Part Number**

|              |               |
|--------------|---------------|
| 934055193115 | 1PS76SB40,115 |
| 934055193135 | 1PS76SB40,135 |
| 934054923115 | 1PS76SB70,115 |
| 934054923135 | 1PS76SB70,135 |
| 934056394115 | 1PS79SB30,115 |
| 934056394135 | 1PS79SB30,135 |
| 934056394315 | 1PS79SB30YL   |
| 934056394335 | 1PS79SB30Z    |
| 934054924115 | 1PS79SB70,115 |
| 934054924315 | 1PS79SB70,315 |
| 934031780115 | 2PA1576Q,115  |
| 934031780135 | 2PA1576Q,135  |
| 934031790115 | 2PA1576R,115  |
| 934031790135 | 2PA1576R,135  |
| 934031800115 | 2PA1576S,115  |
| 934031800135 | 2PA1576S,135  |
| 934031750115 | 2PC4081Q,115  |
| 934031750135 | 2PC4081Q,135  |
| 934031760115 | 2PC4081R,115  |
| 934031760135 | 2PC4081R,135  |
| 934031770115 | 2PC4081S,115  |
| 934031770135 | 2PC4081S,135  |
| 934061217215 | 2PD601ART,215 |
| 934061217235 | 2PD601ART,235 |
| 934034540215 | BAS40-05,215  |
| 934034540235 | BAS40-05,235  |
| 934020800215 | BAS70-04,215  |
| 934020800235 | BAS70-04,235  |
| 934034480115 | BAS70-04W,115 |
| 934034480135 | BAS70-04WF    |
| 933834100215 | BAS70-05,215  |
| 933834100235 | BAS70-05,235  |
| 934034490115 | BAS70-05W,115 |
| 934034490135 | BAS70-05W,135 |
| 934034500115 | BAS70-06W,115 |
| 934026750215 | BAS70-07,215  |
| 934045840115 | BAS70-07S,115 |
| 934059279115 | BAS70H,115    |
| 934057251315 | BAS70L,315    |
| 934034470115 | BAS70W,115    |
| 934034470135 | BAS70WF       |
| 934059956115 | BAS70XY,115   |
| 933932330215 | BCV46,215     |
| 933272310115 | BCX54,115     |
| 933272310146 | BCX54Z        |

|              |                 |
|--------------|-----------------|
| 933665120215 | BF820,215       |
| 933665120235 | BF820,235       |
| 933640890215 | BF822,215       |
| 933737140215 | BSR19A,215      |
| 934064794115 | BZT52H-B10,115  |
| 934064795115 | BZT52H-B11,115  |
| 934064796115 | BZT52H-B12,115  |
| 934064797115 | BZT52H-B13,115  |
| 934064798115 | BZT52H-B15,115  |
| 934064799115 | BZT52H-B16,115  |
| 934064801115 | BZT52H-B18,115  |
| 934064802115 | BZT52H-B20,115  |
| 934064803115 | BZT52H-B22,115  |
| 934064804115 | BZT52H-B24,115  |
| 934064805115 | BZT52H-B27,115  |
| 934064777115 | BZT52H-B2V4,115 |
| 934064778115 | BZT52H-B2V7,115 |
| 934064806115 | BZT52H-B30,115  |
| 934064807115 | BZT52H-B33,115  |
| 934064808115 | BZT52H-B36,115  |
| 934064809115 | BZT52H-B39,115  |
| 934064779115 | BZT52H-B3V0,115 |
| 934064781115 | BZT52H-B3V3,115 |
| 934064782115 | BZT52H-B3V6,115 |
| 934064783115 | BZT52H-B3V9,115 |
| 934064811115 | BZT52H-B43,115  |
| 934064812115 | BZT52H-B47,115  |
| 934064784115 | BZT52H-B4V3,115 |
| 934064785115 | BZT52H-B4V7,115 |
| 934064813115 | BZT52H-B51,115  |
| 934064814115 | BZT52H-B56,115  |
| 934064786115 | BZT52H-B5V1,115 |
| 934064787115 | BZT52H-B5V6,115 |
| 934064815115 | BZT52H-B62,115  |
| 934064816115 | BZT52H-B68,115  |
| 934064788115 | BZT52H-B6V2,115 |
| 934064789115 | BZT52H-B6V8,115 |
| 934064817115 | BZT52H-B75,115  |
| 934064791115 | BZT52H-B7V5,115 |
| 934064792115 | BZT52H-B8V2,115 |
| 934064793115 | BZT52H-B9V1,115 |
| 934059401115 | BZT52H-C10,115  |
| 934059402115 | BZT52H-C11,115  |
| 934059403115 | BZT52H-C12,115  |
| 934059405115 | BZT52H-C13,115  |
| 934059406115 | BZT52H-C15,115  |

|              |                 |
|--------------|-----------------|
| 934059407115 | BZT52H-C16,115  |
| 934059408115 | BZT52H-C18,115  |
| 934059409115 | BZT52H-C20,115  |
| 934059411115 | BZT52H-C22,115  |
| 934059412115 | BZT52H-C24,115  |
| 934059413115 | BZT52H-C27,115  |
| 934059384115 | BZT52H-C2V4,115 |
| 934059385115 | BZT52H-C2V7,115 |
| 934059414115 | BZT52H-C30,115  |
| 934059415115 | BZT52H-C33,115  |
| 934059416115 | BZT52H-C36,115  |
| 934059417115 | BZT52H-C39,115  |
| 934059386115 | BZT52H-C3V0,115 |
| 934059387115 | BZT52H-C3V3,115 |
| 934059388115 | BZT52H-C3V6,115 |
| 934059389115 | BZT52H-C3V9,115 |
| 934059418115 | BZT52H-C43,115  |
| 934059419115 | BZT52H-C47,115  |
| 934059391115 | BZT52H-C4V3,115 |
| 934059392115 | BZT52H-C4V7,115 |
| 934059421115 | BZT52H-C51,115  |
| 934059422115 | BZT52H-C56,115  |
| 934059393115 | BZT52H-C5V1,115 |
| 934059394115 | BZT52H-C5V6,115 |
| 934059423115 | BZT52H-C62,115  |
| 934059424115 | BZT52H-C68,115  |
| 934059395115 | BZT52H-C6V2,115 |
| 934059396115 | BZT52H-C6V8,115 |
| 934059425115 | BZT52H-C75,115  |
| 934059397115 | BZT52H-C7V5,115 |
| 934059398115 | BZT52H-C8V2,115 |
| 934059399115 | BZT52H-C9V1,115 |
| 934663121115 | BZX384-A10X     |
| 934663122115 | BZX384-A11X     |
| 934663123115 | BZX384-A12X     |
| 934663124115 | BZX384-A13X     |
| 934663125115 | BZX384-A15X     |
| 934663126115 | BZX384-A16X     |
| 934663127115 | BZX384-A18X     |
| 934663128115 | BZX384-A20X     |
| 934663129115 | BZX384-A22X     |
| 934663130115 | BZX384-A24X     |
| 934663131115 | BZX384-A27X     |
| 934663106115 | BZX384-A2V4X    |
| 934663107115 | BZX384-A2V7X    |
| 934663132115 | BZX384-A30X     |

|              |                 |
|--------------|-----------------|
| 934663133115 | BZX384-A33X     |
| 934663134115 | BZX384-A36X     |
| 934663135115 | BZX384-A39X     |
| 934663108115 | BZX384-A3V0X    |
| 934663109115 | BZX384-A3V3X    |
| 934663110115 | BZX384-A3V6X    |
| 934663111115 | BZX384-A3V9X    |
| 934663136115 | BZX384-A43X     |
| 934663137115 | BZX384-A47X     |
| 934663112115 | BZX384-A4V3X    |
| 934663113115 | BZX384-A4V7X    |
| 934663138115 | BZX384-A51X     |
| 934663139115 | BZX384-A56X     |
| 934663114115 | BZX384-A5V1X    |
| 934663115115 | BZX384-A5V6X    |
| 934663140115 | BZX384-A62X     |
| 934663141115 | BZX384-A68X     |
| 934663116115 | BZX384-A6V2X    |
| 934663117115 | BZX384-A6V8X    |
| 934663142115 | BZX384-A75X     |
| 934663118115 | BZX384-A7V5X    |
| 934663119115 | BZX384-A8V2X    |
| 934663120115 | BZX384-A9V1X    |
| 934057373115 | BZX384-B10,115  |
| 934057374115 | BZX384-B11,115  |
| 934057375115 | BZX384-B12,115  |
| 934057376115 | BZX384-B13,115  |
| 934057377115 | BZX384-B15,115  |
| 934057377135 | BZX384-B15F     |
| 934057377145 | BZX384-B15Z     |
| 934057378115 | BZX384-B16,115  |
| 934057379115 | BZX384-B18,115  |
| 934057380115 | BZX384-B20,115  |
| 934057381115 | BZX384-B22,115  |
| 934057382115 | BZX384-B24,115  |
| 934057383115 | BZX384-B27,115  |
| 934057358115 | BZX384-B2V4,115 |
| 934057359115 | BZX384-B2V7,115 |
| 934057384115 | BZX384-B30,115  |
| 934057385115 | BZX384-B33,115  |
| 934057385135 | BZX384-B33F     |
| 934057386115 | BZX384-B36,115  |
| 934057387115 | BZX384-B39,115  |
| 934057360115 | BZX384-B3V0,115 |
| 934057361115 | BZX384-B3V3,115 |
| 934057361135 | BZX384-B3V3F    |



|              |                 |
|--------------|-----------------|
| 934057363115 | BZX384-B3V6,115 |
| 934057362115 | BZX384-B3V9,115 |
| 934057388115 | BZX384-B43,115  |
| 934057389115 | BZX384-B47,115  |
| 934057364115 | BZX384-B4V3,115 |
| 934057365115 | BZX384-B4V7,115 |
| 934057390115 | BZX384-B51,115  |
| 934057391115 | BZX384-B56,115  |
| 934057391135 | BZX384-B56F     |
| 934057391145 | BZX384-B56Z     |
| 934057366115 | BZX384-B5V1,115 |
| 934057367115 | BZX384-B5V6,115 |
| 934057392115 | BZX384-B62,115  |
| 934057392135 | BZX384-B62F     |
| 934057392145 | BZX384-B62Z     |
| 934057393115 | BZX384-B68,115  |
| 934057393135 | BZX384-B68F     |
| 934057393145 | BZX384-B68Z     |
| 934057368115 | BZX384-B6V2,115 |
| 934057369115 | BZX384-B6V8,115 |
| 934057394115 | BZX384-B75,115  |
| 934057394135 | BZX384-B75F     |
| 934057370115 | BZX384-B7V5,115 |
| 934057370135 | BZX384-B7V5F    |
| 934057371115 | BZX384-B8V2,115 |
| 934057372115 | BZX384-B9V1,115 |
| 934057640115 | BZX384-C10,115  |
| 934057641115 | BZX384-C11,115  |
| 934057641135 | BZX384-C11F     |
| 934057642115 | BZX384-C12,115  |
| 934057643115 | BZX384-C13,115  |
| 934057644115 | BZX384-C15,115  |
| 934057644135 | BZX384-C15F     |
| 934057645115 | BZX384-C16,115  |
| 934057645135 | BZX384-C16F     |
| 934057646115 | BZX384-C18,115  |
| 934057647115 | BZX384-C20,115  |
| 934057648115 | BZX384-C22,115  |
| 934057649115 | BZX384-C24,115  |
| 934057650115 | BZX384-C27,115  |
| 934057625115 | BZX384-C2V4,115 |
| 934057626115 | BZX384-C2V7,115 |
| 934057651115 | BZX384-C30,115  |
| 934057652115 | BZX384-C33,115  |
| 934057653115 | BZX384-C36,115  |
| 934057654115 | BZX384-C39,115  |

|              |                 |
|--------------|-----------------|
| 934057654135 | BZX384-C39F     |
| 934057627115 | BZX384-C3V0,115 |
| 934057628115 | BZX384-C3V3,115 |
| 934057629115 | BZX384-C3V6,115 |
| 934057630115 | BZX384-C3V9,115 |
| 934057655115 | BZX384-C43,115  |
| 934057656115 | BZX384-C47,115  |
| 934057631115 | BZX384-C4V3,115 |
| 934057632115 | BZX384-C4V7,115 |
| 934057657115 | BZX384-C51,115  |
| 934057657135 | BZX384-C51F     |
| 934057658115 | BZX384-C56,115  |
| 934057633115 | BZX384-C5V1,115 |
| 934057634115 | BZX384-C5V6,115 |
| 934057659115 | BZX384-C62,115  |
| 934057660115 | BZX384-C68,115  |
| 934057635115 | BZX384-C6V2,115 |
| 934057636115 | BZX384-C6V8,115 |
| 934057661115 | BZX384-C75,115  |
| 934057637115 | BZX384-C7V5,115 |
| 934057637135 | BZX384-C7V5F    |
| 934057638115 | BZX384-C8V2,115 |
| 934057639115 | BZX384-C9V1,115 |
| 933958270215 | BZX84-A10,215   |
| 934057614215 | BZX84-A11,215   |
| 934011770215 | BZX84-A12,215   |
| 934055056215 | BZX84-A13,215   |
| 934015880215 | BZX84-A15,215   |
| 934065153215 | BZX84-A16,215   |
| 934065154215 | BZX84-A18,215   |
| 934065154235 | BZX84-A18,235   |
| 934054975215 | BZX84-A20,215   |
| 934065155215 | BZX84-A22,215   |
| 934065155235 | BZX84-A22,235   |
| 934065156215 | BZX84-A24,215   |
| 934016170215 | BZX84-A27,215   |
| 933959650215 | BZX84-A2V4,215  |
| 933959650235 | BZX84-A2V4,235  |
| 934023110215 | BZX84-A2V7,215  |
| 934065157215 | BZX84-A30,215   |
| 934065158215 | BZX84-A33,215   |
| 934039570215 | BZX84-A36,215   |
| 934045850215 | BZX84-A39,215   |
| 934019950215 | BZX84-A3V0,215  |
| 934031330215 | BZX84-A3V3,215  |
| 934043110215 | BZX84-A3V6,215  |

|              |                |
|--------------|----------------|
| 934011760215 | BZX84-A3V9,215 |
| 934054973215 | BZX84-A43,215  |
| 934028460215 | BZX84-A4V3,215 |
| 934032230215 | BZX84-A4V7,215 |
| 934054974215 | BZX84-A51,215  |
| 934013620215 | BZX84-A5V1,215 |
| 934013620235 | BZX84-A5V1,235 |
| 934018180215 | BZX84-A5V6,215 |
| 934015430215 | BZX84-A6V2,215 |
| 934023650215 | BZX84-A6V8,215 |
| 934014600215 | BZX84-A75,215  |
| 934023660215 | BZX84-A7V5,215 |
| 934011750215 | BZX84-A8V2,215 |
| 934014140215 | BZX84-A9V1,215 |
| 933770350215 | BZX84-B10,215  |
| 933770350235 | BZX84-B10,235  |
| 933770360215 | BZX84-B11,215  |
| 933770360235 | BZX84-B11,235  |
| 933770370215 | BZX84-B12,215  |
| 933770380215 | BZX84-B13,215  |
| 933770380235 | BZX84-B13,235  |
| 933770390215 | BZX84-B15,215  |
| 933770390235 | BZX84-B15,235  |
| 933770400215 | BZX84-B16,215  |
| 933770400235 | BZX84-B16VL    |
| 933770410215 | BZX84-B18,215  |
| 933770410235 | BZX84-B18,235  |
| 933770420215 | BZX84-B20,215  |
| 933770420235 | BZX84-B20,235  |
| 933770430215 | BZX84-B22,215  |
| 933770430235 | BZX84-B22,235  |
| 933770440215 | BZX84-B24,215  |
| 933770450215 | BZX84-B27,215  |
| 933770450235 | BZX84-B27,235  |
| 933770280215 | BZX84-B2V4,215 |
| 933770290215 | BZX84-B2V7,215 |
| 933551440215 | BZX84-B30,215  |
| 933770460215 | BZX84-B33,215  |
| 933770470215 | BZX84-B36,215  |
| 933770480215 | BZX84-B39,215  |
| 933770300215 | BZX84-B3V0,215 |
| 933770300235 | BZX84-B3V0,235 |
| 933551430215 | BZX84-B3V3,215 |
| 933770310215 | BZX84-B3V6,215 |
| 933770310235 | BZX84-B3V6VL   |
| 933643790215 | BZX84-B3V9,215 |

|              |                |
|--------------|----------------|
| 933770490215 | BZX84-B43,215  |
| 933770500215 | BZX84-B47,215  |
| 933770320215 | BZX84-B4V3,215 |
| 933770320235 | BZX84-B4V3,235 |
| 933567980215 | BZX84-B4V7,215 |
| 933770510215 | BZX84-B51,215  |
| 933770520215 | BZX84-B56,215  |
| 933643800215 | BZX84-B5V1,215 |
| 933643800235 | BZX84-B5V1,235 |
| 933564710215 | BZX84-B5V6,215 |
| 933564710235 | BZX84-B5V6,235 |
| 933770530215 | BZX84-B62,215  |
| 933770540215 | BZX84-B68,215  |
| 933671120215 | BZX84-B6V2,215 |
| 933671130215 | BZX84-B6V8,215 |
| 933770550215 | BZX84-B75,215  |
| 933696010215 | BZX84-B7V5,215 |
| 933696010235 | BZX84-B7V5,235 |
| 933770330215 | BZX84-B8V2,215 |
| 933770330235 | BZX84-B8V2,235 |
| 933770340215 | BZX84-B9V1,215 |
| 933137460215 | BZX84-C10,215  |
| 933137460235 | BZX84-C10,235  |
| 933137470215 | BZX84-C11,215  |
| 933137470235 | BZX84-C11,235  |
| 933137480215 | BZX84-C12,215  |
| 933137480235 | BZX84-C12,235  |
| 933388250215 | BZX84-C13,215  |
| 933388250235 | BZX84-C13,235  |
| 933388260215 | BZX84-C15,215  |
| 933388260235 | BZX84-C15,235  |
| 933388270215 | BZX84-C16,215  |
| 933388270235 | BZX84-C16,235  |
| 933388280215 | BZX84-C18,215  |
| 933388280235 | BZX84-C18,235  |
| 933388290215 | BZX84-C20,215  |
| 933388290235 | BZX84-C20,235  |
| 933388300215 | BZX84-C22,215  |
| 933388300235 | BZX84-C22,235  |
| 933388310215 | BZX84-C24,215  |
| 933388310235 | BZX84-C24,235  |
| 933388320215 | BZX84-C27,215  |
| 933388320235 | BZX84-C27,235  |
| 933516920215 | BZX84-C2V4,215 |
| 933516920235 | BZX84-C2V4,235 |
| 933516930215 | BZX84-C2V7,215 |

|              |                |
|--------------|----------------|
| 933516930235 | BZX84-C2V7,235 |
| 933388330215 | BZX84-C30,215  |
| 933388330235 | BZX84-C30,235  |
| 933388340215 | BZX84-C33,215  |
| 933388340235 | BZX84-C33,235  |
| 933388350215 | BZX84-C36,215  |
| 933388350235 | BZX84-C36,235  |
| 933388360215 | BZX84-C39,215  |
| 933388360235 | BZX84-C39,235  |
| 933516940215 | BZX84-C3V0,215 |
| 933516940235 | BZX84-C3V0,235 |
| 933516950215 | BZX84-C3V3,215 |
| 933516950235 | BZX84-C3V3,235 |
| 933516960215 | BZX84-C3V6,215 |
| 933516960235 | BZX84-C3V6,235 |
| 933516970215 | BZX84-C3V9,215 |
| 933516970235 | BZX84-C3V9,235 |
| 933388370215 | BZX84-C43,215  |
| 933388380215 | BZX84-C47,215  |
| 933388380235 | BZX84-C47,235  |
| 933516980215 | BZX84-C4V3,215 |
| 933516980235 | BZX84-C4V3,235 |
| 933137380215 | BZX84-C4V7,215 |
| 933137380235 | BZX84-C4V7,235 |
| 933388390215 | BZX84-C51,215  |
| 933388390235 | BZX84-C51,235  |
| 933388400215 | BZX84-C56,215  |
| 933137390215 | BZX84-C5V1,215 |
| 933137390235 | BZX84-C5V1,235 |
| 933137400215 | BZX84-C5V6,215 |
| 933137400235 | BZX84-C5V6,235 |
| 933388410215 | BZX84-C62,215  |
| 933388410235 | BZX84-C62,235  |
| 933388420215 | BZX84-C68,215  |
| 933388420235 | BZX84-C68,235  |
| 933137410215 | BZX84-C6V2,215 |
| 933137410235 | BZX84-C6V2,235 |
| 933137420215 | BZX84-C6V8,215 |
| 933137420235 | BZX84-C6V8,235 |
| 933388430215 | BZX84-C75,215  |
| 933388430235 | BZX84-C75,235  |
| 933137430215 | BZX84-C7V5,215 |
| 933137430235 | BZX84-C7V5,235 |
| 933137440215 | BZX84-C8V2,215 |
| 933137440235 | BZX84-C8V2,235 |
| 933137450215 | BZX84-C9V1,215 |

|              |                |
|--------------|----------------|
| 933137450235 | BZX84-C9V1,235 |
| 934660394135 | BZX84W-B10F    |
| 934660394115 | BZX84W-B10X    |
| 934660395135 | BZX84W-B11F    |
| 934660395115 | BZX84W-B11X    |
| 934660396135 | BZX84W-B12F    |
| 934660396115 | BZX84W-B12X    |
| 934660397135 | BZX84W-B13F    |
| 934660397115 | BZX84W-B13X    |
| 934660398135 | BZX84W-B15F    |
| 934660398115 | BZX84W-B15X    |
| 934660399135 | BZX84W-B16F    |
| 934660399115 | BZX84W-B16X    |
| 934660401135 | BZX84W-B18F    |
| 934660401115 | BZX84W-B18X    |
| 934660402135 | BZX84W-B20F    |
| 934660402115 | BZX84W-B20X    |
| 934660403135 | BZX84W-B22F    |
| 934660403115 | BZX84W-B22X    |
| 934660404135 | BZX84W-B24F    |
| 934660404115 | BZX84W-B24X    |
| 934660405135 | BZX84W-B27F    |
| 934660405115 | BZX84W-B27X    |
| 934660377135 | BZX84W-B2V4F   |
| 934660377115 | BZX84W-B2V4X   |
| 934660378135 | BZX84W-B2V7F   |
| 934660378115 | BZX84W-B2V7X   |
| 934660406135 | BZX84W-B30F    |
| 934660406115 | BZX84W-B30X    |
| 934660407135 | BZX84W-B33F    |
| 934660407115 | BZX84W-B33X    |
| 934660408135 | BZX84W-B36F    |
| 934660408115 | BZX84W-B36X    |
| 934660409135 | BZX84W-B39F    |
| 934660409115 | BZX84W-B39X    |
| 934660379135 | BZX84W-B3V0F   |
| 934660379115 | BZX84W-B3V0X   |
| 934660381135 | BZX84W-B3V3F   |
| 934660381115 | BZX84W-B3V3X   |
| 934660382135 | BZX84W-B3V6F   |
| 934660382115 | BZX84W-B3V6X   |
| 934660383135 | BZX84W-B3V9F   |
| 934660383115 | BZX84W-B3V9X   |
| 934660411135 | BZX84W-B43F    |
| 934660411115 | BZX84W-B43X    |
| 934660413135 | BZX84W-B47F    |

|              |              |
|--------------|--------------|
| 934660413115 | BZX84W-B47X  |
| 934660384135 | BZX84W-B4V3F |
| 934660384115 | BZX84W-B4V3X |
| 934660385135 | BZX84W-B4V7F |
| 934660385115 | BZX84W-B4V7X |
| 934660414135 | BZX84W-B51F  |
| 934660414115 | BZX84W-B51X  |
| 934660415135 | BZX84W-B56F  |
| 934660415115 | BZX84W-B56X  |
| 934660386135 | BZX84W-B5V1F |
| 934660386115 | BZX84W-B5V1X |
| 934660387135 | BZX84W-B5V6F |
| 934660387115 | BZX84W-B5V6X |
| 934660416135 | BZX84W-B62F  |
| 934660416115 | BZX84W-B62X  |
| 934660417135 | BZX84W-B68F  |
| 934660417115 | BZX84W-B68X  |
| 934660388135 | BZX84W-B6V2F |
| 934660388115 | BZX84W-B6V2X |
| 934660389135 | BZX84W-B6V8F |
| 934660389115 | BZX84W-B6V8X |
| 934660418135 | BZX84W-B75F  |
| 934660418115 | BZX84W-B75X  |
| 934660391135 | BZX84W-B7V5F |
| 934660391115 | BZX84W-B7V5X |
| 934660392135 | BZX84W-B8V2F |
| 934660392115 | BZX84W-B8V2X |
| 934660393135 | BZX84W-B9V1F |
| 934660393115 | BZX84W-B9V1X |
| 934660436135 | BZX84W-C10F  |
| 934660436115 | BZX84W-C10X  |
| 934660437135 | BZX84W-C11F  |
| 934660437115 | BZX84W-C11X  |
| 934660438135 | BZX84W-C12F  |
| 934660438115 | BZX84W-C12X  |
| 934660439135 | BZX84W-C13F  |
| 934660439115 | BZX84W-C13X  |
| 934660441135 | BZX84W-C15F  |
| 934660441115 | BZX84W-C15X  |
| 934660442135 | BZX84W-C16F  |
| 934660442115 | BZX84W-C16X  |
| 934660443135 | BZX84W-C18F  |
| 934660443115 | BZX84W-C18X  |
| 934660444135 | BZX84W-C20F  |
| 934660444115 | BZX84W-C20X  |
| 934660445135 | BZX84W-C22F  |

|              |              |
|--------------|--------------|
| 934660445115 | BZX84W-C22X  |
| 934660446135 | BZX84W-C24F  |
| 934660446115 | BZX84W-C24X  |
| 934660447135 | BZX84W-C27F  |
| 934660447115 | BZX84W-C27X  |
| 934660419135 | BZX84W-C2V4F |
| 934660419115 | BZX84W-C2V4X |
| 934660421135 | BZX84W-C2V7F |
| 934660421115 | BZX84W-C2V7X |
| 934660448135 | BZX84W-C30F  |
| 934660448115 | BZX84W-C30X  |
| 934660449135 | BZX84W-C33F  |
| 934660449115 | BZX84W-C33X  |
| 934660451135 | BZX84W-C36F  |
| 934660451115 | BZX84W-C36X  |
| 934660452135 | BZX84W-C39F  |
| 934660452115 | BZX84W-C39X  |
| 934660422135 | BZX84W-C3V0F |
| 934660422115 | BZX84W-C3V0X |
| 934660423135 | BZX84W-C3V3F |
| 934660423115 | BZX84W-C3V3X |
| 934660424135 | BZX84W-C3V6F |
| 934660424115 | BZX84W-C3V6X |
| 934660425135 | BZX84W-C3V9F |
| 934660425115 | BZX84W-C3V9X |
| 934660453135 | BZX84W-C43F  |
| 934660453115 | BZX84W-C43X  |
| 934660454135 | BZX84W-C47F  |
| 934660454115 | BZX84W-C47X  |
| 934660426135 | BZX84W-C4V3F |
| 934660426115 | BZX84W-C4V3X |
| 934660427135 | BZX84W-C4V7F |
| 934660427115 | BZX84W-C4V7X |
| 934660455135 | BZX84W-C51F  |
| 934660455115 | BZX84W-C51X  |
| 934660456135 | BZX84W-C56F  |
| 934660456115 | BZX84W-C56X  |
| 934660428135 | BZX84W-C5V1F |
| 934660428115 | BZX84W-C5V1X |
| 934660429135 | BZX84W-C5V6F |
| 934660429115 | BZX84W-C5V6X |
| 934660457135 | BZX84W-C62F  |
| 934660457115 | BZX84W-C62X  |
| 934660458135 | BZX84W-C68F  |
| 934660458115 | BZX84W-C68X  |
| 934660431135 | BZX84W-C6V2F |



|              |                |
|--------------|----------------|
| 934660431115 | BZX84W-C6V2X   |
| 934660432135 | BZX84W-C6V8F   |
| 934660432115 | BZX84W-C6V8X   |
| 934660459135 | BZX84W-C75F    |
| 934660459115 | BZX84W-C75X    |
| 934660433135 | BZX84W-C7V5F   |
| 934660433115 | BZX84W-C7V5X   |
| 934660434135 | BZX84W-C8V2F   |
| 934660434115 | BZX84W-C8V2X   |
| 934660435135 | BZX84W-C9V1F   |
| 934660435115 | BZX84W-C9V1X   |
| 934061416215 | PBHV8115T,215  |
| 934061414215 | PBHV8540T,215  |
| 934061415215 | PBHV9040T,215  |
| 934061415235 | PBHV9040TVL    |
| 934061417215 | PBHV9115T,215  |
| 934061417235 | PBHV9115TVL    |
| 934058645115 | PBLS4002Y,115  |
| 934056606215 | PBSS4240T,215  |
| 934056606235 | PBSS4240TVL    |
| 934056604215 | PBSS4350T,215  |
| 934056604235 | PBSS4350TVL    |
| 934056607215 | PBSS5240T,215  |
| 934056607235 | PBSS5240TVL    |
| 934056855215 | PBSS5320T,215  |
| 934055946115 | PBSS5350D,115  |
| 934055946125 | PBSS5350D,125  |
| 934055946135 | PBSS5350D,135  |
| 934056605215 | PBSS5350T,215  |
| 934056605235 | PBSS5350TVL    |
| 934057672215 | PBSS8110T,215  |
| 934057672235 | PBSS8110TVL    |
| 934057669215 | PBSS9110T,215  |
| 934058983215 | PDTB123YT,215  |
| 934058981215 | PDTD113ZT,215  |
| 934058981235 | PDTD113ZTVL    |
| 934017340215 | PLVA650A,215   |
| 934017350215 | PLVA653A,215   |
| 934017360215 | PLVA656A,215   |
| 934017370215 | PLVA659A,215   |
| 934017370235 | PLVA659AVL     |
| 934017380215 | PLVA662A,215   |
| 934017390215 | PLVA665A,215   |
| 934017400215 | PLVA668A,215   |
| 934061454115 | PMBT3904YS,115 |
| 934061413215 | PMBTA44,215    |

|              |                 |
|--------------|-----------------|
| 933776100215 | PMBTA92,215     |
| 933776100235 | PMBTA92,235     |
| 934068673115 | PMEG10010ELRX   |
| 934069175115 | PMEG10020AELPX  |
| 934068675115 | PMEG10020AELRX  |
| 934068674115 | PMEG10020ELRX   |
| 934068902115 | PMEG10030ELPX   |
| 934057738115 | PMEG2005AEA,115 |
| 934057738135 | PMEG2005AEAF    |
| 934061457115 | PMEG2010BER,115 |
| 934061471115 | PMEG3010BEP,115 |
| 934061459115 | PMEG3010BER,115 |
| 934061468115 | PMEG3010EP,115  |
| 934061458115 | PMEG3010ER,115  |
| 934061473115 | PMEG3020BEP,115 |
| 934061462115 | PMEG3020BER,115 |
| 934063199115 | PMEG3020CEP,115 |
| 934063201115 | PMEG3020DEP,115 |
| 934061472115 | PMEG3020EP,115  |
| 934061461115 | PMEG3020ER,115  |
| 934061476115 | PMEG3030BEP,115 |
| 934061477115 | PMEG3050BEP,115 |
| 934061475115 | PMEG3050EP,115  |
| 934057752115 | PMEG4005AEA,115 |
| 934057752135 | PMEG4005AEAF    |
| 934057752145 | PMEG4005AEAZ    |
| 934057918115 | PMEG4010BEA,115 |
| 934057918135 | PMEG4010BEA,135 |
| 934061482115 | PMEG4010EP,115  |
| 934061465115 | PMEG4010ER,115  |
| 934065459115 | PMEG4010ETP,115 |
| 934066837115 | PMEG4010ETR,115 |
| 934061483115 | PMEG4020EP,115  |
| 934061466115 | PMEG4020ER,115  |
| 934065469115 | PMEG4020ETP,115 |
| 934065455115 | PMEG4020ETR,115 |
| 934061484115 | PMEG4030EP,115  |
| 934061467115 | PMEG4030ER,115  |
| 934065471115 | PMEG4030ETP,115 |
| 934662964115 | PMEG4030ETRX    |
| 934061485115 | PMEG4050EP,115  |
| 934065472115 | PMEG4050ETP,115 |
| 934060004115 | PMEG6002EB,115  |
| 934060004135 | PMEG6002EBF     |
| 934063241115 | PMEG6002EJ,115  |
| 934059512115 | PMEG6010CEJ,115 |

|              |                 |
|--------------|-----------------|
| 934059512135 | PMEG6010CEJF    |
| 934067653115 | PMEG6010ELRX    |
| 934061478115 | PMEG6010EP,115  |
| 934066838115 | PMEG6010ETR,115 |
| 934069174115 | PMEG6020AELPX   |
| 934068897115 | PMEG6020AELRX   |
| 934067654115 | PMEG6020ELRX    |
| 934061479115 | PMEG6020EP,115  |
| 934061464115 | PMEG6020ER,115  |
| 934066839115 | PMEG6020ETP,115 |
| 934067092115 | PMEG6020ETR,115 |
| 934068901115 | PMEG6030ELPX    |
| 934061481115 | PMEG6030EP,115  |
| 934067348115 | PMEG6030ETPX    |
| 934067592115 | PMEG6030EVPX    |
| 934067593115 | PMEG6045ETPX    |
| 934070876115 | PMEG60T30ELPX   |
| 934057896115 | PUMH15,115      |