

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	006	016	0000001605	See list below	Power Entry Module with Filter	5150	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)





List of part numbers affected				
5150.0011.0	5150.0021.0	5150.0031.0	5150.0041.0	
5150.0011.1	5150.0021.1	5150.0031.1	5150.0041.1	

2 Type of change

Implementation of V-Lock cord retaining feature as standard.

3 Detailed description of change

V-Lock feature integrated as standard (not an option anymore)

Old product appearance	New product appearance
<p>Protection class I</p> 	<p>Protection class I</p> 
<p>Protection class II</p> 	<p>Protection class II</p> 

4 Reason of change

V-Lock feature implemented as a standard feature

Product Change Notification					PCN 5150 with V-Lock		
owner	creation date	release date	released by	change order no	rev	page	D10-006-439
ismailbe	2016-07-06	2017-01-20	blumhe	2011286	A	1 of 2	

5 Release date

The change will be rolled-out starting ww 05/2017 (Date code 1705 or higher on label) and lasts approx. until end of the year 2017 depending on the variant.
For new orders, the order numbers are continuing to use according to the data sheet.
The delivery of the new variants is dependent of sales.

6 Impact of change and recommended action

Form	Yes	Socket has notch for V-Lock cord
Fit	No	There are no dimensional changes
Function	Yes	V-Lock feature is standard (not an option anymore)
Production Site	No	There is no change of the production site
Product Label	No	There is no change on the label

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet	5150	http://www.schurter.com/pdf/english/typ_5150.pdf

Product Change Notification					PCN 5150 with V-Lock		
owner	creation date	release date	released by	change order no	rev	page	D10-006-439
ismailbe	2016-07-06	2017-01-20	blumhe	2011286	A	2 of 2	