
End of Life Notification EOL19.005

10km 10Gb/s Bidi SFP+

FTLX2071D3xx (Gen1) Variants

This document is an End of Life Notification (EOL) for Finisar's variant SFP+ transceivers including 10km 10Gb/s Bidi SFP+ (Gen1)

Affected Part Numbers and Recommended Replacement Part Numbers

The Finisar part numbers affected by this EOL notice are as follows:

Finisar EOL Part Number	Suggested Replacement
FTLX2071D3xx (Gen1)	FTLX2072D3xx (Gen2)

Reason for Discontinuation

Key components have been discontinued, moving from platform Gen1 to Gen2.

End of Life Dates

No last time buy purchase orders

No last time shipment

Order Acceptance/Change Conditions

N/A

RMA Replacements

Finisar reserves the right to replace any of the discontinued products listed above returned under RMA (Return Material Authorization) with either the suggested replacement part or with a credit, at Finisar's discretion.

We apologize in advance for any inconvenience this may cause. Please do not hesitate to call on your local distributor, rep, or local Finisar sales manager for any additional information you need.

For More Information

Finisar Corporation
1389 Moffett Park Drive
Sunnyvale, CA 94089-1134
Tel. (408) 548-1000
Fax (408) 541-6138
sales@finisar.com
www.finisar.com