

**Annoumcent of the  
FA components  
discontinuation**

**IN Better  
Solution**

**Panasonic**  
INDUSTRY

**Product Discontinuation Announcement of  
LC4H Electronic Counter, LC4H-L Electronic Counter,  
LT4H-W Digital Timer, LC4H-W Electronic Counter**

Dear valued customers,

This letter is to notify you that the Timer, Counter, other FA components products will be discontinued due to discontinuation of its main parts and aging production equipment which is difficult to continue the production. We apologize for any inconvenience and appreciate your kind understanding.

**< End of order acceptance >                      End of March 2023**

\*Last delivery will be 6 months from the end of order date.

However, the delivery schedule may change depend on the order quantity.

**< Maintenance period >                      End of March 2027**

\*In case of product failure/defect under manufacturers' liability during the warranty period, we will prepare the replacement.

\*Parts will be prepared by considering above schedule.

However, depend on stocks and part suppliers' status, there is possibility we are unable to accept all orders. There is also possibility that we are unable to repair even within maintenance period, due to above reason.

Discontinuation on March 27th, 2023



< Discontinuation and recommended substitutes >

Discontinued product			Recommended substitute	
Product name		Series name		Number of models
Timer	Digital	LT4H-W Digital Timer (DIN□48)	18	There is no recommended replacement.
Counter		LC4H-W Electronic Counter (DIN□48)	12	
		LC4H Electronic Counter (DIN□48)	36	
		LC4H-L Electronic Counter (DIN□48)	36	


\*Includes special ordered products and accessories and optional items


More than

Discontinuation on March 27th, 2023

Series	Model number	Part number	Recommended substitutes
<b>LT4H-W Digital Timer</b>  *Includes custom-made items.	LT4HW8-AC240V	ATL6137	There is no recommended replacement.
	LT4HW-AC240V	ATL6117	
	LT4HW-AC240VS	ATL6187	
	LT4HW8-AC24V	ATL6130	
	LT4HW-AC24V	ATL6110	
	LT4HW-AC24VS	ATL6180	
	LT4HW8-DC24V	ATL6131	
	LT4HW-DC24V	ATL6111	
	LT4HW-DC24VS	ATL6181	
	LT4HWT8-AC240V	ATL6127	
	LT4HWT-AC240V	ATL6107	
	LT4HWT-AC240VS	ATL6177	
	LT4HWT8-AC24V	ATL6120	
	LT4HWT-AC24V	ATL6100	
	LT4HWT-AC24VS	ATL6170	
	LT4HWT8-DC24V	ATL6121	
	LT4HWT-DC24V	ATL6101	
	LT4HWT-DC24VS	ATL6171	
<b>LC4H-W Electronic Counter</b>  *Includes custom-made items.	LC4H-W-R6-AC240V	AEL6317	There is no recommended replacement.
	LC4H-W-R6-AC240VS	AEL6387	
	LC4H-W-R6-AC24V	AEL6310	
	LC4H-W-R6-AC24VS	AEL6380	
	LC4H-W-R6-DC24V	AEL6311	
	LC4H-W-R6-DC24VS	AEL6381	
	LC4H-W-T6-AC240V	AEL6307	
	LC4H-W-T6-AC240VS	AEL6377	
	LC4H-W-T6-AC24V	AEL6300	
	LC4H-W-T6-AC24VS	AEL6370	
	LC4H-W-T6-DC24V	AEL6301	
	LC4H-W-T6-DC24VS	AEL6371	

Discontinuation on March 27th, 2023

Series	Model number	Part number	Recommended substitutes	
LC4H Electronic Counter 	LC4H8-R4-AC240V	AEL5137	There is no recommended replacement.	
	LC4H-R4-AC240V	AEL5117		
	LC4H-R4-AC240VS	AEL5187		
	LC4H8-R4-AC24V	AEL5130		
	LC4H-R4-AC24V	AEL5110		
	LC4H-R4-AC24VS	AEL5180		
	*Includes custom-made items.	LC4H8-R4-DC24V		AEL5131
	LC4H-R4-DC24V	AEL5111		
	LC4H-R4-DC24VS	AEL5181		
	LC4H8-T4-AC240V	AEL5127		
	LC4H-T4-AC240V	AEL5107		
	LC4H-T4-AC240VS	AEL5177		
	LC4H8-T4-AC24V	AEL5120		
	LC4H-T4-AC24V	AEL5100		
	LC4H-T4-AC24VS	AEL5170		
	LC4H8-T4-DC24V	AEL5121		
	LC4H-T4-DC24V	AEL5101		
	LC4H-T4-DC24VS	AEL5171		
	LC4H8-R6-AC240V	AEL5337		
	LC4H-R6-AC240V	AEL5317		
	LC4H-R6-AC240VS	AEL5387		
	LC4H8-R6-AC24V	AEL5330		
	LC4H-R6-AC24V	AEL5310		
	LC4H-R6-AC24VS	AEL5380		
	LC4H8-R6-DC24V	AEL5331		
	LC4H-R6-DC24V	AEL5311		
	LC4H-R6-DC24VS	AEL5381		
	LC4H8-T6-AC240V	AEL5327		
	LC4H-T6-AC240V	AEL5307		
	LC4H-T6-AC240VS	AEL5377		
LC4H8-T6-AC24V	AEL5320			
LC4H-T6-AC24V	AEL5300			
LC4H-T6-AC24VS	AEL5370			
LC4H8-T6-DC24V	AEL5321			
LC4H-T6-DC24V	AEL5301			
LC4H-T6-DC24VS	AEL5371			

Series	Model number	Part number	Recommended substitutes	
LC4H-L Electronic Counter 	LC4HL8-R4-AC240V	AEL1137	There is no recommended replacement.	
	LC4HL-R4-AC240V	AEL1117		
	LC4HL-R4-AC240VS	AEL1187		
	LC4HL8-R4-AC24V	AEL1130		
	LC4HL-R4-AC24V	AEL1110		
	LC4HL-R4-AC24VS	AEL1180		
	*Includes custom-made items.	LC4HL8-R4-DC24V		AEL1131
	LC4HL-R4-DC24V	AEL1111		
	LC4HL-R4-DC24VS	AEL1181		
	LC4HL8-T4-AC240V	AEL1127		
	LC4HL-T4-AC240V	AEL1107		
	LC4HL-T4-AC240VS	AEL1177		
	LC4HL8-T4-AC24V	AEL1120		
	LC4HL-T4-AC24V	AEL1100		
	LC4HL-T4-AC24VS	AEL1170		
	LC4HL8-T4-DC24V	AEL1121		
	LC4HL-T4-DC24V	AEL1101		
	LC4HL-T4-DC24VS	AEL1171		
	LC4HL8-R6-AC240V	AEL1337		
	LC4HL-R6-AC240V	AEL1317		
	LC4HL-R6-AC240VS	AEL1387		
	LC4HL8-R6-AC24V	AEL1330		
	LC4HL-R6-AC24V	AEL1310		
	LC4HL-R6-AC24VS	AEL1380		
	LC4HL8-R6-DC24V	AEL1331		
	LC4HL-R6-DC24V	AEL1311		
	LC4HL-R6-DC24VS	AEL1381		
	LC4HL8-T6-AC240V	AEL1327		
	LC4HL-T6-AC240V	AEL1307		
	LC4HL-T6-AC240VS	AEL1377		
LC4HL8-T6-AC24V	AEL1320			
LC4HL-T6-AC24V	AEL1300			
LC4HL-T6-AC24VS	AEL1370			
LC4HL8-T6-DC24V	AEL1321			
LC4HL-T6-DC24V	AEL1301			
LC4HL-T6-DC24VS	AEL1371			

**Panasonic**  
INDUSTRY