

## Tools for contacts Han D® (09 15 ...)

| Identification  | Part number           | Drawing   | Dimensions in mm  |
|---|-----------------------|---|---|
| HARTING Service crimping tool<br>with locator<br>set for Han D®, Han E® | <b>09 99 000 0021</b> | Wire gauge Han D®<br>0.14 ... 1.5 mm <sup>2</sup> |    |
| BUCHANAN crimping tool  | <b>09 99 000 0888</b> | Wire gauge<br>0.14 ... 2.5 mm <sup>2</sup>        |    |
| HARTING crimping tool<br>with locator<br>for Han D®, Han E®, Han® C     | <b>09 99 000 0110</b> | Wire gauge Han D®<br>0.14 ... 1.5 mm <sup>2</sup> |   |
| HARTING Pneumatic crimping tool<br>CP 600                               | <b>09 99 000 0810</b> |   |  |
| Crimp die Han D®, Han E®, Han® C  | <b>09 99 000 0813</b> | Wire gauge Han D®<br>0.14 ... 1.5 mm <sup>2</sup> |  |
| Footswitch  | <b>09 99 000 0811</b> |   |  |
| Table fixing  | <b>09 99 000 0812</b> |   |  |

1) For wire gauge 0.14 and 0.25 mm<sup>2</sup> use only male contact 09 15 000 6107 or female contact 09 15 000 6207.