



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: 439

DATE: 13-Feb-2008

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX6909EO30	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6909EO30+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6909EO30+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6909EO30-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6909EO33	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6909EO33+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6909EO33+T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6909EO33-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO30	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO30+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO30+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6910EO30-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO33	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO33+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO33+T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6910EO33-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6916EO30+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6916EO30+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6916EO33+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6916EO33+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6916EO50+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6916EO50+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6917EO30	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO30+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO30+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6917EO30-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Mar-2008

Discontinuance	MAX6917EO33	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO33+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO33+T	N/A	13-May-2008	12-Feb-2010	The part was not released
Discontinuance	MAX6917EO33-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO50	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO50+	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO50+T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured
Discontinuance	MAX6917EO50-T	N/A	13-May-2008	12-Feb-2010	Part can no longer be manufactured