

HellermannTyton

6/15/2018

Re: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type		
<input checked="" type="checkbox"/> Production/assembly location	<input type="checkbox"/> Material	<input type="checkbox"/> End of Life w/ replacement
<input type="checkbox"/> Part Number	<input type="checkbox"/> Packaging	<input type="checkbox"/> End of Life w/o replacement
<input checked="" type="checkbox"/> Country of Origin	<input type="checkbox"/> Point of Purchase	<input type="checkbox"/> Additional tool/refurbishment
<input type="checkbox"/> Design (fit, form, function)	<input type="checkbox"/> Point of Pick up	<input type="checkbox"/> Cost/Lead Time
<input type="checkbox"/> Engineering record (non-fit, form, function)	<input type="checkbox"/> Supply Chain	<input type="checkbox"/> Process
Additional Information		
From: HellermannTyton Milwaukee 6701 W. Good Hope Road Milwaukee, WI 53224, USA	To: HellermannTyton Monterrey Av. Internacional – 140-A VYNMSA General Escobedo, Nuevo Leon, 66053 Mexico	
Scope		
HT PN	Customer PN	Change Effective*
CTAM10C2	1436-1321-ND	12/13/2018
CTAM110C2	1436-1319-ND	12/13/2018
CTAM110M4	1436-1111-ND	12/13/2018
CTAM20C2	1436-1322-ND	12/13/2018
CTAM210C2	1436-1320-ND	12/13/2018
CTAM210M4	1436-1112-ND	12/13/2018
CTM20C2	1436-1353-ND	11/29/2018
CTM20M4	1436-1149-ND	11/29/2018
CTM210C2	1436-1349-ND	11/29/2018
CTM30C2	1436-1352-ND	11/29/2018
CTM30M4	1436-1150-ND	11/29/2018
CTM310C2	1436-1350-ND	11/29/2018
CTM310M4	1436-1142-ND	11/29/2018
CTM40C2	1436-1354-ND	11/29/2018
CTM40M4	1436-1151-ND	11/29/2018
CTM410C2	1436-1351-ND	11/29/2018
CTM410M4	1436-1143-ND	11/29/2018
TM1SF0C2	1436-1328-ND	12/13/2018
TM1SF10C2	1436-1491-ND	12/13/2018
PBM0C2	1436-1342-ND	12/28/2018
PBM0M4	1436-1134-ND	12/28/2018
PBM10C2	1436-1336-ND	12/28/2018
PBM10M4	1436-1125-ND	12/28/2018
CTT20R0HSC2	1436-1645-ND	11/8/2018
CTT20R0HSM4	1436-1100-ND	11/8/2018
CTT20R9C2	1436-1488-ND	11/8/2018
CTT20R9M4	1436-1098-ND	11/8/2018
T18MR0C2	1436-1490-ND	11/8/2018
T18MR0M4	1436-1114-ND	11/8/2018

T18MR9C2	1436-1489-ND	11/8/2018
T18MR9M4	1436-1540-ND	11/8/2018
156-00282	1436-1426-ND	3/23/2019
156-00329	1436-1751-ND	3/23/2019
156-00457	156-00457-ND	3/23/2019
HDM190HIRC2	1436-1823-ND	1/8/2019
HDM3120HIRC2	1436-1016-ND	1/8/2019
IT18FL9C2	1436-1496-ND	11/8/2018
IT18FL9L4	1436-1415-ND	11/8/2018
RT250XL9X2	1436-1273-ND	3/23/2019
126-00049	1436-1040-ND	3/5/2019
HDM250HIRC2	1436-1015-ND	10/23/2018
T30MR0C2	1436-1492-ND	2/8/2019
T30MR0M4	1436-1120-ND	2/8/2019
T30MR9C2	1436-1604-ND	2/8/2019
T30MR9M4	1436-1544-ND	2/8/2019
T30RSF0M4	1436-1551-ND	2/8/2019
T30RSF9C2	1436-1614-ND	2/8/2019
T30RSF9M4	1436-1547-ND	2/8/2019
T50RTM250HSM4	1436-1835-ND	3/23/2019
T50RTM25E8HM4	1436-1153-ND	3/23/2019
T50RDH0UVC2	1436-1502-ND	3/23/2019
T50RSF0C2	1436-1501-ND	3/5/2019
RT250R9X2	1436-1263-ND	3/23/2019
RT255R0HIRX2	1436-1264-ND	3/23/2019
SR255X0HIHSUVX2	SR255X0HIHSUVX2-ND	1/8/2019
T255M0HIRX2	1436-1268-ND	3/23/2019
T255R0HIRX2	1436-1455-ND	3/23/2019
T255S0HIRX2	1436-1260-ND	3/23/2019

*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 6/25/2018, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Todd Franz
Quality Project Administrator
Office: 414 355 1130 x 8656
Email: tfranz@htamericas.com