

Product Discontinuation

PDN-AI-7063-2021

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
AI - Automation Infrastructure	DNN	Product Discontinuation	Notify Distributors and Field	7/26/2021

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Discontinuation due to short notice component obsolescence and supply shortage. If you have any questions, please contact our sales team.

Stock Status

Can existing stock still be used?

Is mixture of stock acceptable?

Transaction Dates

Last Buy from Phoenix Contact: 12/31/2021

Last Scheduled Ship from Phoenix Contact: 2/25/2022

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Ken Austin
kaustin@phoenixcontact.com

Thank you,

Dan Schaffer

Senior Product Marketing Manager



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
2891933	FL SWITCH SFN 16TX	1085255	FL SWITCH 1016N
2891934	FL SWITCH SFN 15TX/FX		
2891935	FL SWITCH SFN 14TX/2FX		