



Product Obsolescence Notification

EC# 10447440

With Replacement

To: All active customers
From: Cathy Maly Product Manager Mini-Fit
cc:
Date February 10, 2010


Series / Product Family: 5556, 5558

Part Numbers Affected:	Part numbers being obsoleted	Replacement part numbers
	39000053	39000430
	39000054	39000431
	39000055	39000428
	39000087	39000432
	39000088	39000433
	39000163	39000428
	39000164	39000429
	39000165	39000434
	39000166	39000435
	39000167	39000447
	39000168	39000448
	39000405	39000440
	39000436	39000153
	50291647	39000434
	50291648	39000447
	50291646	39000428

Product Description: Mini-Fit Jr.™ Crimp Terminals

Reason for Obsolescence: When the RoHS initiative was implemented new part numbers were created in Japan as well as for other specific accounts, which caused duplicate lead free part numbers, these duplicate part numbers are being eliminated in order to reduce redundancies. All parts have drop in replacement part numbers.

Product Image:



Last Order Entry Date: 4/10/2010

Obsolescence Effective Date: 4/10/2010

For further information please contact your local sales representative.