

Information note

Topic u-connectXpress 8.2.0 for ODIN-W2
UBX-22001798 C1-Public

Author Len Albertsson

Date 4 March 2022

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com.
Copyright© u-blox AG.

1 Affected products

Product name	Remarks
ODIN-W260	
ODIN-W262	
ODIN-W263	

2 Type

- | | |
|---|--|
| <input type="checkbox"/> Product status change | <input checked="" type="checkbox"/> Documentation update |
| <input type="checkbox"/> Hardware/component change | <input type="checkbox"/> Certification information |
| <input checked="" type="checkbox"/> Software update | <input type="checkbox"/> Security advisory |
| <input type="checkbox"/> Label change | <input type="checkbox"/> Other |

3 Description

The u-connectXpress software version 8.2.0 for the ODIN-W2 series of Wi-Fi and Bluetooth multiradio modules has now been released. A complete description of the software, including new features and bug corrections, is provided in the release note [1]. The AT commands manual [3] has been updated accordingly.

4 Schedule

u-connectXpress v8.2.0 and related documentation is released and now available for download at u-blox.com

5 Customer impact and recommended action

A review of the software updates described in the release note [1] is advised.

u-connectXpress 8.2.0 can be flashed to any existing ODIN-W2 module.

6 Related documentation

- [1] u-connectXpress 8.2.0 release note, [UBX-22001015](#)
- [2] ODIN-W2 data sheet, [UBX-14039949](#)
- [3] u-connectXpress AT commands manual, [UBX-14044127](#)