

Product Discontinuation Notice


May, 2010

Discontinuation of EP relay (60A)



1. Reason: Replacement part

2. Affected parts:

EP (AEP) relays 	60 A type	AEP160○○
--	-----------	----------

3. Last time buy: End of October 2010

4. Substitution:

EP relays NEW 60 A type	AEP160○○1
----------------------------	-----------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1169)